

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Revert

Claim Reference: SNM18D00703C01/9
Assessment Number: GR000104
Version: CHENGABS/2
Date Calculated: 23/02/2018 08:36

Full Report - V1
Registration: SKA799T
Printed: 23/02/2018 16:37

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR LAU	Date of Incident:	02/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00703C01/9	Estimated Repair Time:	
Policy Number:	DMPCSN3102791600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	C Class
Sub Model:	C 200 CGI BE
Model Sheet Number:	304 26
Registration:	SKA799T
Registration Month:	October
Registration Year:	2010
VIN Number:	WDD2040482A409589
Odometer:	Not Known
Colour:	Black
Engine Number:	27186030087602
Fuel Level:	%



Model Specs

FR A395./F500./R131.	TECH CHANGE 09/02
MODEL 2010	RAIN SENSOR
DIPPING MIRROR	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY
ALU DESIGN PARTS	EQUIPMENT AVANTGARDE
DRIVER SEAT MEMORY	L/F SEAT WITH MEMORY
STRG WHEEL LEATHER	LEATHER STRG WHEEL
H/DUTY ALTERNATOR	ENGINE PROTECTION
AUTO GEARBOX 5 SPEED	PARAMETER STEERING
CRUISE CONTROL	TYRES 225/45 WR 17
WHEELS 7.5J X 17 ALU	SPARE WHEEL
PARKTRONIC SYSTEM	RIGHT HAND DRIVE
TWO COAT METALLIC	CLEAR COAT HARD

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	09/02/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$736.00
Total Paint/Material	\$161.41
Total Parts	\$8,194.66
Total of Additional Costs	\$2,527.30
Excess:	TBA
Grand Total Exc GST:	\$11,619.37
0 % GST:	\$0.00
Grand Total Inc GST:	\$11,619.37

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
 Price/Dent = \$46.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	CARRY OUT SHORT TEST	3.0	13.80
72-1515 01	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	33.0	151.80
72-1682 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-1691 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1751 01	ADDITION TO RENEW R/DOOR (2ND DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1760 01	ADDITION TO RENEW R/DOOR (2ND DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-1640 01	RENEW R/R DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS	37.0	170.20
72-2698 01	RENEW RIGHT REAR LOWER DOOR HINGE	7.0	32.20
88-8802 01	R + R REAR BUMPER	7.0	32.20
88-8806 03)	RENEW REAR BUMPER	2.0	9.20
88-8905 01	ADD TO RENEW REAR BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.80
88-8910 ZAX	ADDITION TO RENEW REAR BUMPER (VEHICLE WITH PARKTRONIC SYSTEM)	3.0	13.80
91-2587 01	R + R R/F HEADREST	3.0	13.80
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.20

LABOUR COST

Total Work Units	106.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	10.6HRS	\$487.60
Paint Labour	5.4HRS	\$248.40
Total Labour	16.0HRS	\$736.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
1482	RIGHT FRONT DOOR NEW PART PAINTING	15.0	
1782	R/R DOOR NEW PART PAINTING	13.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R	12.0	
LABOUR COST - PAINT			
	TIME(PAINT)	40.0	
	Preparation Main Work Metal	9.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	54.0	
	Total Paintwork Labour	5.4HRS	\$248.40
MATERIAL COST - PAINT			
	New Part Painting		\$73.79
	New Part Painting - Plastic K1R		\$60.52
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$161.41
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$161.41

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
2615	1	CTR REAR BUMPER MLDG	204 885 0421		0% 105.00*
1000	1	R/F DOOR CHECKER	Renew		0% 0.00
1578	1	R/F DOOR LOCK	204 720 1635		0% 270.00*
1682	1	R/F DOOR MOULDING	204 720 0280		0% 160.00*
1510	1	R/F DOOR SEAL	204 727 1187		0% 260.00*
4598	1	R/F SEAT HEADREST	204 970 6850 9E43		0% 820.00*
1672	1	R/F UPPER DOOR TRIM	204 725 0271 9051		0% 140.00*
1552	1	R/F WINDOW MOTOR	204 820 0242		0% 580.00*
2646	1	R/R BUMPER DAMPER	204 682 1630		0% 40.00*
1782	1	R/R DOOR	204 730 2200 64		0% 1,400.00*
1000	1	R/R DOOR CHECKER	Renew		0% 0.00
1982	1	R/R DOOR MOULDING	204 730 0280		0% 160.00*
1810	1	R/R DOOR SEAL	204 727 1187		0% 260.00*
1796	1	R/R LWR DOOR HINGE	204 730 1337		0% 135.00*
1848	1	R/R QUARTER GLASS	204 730 3600		0% 37.45U
1852	1	R/R WINDOW MOTOR	204 820 0642		0% 590.00*
2583	1	REAR BUMPER COVER	204 880 1340 9999		0% 1,250.00*
1482	1	RIGHT FRONT DOOR	204 720 6000 64		0% 1,400.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% 50.00*
1849	1	RR D/WDW BONDING KIT	000 670 0100		0% 51.75U

f: OEM Parts	Sub Total	\$7,709.20
g: Original	Mark Up From Cost (5 %)	\$385.46
h: Secondhand	Sundry Parts (Fixed)	\$100.00
p: Parallel	Total Parts	\$8,194.66
x: Exchange		

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras				
Description		Betterment		Price
GST FOR PARTS	SPECIALIST	0%		\$902.30
FRONT RIGHT RIM	SPECIALIST			\$800.00
REAR RIGHT RIM	SPECIALIST	0%		\$800.00
REAR SEALANT	SPECIALIST			\$25.00
			Total Extras	\$2,527.30

Final Calculation

Total Parts		\$8,194.66
Labour		
Total Panel/Mechanical	\$487.60	
Total Paintwork	\$248.40	
Total Labour		\$736.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$2,527.30	
Total of Additional Costs		\$2,527.30
Total Paint/Material Costs		\$161.41
Grand Total Excludes GST		\$11,619.37
GST @ 0 %		\$0.00
Grand Total Includes GST		\$11,619.37

Assessment Notes

Veron Chen (LKKAUTO)

From: CLAIMS@CHENG AUTO.COM
Sent: Thursday, 3 May 2018 10:34 AM
To: Veron Chen (LKKAUTO)
Cc: SUR; Rasul (LKKAUTO)
Subject: Re: SKA 799T-DOA: 2/2/2018

Dear Ms. Veron Chen,

Your Claim Ref. No. : SNM18D00703C01/9

CHENG AUTO Ref. No. : SKA799T / ANG
PUAY
GEE

Insured Name : ANG PUAY GEE
Policy Number : DMPCSN3102791600
Insurer/Policy Type : CHINA TAIPING INSURANCE / COMPREHENSIVE
Date of Loss : 02/02/2018
Our Vehicle No. : SKA799T
TP Vehicle No. : SHC8860X /

We refer to your offer of Lump Sum \$5700/ before excess \$50/. We accept offer.

Thanks & Best Regards,

Muru
Claims Department



CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

Email: cab@chengauto.com

Windscreen

Address: 5 Soon Lee Street #01-41 Pioneer Point, Singapore 627607

Email: windscreen@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

Email: cab@chengauto.com

On 2/5/2018 10:57 AM, Veron Chen (LKKAUTO) wrote:

Dear Sir,

Please refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 30 April 2018 2:52 PM

To: 'CLAIMS@CHENGAUTO.COM' <CLAIMS@CHENGAUTO.COM>

Cc: SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: RE: SKA 799T-DOA: 2/2/2018

Dear Sir,

Please re-confirmed Lump Sum \$5700/ before excess \$50/

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 25 April 2018 5:08 PM

To: CLAIMS@CHENGAUTO.COM

Cc: SUR <sur@lkkauto.com>

Subject: RE: SKA 799T-DOA: 2/2/2018

Dear Sir,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CLAIMS@CHENGAUTO.COM [mailto:CLAIMS@CHENGAUTO.COM]

Sent: Wednesday, 25 April 2018 4:37 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Re: SKA 799T-DOA: 2/2/2018

Dear Veron,

Your Claim Ref. No.	: SNM18D00703C01/9	
CHENG AUTO Ref. No.	: SKA799T	/ ANG PUAY GEE
Insured Name	: ANG PUAY GEE	
Policy Number	: DMPCSN3102791600	
Insurer/Policy Type	: CHINA TAIPING	/
	: INSURANCE	COMPREHENSIVE
Date of Loss	: 02/02/2018	
Our Vehicle No.	: SKA799T	
TP Vehicle No.	: SHC8860X	

We refer to your offer.

We accept the offer S\$6,650.00 (before excess \$50) & 07 days.

Thank you.

Thanks & Best Regards,
Claims Department



CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

Email: cab@chengauto.com

Windscreen

Address: 5 Soon Lee Street #01-41 Pioneer Point, Singapore 627607

Email: windscreen@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

Email: cab@chengauto.com

On 17/4/2018 3:06 PM, Veron Chen (LKKAuto) wrote:

Dear Mu Ru,

Offer Lump Sum \$6650 before excess \$50, please confirmed.

No of days: 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 25 April 2018 5:08 PM
To: CLAIMS@CHENG AUTO.COM
Cc: SUR
Subject: RE: SKA 799T-DOA: 2/2/2018

Dear Sir,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CLAIMS@CHENG AUTO.COM [mailto:CLAIMS@CHENG AUTO.COM]
Sent: Wednesday, 25 April 2018 4:37 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: SKA 799T-DOA: 2/2/2018

Dear Veron,

Your Claim Ref. No.	: SNM18D00703C01/9	
CHENG AUTO Ref. No.	: SKA799T	/ ANG PUAY GEE
Insured Name	: ANG PUAY GEE	
Policy Number	: DMPCSN3102791600	
Insurer/Policy Type	: CHINA TAIPING INSURANCE	/ COMPREHENSIVE
Date of Loss	: 02/02/2018	
Our Vehicle No.	: SKA799T	
TP Vehicle No.	: SHC8860X	

We refer to your offer.

We accept the offer S\$6,650.00 (before excess \$50) & 07 days.

Thank you.

Thanks & Best Regards,
Claims Department



CHENG AUTO BODYWORKS

HP: 8666 7775 | **Office-Tel:** 6631 0707 | **Fax:** 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

Email: cab@chengauto.com

Windscreen

Address: 5 Soon Lee Street #01-41 Pioneer Point, Singapore 627607

Email: windscreen@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

Email: cab@chengauto.com

On 17/4/2018 3:06 PM, Veron Chen (LKKAuto) wrote:

Dear Mu Ru,

Offer Lump Sum \$6650 before excess \$50, please confirmed.

No of days: 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore

408933

Finalised

Claim Reference: SNM18D00703C01/9
Assessment Number: GR000104
Version: LKKAUTOC/4
Date Calculated: 17/04/2018 07:50

Full Report - V1
Registration: SKA799T
Printed: 17/04/2018 14:50

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	02/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00703C01/9	Estimated Repair Time:	
Policy Number:	DMPCSN3102791600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	C Class
Sub Model:	C 200 CGI BE
Model Sheet Number:	304 26
Registration:	SKA799T
Registration Month:	October
Registration Year:	2010
VIN Number:	WDD2040482A409589
Odometer:	Not Known
Colour:	Black
Engine Number:	27186030087602
Fuel Level:	%



Model Specs

FR A395./F500./R131.	TECH CHANGE 09/02
MODEL 2010	RAIN SENSOR
DIPPING MIRROR	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY
ALU DESIGN PARTS	EQUIPMENT AVANTGARDE
DRIVER SEAT MEMORY	L/F SEAT WITH MEMORY
STRG WHEEL LEATHER	LEATHER STRG WHEEL
H/DUTY ALTERNATOR	ENGINE PROTECTION
AUTO GEARBOX 5 SPEED	PARAMETER STEERING
CRUISE CONTROL	TYRES 225/45 WR 17
WHEELS 7.5J X 17 ALU	SPARE WHEEL
PARKTRONIC SYSTEM	RIGHT HAND DRIVE
TWO COAT METALLIC	CLEAR COAT HARD

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
	Date of Inspection: 09/02/2018
Brakes Pedal Travel:	
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	



Addresses

Cost Summary

Total Labour	\$703.80
Total Paint/Material	\$161.41
Total Parts	\$5,843.96
Total of Additional Costs	\$1,625.00
Excess:	TBA
Grand Total Exc GST:	\$8,334.17
0 % GST:	\$0.00
Grand Total Inc GST:	\$8,334.17

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
 Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	CARRY OUT SHORT TEST	3.0	13.80
72-1515 01	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	33.0	151.80
72-1682 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-1691 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1751 01	ADDITION TO RENEW R/DOOR (2ND DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1760 01	ADDITION TO RENEW R/DOOR (2ND DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-1640 01	RENEW R/R DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS	37.0	170.20
88-8802 01	R + R REAR BUMPER	7.0	32.20
88-8806 03)	RENEW REAR BUMPER	2.0	9.20
88-8905 01	ADD TO RENEW REAR BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.80
88-8910 ZAX	ADDITION TO RENEW REAR BUMPER (VEHICLE WITH PARKTRONIC SYSTEM)	3.0	13.80
91-2587 01	R + R R/F HEADREST	3.0	13.80
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.20
LABOUR COST		99.0	
Total Work Units			

Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	9.9HRS	\$455.40
Paint Labour	5.4HRS	\$248.40
Total Labour	15.3HRS	\$703.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
1482	RIGHT FRONT DOOR NEW PART PAINTING	15.0	
1782	R/R DOOR NEW PART PAINTING	13.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R	12.0	
LABOUR COST - PAINT			
	TIME(PAINT)	40.0	
	Preparation Main Work Metal	9.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	54.0	
	Total Paintwork Labour	5.4HRS	\$248.40
MATERIAL COST - PAINT			
	New Part Painting		\$73.79
	New Part Painting - Plastic K1R		\$60.52
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$161.41
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$161.41

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
2615	1	CTR REAR BUMPER MLDG	204 885 0421		0% 105.00*
1000	1	R/F DOOR CHECKER	Renew		0% 0.00
1578	1	R/F DOOR LOCK	204 720 1635		0% 270.00*
1682	1	R/F DOOR MOULDING	204 720 0280		0% 160.00*
1510	1	R/F DOOR SEAL	204 727 1187		0% 260.00*
4598	1	R/F SEAT HEADREST	204 970 6850 9E43		0% 115.00*
1782	1	R/R DOOR	204 730 2200 64		0% 1,400.00*
1000	1	R/R DOOR CHECKER	Renew		0% 0.00
1982	1	R/R DOOR MOULDING	204 730 0280		0% 160.00*
1810	1	R/R DOOR SEAL	204 727 1187		0% 260.00*
1848	1	R/R QUARTER GLASS	204 730 3600		0% 38.69U
2583	1	REAR BUMPER COVER	204 880 1340 9999		0% 1,250.00*
1482	1	RIGHT FRONT DOOR	204 720 6000 64		0% 1,400.00*
1849	1	RR D/WDW BONDING KIT	000 670 0100		0% 51.75U
			Sub Total		\$5,470.44
f: OEM Parts			Mark Up From Cost	(5 %)	\$273.52
g: Original			Sundry Parts	(Fixed)	\$100.00
h: Secondhand			Total Parts		\$5,843.96
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	GST FOR PARTS SPECIALIST	0%	\$0.00
	FRONT RIGHT RIM SPECIALIST		\$800.00
	REAR RIGHT RIM SPECIALIST	0%	\$800.00
	REAR SEALANT SPECIALIST		\$25.00
Total Extras			\$1,625.00

Final Calculation

Total Parts			\$5,843.96
Labour			
	Total Panel/Mechanical	\$455.40	
	Total Paintwork	\$248.40	
Total Labour			\$703.80
Additional Costs			
	Corr Prot Materials External	\$0.00	
	Corr Prot Materials Internal	\$0.00	
	Cost of Specialist	\$1,625.00	
Total of Additional Costs			\$1,625.00
Total Paint/Material Costs			\$161.41
Grand Total Excludes GST			\$8,334.17
	GST @ 0 %		\$0.00
Grand Total Includes GST			\$8,334.17

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore

408933

Re-finalised

Claim Reference: SNM18D00703C01/9
Assessment Number: GR000104
Version: LKKAUTOC/4
Date Calculated: 27/04/2018 02:35

Full Report - V1
Registration: SKA799T
Printed: 27/04/2018 09:36

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	02/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00703C01/9	Estimated Repair Time:	
Policy Number:	DMPCSN3102791600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	C Class
Sub Model:	C 200 CGI BE
Model Sheet Number:	304 26
Registration:	SKA799T
Registration Month:	October
Registration Year:	2010
VIN Number:	WDD2040482A409589
Odometer:	Not Known
Colour:	Black
Engine Number:	27186030087602
Fuel Level:	%



Model Specs

FR A395./F500./R131.	TECH CHANGE 09/02
MODEL 2010	RAIN SENSOR
DIPPING MIRROR	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY
ALU DESIGN PARTS	EQUIPMENT AVANTGARDE
DRIVER SEAT MEMORY	L/F SEAT WITH MEMORY
STRG WHEEL LEATHER	LEATHER STRG WHEEL
H/DUTY ALTERNATOR	ENGINE PROTECTION
AUTO GEARBOX 5 SPEED	PARAMETER STEERING
CRUISE CONTROL	TYRES 225/45 WR 17
WHEELS 7.5J X 17 ALU	SPARE WHEEL
PARKTRONIC SYSTEM	RIGHT HAND DRIVE
TWO COAT METALLIC	CLEAR COAT HARD

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	09/02/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$703.80
Total Paint/Material	\$161.41
Total Parts	\$5,843.96
Total of Additional Costs	\$400.00
Excess:	TBA
Grand Total Exc GST:	\$7,109.17
0 % GST:	\$0.00
Grand Total Inc GST:	\$7,109.17

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
 Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	CARRY OUT SHORT TEST	3.0	13.80
72-1515 01	RENEW R/F DOOR	33.0	151.80
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
72-1682 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-1691 01	ADDITION TO RENEW R/DOOR (1ST DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1751 01	ADDITION TO RENEW R/DOOR (2ND DOOR) (VEHICLE WITH DOOR SPEAKERS)	2.0	9.20
72-1760 01	ADDITION TO RENEW R/DOOR (2ND DOOR) (VEHICLE WITH LOWER MOULDING)	1.0	4.60
72-1640 01	RENEW R/R DOOR	37.0	170.20
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS		
88-8802 01	R + R REAR BUMPER	7.0	32.20
88-8806 03)	RENEW REAR BUMPER	2.0	9.20
88-8905 01	ADD TO RENEW REAR BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.80
88-8910 ZAX	ADDITION TO RENEW REAR BUMPER (VEHICLE WITH PARKTRONIC SYSTEM)	3.0	13.80
91-2587 01	R + R R/F HEADREST	3.0	13.80
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.20
LABOUR COST			
Total Work Units		99.0	

Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	9.9HRS	\$455.40
Paint Labour	5.4HRS	\$248.40
Total Labour	15.3HRS	\$703.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
1482	RIGHT FRONT DOOR NEW PART PAINTING	15.0	
1782	R/R DOOR NEW PART PAINTING	13.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R	12.0	
LABOUR COST - PAINT		40.0	
TIME(PAINT)		9.0	
Preparation Main Work Metal		5.0	
Preparation Comp. Work Plastic		0.0	
Preparation Work Multi Layer Paint		54.0	
Total Work Units (10WU/HR)		5.4HRS	\$248.40
Total Paintwork Labour			Cost Price
MATERIAL COST - PAINT			\$73.79
New Part Painting			\$60.52
New Part Painting - Plastic K1R			\$18.10
Material-Const Main Work Metal			\$9.00
Material-Const Comp. Work Plastic			\$161.41
Total Excluding Pearlescent Uplift			\$0.00
Pearlescent Uplift @ 0.0%			\$161.41
Total Paint Material Cost			

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
2615	1	CTR REAR BUMPER MLDG	204 885 0421		0% 105.00*
1000	1	R/F DOOR CHECKER	Renew		0% 0.00
1578	1	R/F DOOR LOCK	204 720 1635		0% 270.00*
1682	1	R/F DOOR MOULDING	204 720 0280		0% 160.00*
1510	1	R/F DOOR SEAL	204 727 1187		0% 260.00*
4598	1	R/F SEAT HEADREST	204 970 6850 9E43		0% 115.00*
1782	1	R/R DOOR	204 730 2200 64		0% 1,400.00*
1000	1	R/R DOOR CHECKER	Renew		0% 0.00
1982	1	R/R DOOR MOULDING	204 730 0280		0% 160.00*
1810	1	R/R DOOR SEAL	204 727 1187		0% 260.00*
1848	1	R/R QUARTER GLASS	204 730 3600		0% 38.69U
2583	1	REAR BUMPER COVER	204 880 1340 9999		0% 1,250.00*
1482	1	RIGHT FRONT DOOR	204 720 6000 64		0% 1,400.00*
1849	1	RR D/WDW BONDING KIT	000 670 0100		0% 51.75U
f: OEM Parts		Sub Total			\$5,470.44
g: Original		Mark Up From Cost		(5 %)	\$273.52
h: Secondhand		Sundry Parts		(Fixed)	\$100.00
p: Parallel		Total Parts			\$5,843.96
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description		Betterment	Price
	FRONT RIGHT RIM	SPECIALIST	0%	\$0.00
	REAR RIGHT RIM	SPECIALIST		\$400.00
	REAR SEALANT	SPECIALIST	0%	\$0.00
			Total Extras	\$400.00

Final Calculation			\$5,843.96
Total Parts			
Labour	Total Panel/Mechanical	\$455.40	
	Total Paintwork	\$248.40	
			\$703.80
Total Labour			
Additional Costs			
	Corr Prot Materials External	\$0.00	
	Corr Prot Materials Internal	\$0.00	
	Cost of Specialist	\$400.00	
			\$400.00
Total of Additional Costs			\$161.41
Total Paint/Material Costs			\$7,109.17
Grand Total Excludes GST			\$0.00
GST @ 0 %			\$7,109.17
Grand Total Includes GST			

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Feb 2018 Sendback Est	09 Feb 2018 18:52 S\$18,324.54	12 Feb 2018 12:32 Edit Adj Rpt	S\$6,650.00 Edit Estimates	S\$6,650.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ANG PUAY GEE, ID: S8040943E, Tel: +6594384378, Email: evas.ang3@gmail.com		
Vehicle Reg. No.:	SKA799T	Date of Loss:	02/02/2018 22:00 - :59 [87 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D00703C01/9	Policy/Cover Note No.:	DMPCSN3102791600 (Comprehensive)
		Excess:	S\$50.00
Repairer:	Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point, 627607 Pioneer - Tel: 6631 0707		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/02/2018]		
Driver/Custodian:	ANG PUAY GEE (37 / Female), NRIC: S8040943E, Tel: +6594384378		
Adj Asg. Remarks:	Please survey/revert and advise whether damages are consistent. Vehicle will only be in workshop on 22.02.2018 as advised by M/s Cheng Auto.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (26/02/2018): Alert - Adj Mandate Approved (S\$9300.00) - SKA799T - Claim Handler: Sharon Han

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKA799T (SNM18D00703C01/9)

OD

Feb 2 2018 10:00PM

[ANG PUAY GEE]

Cheng Auto Bodyworks

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	05/02/18 18:51	Accident Statement	Load HTM	
2	09/02/18 18:52	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 16:57	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	05/02/18 16:12	Identification Card [Linked Accident Report Documents]	Load JPG	☒
2	05/02/18 16:12	Identification Card [Linked Accident Report Documents]	Load JPG	☒
3	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
12	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
13	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
14	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
15	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
16	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
17	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
18	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
19	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
20	05/02/18 16:13	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 17:07	SURVEY PHOTOS	Load PDF	
2	26/04/18 08:21	Reinspection Photo	Load PDF	

Documentation			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	05/02/18 14:54	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
2	05/02/18 14:54	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/02/18 12:38	REPORT OF SHC8860X	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 16:49	MARK ESTIMATE	Load PDF	
2	23/02/18 17:07	AUDATEX	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	05/02/18 18:51	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	05/02/18 16:12	Identification Card	Load JPG	☒
2	05/02/18 16:12	Identification Card	Load JPG	☒
3	05/02/18 16:13	Accident Photo	Load JPG	☒
4	05/02/18 16:13	Accident Photo	Load JPG	☒
5	05/02/18 16:13	Accident Photo	Load JPG	☒
6	05/02/18 16:13	Accident Photo	Load JPG	☒
7	05/02/18 16:13	Accident Photo	Load JPG	☒
8	05/02/18 16:13	Accident Photo	Load JPG	☒
9	05/02/18 16:13	Accident Photo	Load JPG	☒
10	05/02/18 16:13	Accident Photo	Load JPG	☒
11	05/02/18 16:13	Accident Photo	Load JPG	☒
12	05/02/18 16:13	Accident Photo	Load JPG	☒
13	05/02/18 16:13	Accident Photo	Load JPG	☒
14	05/02/18 16:13	Accident Photo	Load JPG	☒
15	05/02/18 16:13	Accident Photo	Load JPG	☒
16	05/02/18 16:13	Accident Photo	Load JPG	☒
17	05/02/18 16:13	Accident Photo	Load JPG	☒
18	05/02/18 16:13	Accident Photo	Load JPG	☒
19	05/02/18 16:13	Accident Photo	Load JPG	☒
20	05/02/18 16:13	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	05/02/18 14:54	Accident Sketch Plan	Load JPG	☒
2	05/02/18 14:54	Accident Sketch Plan	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18002831/R1VD3S2

Date: 04/05/2018

REFERENCE

Insured/Claimant: ANG PUAY GEE Policy No: DMPCSN3102791600
Date of Loss: 02/02/2018 Nature of Claim: OD Claim No: SNM18D00703C01/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA799T**
Make & Model: MERCEDES-BENZ C200, 1.8 CGI (A) Engine No: 27186030087602
Reg. Date: 29/10/2010 (Man. Year: 2010) Chassis No: WDD2040482A409589
Colour: Black Odometer: 192432 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$58,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,255.46	6,243.96	10,011.50	61.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,069.08	865.21	1,203.87	58.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,324.54	7,109.17	11,215.37	61.20
Approved Total (Overridden) (S\$)		6,650.00		
- Excess (S\$)	0.00	50.00	-50.00	
(S\$)	18,324.54	6,600.00	11,724.54	63.98
+ GST 0.00/7.00% (S\$)	0.00	462.00	-462.00	
Nett Amount (S\$)	18,324.54	7,062.00	11,262.54	61.46

INSPECTION

Date of Assignment: 12/02/2018 Present Location: Cheng Auto Bodyworks (HQ)
Cheng Auto Bodyworks (HQ)
Date Inspected: 22/02/2018 Inspected At: 5 Soon Lee Street #01-62 Pioneer Point
Singapore 627607
Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=683074&extid=264377&CFID=33189620&CFTOKEN=

5/4/2018

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 May 2018)

Parts: 143 MERCEDES-BENZ C200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA799T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*CTR REAR BUMPER MLDG (WCP)	Necessary	105.00 F	*105.00 F
2	1	NA	*FUEL FILLER FLAP (WCP)	Serviceable	85.00 F	*- F
3	1	NA	*L/R BUMPER DAMPER (WCP)	Serviceable	40.00 F	*- F
4	1	NA	*R/DOOR MIRROR HSG (WCP)	Serviceable	2,200.00 F	*- F
5	1	NA	*R/F DOOR CHECKER (WCP)	Serviceable	120.00 F	*- F
6	1	NA	*R/F DOOR LOCK (WCP)	Bent	270.00 F	*270.00 F
7	1	NA	*R/F DOOR MOULDING (WCP)	Necessary	160.00 F	*160.00 F
8	1	NA	*R/F DOOR OUT HANDLE (WCP)	Serviceable	150.00 F	*- F
9	1	NA	*R/F DOOR SEAL (WCP)	Necessary	260.00 F	*260.00 F
10	1	NA	*R/F DOOR STRIKER (WCP)	Serviceable	30.00 F	*- F
11	1	NA	*R/F LOWER DOOR HINGE (WCP)	Serviceable	135.00 F	*- F
12	1	NA	*R/F SEAT HEADREST (WCP)	Activated	820.00 F	*115.00 F
13	1	NA	*R/F UPPER DOOR HINGE (WCP)	Serviceable	105.00 F	*- F
14	1	NA	*R/F UPPER DOOR TRIM (WCP)	Serviceable	140.00 F	*- F
15	1	NA	*R/F WINDOW MOTOR (WCP)	Serviceable	580.00 F	*- F
16	1	NA	*R/R BUMPER DAMPER (WCP)	Serviceable	40.00 F	*- F
17	1	NA	*R/R DOOR (WCP)	Bent	1,400.00 F	*1,400.00 F
18	1	NA	*R/R DOOR CHECKER (WCP)	Serviceable	120.00 F	*- F
19	1	NA	*R/R DOOR LOCK (WCP)	Serviceable	270.00 F	*- F
20	1	NA	*R/R DOOR MOULDING (WCP)	Necessary	160.00 F	*160.00 F
21	1	NA	*R/R DOOR OUT HANDLE (WCP)	Serviceable	160.00 F	*- F
22	1	NA	*R/R DOOR SEAL (WCP)	Necessary	260.00 F	*260.00 F
23	1	NA	*R/R DOOR STRIKER (WCP)	Serviceable	30.00 F	*- F
24	1	NA	*R/R LWR DOOR HINGE (WCP)	Serviceable	135.00 F	*- F
25	1	NA	*R/R QUARTER GLASS (WCP)	Necessary	37.45 F	*38.69 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1	NA	*R/R UPPER DOOR HINGE (WCP)	Serviceable	135.00 F	*- F
27	1	NA	*R/R WINDOW MOTOR (WCP)	Serviceable	590.00 F	*- F
28	1	NA	*R/R WING (WCP)	Repair	1,690.00 F	*- F
29	1	NA	*REAR BUMPER COVER (WCP)	Scratched	1,250.00 F	*1,250.00 F
30	1	NA	*RIGHT FRONT DOOR (WCP)	Bent	1,400.00 F	*1,400.00 F
31	1	NA	*RR BUMPER CLAMP KIT (WCP)	Serviceable	50.00 F	*- F
32	1	NA	*RR D/WDW BONDING KIT (WCP)	Necessary	51.75 F	*51.75 F
33	1	NA	*SPECIALIST FRONT RIGHT RIM	Serviceable	800.00 FS	*- FS
34	1	NA	*SPECIALIST GST FOR PARTS		902.30 FS	*- FS
35	1	NA	*SPECIALIST REAR RIGHT RIM	Scratched	800.00 FS	*400.00 FS
36	1	NA	*SPECIALIST REAR SEALANT	Not Necessary	25.00 FS	*- FS
37	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					15,606.50	5,970.44
+ Margin on L,N Items 5.00/5.00% (S\$)					648.96	273.52
Total Parts (S\$)					16,255.46	6,243.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	492.20	248.40
2	Total Paint Materials	New	201.48	161.41
3	Total Panel/Mechanical Labour	New	1,375.40	455.40
Gross Labour Cost (\$\$)			2,069.08	865.21

Report was unsubmitted during this print-out.

< END OF ESTIMATES >