



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

32 2016 MAZDA MAZDA3 4-DOOR SEDAN MAZXXX (SLF9749R)

Date of Loss

27 January 2018

Time of Loss

16.20

Loss Description

SLF9749R (INSD) >SKE9222K (TP) > SBL75Y

Comment

Workshop Details

Total Rebate Amount

54845

Nett Loss Amount

\$15,155.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

10/07/2018



Days of work completion *

148



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SLF9749R

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

16/09/2016



Mileage

82571

Age of Vehicle

1

Driver Details

CATEGORY

Manufacturing Year

CATEGORY

Driver Name

POLICY INFORMAT... 2016

FNOL INFORMATI... CANAGARADJ RAMASWAMY

ASSESSMENT INFO... 2016

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MAZDA MAZDA3 4-DOOR SEDAN

ASSESSMENT INFO... MAZDA

CATEGORY Model

POLICY INFORMAT... MAZXXX

ASSESSMENT INFO... MAZDA3 4-DOOR SEDAN 1.5L SP.6EA

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JM6BM42A8G0345290

CATEGORY Date of Birth

FNOL INFORMATI... 25 January 1973

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 45

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JM6BM42A8G0345290

CATEGORY Engine No

POLICY INFORMAT... P520372513

ASSESSMENT INFO... P520372513

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1496

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 70000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF... ▼

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Address

FNOL INFORMATI... BLK 624 SENJA ROAD, #11-104, 670624,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7366681C

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/60R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

205/60R16

Front left side

TOYO6mm

Front right side

TOYO6mm

Rear left side

TOYO6mm

Rear right side

TOYO6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
		1	1			FRONT BONNET			Bent	991.6		20		793.28	Review
		2	1			FRONT BONNET SEAL INNER			Serviceable	0	0	0	0	0	Deny
		3	1			FRONT BONNET SEAL OUTER			Twisted	68.8		20		55.04	Review
		4	1			FRONT BONNET LOCK			Bent	186.9		20		149.52	Review
		5	2			FRONT BONNET HINGES R/L			Serviceable	0	0	0	0	0	Deny
		6	1			FRONT BUMPER			Deformed	1081.7		20		865.36	Review
		7	1			FRONT BUMPER TOW COVER			Serviceable	0	0	0	0	0	Deny
		8	1			FRONT BUMPER TOP PAD			Deformed	288.9		20		231.12	Review
		9	1			FRONT BUMPER CHROME MOULDINGS LH			Cut	186.9		20		149.52	Review
		10	1			FRONT BUMPER CHROME MOULDINGS RH			Serviceable	0	0	0	0	0	Deny
		11	1			FRONT BUMPER TOP FRAME PAD			Serviceable	0	0	0	0	0	Deny
		12	1			FRONT BUMPER TOP BEAM			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
		13	1			FRONT BUMPER REINFORCEMENT			Bent	524.7		20		419.76	Review
		14	1			FRONT BUMPER REINFORCEMENT PAD			Deformed	161.2		20		128.96	Review
		15	2			FRONT BUMPER BRACKETS R/L			Serviceable	0	0	0	0	0	Deny
		16	2			FRONT BUMPER SIDE RETAINERS R/L			Necessary	38.6		20		61.76	Review
		17	1			FRONT BUMPER LOWER GRILLE CTR			Cracked	86.2		20		68.96	Review
		18	1			FRONT BUMPER SIDE COVER LH			Missing	18.6		20		14.88	Review
		19	1			FRONT BUMPER SIDE COVER RH			Serviceable	0	0	0	0	0	Deny
		20	2			FRONT BUMPER FOG LAMPS R/L			Serviceable	0	0	0	0	0	Deny
		21	2			FRONT BUMPER FOG LAMP COVER R/L			Serviceable	0	0	0	0	0	Deny
		22	1			FRONT BUMPER SIGNAL LAMPS LH			Cracked	155.6		20		124.48	Review
		23	1			FRONT BUMPER SIGNAL LAMPS RH			Serviceable	0	0	0	0	0	Deny
		24	10			FRONT BUMPER CLIPS			Necessary	4.5		20		36	Review
		25	1			FRONT GRILLE			Cut	481.6		20		385.28	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		26	1			FRONT GRILLE LOGO			Necessary	58.6		20		46.88	Review
		27	2			FRONT HEADLAMPS R/L			Cracked	1889		20		3022.4	Review
		28	1			FRONT FENDERS LH			Buckled	333.9		20		267.12	Review
		29	1			FRONT FENDERS LH			Repair	0	0	0	0	0	Deny
		30	1			FRONT FENDER INNER SHIELDS LH			Deformed	129.5		20		103.6	Review
		31	1			FRONT FENDER INNER SHIELDS RH			Serviceable	0	0	0	0	0	Deny
		32	15			FRONT FENDER INNER SHIELD CLIPS LH			Necessary	4.5		20		54	Review
		33	15			FRONT FENDER INNER SHIELD CLIPS RH			Serviceable	0	0	0	0	0	Deny
		34	1			FRONT SUPPORT PANEL ASSY			Cracked	569		20		455.2	Review
		35	1			FRONT SUPPORT TOP PANEL			Buckled	245		20		196	Review
		36	1			FRONT SUPPORT TOP GARNISH			Deformed	335		20		268	Review
		37	1			AIR CLEANER INTAKE DUCT			Cracked	98.6		20		78.88	Review
		38	1			AIR CLEANER BOX ASSY			Cut	216.8		20		173.44	Review
		39	1			AIR CON CONDENSER			Bent	1063		20		850.4	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		40	1			AIR CON DISCHARGE PIPE			Serviceable	0	0	0	0	0	Deny
		41	1			AIR CON SUCTION PIPE			Serviceable	0	0	0	0	0	Deny
		42	1			AIR CON LIQUID PIPE			Serviceable	0	0	0	0	0	Deny
		43	1			RADIATOR ASSY			Bent	1064		20		851.2	Review
		44	2			RADIATOR TOP MOUNT			Serviceable	0	0	0	0	0	Deny
		45	1			RADIATOR TOP HOSE			Serviceable	0	0	0	0	0	Deny
		46	1			SET RADIATOR AUXILIARY FAN ASSY			Cracked	1259.8		20		1007.84	Review
		47	1			RADIATOR BOTTOM HOSE			Serviceable	0	0	0	0	0	Deny
		48	1			RADIATOR SPARE TANK			Serviceable	0	0	0	0	0	Deny
		49	1			ENGINE MOUNTING RH			Serviceable	0	0	0	0	0	Deny
		50	1			ENGINE MOUNTING LH			Serviceable	0	0	0	0	0	Deny
		51	1			ENGINE MOUNTING REAR			Serviceable	0	0	0	0	0	Deny
		52	1			MAIN FUSE BOX			Serviceable	0	0	0	0	0	Deny
		53	2			HORN			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		TOWING CHARGES	0	0	0	Deny		1
		2		TO CHECK FRONT ELECTRICAL WIRING	30	0	0	Reviewing		1
		3		TO REMOVE, REFIX A/C CONDENSER AND REFILL A/C GAS	100	0	0	Reviewing		1
		4		TO REMOVE, REFIX ENGINE PARTS	0	0	0	Deny		1
		5		TO DIGNOS ERASE FAULT MEMORY AFTER REPAIR	100	0	0	Reviewing		1
		6		TO RESPRAY PAINTING AND ETC	600	0	0	Reviewing		1
		7		PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	600	0	0	Reviewing		1

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 5 DAYS	Reviewing			
☐		2	ELECTRICAL CAPACITOR ASSY	Reviewing	250	DAMAGED	
☐		3	FRONT NUMBER PLATE	Reviewing	40	CRACKED	
☐		4	BOTTLE AIR CON OIL	Deny	0	NOT NECESSARY	
☐		5	BOTTLE RADIATOR COOLANT	Reviewing	40	NECESSARY	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$10,618.88

Claim Amount\$10,618.88

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,430.00	\$1,430.00
Miscellaneous	\$330.00	\$330.00
Excess	-\$2,000.00	-\$2,000.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	10000		