

ASS. REC. BY:

REF:CS/FCI18002847/Urbn2

Special Instruction:

Surveyor

Marcus

ASSIGNMENT (Office)

From (Person):

Serene Ter

of

FCI

Date/Time: 13/2/18 3:24pm

Estimated Cost:

Bill to:

$$OD + (TP) \cdot WS + TP \cdot RES + OD \cdot RES + EVA + INV + MV + CS$$

To Inspect Vehicle No:

XD 29171

Insured:

SHB 4079S

at Workshop m/s

VFIX AUTO

Tel:

64489 268

of

60 kaki Bukit Ave 6

Policy No:

Claim No:

D18001266MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp'

H.O.D. Endorsement:

Date/Time

4:27 pm 13/2/18

Person Contacted:

Irene

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction	Date	Time	Location	Weather	Wind	Temp	Humidity	Pressure	Visibility	Clouds	Precip	Remarks
1. Start engine	10/10/2023	08:00	Garage	Clear	0 mph	72°F	45%	30.1 inHg	10 mi	0%	0 in	Engine started successfully.
2. Check oil level	10/10/2023	08:05	Garage	Clear	0 mph	72°F	45%	30.1 inHg	10 mi	0%	0 in	Oil level is at the top of the range.
3. Drive to work	10/10/2023	08:15	Highway	Clear	60 mph	75°F	48%	30.1 inHg	10 mi	0%	0 in	Arrived at work on time.
4. Park car	10/10/2023	08:30	Parking lot	Clear	0 mph	75°F	48%	30.1 inHg	10 mi	0%	0 in	Car parked safely.
5. End log	10/10/2023	08:35	Parking lot	Clear	0 mph	75°F	48%	30.1 inHg	10 mi	0%	0 in	Log completed.

15

Estimate

Struktur

REF: FCA

ASSIGNMENT

From: Date: 13.02.2018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 2917L

at Workshop m/s: Vfix Auto

of: 60 Kaki Bukit Ave 6

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

CA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle. IN / OUT

Date: Person Contacted:

Veh No: XD2917L Yr Regn: 10 08

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or cm /

Make: 1 Suzu CY252L C/C 15681

Colour: white A/C Insured / Std / NI / NA

Sp. Reading: 632302 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JALCY252L 87000056

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/60 R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CH KING

Front

Rear

R/Bal: 6 mm R/Bal: 6/6 6/6 mm

L/Bal: 6 mm L/Bal: 6/6 6/6 mm

D.O.A: 8/2/18 D.O.I: 13/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

13/2/18 Confirmed f. n/ by \$300 with her -
Red: \$200, 40%.

RECEIVED 13 FEB 2018

RECEIVED 13 FEB 2018

Date/Time File Pass to? ☐ : Preli. Report

1) typist ☒ : Final Report

Date/Time File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: -

Survey Fee

Transportation

S - RS - SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 300

80

50

10

140



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002847/Urb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4079S	Veh. Inspected	XD 2917L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2018	Inspection Date	13/02/2018	
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001266MFSH

Our Ref: CS/FCI18002847/Urb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. XD 2917L

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/02/2017 at the premises of M/s VFIX AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 500.00 .
Revised Estimate Amount	: S\$ 300.00 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at n/s rear portion.



Yours faithfully
MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-02-2018	Our Ref No. D18001266MFSH
Accident Date	08-02-2018	Claim Type. Third Party
Insured Vehicle	SHB4079S	Third Party Vehicle. XD2917L
Survey Location	60 KAKI BUKIT AVE 6 ARK@KB	
Contact Person.	KELVIN POH	
Contact No.	64489268/ 96890102	Fax No. 6452368
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VFIX AUTO SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234904)



PRI Documents



Close X

PRI Header Details

Claim No	D18001266MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & VFIX AUT
Workshop Name	VFIX AUTO SERVICE PTE LTD (Contact Person : KELVIN POH)	Survey Location & Contact Details	60 KAKI BUKIT AVE 6 ARK@KB Mobile: 96890102 , Phone: 64489268 , Fax: 6452368 EmailId: VFIXAUTO@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4079S	TP Vehicle No	XD2917L
PRI Recieved Date	09-02-2018 08:58:32 PM	Surveyor Appointed Date	13-02-2018 04:23:16 PM	Surveyor Accept Date	13-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-02-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, February 26, 2018 4:53 PM
To: 'Claim Workflow System'
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001266MFSH/1
Attachments: XD 2917L.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **XD 2917L**.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, February 13, 2018 4:28 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001266MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 13 February 2018 4:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001266MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 4117E

Vehicle Details

Vehicle No.: XD2917L

Vehicle to be Exported: No

Intended De-registration Date: 14 Feb 2018

Vehicle Make: ISUZU

Vehicle Model: CYZ52L

Primary Colour: White

Manufacturing Year: 2008

Engine No.: 6WG1408348

Chassis No.: JALCYZ52L87000056

Maximum Power Output: -

Open Market Value: \$84,235.00

Original Registration Date: 17 Oct 2008

First Registration Date: 17 Oct 2008

Transfer Count: 0

Actual ARF Paid: \$4,212.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Oct 2018

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$14,890.00

COE Rebate Amount: \$1,000.00

Total Rebate Amount: \$1,000.00

The information contained herein is correct as at 14 Feb 2018

OK

M/s First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ESTIMATE

DATE : 13/02/2018
ACC DATE : 08/02/2018
REF NO. : VFIX-TP20180421
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO : XD2917L ISUZU CXZ

LABOUR & MISCELLANEOUS:	AMOUNT S\$	
1 To spray paint repaired rear left fender inclusive of preparatory works and painting materials	300 \$	500.00

GRAND TOTAL : \$ 500.00

SINGAPORE DOLLARS : FIVE HUNDRED ONLY

Vfix Auto Service Pte Ltd



*Not Allowed
LKR
to be ph. to other rep-
1 day.
P/P \$ 300 ok.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002847/Urbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4079S	Veh. Inspected	XD 2917L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001266MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU CYZ52L (M)	c.c	15681	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JALCYZ52L87000056	Colour	WHITE	
Odometer	632302	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	CHKING	6/6 mm	
L/H Front Tyre	295/80 R22.5	CHKING	6/6 mm	
R/H Rear Tyre	295/80 R22.5 (D/D)	CHKING	6/6 6/6 mm	
L/H Rear Tyre	295/80 R22.5 (D/D)	CHKING	6/6 6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	13/02/2018	
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2917L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO SPRAY PAINT REPAIRED REAR LEFT FENDER INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		500.00	300.00
			500.00	300.00
	GRAND TOTAL		500.00	300.00
RECOMMENDED COST OF REPAIRS				300.00

Report Ref No. CS/FCI18002847/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.