

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC18002860/K1rbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	22-02-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJW 4835S	1	nspected	SHC 3347U	
	Policy No.	5093749417	Cover	age (\$)	0.00	
	Claim No.	MT/0981751-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	12/02/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI SONATA	c.c		1991	
	Engine No.	HIDDEN	Year o	f Reg.	2011	
	Chassis No.	KMHET41VMBA805567	Colou	r	BLUE	
	Odometer	171788	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	MAXXI	3	7 mm	
	L/H Front Tyre	215/60 R16	MAXXI		7 mm	
	R/H Rear Tyre	215/60 R16	MAXXI		7 mm	
	L/H Rear Tyre	215/60 R16	MAXXI		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/02/2018		tion Date	12/02/2018	
	Survey held at	sy held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					