

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTMSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807**Our File No:** CS/MSG18002867/UTD3E2**Date:** 29/03/2018REFERENCE

Insured/Claimant:	NG YEN HUI ELINOR	Policy No:	A28672148QMY	
Date of Loss:	08/02/2018	Nature of Claim:	OD	Claim No: 549219

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR5271B		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2086562A
Reg. Date:	12/02/2015 (Man. Year: 2014)	Chassis No:	SJNFEAJ11U1244438
Colour:	White	Odometer:	56683 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,179.00	7,153.15	7,025.85	49.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	1,920.00	2,450.00	56.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,549.00	9,073.15	9,475.85	51.09
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	18,049.00	8,573.15	9,475.85	52.50
+ GST 7.00/7.00% (\$\$)	1,263.43	600.12	663.31	52.50
Nett Amount (\$\$)	19,312.43	9,173.27	10,139.16	52.50

INSPECTION

Date of Assignment:	12/02/2018
Date Inspected:	21/02/2018 Inspected At:

Kinsmen Auto Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6, #02-19
AUTOBAY BUILDING
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2018)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR5271B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Dented / Buckled	660.00 F	*660.00 F
2	1		*BONNET LOCK (WCP)	Not Necessary	78.00 F	*- F
3	1		*BONNET LOCK GARNISH (WCP)	Not Necessary	45.00 F	*- F
4	1		*BONNET LOCK CABLE (WCP)	Not Necessary	70.00 F	*- F
5	1		*BONNET RUBBER BEADING (SMALL) (WCP)	Not Necessary	15.00 F	*- F
6	1		*BONNET RUBBER BEADING (BIG) (WCP)	Not Necessary	15.00 F	*- F
7	13		*BONNET HEAT LINNING CLIP (WCP)	Not Necessary	52.50 F	*- F
8	2		*BONNET HINGE (WCP)	Repair	120.00 F	*- F
9	2		*BONNET STOPPER (WCP)	Not Necessary	20.00 F	*- F
10	2		*BONNET PLASTIC STOPPER (WCP)	Not Necessary	20.00 F	*- F
11	1		*FRONT GRILLE (WCP)	Cracked	384.00 F	*384.00 F
12	1		*FRONT GRILLE BADGE (WCP)	Necessary	55.00 F	*55.00 F
13	7		*FRONT GRILLE CLIP (WCP)	Necessary	17.50 F	*17.50 F
14	1		*FRONT GRILLE CHROME (WCP)	Not Necessary	384.00 F	*- F
15	2		*HEAD LAMP ASSY (WCP)	N/S Holder Cracked/O/ SCracked	960.00 F	*960.00 F
16	2		*HEAD LAMP LOWER BRACKET (WCP)	Not Necessary	130.00 F	*- F
17	1		*FRONT BUMPER SIDE ATTACHMENT (WCP)	O/S Bent	60.00 F	*22.00 F
18	8		*FRONT BUMPER CLIP (WCP)	Not Necessary	20.00 F	*- F
19	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	280.00 F	*280.00 F
20	1		*FRONT BUMPER SPONGE (WCP)	Torn	180.00 F	*180.00 F
21	1		*FRONT BUMPER FOG LAMP CHROME (RH) (WCP)	Not Necessary	85.00 F	*- F
22	1		*FRONT BUMPER FOG LAMP (RH) (WCP)	Not Necessary	310.00 F	*- F
23	1		*FRONT DEFLECTOR (RH) (WCP)	Torn	98.00 F	*98.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	3		*FRONT DEFLECTOR CLIP (RH) (WCP)	Not Necessary	7.50 F	*- F
25	1		*RADIATOR ASSY (WCP)	Not Necessary	540.00 F	*- F
26	2		*RADIATOR MOUNTING (WCP)	Not Necessary	20.00 F	*- F
27	2		*RADIATOR BRACKET (TOP) (WCP)	Not Necessary	20.00 F	*- F
28	1		*AIR - CON CONDENSER (WCP)	Not Necessary	600.00 F	*- F
29	2		*AIR - CON CONDENSOR MOUNTING (WCP)	Not Necessary	30.00 F	*- F
30	1		*AIR - CON DISCHARGE HOSE (WCP)	Not Necessary	145.00 F	*- F
31	1		*AIR - CON SUCTION HOSE (WCP)	Not Necessary	190.00 F	*- F
32	1		*AIR - CON LIQUID PIPE (WCP)	Not Necessary	200.00 F	*- F
33	1		*TURBO INTERCOOLER (WCP)	Punctured	1,800.00 F	*1,800.00 F
34	1		*HORN (RH) (WCP)	Not Necessary	90.00 F	*- F
35	1		*WIPER TANK (WCP)	Not Necessary	170.00 F	*- F
36	1		*WIPER TANK NECK HOSE (WCP)	Not Necessary	55.00 F	*- F
37	1		*WIPER TANK NECK CLIP (WCP)	Not Necessary	38.00 F	*- F
38	1		*FRONT CHASSIS MEMBER (RH) (WCP)	Repair	750.00 F	*- F
39	1		*FRONT WHEEL HOUSING PANEL (RH) (WCP)	Not Necessary	455.00 F	*- F
40	1		*FRONT FENDER (RH) (WCP)	Bent / Twisted	456.00 F	*456.00 F
41	1		*FRONT FENDER INNER COWLING (RH) (WCP)	Not Necessary	95.00 F	*- F
42	10		*FRONT FENDER INNER COWLING CLIP (RH) (WCP)	Not Necessary	25.00 F	*- F
43	1		*FRONT FENDER PROTECTOR (RH) (WCP)	Torn	335.00 F	*335.00 F
44	1		*FRONT BUMPER (WCP)	Dented / Deformed	456.00 F	*456.00 F
45	1		*FRONT LICENCE PLATE (EMBOSS)	Bent	40.00 FS	*40.00 FS
46	1		*FRONT BUMPER REINFORCEMENT BRACKET (RH) (WCP)	Dented	98.00 F	*95.00 F
47	1		*FRONT SUPPORT TOP CENTRAL (WCP)	Bent / Twisted	588.00 F	*588.00 F
48	1		*HEAD LAMP SUPPORT O/S (WCP)	Bent / Twisted	80.00 F	*80.00 F
49	1		*HEAD LAMP ASSY (WCP)	Repeated	480.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$)	11,822.50	6,506.50
+ Margin on L,N Items 20.00/10.00% (\$)	2,356.50	646.65
Total Parts (\$)	14,179.00	7,153.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM	New	50.00	20.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	0.00
3	TO REMOVE AND REFIX AIR - CON CONDENSOR, PIPING SYSTEM AND TOP UP GAS	New	220.00	100.00
4	TO REMOVE AND REFIX RADIATOR ASSY AND CONDUCT PRESSOR TEST	New	180.00	0.00
5	TO REMOVE AND REFIX HEAD LAMP ASSY AND REALIGNMENT LIGHTING SYSTEM	New	120.00	0.00
6	TO REMOVE AND REFIX ON CAR O LINER	New	380.00	0.00
7	TO REPLACE AND NEW PARTS, CUT, WELD, KNOCK ETC	New	1,760.00	800.00
8	TO RESPRAY ON THE AFFECTED AREAS	New	1,540.00	1,000.00
Gross Labour Cost (S\$)			4,370.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >