

ASS. REC. BY:

REF:

CS/ICS18002907/Gilber

Special Instruction:

Surveyor

GA

ASSIGNMENT (Office)

From (Person):

Came Tan

of

ICS

Date/Time:

13022018 942am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 3381T

Insured:

SKS 7611K

at Workshop m/s

Torque 5

Tel:

91478841

of

8 Kak Bukit Ave 4 #01-49

Policy No:

Claim No:

DMPC1800049H/CS

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13022018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

10am

H.O.D. Endorsement:

Date/Time:

13022018 9.45am

Person Contacted:

Stephanie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJM 3381T - X
	SKS 7611K - X
17/8/18	offer \$5500.
23/8/18	lump sum \$5500, 5 days (Red: 9424.50, 63%)


ASSIGNMENT

(-2026)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Torque S
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$69k.
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJM3381T Yr Regn: 19 May 2006
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Previa C.C. 2362
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 164878 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: JTEGD 54M 707023291

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S.Rim / STD A/Rim or

Tyre Size: F: 215/55 R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 13-02-18

Survey held at W/S 10AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date price checked. Goo Qiang

RECEIVED 23 AUG 2018

RECEIVED 11 SEP 2018 extend w

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

1) 23/8 Typist

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 390

Transportation: _____

_____ S + RS. _____ SI

Photos _____

Others _____

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 5500)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

10

360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS/ICS18002909/Gtb	
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 13-02-2018	
		Code : ICS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKS 7611K	Veh. Inspected	SJM 3381T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CARRIE TAN	Assign Date	13/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/02/2018	Inspection Date	13/02/2018
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Tuesday, 13 February, 2018 9:42 AM
To: Torque 5 Assessment; ECICS Claims
Cc: sam.chang@torque5.com; eric.lee@torque5.com; claims@torque5.com; assignments@lkkauto.com
Subject: RE: Accident involving SJM3381T & SKS7611K on 09/02/2018 (PRE-REPAIR SURVEY REQUEST)

Dear Lee Yi,

Noted with thanks.

Dear LKK,

As spoken, please assist to do the PRI at 10am @ Torque 5.

Thank you.

Regards,
Carrie Tan
Claims Division
DID: +65 63030308
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Torque 5 Assessment [mailto:assessment@torque5.com]
Sent: Saturday, 10 February, 2018 9:52 AM
To: ECICS Claims
Cc: assessment@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; claims@torque5.com
Subject: Accident involving SJM3381T & SKS7611K on 09/02/2018 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Chia Yong Seng , to notify you of the aforesaid accident involving our client's vehicle SJM 3381 T and your insured's vehicle SKS 7611 K on 09/02/2018.

Please find enclose our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against SKS 7611 K for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least **ten (10) motor surveyors**.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Contact Person: Stephanie Teo (9147 8841)

Contact Email: assessment@torque5.com

VEH IN (Date & Time) : 13/02/2018 10.00AM

PRS ARRANGEMENT (Date & Time) : 10/02/2018 09.55AM

PRS ACKNOWLEDGEMENT

Appointed Surveyor
(Name & Signature)

Date & Time of Inspection

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Warmest Regards,

Heng Lee Yi

Administrative Assistant | Motor Claims Department





(65) 6452 4457 | Fax (65) 6452 4584

Address

8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



REVIVE YOUR DRIVE

☐	☐	☐
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAUTO)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 20 August 2018 10:53 AM
To: Denise Tay (LKKAUTO)
Cc: assignments; Crystabelle Tan Gek Peng (ECICS, Claims); Admin-D (LKKAUTO); ECICS Claims; SUR
Subject: RE: Accident involving SJM3381T & SKS7611K on 09/02/2018 (PRE-REPAIR SURVEY REQUEST)

Hi Denise

Our claim no DMPC1800049H/CT and case handler is Ms Crystabelle Tan.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, 17 August, 2018 4:45 PM
To: Admin-D (LKKAUTO); ECICS Claims; SUR
Cc: assignments
Subject: RE: Accident involving SJM3381T & SKS7611K on 09/02/2018 (PRE-REPAIR SURVEY REQUEST)

Dear Sir,

Please provide claim number

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 13 February 2018 10:22 AM
To: 'ECICS Claims' <claims@ecics.com.sg>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: Accident involving SJM3381T & SKS7611K on 09/02/2018 (PRE-REPAIR SURVEY REQUEST)

Denise Tay (LKKAuto)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Thursday, 23 August 2018 10:22 AM
To: Denise Tay (LKKAuto)
Cc: Guo Qiang (LKKAuto); SUR; 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com
Subject: RE: ** URGaENT **

Dear Denise,



We hereby confirm the final amount of L/S \$5,500 (before GST @ 5 repair days) for **SJM 3381 T**.
Thank you.

Warmest Regards,
Stephanie Teo
Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0063D
Vehicle Details	
Vehicle No.:	SJM3381T
Vehicle to be Exported:	No
Intended De-registration Date:	13 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PREVIA 7 SEATER MR
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	2AZ2203884
Chassis No.:	JTEGD54M707023291
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$38,944.00
Original Registration Date:	19 May 2006
First Registration Date:	19 May 2006
Transfer Count:	3
Actual ARF Paid:	\$42,839.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$38,051.00
Total Rebate Amount:	\$38,051.00

The information contained herein is correct as at 13 Feb 2018

OK

Tuesday 10am (S)

13/2/2018

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 9 / 2 / 2018 (dd/mm/yy) Time of Accident: 16 : 50 (24-HR-FORMAT)

Vehicle No.: SJM 3381T Vehicle Make & Model: Toyota Previa

Exact location of Accident: Jalan Kayu slip Rd to Sengkang West way

Policyholder's Name / IC No.: Chia Yong Seng / S 68600630

Driver's Name / IC No.: _____ (As Above) ☒

Driver's Contact No.: 9739 1529 Company Contact No: _____

Driver's Address: B1K 4530 Fernvale Rd #11-541 S(794453)

Insurance Company: AXA Email address (if any): _____

Relationship between Owner & Driver: (Please CIRCLE one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle
Was being used at time of accident?**

☒ Private use / ☐ Work purpose

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

No. of Passengers (Including Driver): 01

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☐ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☐ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: SKS 7611K

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: _____


Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

* If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A was at the slip road trying to turn left. I saw a car trying to pass through so I stopped. Suddenly vehicle B hit onto my stationary vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Vehicle No : SJM3381T
Make & Model : TOYOTA, PREVIA 7 SEATER
MR, JTEGD54M707023291
Year of Manufacture : 2006

ESTIMATION REPORT

Estimation No. : E18020023
DOA : 09/02/2018

Caro Corp
23/2/18.

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Tail gate / <i>Bmt</i>	1.00	0.00	0.00 1560.00
2	Tail gate absorber (LH) X <i>nn</i>	1.00	0.00	0.00
3	Tail gate absorber (RH) X <i>nn</i>	1.00	0.00	0.00
4	Tail gate lock / <i>cut</i>	1.00	0.00	0.00
5	Tail gate weather strip / <i>Twf</i>	1.00	0.00 466.1	0.00 466.10
6	Tail gate logo / <i>mbc</i>	1.00	0.00 311.1	0.00 311.10
7	Tail gate chrome handle X	1.00	0.00	0.00 65.00
8	Tail gate inner trim / <i>ee</i>	1.00	0.00	0.00
9	Tail gate inner trim clip / <i>mbc</i>	1.00	0.00	0.00 718.00
10	Rear windscreen moulding / <i>mbc</i>	1.00	0.00	0.00 50.00
11	Rear bumper / <i>re</i>	1.00	0.00 97.3	0.00 97.30
12	Rear bumper clip / <i>mbc</i>	1.00	0.00	0.00 570.80
13	Rear bumper retainer (LH) / <i>3nee</i>	1.00	0.00 48	0.00 48.00
14	Rear bumper retainer (RH) / <i>3nee</i>	1.00	0.00 36.8	0.00 36.80
15	Rear bumper bracket (LH) X	1.00	0.00 36.8	0.00 36.80
16	Rear bumper bracket (RH) X	1.00	0.00 X	0.00 84.00
17	Rear bumper reinforcement X	1.00	0.00 X	0.00 84.00
18	Rear bumper sponge X	1.00	0.00	0.00
19	Rear bumper reflector (LH) X	1.00	0.00 X	0.00 78.90
20	Rear bumper towing cap (LH) / <i>cut</i>	1.00	0.00 59.8	0.00 59.80
21	Rear bumper lower X	1.00	0.00 21.23	0.00 21.23
22	Tail lamp (LH) X	1.00	0.00	0.00
23	Tail lamp clip (LH) X	1.00	0.00 X	0.00 445.00
24	Rear fender (LH) X	1.00	0.00 X	0.00 30.00

Supp:

⇒ bumper garnish (L) / cut

Continue on next page...

5918



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM3381T
Make & Model : TOYOTA, PREVIA 7 SEATER
MR, JTEGD54M707023291
Year of Manufacture : 2006

Estimation No. : E18020023
DOA : 09/02/2018

No	Description	Qty	U/P	Amt
25	Rear fender inner trim (LH) <i>broken</i>	1.00	0.00	845.10
26	Rear fender inner trim clip (LH) <i>nee</i>	1.00	0.00	30 0.00 50.00
27	Rear end panel <i>Buc</i>	1.00	0.00	0.00 571.00
28	Rear end panel top garnish <i>de</i>	1.00	0.00	268.30 0.00 488.90
29	Rear end panel top garnish clip <i>mc</i>	1.00	0.00	20 0.00 150.00
30	Spare wheel panel <i>X repair.</i>	1.00	0.00	X 0.00 920.50
31	Spare wheel panel top board <i>cut.</i>	1.00	0.00	0.00 869.00
32	Spare wheel panel sponge <i>X 3 mm</i>	1.00	0.00	X 0.00 450.00
33	Exhaust pipe <i>X</i>	1.00	0.00	0.00
34	Exhaust pipe mounting <i>X 3 mm</i>	1.00	0.00	0.00 3080.10
35	Exhaust pipe gasket <i>X</i>	1.00	0.00	0.00
36	Exhaust pipe heat shield <i>X</i>	1.00	0.00	0.00 10392.10
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00
				25%! 5028.29
Section: Special Nett Items				
37	Rear windscreen sealant <i>nee</i>	1.00	80.00	40 80.00
38	Rear fender sealant <i>X</i>	1.00	80.00	80.00
39	Rear end panel sealant <i>X</i>	1.00	80.00	80.00 40
				Amt S\$ 240.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 240.00
Section: Labour Items				
40	To R&R accident affected areas	1.00	1,500.00	1,500.00 700
41	To putty & respray accident affected areas	1.00	1,300.00	1,300.00 600 700

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM3381T
Make & Model : TOYOTA, PREVIA 7 SEATER
MR, JTEGD54M707023291
Year of Manufacture : 2006

Estimation No. : E18020023
DOA : 09/02/2018

No	Description	Qty	U/P	Amt
42	To rust proof accident affected areas	1.00	60.00	60.00
43	To R&R tailgate mechanism	1.00	80.00	80.00
44	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
45	To R&R rear luggage compartment	1.00	200.00	200.00
46	To R&R rear windscreen	1.00	150.00	150.00
47	To check wiring layout of tail lamp	1.00	80.00	80.00
48	To R&R exhaust pipe assy	1.00	180.00	180.00
49	To do wheel alignment	1.00	180.00	180.00
50	To check for water seepage	1.00	100.00	100.00
				Amt S\$ 3,910.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,910.00

5 Days.

Lumpsum Repair.

After repair photos.

Guo Qiang - 8288 0282

13/2/18.

[Signature]
17/8/18

6878.24

20%: 5500

1710

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 240.00
Labour Items Subtotal S\$ 3,910.00
Total S\$ 4,150.00

PAGE 3 OF 3

14924.50

18925.30



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SJM3381T
Make & Model : TOYOTA, PREVIA 7 SEATER
MR, JTEGD54M707023291
Year of Manufacture : 2006

Estimation No. : E18020031
DOA : 09/02/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Bumper garnish (LH) <i>cut</i>	1.00	383.20	383.20
				Amt S\$ 383.20
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 383.20

- 60
(SN)

P = 6531 - 25%

= 4898.25

? = 3769 - 26%

= 2826.00 (given add reinforcement)

SN: 80.00

? = 80.00

L: 1510.00

? = 200.00

6488.25

8296.00

* 4/5 \$5190 @ 5 repair days. (w/o ?)

* 4/5 \$6640 @ 5 repair days (w/o ?)

P: 8683.70 - 25%

= 6512.77

SN: 160.00

L: 1710.00

8382.77

* 4/5 \$6710 @ 5 repair days.

List Items Subtotal S\$ 383.20
Total S\$ 383.20



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM3381T
Make & Model : TOYOTA, PREVIA 7 SEATER
MR, JTEGD54M707023291
Year of Manufacture : 2006

Estimation No. : E18020023
DOA : 09/02/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Tail gate / <i>Bml</i>	1.00	0.00	0.00
2	Tail gate absorber (LH) <i>X</i> <i>GNN</i>	1.00	0.00	0.00
3	Tail gate absorber (RH) <i>X</i>	1.00	0.00	0.00
4	Tail gate lock / <i>Cut</i>	1.00	0.00	0.00
5	Tail gate weather strip / <i>Trim</i>	1.00	0.00	0.00
6	Tail gate logo / <i>MBC</i>	1.00	0.00	0.00
7	Tail gate chrome handle <i>X</i> <i>IN</i>	1.00	0.00	0.00
8	Tail gate inner trim / <i>ee</i>	1.00	0.00	0.00
9	Tail gate inner trim clip / <i>MBC</i>	1.00	0.00	0.00
10	Rear windscreen moulding / <i>MBC</i>	1.00	0.00	0.00
11	Rear bumper / <i>ee</i>	1.00	0.00	0.00
12	Rear bumper clip / <i>MBC</i>	1.00	0.00	0.00
13	Rear bumper retainer (LH) / <i>MBC</i>	1.00	0.00	0.00
14	Rear bumper retainer (RH) / <i>MBC</i>	1.00	0.00	0.00
15	Rear bumper bracket (LH) ?	1.00	0.00	0.00
16	Rear bumper bracket (RH) ?	1.00	0.00	0.00
17	Rear bumper reinforcement ?	1.00	0.00	0.00
18	Rear bumper sponge ?	1.00	0.00	0.00
19	Rear bumper reflector (LH) ?	1.00	0.00	0.00
20	Rear bumper towing cap (LH) / <i>Cut</i>	1.00	0.00	0.00
21	Rear bumper lower <i>X</i>	1.00	0.00	0.00
22	Tail lamp (LH) <i>X</i> <i>GNN</i>	1.00	0.00	0.00
23	Tail lamp clip (LH) <i>X</i>	1.00	0.00	0.00
24	Rear fender (LH) <i>X</i>	1.00	0.00	0.00

Supp:

⇒ bumper garnish (L) / Cut

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM3381T
Make & Model : TOYOTA, PREVIA 7 SEATER
 MR,JTEGD54M707023291
Year of Manufacture : 2006

Estimation No. : E18020023
DOA : 09/02/2018

No	Description	Qty	U/P	Amt
25	Rear fender inner trim (LH) ?	1.00	0.00	0.00
26	Rear fender inner trim clip (LH) ?	1.00	0.00	0.00
27	Rear end panel ?	1.00	0.00	0.00
28	Rear end panel top garnish / RE	1.00	0.00	0.00
29	Rear end panel top garnish clip / MC	1.00	0.00	0.00
30	Spare wheel panel ?	1.00	0.00	0.00
31	Spare wheel panel top board / RE	1.00	0.00	0.00
32	Spare wheel panel sponge ?	1.00	0.00	0.00
33	Exhaust pipe X	1.00	0.00	0.00
34	Exhaust pipe mounting X	1.00	0.00	0.00
35	Exhaust pipe gasket X	1.00	0.00	0.00
36	Exhaust pipe heat shield X	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

37	Rear windscreen sealant / MC	1.00	80.00	80.00	40
38	Rear fender sealant X NN	1.00	80.00	80.00	X
39	Rear end panel sealant ?	1.00	80.00	80.00	40

Amt S\$ 240.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 240.00

Section: Labour Items

40	To R&R accident affected areas	1.00	1,500.00	1,500.00	600
41	To putty & respray accident affected areas	1.00	1,300.00	1,300.00	600

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJM3381T
Make & Model : TOYOTA, PREVIA 7 SEATER
MR, JTEGD54M707023291
Year of Manufacture : 2006

Estimation No. : E18020023
DOA : 09/02/2018

No	Description	Qty	U/P	Amt
42	To rust proof accident affected areas	1.00	60.00	60.00
43	To R&R tailgate mechanism	1.00	80.00	80.00
44	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
45	To R&R rear luggage compartment	1.00	200.00	200.00
46	To R&R rear windscreen	1.00	150.00	150.00
47	To check wiring layout of tail lamp	1.00	80.00	80.00
48	To R&R exhaust pipe assy	1.00	180.00	180.00
49	To do wheel alignment	1.00	180.00	180.00
50	To check for water seepage	1.00	100.00	100.00

✓
60
X NN
60
120
30
X
X } NN
X

Amt S\$ 3,910.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,910.00

5 Days.

Lumpsum Repair.

After repair photos.

Guo Qiang - 8288 0282

13/2/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 240.00
Labour Items Subtotal S\$ 3,910.00
Total S\$ 4,150.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018 14:36 Edit Reg		13 Feb 2018 00:00 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: -									
Vehicle Reg. No.: SJM3381T		Date of Loss: 09/02/2018 16:00 - :59 [140 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SKS7611K		Policy No. (Claimant):							
		Excess:							
Repairer: Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/02/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM3381T

[SKS7611K]

TP

-

Feb 9 2018 4:00PM

[-]

Torque 5 Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	17/08/18 13:15	General View						Load JPG	☒	
2	17/08/18 13:15	General View						Load JPG	☒	
3	17/08/18 13:15	General View						Load JPG	☒	
4	17/08/18 13:15	General View						Load JPG	☒	
5	17/08/18 13:15	General View						Load JPG	☒	
6	17/08/18 13:15	General View						Load JPG	☒	
7	17/08/18 13:15	General View						Load JPG	☒	
8	17/08/18 13:15	General View						Load JPG	☒	
9	17/08/18 13:15	General View						Load JPG	☒	
10	17/08/18 13:15	General View						Load JPG	☒	
11	17/08/18 13:15	General View						Load JPG	☒	
12	17/08/18 13:15	General View						Load JPG	☒	
13	17/08/18 13:15	General View						Load JPG	☒	
14	17/08/18 13:15	General View						Load JPG	☒	
15	17/08/18 13:15	General View						Load JPG	☒	
16	17/08/18 13:15	General View						Load JPG	☒	
17	17/08/18 13:15	General View						Load JPG	☒	
18	17/08/18 13:15	General View						Load JPG	☒	
19	17/08/18 13:15	General View						Load JPG	☒	
20	17/08/18 13:15	General View						Load JPG	☒	
21	17/08/18 13:15	General View						Load JPG	☒	
22	17/08/18 13:15	General View						Load JPG	☒	
23	17/08/18 13:15	General View						Load JPG	☒	
24	17/08/18 13:15	General View						Load JPG	☒	
25	17/08/18 13:15	General View						Load JPG	☒	
26	17/08/18 13:15	General View						Load JPG	☒	
27	17/08/18 13:15	General View						Load JPG	☒	
28	17/08/18 13:15	General View						Load JPG	☒	
29	17/08/18 13:15	General View						Load JPG	☒	
30	17/08/18 13:15	General View						Load JPG	☒	
31	17/08/18 13:15	General View						Load JPG	☒	
32	17/08/18 13:15	General View						Load JPG	☒	
33	17/08/18 13:15	General View						Load JPG	☒	
34	17/08/18 13:15	General View						Load JPG	☒	
35	17/08/18 13:15	General View						Load JPG	☒	
36	17/08/18 13:15	General View						Load JPG	☒	
37	17/08/18 13:15	General View						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/08/18 13:15	General View	 Load JPG	☒
39	17/08/18 13:15	General View	 Load JPG	☒
40	17/08/18 13:15	General View	 Load JPG	☒
41	17/08/18 13:15	General View	 Load JPG	☒
42	17/08/18 13:15	General View	 Load JPG	☒
43	17/08/18 13:15	General View	 Load JPG	☒
44	17/08/18 13:15	General View	 Load JPG	☒
45	17/08/18 13:15	General View	 Load JPG	☒
46	17/08/18 13:15	General View	 Load JPG	☒
47	17/08/18 13:15	General View	 Load JPG	☒
48	17/08/18 13:15	General View	 Load JPG	☒
49	17/08/18 13:15	General View	 Load JPG	☒
50	17/08/18 13:15	General View	 Load JPG	☒
51	17/08/18 13:15	General View	 Load JPG	☒
52	17/08/18 13:15	General View	 Load JPG	☒
53	17/08/18 13:15	General View	 Load JPG	☒
54	17/08/18 13:15	General View	 Load JPG	☒
55	17/08/18 13:15	General View	 Load JPG	☒
56	17/08/18 13:15	General View	 Load JPG	☒
57	17/08/18 13:15	General View	 Load JPG	☒
58	17/08/18 13:15	General View	 Load JPG	☒
59	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
60	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
61	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
62	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
63	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
64	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
65	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
66	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
67	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
68	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
69	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
70	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
71	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
72	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
73	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
74	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
75	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
76	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
77	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
78	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
79	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
80	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
81	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
82	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
83	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
84	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
85	23/08/18 14:55	Reinspection Photo	 Load JPG	☒
86	23/08/18 14:55	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 14:49	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18002909/GTBE2

Date: 11/09/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SJM3381T	Insured Vehicle No :	SKS7611K
Date of Loss:	09/02/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM3381T	Engine No:	2AZ2203884
Make & Model:	TOYOTA PREVIA, 2.4 7-seater (A)	Chassis No:	JTEGD54M707023291
Reg. Date:	19/05/2006 (Man. Year: 2006)	Odometer:	164878 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,015.30	5,168.25	5,847.05	53.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	1,710.00	2,200.00	56.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,925.30	6,878.25	8,047.05	53.92
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	14,925.30	5,500.00	9,425.30	63.15
+ GST 7.00/7.00% (S\$)	1,044.77	385.00	659.77	63.15
Nett Amount (S\$)	15,970.07	5,885.00	10,085.07	63.15

INSPECTION

Date of Assignment:	13/02/2018	
Date Inspected:	13/02/2018	Inspected At: Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4., #01-50 Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2018)
Parts: M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM3381T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Buckled	1,560.00 F	*1,560.00 FL
2	1		*TAIL GATE ABSORBER (LH) (NPA)	Not Necessary	0.00 F	*- FL
3	1		*TAIL GATE ABSORBER (RH) (NPA)	Not Necessary	0.00 F	*- FL
4	1		*TAIL GATE LOCK	Cut	766.20 F	*466.10 FL
5	1		*TAIL GATE WEATHER STRIP	Twisted	390.50 F	*311.10 FL
6	1		*TAIL GATE LOGO	Necessary	65.00 F	*65.00 FL
7	1		*TAIL GATE CHROME HANDLE (NPA)	Not Necessary	0.00 F	*- FL
8	1		*TAIL GATE INNER TRIM	Deformed	778.00 F	*778.00 FL
9	1		*TAIL GATE INNER TRIM CLIP	Necessary	50.00 F	*50.00 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	150.00 F	*97.30 FL
11	1		*REAR BUMPER	Deformed	570.80 F	*570.80 FL
12	1		*REAR BUMPER CLIP	Necessary	150.00 F	*48.00 FL
13	1		*REAR BUMPER RETAINER (LH)	Necessary	95.70 F	*36.80 FL
14	1		*REAR BUMPER RETAINER (RH)	Necessary	95.70 F	*36.80 FL
15	1		*REAR BUMPER BRACKET (LH)	Not Necessary	84.00 F	*- FL
16	1		*REAR BUMPER BRACKET (RH)	Not Necessary	84.00 F	*- FL
17	1		*REAR BUMPER REINFORCEMENT (NPA)	Not Necessary	0.00 F	*- FL
18	1		*REAR BUMPER SPONGE	Not Necessary	78.90 F	*- FL
19	1		*REAR BUMPER REFLECTOR (LH)	Cracked	470.00 F	*59.80 FL
20	1		*REAR BUMPER LOWER (NPA)	Not Necessary	0.00 F	*- FL
21	1		*TAIL LAMP (LH)	Not Necessary	445.00 F	*- FL
22	1		*TAIL LAMP CLIP (LH)	Not Necessary	30.00 F	*- FL
23	1		*REAR FENDER (LH) (NPA)	Not Necessary	0.00 F	*- FL
24	1		*REAR FENDER INNER TRIM (LH)	Broken	1,060.90 F	*845.10 FL
25	1		*REAR FENDER INNER TRIM CLIP (LH)	Necessary	50.00 F	*30.00 FL
26	1		*REAR END PANEL	Buckled	571.00 F	*571.00 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	408.90 F	*268.30 FL
28	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	150.00 F	*20.00 FL
29	1		*SPARE WHEEL PANEL	Repair	920.50 F	*- FL
30	1		*SPARE WHEEL PANEL TOP BOARD	Cut	869.00 F	*869.00 FL
31	1		*SPARE WHEEL PANEL SPONGE	Not Necessary	450.00 F	*- FL
32	1		*EXHAUST PIPE (NPA)	Not Necessary	0.00 F	*- FL
33	1		*EXHAUST PIPE MOUNTING (NPA)	Not Necessary	0.00 F	*- FL
34	1		*EXHAUST PIPE GASKET (NPA)	Not Necessary	0.00 F	*- FL
35	1		*EXHAUST PIPE HEAT SHIELD (NPA)	Not Necessary	0.00 F	*- FL
36	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*BUMPER GARNISH (LH)	Cut	383.20 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BUMPER TOWING CAP (LH)	Cut	48.00 F	*21.23 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					11,015.30	6,844.33
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	1,676.08
Total Parts (\$\$)					11,015.30	5,168.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT AFFECTED AREAS	New	1,500.00	700.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	1,300.00	700.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	60.00	60.00
4	TO R&R TAILGATE MECHANISM	New	80.00	60.00
5	TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION	New	80.00	0.00
6	TO R&R REAR LUGGAGE COMPARTMENT	New	200.00	60.00
7	TO R&R REAR WINDSCREEN	New	150.00	100.00
8	TO CHECK WIRING LAYOUT OF TAIL LAMP	New	80.00	30.00
9	TO R&R EXHAUST PIPE ASSY	New	180.00	0.00
10	TO DO WHEEL ALIGNMENT	New	180.00	0.00
11	TO CHECK FOR WATER SEEPAGE	New	100.00	0.00
Gross Labour Cost (S\$)			3,910.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >