No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Sing

Ref No: GY8464C180204

display damaged part(s) during resurvey Parts prices are subject to confirmation

No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: Date:

Third party survey is on a "Without Prejudice" basis

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: fixel Customer Date: 12-02-18 AIG Asia Pacific Insurance Pte Ltd Name: GY8464C Vehicle No: Address: Motor Claims Department 78 Shenton Way #07-16 Model/Make: Toyota Hiace Singapore 079120 Manual AIG Building Revised Original Ouotation / Quotation / Item No. Descriptions Of Parts Cost Of Estimation Repair 2,050.00 Rear 🏖 Tailgate 70.50 Tailgate "Toyota Logo" Motif 🖊 2 387.90 Tailgate Weatherstrip 3 Tailgate "70 KM/H" Sticker 7w1 15.00 \$ 4 SN 105.1 \$ 15.00 5 Tailgate "8 PAX" Sticker 354.00 Tail Lamp 1/5 6 75.00 Tail Lamp Lower Garnish 14 7 Tail Lamp Housing Panel 258.00 8 Bumper 7.5 Bumper Side Holder (~a 428.10 9 69.10 10 60.00 Bumper Clips 1 set un 11 1,308.30 Fender NU JASO/Ju(12 \$ 936.20 Inner Panel 13 \$ 425.00 Outer Panel 14 \$ 388.20 Fender Panel Side Railing 15 80.00 Remove and refix rear Bumper distance sensor 60.00 \$ Remove and refix rear tailgate components & wiper mechanism \$ 50.00 To check all wiring & electrical component for proper function 1,500.00 Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs \$ 1,200.00 To putty & spray painting & including touch up paint on accident affecteed areas 100.00 To apply Rust Proofing, reseal tuff-coating treatment on accident area \$ 9,830.30 Total Parts & Labour of estimate for damaged vehicle Total amount in Lump Sum Basis for repaired vehicle P-3339.1 SDLS: N. Anthornal 40432 M/s Liu's Brother Auto Workshop 4(14) LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting