

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC18002950/K1vbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	20-02-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJF 9837T	Veh. Ir	nspected	SHC 7245D	
	Policy No.	5091369180	Coverage (\$)		0.00	
	Claim No.	MT/0981878-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	13/02/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU092570	Colou	r	YELLOW	
	Odometer	283096	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	TRIAN	GLE	7 mm	
	L/H Front Tyre	205/60 R16	TRIAN		7 mm	
	R/H Rear Tyre	205/60 R16	TRIAN		7 mm	
	L/H Rear Tyre	205/60 R16	TRIAN		7 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/02/2018	Insped	tion Date	13/02/2018	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					