

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Paamee Go		Cust No/Name	/Paamee Go
Blk718A Upper Changi Road East		Reg No/Reg Date	SKU4830D / 30/07/2015
#01-05 Changi Green		Date In/Mileage	/ 0
Singapore 486850		Chassis No	VF73A9HC8FJ651615
Contact No	Mobile: 91067570	Engine No	10JBEX3056680
		Make/Model	CIT/GC4P INTENSIVE 1.6 E-HDI 115 ETG
		Colour/Trim	9PM / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	12/02/2018/ 20:03	TLC	442 / CocoLu	13240

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW FRT DOOR LH, SIDE SILL LH, REPAIR REAR DOOR LH				4800.00
E PNT98000 TO SPRAY PAINT FOR FRT DOOR LH, REAR DOOR LH, SIDE SILL LH				1680.00
E PNT88000 TO REMOVE & INSTALL FRT DOOR TRIMS AND GLASS TO FACILITATE REPAIR				280.00
M SUNDRY TO APPLY SEALANT FOR ACCIDENT AFFECTED AREA				80.00
A 54900099 TO CHECK WIRING & ELECTRICAL SYSTEM				50.00
A 54900099 TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				300.00
M SUNDRY Sundry				20.00
M FRONT DOOR LH ASS	1.00	1234.00	0.00	1234.00
M DOOR HINGE LH INF	1.00	73.00	0.00	73.00
M DOOR HINGE LH SUP	1.00	73.00	0.00	73.00
M DOOR STOP	1.00	86.00	0.00	86.00
M DR WEATHERSTRIP LH AV	1.00	67.00	0.00	67.00
M DR WEATHERSTRIP LH INF	1.00	75.00	0.00	75.00
M DR WEATHERSTRIP LH SUP	1.00	119.00	0.00	119.00
M SEALING PANEL LH	1.00	177.00	0.00	177.00
M MOULDING LH	1.00	72.00	0.00	72.00
M TRIM LH	1.00	44.00	0.00	44.00
M DOOR FIXINGS	1.00	219.00	0.00	219.00
M WINDOW CHANNEL LH	1.00	183.00	0.00	183.00
M WINDOW LIFTER LH	1.00	523.00	0.00	523.00
M UNDER-BODY LH	1.00	847.00	0.00	847.00

Confirm & accepted by

Parts	3,792.00
Labour	7,110.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	100.00
Total (w/o GST)	11,002.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.