

12/03/2002

ASS. REC. BY:

REF: CS/MSG18002993/Svd301

Special Instruction:

Surveyor: Sebastian
Merimen

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSG

Date/Time:

13/2/18 @

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 4515Z

Insured:

SKW 2851 X

at Workshop m/s

Kah Motor

Tel:

6514 5248

8288 6309

of

8 Mundai Estate

Policy No:

MSD / VPCP / 17-002282

Claim No:

MSC / V / 18-000209

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/02/2018

CA / REV / REP. / REV 24 HRS

wp?

H.O.D. Endorsement:

Date/Time:

9.50am @ 14/2/18

Person Contacted:

jason

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKX 4515Z - X

SKW 2851 X - NA / MSG17024214 / 24

D.O.A 12/12/17

Sent poli thru merimen

8/3/18

@ 217pm Jason Said vehicle just completed repair

15/3/18

Final fig \$ 16,527.43 (Reel 7507.37, 317) confirmed by email

MS1G

Merimen e-Claims

Date 14/12/18

SKX 4515Z

14/12/2018

Estimated Cost

CD (T) WS TR RES OD RES LEVA (W) MW

To Insured Vehicle No

SKX 4515Z

Insured Name

Kah Motor

Address

8 Mandai Estate

Insured

Policy No

Claims No

Sum Insured

Excess


Claims Record

jason

Manufacturer

Policy Condition

Remains The veh had commenced its repair at the time of inspection.



Salvage/Market Value

DAG Accident Report

Consistent? Yes or No

DAG Rep Seen

Consistent? Yes or No

Est Repair in 15 days

Repair Yes or No

Lm Sum

%

3 val Yes or No

DAG REP

REP 24 HRS

1wp

Date

Person Contacted

Vehicle IN OUT

Date Time Action Instruction

Type (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

Type (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

Type

Honda Jazz

Color

White

Seating

33657

Engine

Date

JITMGR 5850 GX 201197

Get Date Good (A) Poor Burnt

Steering (A) Damaged Leaked Burnt

Brake (A) Damaged Leaked Burnt

Wash (A) SP - STDAR -

Tire Size

185/55R16

R

11

ES. DLY EXNO. A 34 RS LZA (A) C-TS. PR SUM

TOYO YOKO

Front

R.Ba

6

L.Ba

6

D.O.A

2/7/18

Survey Report

Kah Motor

Date of Damages (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

(2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

(2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

(2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

The L.O. Chassis frame Body Structure affected due to

RECEIVED 14/12/2018

Use The Ref Pass



Days Of Report

15

Reserve No of Trip

1

Date Rep

300

Use The Ref Pass

15/3- Typist

Add Fee

Date Rep

Date Rep

Date Rep

Date Rep

Date Rep

10

310

merimen

P/P \$16,527.43

Survey Department Check List (Case Handler)

Reference No.: CS MSG 18002993 Svc3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 15/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18002993/Svd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 14-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 2851X	Veh. Inspected	SKX 4515Z	
Policy No.	MSD/VPCP/17-002282	Coverage (\$)	0.00	
Claim No.	MSC/V/18-000209	Excess (\$)	0.00	
Assign From	MERIMEN (LIONEL TAN)	Assign Date	14/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/02/2018	Inspection Date	14/02/2018	
Survey held at	KAH MOTOR.CO.SDN.BHD 8 MANDAI ESTATE SINGAPORE 729903			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		13 Feb 2018 15:41 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N

Main Claimant:

TAN KIAN WEE KENNETH, ID: S8500377A

Vehicle Reg. No.:

SKX4515Z

Date of Loss:

02/02/2018 09:00 - :59

Claim Type:

TP / MSC/V/18-000209

Policy/Cover Note No.:

MSD/VPCP/17-002282
(Comprehensive)
Coverage: 23/10/2017 - 22/10/2018

Vehicle Reg. No. (Insured):

SKW2851X

Policy No. (Claimant):

Excess:

S\$1,500.00

Repairer:

Kah Motor Co Sdn Bhd (Mandai) 8 Mandai Estate, CBODY REPAIR AND PAINT CENTRE, 729905 Mandai - Tel: 90721767

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/02/2018]

Driver/Custodian (Insured):

SARAH LING JIN HUI (20 / Female), NRIC: S9714585G, Tel: +6592293168

Adj Asg. Remarks:

CAR-IN - SURVEY BY TODAY Please contact MR JASON HENG @ 6514 5248 or 8288 6309 to arrange for survey.

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 22 Feb 2018

Preliminary Advice

Insured Vehicle No	: SKW2851X	Accident Date	: 02/02/2018
TP Vehicle No	: SKX4515Z	Assignment Date	: 13/02/2018
Make	: HONDA JAZZ	Est. Duration of Repair	: 12.00
Date of Inspection	: 14/02/2018		
Inspection At	: KAH MOTOR CO SDN BHD (MANDAI) 8 MANDAI ESTATE, CBODY REPAIR AND PAINT CENTRE SINGAPORE 729905		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,951.25
Revised Amount	:S\$	16,438.26
Check Items (Estimated)	:S\$	2,480.41
Total	:S\$	18,918.67

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0377A

Vehicle Details

Vehicle No.: SKX4515Z

Vehicle to be Exported: No

Intended De-registration Date: 19 Feb 2018

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Primary Colour: White

Manufacturing Year: 2015

Engine No.: L15B31020354

Chassis No.: JHMGK5850GX201197

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$15,417.00

Original Registration Date: 14 Dec 2015

First Registration Date: 14 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$10,417.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Dec 2025

PARF Rebate Amount: \$7,812.00

Intended COE Rebate Details

COE Expiry Date: 13 Dec 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$56,001.00

COE Rebate Amount: \$43,767.00

Total Rebate Amount: \$51,579.00

The information contained herein is correct as at 19 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/02/2018 18:06
Date Of Accident	02/02/2018 08:50
Exact Location Of Accident	AYE TOWARDS TUAS NEAR DEPOT RD (L/P245)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX4515Z
Insured/Policyholder	
Name Of Registered Owner	TAN KIAN WEE KENNETH
NRIC No	S8500377A
Email Address	DOWNHERE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97659149
Alternative Phone No	OFFICE-97659149
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ-1.5 RS (GK5) (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MW010894-R02
Cover Note Number	
Driver	
Name of Driver	TAN KIAN WEE KENNETH
NRIC No	S8500377A
Date Of Birth	03/01/1985
Occupation	INDOOR
Date Of Driving Pass	08/07/2005
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97659149
Fax Number	
Contact Number	OFFICE-97659149
Email Address	DOWNHERE@GMAIL.COM

Address	BLK 842 SIMS AVE #17-770
Postcode	S400842
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NO 1 INJURY DURING THE ACCIDENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW2851X
Vehicle Make/Model/Colour	HONDA/VEZEL/BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	92293168
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJV1706G
Vehicle Make/Model/Colour	SUBARU/IMPREZA/SILVER

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	CHAN PUI CHUNG STEPHEN
NRIC/Passport Number	S2768200F
Contact Number	96467273
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

Vehicle No SKX4515Z

SKETCH PLAN

ANNEX D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



AYZ NEAR OZPOT ROAD.

13:13pm
02 FEB 2018 ARY CHUA

A= SJV 1706 G
B= SKX 4515Z
C= SKW 2851X

Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No SKX 4515Z

Annex E

Describe Circumstances of the Accident

I was driving on AYE towards # Tuas when the front car braked. I applied the brakes as well and stopped (SJV 1706G) before the front car. Subsequently, I was hit from behind by SKW 2851X, which caused me to hit SJV 1706G in front.

~~We~~ ex

I exited from the car and noted that the driver of SJV 1706G, a middle aged man was uninjured, and the driver of SKW 2851X, a young lady, was uninjured.

We exchanged contacts and documented the accident. As no one was injured in the accident, we moved our vehicles from the scene.

Declaration

We declare the foregoing particulars are true in every respect.

 2/2/18 1:13pm
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

13:13pm
02 FEB 2018
ARY CHUA
Witnessed by Reporting Centre Personnel



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SKX4515Z
Chassis No : JHMGK5850GX201197
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : TAN KIAN WEE KENNETH
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 2/2/2018

Document No. : SQT18000510
Date : 2. Feb 2018
Customer No. : WZM003
Svc Advisor : JASON HENG
Engine No : L15B31020354
Date | Time : 2. Feb 2018 1:12:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	THIRD PARTY CLAIMS (J/NO: 10342) OWNER: TAN KIAN WEE KENNETH OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 2/2/18 SURVEYED BY: DATE: TP INSURER: TP VEH:						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER ✓ NEC	1	11.20	25	✓ 8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER ✓ NEC	2	6.30	25	✓ 9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5 ✓ NEC	1	8.30	25	✓ 6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ✓ NEC	2	60.00		✓ 120.00	8.40	128.40
04715-T5B-000ZZ	FACERR.BUMPER ✓ Deform.	1	492.60	25	✓ 369.45	25.86	395.31
71502-T5A-000	GARNISHR.RR.BUMPER X NN	1	14.00	25	10.50	0.74	11.24
71507-T5A-000	GARNISHL.RR.BUMPER ✓ Deform.	1	14.00	25	✓ 10.50	0.74	11.24
71593-T5A-000	SPACERR.RR.BUMPER ✓ NEC	1	11.50	25	✓ 8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER ✓ NEC	1	11.50	25	✓ 8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER ✓ NEC	5	2.00	25	✓ 7.50	0.53	8.03
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ✓ DMG	1	320.00		✓ 320.00	22.40	342.40
74940-SZW-003	BUZZER ASSYSMART ✓ CRK 44.47	1	60.10	25	✓ 45.07	3.15	48.22
38387-SLE-003	ANTENNA ASSY,LRR. ✓ DMG 43.57	1	59.40	25	✓ 44.55	3.12	47.67
68100-TAS-Z50ZZ	TAILGATE COMP ✓ DT	1	716.30	25	✓ 537.22	37.61	574.83
75722-T5L-T01	EMBLEMRR. ✓ NEC	1	10.50	25	✓ 7.87	0.55	8.42
74890-T5B-911	GARNISH ASSYRR.LICENSE X NN	1	194.70	25	146.02	10.22	156.24
74440-T5A-003	WEATHERSTRIPTAILGATE ✓ NEC	1	92.30	25	✓ 69.22	4.85	74.07
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER X NN	1	52.10	25	39.07	2.73	41.80
74800-T5S-K61	LOCK ASSY,TAILGATE ✓ JM	1	77.10	25	✓ 57.82	4.05	61.87
66100-TAR-T10ZZ	PANEL COMPRR. End Panel ✓ DT	1	314.00	25	✓ 235.50	16.49	251.99
04655-TAS-300ZZ	PANEL SET,RR.FLOOR R	1	669.90	25	502.42	35.17	537.59
72841-SH3-315	OILSHEET X NN	1	39.90	25	29.92	2.09	32.01



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SKX4515Z
Chassis No : JHMGK5850GX201197
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : TAN KIAN WEE KENNETH
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 2/2/2018

Document No. : SQT18000510
Date : 2. Feb 2018
Customer No. : WZM003
Svc Advisor : JASON HENG
Engine No : L15B31020354
Date | Time : 2. Feb 2018 1:12:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84640-T5A-003ZA	LINING ASSYRR.PANEL End Panel Garnish ✓ Deform.	1	60.80	25	✓ 45.60	3.19	48.79
84521-T5A-901ZA	LID ASSYSPARE TIRE X NV	1	186.00	25	✓ 139.50	9.77	149.27
84550-T5S-M10	BOX ASSYCARGO FLOOR X NV	1	103.90	25	✓ 77.92	5.45	83.37
33500-T5A-J02	TAILLIGHT ASSYR. X NV	1	217.40	25	✓ 163.05	11.41	174.46
33550-T5A-J02	TAILLIGHT ASSYL. ✓ CRK	1	217.40	25	✓ 163.05	11.41	174.46
34150-T5A-J01	LIGHT ASSYR.LID X NV	1	79.30	25	✓ 59.47	4.16	63.63
34155-T5A-J01	LIGHT ASSYL.LID X NV	1	79.30	25	✓ 59.47	4.16	63.63
04711-T5A-000ZZ	FACEFR.BUMPER ✓ Deform.	1	494.70	25	✓ 371.02	25.97	396.99
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) ✓ BT	2	45.00	✓ 90	45.00	3.15	48.15
71145-T5A-000	BASEFR.LICENCE PLATE ✓ BT	1	50.90	25	✓ 38.17	2.67	40.84
71193-T5A-000	SPACERR.FR.BUMPER ✓ NEC	1	10.40	25	✓ 7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER ✓ NEC	1	10.40	25	✓ 7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER ✓ NEC	17	2.00	25	✓ 25.50	1.79	27.29
33100-T5A-J21	HEADLIGHT ASSYR. ? NV	1	1118.60	25	✓ 838.95	58.73	897.68
33150-T5A-J21	HEADLIGHT ASSYL. ✓ CRK	1	1118.60	25	✓ 838.95	58.73	897.68
71140-T5A-000	BRACKETR.HEADLIGHT ✓ CRK	1	23.60	25	✓ 17.70	1.24	18.94
71190-T5A-000	BRACKETL.HEADLIGHT ✓ CRK	1	21.90	25	✓ 16.42	1.15	17.57
33600-T5A-003	LIGHT ASSYR.FR.POSITION ?	1	180.60	25	✓ 135.45	9.48	144.93
33650-T5A-003	LIGHT ASSYL.FR.POSITION ?	1	180.60	25	✓ 135.45	9.48	144.93
33900-TY0-003	LIGHT ASSY FR.FOG ? NV	1	261.90	25	✓ 196.42	13.75	210.17
33950-TY0-003	LIGHT ASSY FR.FOG ?	1	261.90	25	✓ 196.42	13.75	210.17
71103-T5A-N00	GARNISHR.FR.BUMPER ?	1	23.30	25	✓ 17.47	1.22	18.69
71108-T5A-N00	GARNISHL.FR.BUMPER ?	1	23.30	25	✓ 17.47	1.22	18.69
71120-TAS-003	GRILLE ASSYFR. ✓ CRK	1	288.90	25	✓ 216.67	15.17	231.84
71130-T5A-000ZZ	BEAM COMPFR.BUMPER ✓ DT	1	219.40	25	✓ 164.55	11.52	176.07
60400-T5B-310ZZ	BULKHEAD COMPFR. ✓ DT	1	374.30	25	✓ 280.72	19.65	300.37
60100-T5A-000ZZ	HOOD COMP R	1	527.00	25	✓ 395.25	27.67	422.92
19043-PLA-E00	LABELCOOLANT INFORMATION X NV	1	4.90	25	✓ 3.67	0.26	3.93
80050-SP0-000	LABELAIR CONDITIONER CAUTION X NV	1	1.80	25	✓ 1.35	0.09	1.44
80100-T5B-003	CONDENSER ASSY ✓ DT	1	704.40	25	✓ 528.30	36.98	565.28

Printed on 12/2/2018 3:17:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SKX4515Z
Chassis No : JHMGK5850GX201197
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : TAN KIAN WEE KENNETH
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 2/2/2018

Document No. : SQT18000510 Page 3
Date : 2. Feb 2018
Customer No. : WZM003
Svc Advisor : JASON HENG
Engine No : L15B31020354
Date | Time : 2. Feb 2018 1:12:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
19010-5R1-901	RADIATOR COMP ? NV	1	1187.40	25	890.55	62.34	952.89
08CLA-P9911LK8	COOLANTANTI-FREEZE ? 87 (5PCS) N/C	3	23.20	25	52.20	3.65	55.85
Sum Item					8741.25	611.90	9,353.15
					8824.80		
BOSUN	SUNDRIES	1	100.00	50 ✓	100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	300.00	280 ✓	300.00	21.00	321.00
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	80 ✓	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00	✓ ✓	140.00	9.80	149.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	✓ ✓	140.00	9.80	149.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00	120 ✓	160.00	11.20	171.20
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00	80 ✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00	80 ✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	100.00	X	100.00	7.00	107.00
BOMISC1	RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	160.00	✓ ✓	160.00	11.20	171.20
BOMISC1	RESET & CALIBRATE REAR VIEW CAMERA (N)	1	160.00	✓ ✓	160.00	11.20	171.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	560 ✓	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	420 ✓	800.00	56.00	856.00
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	300.00	280 ✓	300.00	21.00	321.00
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	250.00	230 ✓	250.00	17.50	267.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	3500.00	2240 ✓	3500.00	245.00	3745.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00	2250 ✓	2500.00	175.00	2675.00
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN	1	3000.00	2240 ✓	3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00	2250 ✓	2500.00	175.00	2675.00
Sum Labor					15210.00	1,064.70	16,274.70

Survey By _____
Date & Time _____
Excess _____

Total Amount 23,951.25 1,676.60 25,627.85
Total (Inclusive of GST) 25,627.85

Printed on 12/2/2018 3:17:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

24,034.80



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SKX4515Z
Chassis No : JHMGK5850GX201197
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : TAN KIAN WEE KENNETH
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 2/2/2018

Document No. : SQT18000510 **Page** 4
Date : 2. Feb 2018
Customer No. : WZM003
Svc Advisor : JASON HENG
Engine No : L15B31020354
Date | Time : 2. Feb 2018 1:12:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Status							
Signature							

Sebastian.
14/2/18.
- Part by part repair.
- Question Mark Item
Photo.
- Photo Before Paint.
90036121

12 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

sebastianyeang@lkkauto.com.

23/2/2018

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 March 2018 10:32 AM
To: 'Jason Heng'; SUR
Subject: RE: Finalization For SKX4515Z - DOA 2/2/18

Dear Jason,

Confirmed finalize amount \$16,527.43 before GST

Surveyor's recommended no of days: 15 days

Final invoice and all supporting documents sent to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Heng [mailto:jasonheng@honda.com.sg]
Sent: Wednesday, 14 March 2018 11:27 AM
To: SUR <sur@lkkauto.com>
Subject: FW: Finalization For SKX4515Z - DOA 2/2/18

Dear Veron,

As requested. FYI.

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: Jason Heng
Sent: Saturday, 10 March, 2018 12:46 PM
To: sebastianyeang@lkkauto.com
Subject: Finalization For SKX4515Z - DOA 2/2/18

Dear Sebastian,

We enclosed the total final repair costs for,

Vehicle No.	SKX4515Z
-------------	----------

Final Repair Costs (exclude GST)	\$16,527.43
Repair Period* (Days)	17 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Regards,
Jason

Jason Heng
Kah Motor Body & Paint Centre
6A Mandai Estate
Singapore 729903

DID: 65145248

Mobile: 82886309

Email: jasonheng@honda.com.sg

KAHMOTOR
(A MEMBER OF ORIENTAL HOLDINGS BERHAD)

HONDA
The Power of Dreams



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14. February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	THIRD PARTY CLAIMS (J/NO: 10342)						
	OWNER: TAN KIAN WEE KENNETH						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 2/2/18						
	SURVEYED BY:						
	DATE:						
	TP INSURER:						
	TP VEH:						
	ADDITIONAL PART						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20	✓ 25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30	✓ 25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	✓ 25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00	✓ 25	120.00	8.40	128.40
04715-T5B-000ZZ	FACERR.BUMPER	1	492.60	✓ 25	369.45	25.86	395.31
71507-T5A-000	GARNISHL.RR.BUMPER	1	14.00	✓ 25	10.50	0.74	11.24
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	✓ 25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	✓ 25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	2.00	✓ 25	7.50	0.53	8.03
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00	✓ 25	320.00	22.40	342.40
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	✓ 25	44.47	3.11	47.58
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	✓ 25	43.57	3.05	46.62
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	✓ 25	537.22	37.61	574.83
75722-T5L-T01	EMBLEMRR.	1	10.50	✓ 25	7.87	0.55	8.42
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	✓ 25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE	1	77.10	✓ 25	57.82	4.05	61.87
66100-TAR-T10ZZ	PANEL COMPRR.	1	314.00	✓ 25	235.50	16.49	251.99
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	✓ 25	45.60	3.19	48.79
33550-T5A-J02	TAILLIGHT ASSYL.	1	217.40	✓ 25	163.05	11.41	174.46
04711-T5A-000ZZ	FACEFR.BUMPER	1	494.70	✓ 25	371.02	25.97	396.99
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	2	45.00	✓ 25	90.00	6.30	96.30
71145-T5A-000	BASEFR.LICENCE PLATE	1	50.90	✓ 25	38.17	2.67	40.84
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	✓ 25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	✓ 25	7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER	17	2.00	✓ 25	25.50	1.79	27.29
33150-T5A-J21	HEADLIGHT ASSYL.	1	1,118.60	✓ 25	838.95	58.73	897.68
71140-T5A-000	BRACKETR.HEADLIGHT	1	23.60	✓ 25	17.70	1.24	18.94
71190-T5A-000	BRACKETL.HEADLIGHT	1	21.90	✓ 25	16.42	1.15	17.57
71120-TAS-003	GRILLE ASSYFR.	1	288.90	✓ 25	216.67	15.17	231.84
71130-T5A-000ZZ	BEAM COMPFR.BUMPER	1	219.40	✓ 25	164.55	11.52	176.07
60400-T5B-310ZZ	BULKHEAD COMPFR.	1	374.30	✓ 25	280.72	19.65	300.37
80100-T5B-003	CONDENSER ASSY	1	704.40	✓ 25	528.30	36.98	565.28
08CLA-P9911LK8	COOLANTANTI-FREEZE	5	23.20	✓ 25	87.00	6.09	93.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.00	✓ 25	3.75	0.26	4.01
	SUM PARTS:				4,767.43	333.75	5,101.18
BOSUN		1	50.00	✓ 25	50.00	3.50	53.50

(A)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14. February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

	SUNDRIES						
BG02R		1	280.00	✓	280.00	19.60	299.60
	REPLACE RR. WINDSCREEN.(N)						
BODAMKIT		1	80.00	✓	80.00	5.60	85.60
	WINDSCREEN DAM KIT.						
BML01I		1	140.00	✓	140.00	9.80	149.80
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BML02I		1	140.00	✓	140.00	9.80	149.80
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R		1	120.00	✓	120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOJSE		1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT FOR TAILGATE						
BOJSE		1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT FOR END PANEL						
BOMISC1		1	160.00	✓	160.00	11.20	171.20
	RESET & CALIBRATE SMART ENTRY SYSTEM (N)						
BOMISC1		1	160.00	✓	160.00	11.20	171.20
	RESET & CALIBRATE REAR VIEW CAMERA (N)						
BKTG02R		1	560.00	✓	560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BMI03D		1	420.00	✓	420.00	29.40	449.40
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BMA01D		1	280.00	✓	280.00	19.60	299.60
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)						
BMC01D		1	230.00	✓	230.00	16.10	246.10
	REMOVE & INSTALL RADIATOR WITH FITTINGS. PRESSURE TEST COOLING SYSTEM.(N)						
BKRP02M		1	2,240.00	✓	2,240.00	156.80	2,396.80
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.						
BP05R		1	2,250.00	✓	2,250.00	157.50	2,407.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14. February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN ALIGN CHASSIS & RENEW DAMAGE PARTS.	1	2,240.00 ✓	2,240.00	156.80	2,396.80
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,250.00 ✓	2,250.00	157.50	2,407.50
SUM LABOUR:				11,760.00	823.20	12,583.20
TOTAL SGD				16,527.43	1,156.95	17,684.38
Total Payable (SGD)						17,684.38

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: S8500377A / TAN KIAN WEE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14, February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	SUPPLEMENTARY PARTS						
84441-T5A-003ZB	POCKETTAILGATE LINING PULL SCR	1	5.00	25	3.75	0.26	4.01
	SUM PARTS:				3.75	0.26	4.01
	TOTAL SGD				3.75	0.26	4.01

Total Payable (SGD) 4.01

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		13 Feb 2018 15:41 Edit Adj Rpt	S\$16,527.43 Edit Estimates	S\$16,527.43 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by Insurer]
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	TAN KIAN WEE KENNETH, ID: S8500377A		
Vehicle Reg. No.:	SKX4515Z	Date of Loss:	02/02/2018 09:00 - :59
Claim Type:	TP / MSC/V/18-000209	Policy/Cover Note No.:	MSD/VPCP/17-002282 (Comprehensive) Coverage: 23/10/2017 - 22/10/2018
Vehicle Reg. No. (Insured):	SKW2851X	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Kah Motor Co Sdn Bhd (Mandai) 8 Mandai Estate, CBODY REPAIR AND PAINT CENTRE, 729905 Mandai - Tel: 90721767		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 15/03/2018]		
Driver/Custodian (Insured):	SARAH LING JIN HUI (20 / Female), NRIC: S9714585G, Tel: +6592293168		
Adj Asg. Remarks:	CAR-IN - SURVEY BY TODAY Please contact MR JASON HENG @ 6514 5248 or 8288 6309 to arrange for survey.		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS ☐										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SKX4515Z (MSC/V/18-000209)
[SKW2851X]
TP
TAN KIAN WEE KENNETH
Feb 2 2018 9:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/02/18 15:14	Accident Statement From:OD - Reg. No: SKW2851X, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/02/18 19:52	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/02/18 08:55	General View	1	Load JPG	☒
2	15/02/18 08:55	General View	1	Load JPG	☒
3	15/02/18 08:55	General View	1	Load JPG	☒
4	15/02/18 08:55	General View	1	Load JPG	☒
5	15/02/18 08:55	General View	1	Load JPG	☒
6	15/02/18 08:55	General View	1	Load JPG	☒
7	15/02/18 08:55	General View	1	Load JPG	☒
8	15/02/18 08:55	General View	1	Load JPG	☒
9	15/02/18 08:55	General View	1	Load JPG	☒
10	15/02/18 08:55	General View	1	Load JPG	☒
11	15/02/18 08:55	General View	1	Load JPG	☒
12	15/02/18 08:55	General View	1	Load JPG	☒
13	15/02/18 08:55	General View	1	Load JPG	☒
14	15/02/18 08:55	General View	1	Load JPG	☒
15	15/02/18 08:55	General View	1	Load JPG	☒
16	15/02/18 08:55	General View	1	Load JPG	☒
17	15/02/18 08:55	General View	1	Load JPG	☒
18	15/02/18 08:55	General View	1	Load JPG	☒
19	15/02/18 08:55	General View	1	Load JPG	☒
20	15/02/18 08:55	General View	1	Load JPG	☒
21	15/02/18 08:55	General View	1	Load JPG	☒
22	15/02/18 08:55	General View	1	Load JPG	☒
23	15/02/18 08:55	General View	1	Load JPG	☒
24	15/02/18 08:55	General View	1	Load JPG	☒
25	15/02/18 08:55	General View	1	Load JPG	☒
26	15/02/18 08:55	General View	1	Load JPG	☒
27	15/02/18 08:55	General View	1	Load JPG	☒
28	15/02/18 08:55	General View	1	Load JPG	☒
29	15/02/18 08:55	General View	1	Load JPG	☒
30	15/02/18 08:55	General View	1	Load JPG	

					☒
31	15/02/18 08:55	General View		Load JPG	☒
32	15/02/18 08:55	General View		Load JPG	☒
33	15/02/18 08:55	General View		Load JPG	☒
34	15/02/18 08:55	General View		Load JPG	☒
35	15/02/18 08:55	General View		Load JPG	☒
36	15/02/18 08:55	General View		Load JPG	☒
37	15/02/18 08:55	General View		Load JPG	☒
38	15/02/18 08:55	General View		Load JPG	☒
39	15/02/18 08:55	General View		Load JPG	☒
40	15/02/18 08:55	General View		Load JPG	☒
41	15/02/18 08:55	General View		Load JPG	☒
42	15/02/18 08:55	General View		Load JPG	☒
43	15/02/18 08:55	General View		Load JPG	☒
44	15/02/18 08:55	General View		Load JPG	☒
45	15/02/18 08:55	General View		Load JPG	☒
46	15/02/18 08:55	General View		Load JPG	☒
47	15/02/18 08:55	General View		Load JPG	☒
48	15/02/18 08:55	General View		Load JPG	☒
49	15/02/18 08:55	General View		Load JPG	☒
50	15/02/18 08:55	General View		Load JPG	☒
51	15/02/18 08:55	General View		Load JPG	☒
52	15/02/18 08:55	General View		Load JPG	☒
53	15/02/18 08:55	General View		Load JPG	☒
54	15/02/18 08:55	General View		Load JPG	☒
55	15/02/18 08:55	General View		Load JPG	☒
56	15/02/18 08:55	General View		Load JPG	☒
57	15/02/18 08:55	General View		Load JPG	☒
58	15/02/18 08:55	General View		Load JPG	☒
59	15/02/18 08:55	General View		Load JPG	☒
60	15/02/18 08:55	General View		Load JPG	☒
61	15/02/18 08:55	General View		Load JPG	☒
62	15/02/18 08:55	General View		Load JPG	☒
63	15/02/18 08:55	General View		Load JPG	☒
64	15/02/18 08:55	General View		Load JPG	☒
65	15/02/18 08:55	General View		Load JPG	☒
66	15/02/18 08:55	General View		Load JPG	☒
67	15/02/18 08:55	General View		Load JPG	☒
68	15/02/18 08:55	General View		Load JPG	☒
69	15/02/18 08:55	General View		Load JPG	☒
70	15/02/18 08:55	General View		Load JPG	☒
71	15/02/18 08:55	General View		Load JPG	☒
72	15/02/18 08:55	General View		Load JPG	☒
73	15/02/18 08:55	General View		Load JPG	☒
74	15/02/18 08:55	General View		Load JPG	☒
75	15/02/18 08:55	General View		Load JPG	☒
76	15/02/18 08:55	General View		Load JPG	☒
77	15/02/18 08:55	General View		Load JPG	☒
78	15/02/18 08:55	General View		Load JPG	☒
79	15/02/18 08:55	General View		Load JPG	☒

80	15/02/18 08:55	General View	1	Load JPG	☒
81	15/02/18 08:55	General View	1	Load JPG	☒
82	15/02/18 08:55	General View	1	Load JPG	☒
83	15/02/18 08:55	General View	1	Load JPG	☒
84	15/02/18 08:55	General View	1	Load JPG	☒
85	15/02/18 08:55	General View	1	Load JPG	☒
86	15/02/18 08:55	General View	1	Load JPG	☒
87	15/02/18 08:55	General View	1	Load JPG	☒
88	15/02/18 08:55	General View	1	Load JPG	☒
89	15/02/18 08:55	General View	1	Load JPG	☒
90	15/02/18 08:55	General View	1	Load JPG	☒
91	15/02/18 08:55	General View	1	Load JPG	☒
92	15/02/18 08:55	General View	1	Load JPG	☒
93	15/02/18 08:55	General View	1	Load JPG	☒
94	15/02/18 08:55	General View	1	Load JPG	☒
95	15/02/18 08:55	General View	1	Load JPG	☒
96	15/02/18 08:55	General View	1	Load JPG	☒
97	15/02/18 08:55	General View	1	Load JPG	☒
98	15/02/18 08:55	General View	1	Load JPG	☒
99	15/02/18 08:55	General View	1	Load JPG	☒
100	15/02/18 08:55	General View	1	Load JPG	☒
101	15/02/18 08:55	General View	1	Load JPG	☒
102	15/02/18 08:55	General View	1	Load JPG	☒
103	15/02/18 08:55	General View	1	Load JPG	☒
104	15/02/18 08:55	General View	1	Load JPG	☒
105	15/02/18 08:55	General View	1	Load JPG	☒
106	15/02/18 08:55	General View	1	Load JPG	☒
107	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
108	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
109	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
110	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
111	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
112	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
113	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
114	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
115	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
116	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
117	14/03/18 11:36	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page v	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/02/18 15:14	TPD SKX4515Z GIA REPORT	1	Load PDF	
2	13/02/18 15:14	TPD SKX4515Z - ESTIMATE REPAIR	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002993/SVD3E2

Date: 19/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/PCP/17-002282
Claimant Vehicle No :	SKX4515Z	Insured Vehicle No :	SKW2851X
Date of Loss:	02/02/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000209

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX4515Z	Engine No:	L15B31020354
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Chassis No:	JHMGK5850GX201197
Reg. Date:	14/12/2015 (Man. Year: 2015)	Odometer:	33657 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,924.80	4,817.43	4,107.37	46.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,110.00	11,710.00	3,400.00	22.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,034.80	16,527.43	7,507.37	31.24
+ GST 7.00/7.00% (S\$)	1,682.44	1,156.92	525.52	31.24
Nett Amount (S\$)	25,717.24	17,684.35	8,032.89	31.24

INSPECTION

Date of Assignment:	13/02/2018	
Date Inspected:	14/02/2018 Inspected At:	Kah Motor Co Sdn Bhd (Mandai) 8 Mandai Estate, CBODY REPAIR AND PAINT CENTRE Singapore 729905
Estimated Period of Repair:	15.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2018)
 Parts: 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKX4515Z)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RUBBER C WINDSHIELD DAMPER	Necessary	8.40 FS	*8.40 FS
2	1		*RUBBER WINDSHIELD DAMPER (2PCS)	Necessary	9.45 FS	*9.45 FS
3	1		*DAMPER STD 5X5	Necessary	6.22 FS	*6.22 FS
4	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
5	1		*FACERR.BUMPER	Deformed	369.45 FS	*369.45 FS
6	1		*GARNISH R.R.BUMPER	Not Necessary	10.50 FS	*- FS
7	1		*GARNISH L.R.R.BUMPER	Deformed	10.50 FS	*10.50 FS
8	1		*SPACERR.RR.BUMPER	Necessary	8.62 FS	*8.62 FS
9	1		*SPACER L.RR.BUMPER	Necessary	8.62 FS	*8.62 FS
10	5		*CLIP BUMPER	Necessary	7.50 FS	*7.50 FS
11	1		*4PCS ACT RR.SENSOR	Damaged	320.00 FS	*320.00 FS
12	1		*BUZZER ASSY SMART	Cracked	45.07 FS	*44.47 FS
13	1		*ANTENNE ASSY, L.RR	Damaged	44.55 FS	*43.57 FS
14	1		*TAILGATE COMP	Dented	537.22 FS	*537.22 FS
15	1		*EMBLEM RR	Necessary	7.87 FS	*7.87 FS
16	1		*GARNISH ASSY RR.LICENSE	Not Necessary	146.02 FS	*- FS
17	1		*WEATHER STRIP TAILGATE	Necessary	69.22 FS	*69.22 FS
18	1		*LINING ASSY TAILGATE LOWER	Not Necessary	39.07 FS	*- FS
19	1		*LOCK ASSY, TAILGATE	Jammed	57.82 FS	*57.82 FS
20	1		*PANEL COM PR	Dented	235.50 FS	*235.50 FS
21	1		*PANEL SET, RR.FLOOR	Repair	502.42 FS	*- FS
22	1		*OIL SHEET	Not Necessary	29.92 FS	*- FS
23	1		*LINING ASSY RR.PANEL	Deformed	45.60 FS	*45.60 FS
24	1		*LID ASSY SPARE TIRE	Not Necessary	139.50 FS	*- FS
25	1		*BOX ASSY CARGO FLOOR	Not Necessary	77.92 FS	*- FS
26	1		*TAILLIGHT ASSY R	Not Necessary	163.05 FS	*- FS
27	1		*LIGHT ASSY R.LID	Not Necessary	59.47 FS	*- FS
28	1		*LIGHT ASSY L.LID	Not Necessary	59.47 FS	*- FS
29	1		*FACE FR.BUMPER	Deformed	371.02 FS	*371.02 FS
30	2		*NUMBER PLATE WITH CASING - L(N)	Bent	90.00 FS	*90.00 FS
31	1		*BASE FR.LICENSE PLATE	Bent	38.17 FS	*38.17 FS
32	1		*SPACERR.FR.BUMPER	Necessary	7.80 FS	*7.80 FS
33	1		*SPACER L.FR.BUMPER	Necessary	7.80 FS	*7.80 FS
34	17		*CLIP BUMPER	Necessary	25.50 FS	*25.50 FS
35	1		*HEADLIGHT ASSY, R	Not Necessary	838.95 FS	*- FS
36	1		*HEADLIGHT ASSY L	Cracked	838.95 FS	*838.95 FS
37	1		*BRACKET R.HEADLIGHT	Cracked	17.70 FS	*17.70 FS
38	1		*BRACKET L.HEADLIGHT	Cracked	16.42 FS	*16.42 FS
39	1		*LIGHT ASSY R.FR POSITION	Not Necessary	135.45 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*LIGHT ASSY.L.FR POSITION	Not Necessary	135.45 FS	*- FS
41	1		*LIGHT ASSY FR FOG	Not Necessary	196.42 FS	*- FS
42	1		*LIGHT ASSY FR. FOG	Not Necessary	196.42 FS	*- FS
43	1		*GARNISHR.FR.BUMPER	Not Necessary	17.47 FS	*- FS
44	1		*GARNISHL.FR.BUMPER	Not Necessary	17.47 FS	*- FS
45	1		*GRILLE ASSYFR	Cracked	216.67 FS	*216.67 FS
46	1		*BEAM COMPFR.BUMPER	Dented	164.55 FS	*164.55 FS
47	1		*BULKHEAD COMPFR	Dented	280.72 FS	*280.72 FS
48	1		*HOOD COMP	Repair	395.25 FS	*- FS
49	1		*LABELCOOLANT INFORMATION	Not Necessary	3.67 FS	*- FS
50	1		*LABELAIR CONDITIONER CAUTION	Not Necessary	1.35 FS	*- FS
51	1		*CONDENSER ASSY	Dented	528.30 FS	*528.30 FS
52	1		*RADIATOR COMP	Not Necessary	890.55 FS	*- FS
53	5		*COOLANT ANTI-FREEZE	Necessary	87.00 FS	*87.00 FS
54	1		*TAILLIGHT ASSYL	Cracked	163.05 FS	*163.05 FS
55	1		*POCKETTAILGATE LINING PULL	Scratched	3.75 FS	*3.75 FS
56	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,924.80	4,817.43
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RR WINDSCREEN (N)	New	300.00	280.00
2	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	140.00	140.00
3	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	140.00	140.00
4	REMOVE & RENEW REVERSE SENSORS - 4PCS (N)	New	160.00	120.00
5	BODY JOINT SEALANT FOR TAILGATE	New	100.00	80.00
6	BODY JOINT SEALANT FOR END PANEL	New	100.00	80.00
7	BODY JOINT SEALANT FOR FLOOR PANEL	New	100.00	0.00
8	RESET & CALIBRATE SMART ENTRY SYSTEM (N)	New	160.00	160.00
9	RESET & CALIBRATE REAR VIEW CAMERA (N)	New	160.00	160.00
10	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	800.00	560.00
11	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	800.00	420.00
12	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	300.00	280.00
13	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	250.00	230.00
14	CUT OFF & RENEW RR PANEL. STRAIGHTEN	New	3,500.00	2,240.00
15	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	2,500.00	2,250.00
16	CUT OFF & RENEW BULKHEAD. STRAIGHTEN	New	3,000.00	2,240.00
17	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	2,500.00	2,250.00
18	WINDSCREEN DAM KIT	New	100.00	80.00
Gross Labour Cost (\$\$)			15,110.00	11,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >