

ASS. REC. BY:

REF:

C83/MSG17018544/

GIVE

Special Instruction: v Paper Survey

Surveyor:
Mennen

CIB

ASSIGNMENT (Office)

From (Person): Catherine Thia

of MSIG

Date/Time: 14.02.2018

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 5599A

Insured: SLA 1146J

at Workshop m/s HS Automotive Services (Kaki Bukit)

Tel: 67472755

of Blk 2 Kaki Bukit Avenue 2 # 01-15 Kaki Bukit

Policy No: A2869155 AVW

Claim No: M530874

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/9/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

28/9/17 anytime

H.O.D. Endorsement:

Date/Time: 27/9/17

Person Contacted: Alex

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SJL 5599A - NA/MSG17018453/r3	Don: 23/9/2017
	SLA 1146J - CS/MSG17018538/Rlg	Don: 23/9/2017
	Dismantle Part: 29.07.2017	
	After repair: 10.10.2017	
26.10.17 442pm Email to Catherine Thia thru Mennen		

27/1/18 LS \$9000, 10 Days. (Red 5400, 3870)

27/2/2018

RECEIVED 28 FEB 2018

REF: MSIG

48442

ASSIGNMENT

Form _____ Date 28/1/17

Estimated Cost _____

OD / ☒ P / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SJL 5599 A

at Workshop / M / S HS Automotive

at Blk 2 Kaki Bukit Ave 2 #01-15 Kaki Bukit

Insured _____

Policy No _____

Claims No _____

Sum Insured _____ Excess _____

(Client's Record)

Make of car _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bar or Market Value \$25k

DAC Accident Report _____ Consistent? Yes or No

GI4 PR Seen _____ Consistent? Yes or No

Est Repairs 10 days Res Yes or No

Lum Sum 20 % 3 Val Yes or No

CA / REV / REP / 24 HRS 'up'

Date _____ Person Contacted _____ Vehicle IN / OUT

Date Time Action / Instruction

Veh No SJL 5599A Reg No 02 REC 2008

Type ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make Honda Cross road cc 1799

Colour Black AC Insured / Std / N / NA

Go Reseng 132629 T Rego Insured / Std / N / NA

Eng No _____

C No RTU1008151

Gen Cond ☒ Good / Fair / Poor / Burnt

Steering ☒ In order / Jammed / Leaked / Burnt or _____

Brake ☒ In order / Jammed / Leaked / Burnt or _____

Mod NB / S Rim / STD A/Rim or _____

Wre Size F: 235/60 R16

R: 11

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R Ba 6 mm R Ba 5 mm

L Ba 5 mm L Ba 5 mm

D O A 26.09.2017 D O I 28.09.2017 @ 5:30pm

Survey held at w/s HS Automotive

Des of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or _____

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision

Estimated repair range \$6,000 - \$8,000

1/2/2018

RECEIVED 01 FEB 2018

Date/Time File Pass to: ☐ : Prel. Report
 - 01/12/2018 ☐ : Final Report
 Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Keywords: *Self-esteem, self-esteem threat, self-esteem threat sensitivity, self-esteem threat sensitivity scale, self-esteem threat sensitivity scale-2*

6-96-3

Figure 1

Others

Total

Report Format: PRS
Lump Sum / I.B.I. (S)

Add Fee: ☐ Site Insp (\$
☐ Interview (\$
☐ Tech Invs (\$
☐ Weekend (\$

Survey Fee	
Transportation	
6 - RE	
Photos	
Others	
TOTAL	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17018544/Gvb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-02-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLA 1146J	Veh. Inspected	SJL 5599A
Policy No.		Coverage (\$)	0.00
Claim No.	M530874	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	14/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/09/2017	Inspection Date	14/02/2018
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Eng Huey Ni

From: Eng Huey Ni
Sent: Monday, 12 February 2018 3:29 PM
To: Shiao Chan (LKKAUTO)
Cc: Ng Chen How
Subject: To do Paper Re-survey - TP SJL5599A; DOA: 26/9/2017- (Pre-repair survey was done by you earlier) - Our Ref: M530874

Hi Shiao Chan,

As spoken, your surveyor Mr Xing Guo Qiang has done the pre-repair survey on the above third party vehicle.

We have now received the full set of survey report and colour photos from third party lawyer JusEquity Law Corporation.

I have make a copy of the survey report and colour photos.

Please assist to do a paper re-survey and let us have your recommended repair cost and no. of days for repair.

Thank you.

Note: I have left the documents with Chen How as I will be on leave from tomorrow afternoon. Please request for dispatch to look for Chen how. Thanks

Chen How - thanks.

Eng Huey Ni
Senior Executive, Claims Services
D: +65 6643 1314 | F: +65 6225 7402 | hueyni_eng@sg.msigg-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msigg.com.sg



A Member of **MS&AD** INSURANCE GROUP

MC-COY

APPRAISER PTE LTD
No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017
Registration No: 200723252D

Invoice No 17034-09/MY

Billing Name & Address

Date 16 Nov 2017

Ting Ah Kau
Blk 649 Jalan Tenaga
#08-155
Singapore 410649

Vehicle No : SJL 5599 A

Model : Honda Crossroad

Item	Descriptions	Amount S\$
1	Date of inspection : <u>28 Sep 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>255</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1130.00</u>
	SDLS : ONE THOUSAND ONE HUNDRED AND THIRTY ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O.E

MC-COY

APPRAISER PTE LTD

No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017
Registration No: 200723252D

Report Reference : TP / 17034-09/MY / 2017
Date of Report : 16 Nov 2017

Ting Ah Kau
Blk 649 Jalan Tenaga
#08-155
Singapore 410649

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 26 Sep 2017

Workshop Address : HS Automotive Services
Blk 2 Kaki Bukit Ave 2
#02-25 Autohub@Kaki Bukit
Singapore 417921

As per your instruction dated **28 Sep 2017** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SJL 5599 A**. We enclosed herewith our report and findings as follows:

1. 1st Inspection Date : Pre repair : 27 Sep 2017 2nd Inspection : 29 Sep 2017
Final Inspection : 10 Oct 2017

2. VEHICLE PARTICULARS

Registration No : SJL 5599 A
Model : Honda Crossroad
Year / Capacity : 2008/1799
Chassis No : RT1-1008151

Engine No : R18A3011092
Mileage : 132630
Colour : Black

3. TYRES CONDITION

		Made	Balance		Rim
FRONT O/S	: 235/60 R16	Bridgestone	4.00	mm	Sport
REAR O/S	: 235/60 R16	Bridgestone	4.00	mm	Sport
FRONT N/S	: 235/60 R16	Bridgestone	4.00	mm	Sport
REAR N/S	: 235/60 R16	Bridgestone	4.00	mm	Sport



No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017
Registration No. 200723252D

4. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear n/s and undercarriage portion(s). For more detail of the damages, please see photograph attached.

5. Estimated normal period of repair : 13 working days to complete.
6. Enclosed number of photograph : 255 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SJL 5599 A**
 Report No: **TP/ 17034-09/MY / 2017**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear tailgate outer garnish	Damage	\$ 689.50	\$ 689.50 535.3
1	Rear taillamp	Damage	\$ 654.50	\$ 654.50 435
1	Rear end panel inner garnish	Damage	\$ 386.50	\$ 386.50 240.7
1	Rear bumper	Damage	\$ 1385.00	\$ 1385.00 1247
1	Rear bumper clip (1 set)	Necessary	\$ 35.00	\$ 35.00 /
1	Rear bumper lower bracket	Necessary	\$ 65.50	\$ 65.50 /
1	Rear bumper side	Damage	\$ 189.50	\$ 189.50 /
1	Rear bumper side retainer	Damage	\$ 48.50	\$ 48.50 27.5
1	Rear exhaust silencer muffler	Damage	\$ 943.80	\$ 943.80 /
1	Rear fender	Damage	\$ 1099.70	\$ 1099.70 /
1	Rear fender air gate	Damage	\$ 85.20	\$ 85.20 /
1	Rear fender inner shield	Damage	\$ 86.50	\$ 86.50 /
1	Rear fender inner trim	Damage	\$ 689.50	\$ 689.50 /
1	Rear fender wheel arch garnish	Damage	\$ 541.50	\$ 541.50 288.6
1	Rear quarter glass moulding	Necessary	\$ 140.00	\$ 140.00 /
1	Rear fender arch extension moulding	Necessary	\$ 165.40	\$ 165.40 /
1	Rear wheel house panel	Damage	\$ 480.00	\$ 480.00 Repair
1	Rear shock absorber	Damage	\$ 300.60	\$ 300.60 /
1	Rear shock absorber mounting	Damage	\$ 250.00	\$ 250.00 /
1	Rear shock absorber spring	Damage	\$ 368.10	\$ 368.10 /
1	Rear knuckle arm	Damage	\$ 430.60	\$ 430.60 /
1	Rear knuckle arm c/w bearing	Necessary	\$ 367.10	\$ 367.10 276.5
1	Rear trailing arm	Damage	\$ 384.10	\$ 384.10 /
1	Rear sub crossmember	Damage	\$ 540.00	\$ 540.00 /
2	Rear trailing arm brackets	Necessary	\$ 76.00	\$ 76.00 /
2	Rear stabilizer bar linkages	Damage	\$ 150.00	\$ 150.00 /
1	Rear stabilizer bar	Damage	\$ 285.00	\$ 285.00 /
1	Rear brake disc base plate	Damage	\$ 289.30	\$ 289.30 NN
1	Rear stay arm	Damage	\$ 98.00	\$ 98.00 /
1	Rear break hose	Damage	\$ 78.00	\$ 78.00 /
1	Rocker panel	Repair	\$ 580.00	\$ 580.00 /
1	Rocker panel side skier	Damage	\$ 1100.00	\$ 1100.00 Repair
1	Rear door	Damage	\$ 1450.00	\$ 1450.00 Repair
1	Rear door checker	Intact	\$ 82.50	\$ 82.50 /
1	Rear door glass outer moulding	Necessary	\$ 126.20	\$ 126.20 NN
1	Rear door hinge	Intact	\$ 85.00	\$ 85.00 /
1	Rear door inner board	Intact	\$ 650.00	\$ 650.00 /

List Items Sub Total \$ 15376.10 \$ 13978.60

Vehicle No: **SJL 5599 A**
 Report No: **TP/ 17034-09/MY / 2017**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

List Items Total c/f \$ 15376.10 \$ 13978.60

<u>List Items</u>				
1	Rear door lock	Damage	\$ 280.00	\$ X 280.00 NV
1	Rear door outer garnish	Damage	\$ 665.20	\$ 665.20 426.3
1	Rear door regulator	Intact	\$ 488.00	\$
1	Rear door rubber	Necessary	\$ 142.60	\$ 142.60 /
1	Rear door arch seal	Damage	\$ 70.00	\$ 70.00 /
1	Rear door vertical trim	Intact	\$ 128.00	\$
1	Rear safety belt	Damage	\$ 350.00	\$ X 350.00 NV
			<u>\$ 17499.90</u>	<u>\$ 15486.40</u>
Discount 20.0%			\$ 3499.98	\$ 3097.28
			<u>\$ 13999.92</u>	<u>\$ 12389.12</u>

<u>Special Nett Items</u>				
1	Rear tyre (Depreciation)	Damage	\$ 320.00	\$ 160.00 100
1	Rear sport rim	Damage	\$ 550.00	\$ 550.00 300
1	Rear door sound proof seal	Necessary	\$ 350.00	\$ X 350.00 NV
1	Quarter glass sealant	Damage	\$ 20.00	\$ X 20.00
1	Rear fender inner shield clip (1 set)	Necessary	\$ 35.00	\$ 35.00
			<u>\$ 1275.00</u>	<u>\$ 1115.00</u>

435

4593.9

20% : 7675.12

Spare Parts Total \$ 15274.92 \$ 13504.12

Vehicle No: **SJL 5599 A**
 Report No: **TP/ 17034-09/MY / 2017**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 15274.92	\$ 13504.12
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 60.00	\$ 40.00 30
2	To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	\$ 300.00	\$ 220.00 80
3	To remove and refit fuel tank system.	\$ 100.00	\$ 80.00 60
4	To remove and refit rear bumper sensor.	\$ 200.00	\$ X 120.00 N/A
5	To remove and refit rear undercarriage.	\$ 750.00	\$ 500.00 300
6	To check and re-adjust (Computerized) all wheel alignment.	\$ 140.00	\$ 120.00 60
7	To remove and refit quarter glass to facilitate the repairs.	\$ 100.00	\$ 60.00 40
8	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$ 150.00	\$ X 120.00 N/A
9	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1800.00	\$ 1500.00 1200
10	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1800.00	\$ 1625.00 1300
11	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 120.00	\$ 90.00 60
Total		\$ 20794.92	\$ 17979.12 3130

11240.12
 req. 9000

Vehicle No: **SJL 5599 A**
Report No: **TP/ 17034-09/MY / 2017**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
------	------------------	--------------------------	---------------------------

Total c/f \$ 20794.92 \$ 17979.12

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 14400.00

SDLS: FOURTEEN THOUSAND FOUR HUNDRED ONLY



Qualified Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2017		27 Sep 2017 14:15 Edit Adj Rpt	S\$9,000.00 Edit Estimates	S\$9,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN KIM CHOON, ID: S1392606I, Tel: +6597611286, Email: ALAN_FTSS@YAHOO.COM.SG		
Main Claimant:	TING AH KAU, ID: S2504844Z		
Vehicle Reg. No.:	SJL5599A	Date of Loss:	26/09/2017 09:00 - :59
Claim Type:	TP / 530874	Policy/Cover Note No.:	A2869155AVW (Comprehensive) Coverage: 22/02/2017 - 21/02/2018
Vehicle Reg. No. (Insured):	SLA1146J	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	H S Automotive Services (Kaki Bukit) BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 67472755		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/03/2018]		
Driver/Custodian (Insured):	TAN KIM CHOON (57 / Male), NRIC: S1392606I, Tel: +6597611286		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG_SG (01/03/2018): Report Send Back Alerts - SJL5599A (TP)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL5599A (530874)**

[SLA1146J]

TP

TING AH KAU

Sep 26 2017 9:00AM

[TAN KIM CHOON]

H S Automotive Services

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/09/17 14:17	Accident Statement From:OD - Reg. No: SLA1146J, Claimant: TAN KIM CHOON	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/17 16:38	General View	Load JPG	☒
2	26/10/17 16:38	General View	Load JPG	☒
3	26/10/17 16:38	General View	Load JPG	☒
4	26/10/17 16:38	General View	Load JPG	☒
5	26/10/17 16:38	General View	Load JPG	☒
6	26/10/17 16:38	General View	Load JPG	☒
7	26/10/17 16:38	General View	Load JPG	☒
8	26/10/17 16:38	General View	Load JPG	☒
9	26/10/17 16:38	General View	Load JPG	☒
10	26/10/17 16:38	General View	Load JPG	☒
11	26/10/17 16:38	General View	Load JPG	☒
12	26/10/17 16:38	General View	Load JPG	☒
13	26/10/17 16:38	General View	Load JPG	☒
14	26/10/17 16:38	General View	Load JPG	☒
15	26/10/17 16:38	General View	Load JPG	☒
16	26/10/17 16:38	General View	Load JPG	☒
17	26/10/17 16:38	General View	Load JPG	☒
18	26/10/17 16:38	General View	Load JPG	☒
19	26/10/17 16:38	General View	Load JPG	☒
20	26/10/17 16:38	General View	Load JPG	☒
21	26/10/17 16:38	General View	Load JPG	☒
22	26/10/17 16:38	General View	Load JPG	☒
23	26/10/17 16:38	General View	Load JPG	☒
24	26/10/17 16:38	General View	Load JPG	☒
25	26/10/17 16:38	General View	Load JPG	☒
26	26/10/17 16:38	General View	Load JPG	☒
27	26/10/17 16:38	General View	Load JPG	☒
28	26/10/17 16:38	General View	Load JPG	☒
29	26/10/17 16:38	General View	Load JPG	☒
30	26/10/17 16:38	General View	Load JPG	☒

31	26/10/17 16:38	General View	1	Load JPG	✓
32	26/10/17 16:38	General View	1	Load JPG	✓
33	26/10/17 16:38	General View	1	Load JPG	✓
34	26/10/17 16:38	General View	1	Load JPG	✓
35	26/10/17 16:38	General View	1	Load JPG	✓
36	26/10/17 16:38	General View	1	Load JPG	✓
37	26/10/17 16:38	General View	1	Load JPG	✓
38	26/10/17 16:38	General View	1	Load JPG	✓
39	26/10/17 16:38	General View	1	Load JPG	✓
40	26/10/17 16:38	General View	1	Load JPG	✓
41	26/10/17 16:38	General View	1	Load JPG	✓
42	26/10/17 16:38	General View	1	Load JPG	✓
43	26/10/17 16:38	General View	1	Load JPG	✓
44	26/10/17 16:38	General View	1	Load JPG	✓
45	26/10/17 16:38	General View	1	Load JPG	✓
46	26/10/17 16:38	General View	1	Load JPG	✓
47	26/10/17 16:38	General View	1	Load JPG	✓
48	26/10/17 16:38	General View	1	Load JPG	✓
49	26/10/17 16:38	General View	1	Load JPG	✓
50	26/10/17 16:38	Chassis Number	1	Load JPG	✓
51	26/10/17 16:38	Odometer Reading	1	Load JPG	✓
52	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
53	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
54	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
55	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
56	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
57	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
58	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
59	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
60	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
61	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
62	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
63	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
64	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
65	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
66	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
67	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
68	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
69	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
70	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
71	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
72	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
73	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
74	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
75	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
76	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
77	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
78	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓

79	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
80	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
81	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
82	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
83	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
84	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
85	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
86	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
87	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
88	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
89	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
90	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
91	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
92	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
93	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
94	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
95	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
96	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
97	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
98	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
99	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
100	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
101	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
102	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
103	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
104	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
105	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
106	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
107	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
108	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
109	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
110	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
111	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
112	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
113	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
114	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
115	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
116	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
117	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
118	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
119	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
120	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
121	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
122	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
123	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
124	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
125	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓
126	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	✓

127	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
128	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
129	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
130	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
131	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
132	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
133	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
134	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
135	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
136	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
137	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
138	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
139	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
140	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
141	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
142	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
143	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
144	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
145	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
146	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
147	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
148	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
149	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
150	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
151	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
152	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
153	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
154	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
155	26/10/17 16:39	Photographs of Damaged Parts	1	Load JPG	☒
156	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
157	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
158	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
159	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
160	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
161	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
162	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
163	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
164	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
165	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
166	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
167	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
168	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
169	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
170	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
171	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
172	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
173	26/10/17 16:41	Photo After Spray	1	Load JPG	☒
174	26/10/17 16:41	Photo After Spray	1	Load JPG	☒

175	26/10/17 16:41	Photo After Spray		Load JPG	☒
176	26/10/17 16:41	Photo After Spray		Load JPG	☒
Documentation					
				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/09/17 14:17	TP SJL5599A GIA REPORT From:OD - Reg. No: SLA1146J, Claimant: TAN KIM CHOON		Load PDF	
2	27/09/17 14:18	Email to TP to appoint LKK		Load PDF	
3	27/09/17 15:06	PRI		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 16:54	PRS INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17018544/GVBS2-1

Date: 01/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A2869155AVW

Claimant Vehicle No : SJL5599A

Insured Vehicle No : SLA1146J

Date of Loss: 26/09/2017

Nature of Claim: TP

Claim No: 530874

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL5599A

Make & Model: HONDA CROSSROAD, 1.8 (A)

Engine No: R18A3011092

Reg. Date: 02/12/2008 (Man. Year: 2008)

Chassis No: RT11008151

Colour: Black

Odometer: 132629 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 235/60R16

Rear Tyre Size: 235/60R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,274.92	8,110.12	7,164.80	46.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,520.00	3,130.00	2,390.00	43.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,794.92	11,240.12	9,554.80	45.95
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	20,794.92	9,000.00	11,794.92	56.72

INSPECTION

Date of Assignment: 27/09/2017

Date Inspected: 28/09/2017 Inspected At:

H S Automotive Services (Kaki Bukit)
BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2018)
Parts:	M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL5599A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE OUTER GARNISH	Damaged	689.50 FL	*535.30 FL
2	1		*REAR TAILLAMP	Damaged	654.50 FL	*435.00 FL
3	1		*REAR END PANEL INNER GARNISH	Damaged	386.50 FL	*240.70 FL
4	1		*REAR BUMPER	Damaged	1,385.00 FL	*1,247.00 FL
5	1		*SET REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
6	1		*REAR BUMPER LOWER BRACKET	Necessary	65.50 FL	*65.50 FL
7	1		*REAR BUMPER SIDE	Damaged	189.50 FL	*189.50 FL
8	1		*REAR BUMPER SIDE RETAINER	Damaged	48.50 FL	*27.50 FL
9	1		*REAR EXHAUST SILENCER MUFFLER	Damaged	943.80 FL	*943.80 FL
10	1		*REAR FENDER	Damaged	1,099.70 FL	*1,099.70 FL
11	1		*REAR FENDER AIR GATE	Damaged	85.20 FL	*85.20 FL
12	1		*REAR FENDER INNER SHIELD	Damaged	86.50 FL	*86.50 FL
13	1		*REAR FENDER INNER TRIM	Damaged	689.50 FL	*689.50 FL
14	1		*REAR FENDER WHEEL ARCH GARNISH	Damaged	541.50 FL	*288.60 FL
15	1		*REAR QUARTER GLASS MOULDING	Necessary	140.00 FL	*140.00 FL
16	1		*REAR FENDER ARCH EXTENSION MOULDING	Necessary	165.40 FL	*165.40 FL
17	1		*REAR WHEEL HOUSE PANEL	Repair	480.00 FL	*- FL
18	1		*REAR SHOCK ABSORBER }	Damaged	300.60 FL	*362.60 FL
19	1		*REAR SHOCK ABSORBER MOUNTING }		250.00 FL	*- FL
20	1		*REAR SHOCK ABSORBER SPRING }		368.10 FL	*- FL
21	1		*REAR KNUCKLE ARM	Damaged	430.60 FL	*430.60 FL
22	1		*REAR KNUCKLE ARM C/W BEARING	Necessary	367.10 FL	*276.50 FL
23	1		*REAR TRAILING ARM	Damaged	384.10 FL	*384.10 FL
24	1		*REAR SUB CROSSMEMBER	Damaged	540.00 FL	*540.00 FL
25	2		*REAR TRAILING ARM BRACKETS	Necessary	76.00 FL	*76.00 FL
26	2		*REAR STABILIZER BAR LINKAGES	Damaged	150.00 FL	*150.00 FL
27	1		*REAR STABILIZER BAR	Damaged	285.00 FL	*285.00 FL
28	1		*REAR BRAKE DISC BASE PLATE	Not Necessary	289.30 FL	*- FL
29	1		*REAR STAY ARM	Damaged	98.00 FL	*98.00 FL
30	1		*REAR BRAKE HOSE	Damaged	78.00 FL	*78.00 FL
31	1		*ROCKER PANEL	Repair	580.00 FL	*- FL
32	1		*ROCKER PANEL SIDE SKIER	Repair	1,100.00 FL	*- FL
33	1		*REAR DOOR	Repair	1,450.00 FL	*- FL
34	1		*REAR DOOR CHECKER	Intact	82.50 FL	*- FL
35	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	126.20 FL	*- FL
36	1		*REAR DOOR HINGE	Intact	85.00 FL	*- FL
37	1		*REAR DOOR INNER BOARD	Intact	650.00 FL	*- FL
38	1		*REAR DOOR LOCK	Not Necessary	280.00 FL	*- FL
39	1		*REAR DOOR OUTER GARNISH	Damaged	665.20 FL	*426.30 FL
40	1		*REAR DOOR REGULATOR	Intact	488.00 FL	*- FL
41	1		*REAR DOOR RUBBER	Necessary	142.60 FL	*142.60 FL
42	1		*REAR DOOR ARCH SEAL	Damaged	70.00 FL	*70.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR DOOR VERTICAL TRIM	Intact	128.00 FL	*- FL
44	1		*REAR SAFETY BELT	Not Necessary	350.00 FL	*- FL
45	1		*REAR TYRE	Damaged	320.00 FS	*100.00 FS
46	1		*REAR SPORT RIM	Damaged	550.00 FS	*300.00 FS
47	1		*REAR DOOR SOUND PROOF SEAL	Not Necessary	350.00 FS	*- FS
48	1		*QUARTER GLASS SEALANT	Not Necessary	20.00 FS	*- FS
49	1		*SET REAR FENDER INNER SHIELD CLIP	Necessary	35.00 FS	*35.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$)	18,774.90	10,028.90
- List Item Discount on L Items 20.00/20.00% (\$)	3,499.98	1,918.78
Total Parts (\$)	15,274.92	8,110.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.	New	60.00	30.00
2	TO REMOVE AND REFIT REAR CUSHION SEATS, RADIO SPEAKER BOARD, INTERIOR UPHOLSTERY TO FACILITATE THE REPAIRS.	New	300.00	80.00
3	TO REMOVE AND REFIT FUEL TANK SYSTEM.	New	100.00	60.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR.	New	200.00	0.00
5	TO REMOVE AND REFIT REAR UNDERCARRIAGE.	New	750.00	300.00
6	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.	New	140.00	60.00
7	TO REMOVE AND REFIT QUARTER GLASS TO FACILITATE THE REPAIRS.	New	100.00	40.00
8	TO REMOVE AND REFIT THE DOOR LOCK MECHANISM, REGULATOR GEAR, WINDOW GLASS, HANDLE, INNER BOARD, HINGES, CHANNEL TO FACILITATE THE REPAIRS.	New	150.00	0.00
9	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS, TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,800.00	1,200.00
10	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	1,800.00	1,300.00
11	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	120.00	60.00
Gross Labour Cost (\$\$)			5,520.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >