

11/03/2017

ASS. REC. BY:

REF:

CS3/MSH/7021010/Srb-1

Special Instruction:

Fudge

SURVEYOR

Srb-1

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSH

Date/Time:

09.03.2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 1984Y

Insured:

SKK 3393H

at Workshop m/s

D Motor Werkz

Tel:

6734 7260

of

28 0 Woodlands Ind 25 # 01-03

Policy No:

60270344DMA

Claim No:

535220

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

03.11.2017

H.O.D. Endorsement:

Date/Time:

02.11.2017 5:47pm

Person Contacted:

Fion

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	27.10.2017 X
	28.10.2017 X
	Dismantle Part 06.11.2017
	After repair. 10.11.2017

25.11.17 5:00pm Email to Katherine Wong thm mofman.

1400 ✓ 13/4

1400

1400

Let me know

10/4.

Submit LIs \$1400, 3 days
Red: \$500, 26%

RECEIVED 16 APR 2018

MSIG

MSIG

Date

3/11/2017

SJL 1984Y

2008 Nov 18

Endorsement

Truck/Tractor

OD (TP) WS/TF RES/OD RES EXA IN/ MV

Truck/Tractor

To inspect vehicle No

SJL 1984Y

Make

Swan SWH 13M

1328

Insured Name

D Motor Werkz

Color

Black

Insured State N/A

280, Woodlands Ind ES #01-03, 757322

St Features

9416

Tractor Insured State N/A

Insured

Eng No

Ch No

2 CUS 400161

Policy No

Damage

Gen Cond Good/Fair/Poor/Burnt

Sum Insured

Excess

Steering Inop/Jammed/Leaked/Burnt


Claims Record

Brake Inop/Jammed/Leaked/Burnt

Make of Veh

Mod S Rim / STD A/Rim

Policy Condition



Remark The veh had commenced its repair at the time of inspection

Tyre Size

R 195/55R15

R

BS/DUN/EXNOVA/GY FS/LZA/MID/HTBU/PIR/SUM

TOYO/YOKO or

Good/Yea

Ball or Marker Value

EAC Accident Report

Consistent Yes or No

Front

Rear

R Ba

P Ba

3/4 - EP Seal

Consistent Yes or No

U Ba

L Ba

Est Repairs

days

Yes

Yes or No

C/D/A

C/D

Lim EUT

Yes

Yes

Yes or No

Survey held at

D Motor Werkz

3/11/17 @ 12.01pm

CA - REV / REP. / 24 HRS

wp

Des of Damages

Fat

Fat

DIS

N/S

U/C

Roofed or

Date

Person Contacted

Vehicle IN/OUT

The U/C : Chassis frame Body Structure affected due to collision

Date Time

Action Instruction

3/11/2017

No GH

RECEIVED

Ins Time File Passed



Preli Report

Final Report

Days Of Repair

Resurvey No. of Trip

05-01-2018

Out Time File Passed

Add Fee



Site Insd \$



Man Insd \$



Tr Insd \$




Tr Insd \$

Person Reported

PRC

Joint Sign off






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17021010/Srb-1		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-02-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 3393H	Veh. Inspected	SJL 1984Y	
Policy No.	60270334DMA	Coverage (\$)	0.00	
Claim No.	535220	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/10/2017	Inspection Date	14/02/2018	
Survey held at	D MOTORWERKZ PTE LTD 280 WOODLANDS INDUSTRIAL PARK E5 #01-03 SINGAPORE 757322			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		02 Nov 2017 15:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BOK SHI CHIEH, ID: S8110285F								
Main Claimant:	EDDY BIN HENDRA, ID: S8542300B								
Vehicle Reg. No.:	SJL1984Y	Date of Loss:	31/10/2017 22:00 - :59						
Claim Type:	TP / 535220	Policy/Cover Note No.:	60270344DMA (Comprehensive) Coverage: 27/03/2017 - 26/03/2018						
Vehicle Reg. No. (Insured):	SKK3393H	Policy No. (Claimant):							
		Excess:							
Repairer:	D Motorwerkz Pte Ltd (HQ) NO. 280 Woodlands Industrial ES, #01-03 Harvest @ Woodlands, 757322 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 13/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (09/02/2018): Report Send Back Alerts - SJL1984Y (TP) 									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2300B

Vehicle Details

Vehicle No.:	SJL1984Y
Vehicle to be Exported:	No
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.3 M
Primary Colour:	Pink
Secondary Colour:	Black
Manufacturing Year:	2008
Engine No.:	M13A1937596
Chassis No.:	ZC11S400161
Maximum Power Output:	67.0 kW (89 bhp)
Open Market Value:	\$10,193.00
Original Registration Date:	18 Nov 2008
First Registration Date:	18 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$4,182.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2018
PARF Rebate Amount:	\$2,091.00

Intended COE Rebate Details

COE Expiry Date:	17 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$2,091.00

The information contained herein is correct as at 26 Feb 2018

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 20100026810

Report Reference : TP / 11-17002/AY / 2017
Date of Report : 13 Nov 2017

Eddy Bin Hendra
c/o 280 Woodlands Industrial Park E5
#01-03 Harvest@Woodlands
Singapore 757322

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 31 Oct 2017

As per your instruction dated 2 Nov 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SJL 1984 Y. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SJL 1984 Y
Model : Suzuki Swift
Year / Capacity : 2008/1328
Chassis No : ZC11S-400161
Engine No : M13A1937596
Mileage : 94216
Colour : Pink

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 195/55 R15	Good Year	6.00	mm	Sport
REAR	O/S	: 195/55 R15	Good Year	6.00	mm	Sport
FRONT	N/S	: 195/55 R15	Good Year	6.00	mm	Sport
REAR	N/S	: 195/55 R15	Good Year	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 2010002681D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : D Motorwerkz
280 Woodlands Industrial Park E5
#01-03 Harvest@Woodlands
Singapore 757322

5. Estimated normal period of repair : 4 working days to complete.
6. Enclosed number of photograph : 83 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJL 1984 Y
 Report No: TP/ 11-17002/AY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
2	Rear taillamps	Damage	\$ 475.00	\$ 475.00
1	Rear end panel	Repair	\$ 237.65	\$
1	Rear end panel inner garnish	Intact	\$ 68.55	\$
1	Rear bumper	Damage	\$ 518.75	\$ 518.75
2	Rear bumper brackets	Damage	\$ 56.90	\$ 56.90
2	Rear bumper side retainers	Necessary	\$ 41.50	\$ 41.50
2	Rear number plate lamps	Damage	\$ 36.80	\$ 36.80
			<u>\$ 1435.15</u>	<u>\$ 1128.95</u>
Discount		15.0%	\$ 215.27	\$ 169.34
			<u>\$ 1219.88</u>	<u>\$ 959.61</u>
<u>Special Nett Items</u>				
1	Rear bumper clip (1 set)	Necessary	\$ 20.00	\$ 20.00
1	Rear weekend plate	Necessary	\$ 50.00	\$ 45.00
1	Rear weekend plate seal	Necessary	\$ 50.00	\$ 45.00
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00
			<u>\$ 400.00</u>	<u>\$ 390.00</u>

Spare Parts Total \$ 1619.88 \$ 1349.61

Vehicle No: SJL 1984 Y
Report No: TP/ 11-17002/AY / 2017

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 1619.88	\$ 1349.61
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 30
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 100.00	\$ 80.00 60
3	To remove and refit rear bumper sensor.	\$ 120.00	\$ 80.00 60.
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 700.00	\$ 440.00 350.
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 700.00	\$ 440.00 350
Total		\$ 3289.88	\$ 2429.61

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:


\$ 1900.00

250
125
375

SDLS: ONE THOUSAND NINE HUNDRED ONLY


Qualified Appraiser

US 20%
let me know
10/4/18.


3 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Nov 2017		02 Nov 2017 15:50 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BOK SHI CHIEH , ID: S8110285F								
Main Claimant:	EDDY BIN HENDRA , ID: S8542300B								
Vehicle Reg. No.:	SJL1984Y	Date of Loss:	31/10/2017 22:00 - :59 [107 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 535220	Policy/Cover Note No.:	60270344DMA (Comprehensive) Coverage: 27/03/2017 - 26/03/2018						
Vehicle Reg. No. (Insured):	SKK3393H	Policy No. (Claimant):							
		Excess:							
Repairer:	D Motorwerkz Pte Ltd (HQ) NO. 280 Woodlands Industrial E5, #01-03 Harvest @ Woodlands, 757322 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 13/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (12/03/2018): Paper survey report MSIG_SG (09/02/2018): Report Send Back Alerts - SJL1984Y (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL1984Y (535220)**

[SKK3393H]



































TP



















































EDDY BIN HENDRA

















Oct 31 2017 10:00PM

[BOK SHI CHIEH]

D Motorwerkz Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print
1	07/11/17 10:13	Accident Statement From: SC - Reg. No: SKK3393H, Claimant: BOK SHI CHIEH							Load HTM	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
2	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
3	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
4	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
5	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
6	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
7	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
8	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
9	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
10	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
11	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
12	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
13	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
14	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
15	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
16	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
17	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
18	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
19	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
20	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
21	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
22	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
23	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
24	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
25	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
26	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
27	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
28	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
29	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
30	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
31	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
32	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>
33	05/01/18 15:00	General View							Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	05/01/18 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/01/18 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/01/18 15:00	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
37	05/01/18 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/01/18 15:00	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
39	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	05/01/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	05/01/18 15:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
85	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
86	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
87	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
88	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
89	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
90	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
91	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
92	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
93	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
94	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
95	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
96	05/01/18 15:01	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/11/17 10:13	SJL1984Y E FILE REPORT From: SC - Reg. No: SKK3393H, Claimant: BOK SHI CHIEH		<input type="checkbox"/>
2	08/02/18 17:12	surveyor report		<input type="checkbox"/>
3	08/02/18 17:12	surveyor photos		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021010/SRBE2-1

Date: 18/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 60270344DMA

Claimant Vehicle No : SJL1984Y

Insured Vehicle No : SKK3393H

Date of Loss: 31/10/2017

Nature of Claim: TP

Claim No: 535220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL1984Y

Make & Model: SUZUKI SWIFT, 1.3 (M)

Engine No: M13A1937596

Reg. Date: 18/11/2008 (Man. Year: 2008)

Chassis No: ZC11S400161

Colour: Pink

Odometer: 94216 km

Engine Capacity: 1328 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15

Rear Tyre Size: 195/55R15

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,619.88	945.86	674.02	41.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	850.00	820.00	49.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,289.88	1,795.86	1,494.02	45.41
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	3,289.88	1,400.00	1,889.88	57.45

INSPECTION

Date of Assignment: 02/11/2017

Date Inspected: 03/11/2017 Inspected At:

D Motorwerkz Pte Ltd (HQ)
NO. 280 Woodlands Industrial E5, #01-03
Harvest @ Woodlands
Singapore 757322

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Apr 2018)
Parts: 144 SUZUKI SWIFT 1.3 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJL1984Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAILLAMPS	Serviceable	475.00 FL	*- FL
2	1		*REAR END PANEL	Repair	237.65 FL	*- FL
3	1		*REAR END PANEL INNER GARNISH	Intact	68.55 FL	*- FL
4	1		*REAR BUMPER	Damaged	518.75 FL	*518.75 FL
5	2		*REAR BUMPER BRACKETS	Damaged	56.90 FL	*56.90 FL
6	2		*REAR BUMPER SIDE RETAINERS	Necessary	41.50 FL	*41.50 FL
7	2		*REAR NUMBER PLATE LAMPS	Damaged	36.80 FL	*36.80 FL
8	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
9	1		*REAR WEEKEND PLATE	Necessary	50.00 FS	*45.00 FS
10	1		*REAR WEEKEND PLATE SEAL	Necessary	50.00 FS	*45.00 FS
11	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*280.00 FS
Sub Total (\$\$)					1,835.15	1,043.95
- List Item Discount on L Items 15.00/15.00% (\$\$)					215.27	98.09
Total Parts (\$\$)					1,619.88	945.86

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING,REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	50.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS,INNER GARNISHES,TO FACILITATE THE REPAIRS	New	100.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	120.00	60.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	700.00	350.00
5	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	700.00	350.00
Gross Labour Cost (\$\$)			1,670.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >