

Handbrake (Serviceable)

Engine Modification

Pre-accident condition

Excellent



Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

Driver License #

License Type

License Issue Date

License Expiration Date

Address

Singapore

Address type

Personal Correspondence

CANTER FEB21ER4SDEB (CBU)

Type

Listed on policy ▼

Type of Paint

Chassis No

FEB21EA21364

Engine No

4P10C48561

Engine Capacity

Sum Insured

0

3/12/2018

Claim Portal

Menu

Model

Service Address

...

Primary Contact/Insured

SOURCE WATERPROOFING PTE LTD

8 KAKI BUKIT AVENUE 4, #01-46 PREMIER @ KAKI BUKIT, 415875, Singapore

90088870

source46@singnet.com.sg

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

	▼
--	---

Upload Documents

LKK RESURVEY PHOTO.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

March 7, 2018

LKK SURVEY PHOTO.pdf

Model

Service Address

...

Primary Contact/Insured

SOURCE WATERPROOFING PTE LTD
8 KAKI BUKIT AVENUE 4, #01-46 PREMIER @ KAKI BUKIT, 415875, Singapore
90088870
source46@singnet.com.sg

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Add

NIKAM Santosh Pandurang

2/14/18 2:32 PM

\$0.00

\$0.00

Open

Share

Clone