

Handbrake (Serviceable)

Engine Modification

Pre-accident condition

Excellent ▼

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

Driver License #

License Type

License Issue Date

License Expiration Date

Address

Singapore

Address type

Personal Correspondence

Type

Listed on policy ▼

Type of Paint

Chassis No

Engine No

Engine Capacity

Sum Insured

Model
LATIO 1.5 L

Service Address

...

Primary Contact/Insured

ENG TECK SENG
BLK 309 SHUNFU ROAD, #03-191, 570309, Singapore
91450810

Claim Handler

TAN Jun Hong

junhong.tan@axa.com.sg
Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Add

DHIWAR Namrata

2/14/18 11:50 AM

\$0.00

\$0.00

Open

Share

Clone

February 14, 2018

SLU5070L INSD GIA.PDF

Reports & Statement

GIA Report

NIKAM Santosh Pandurang

February 14, 2018

Model

LATIO 1.5 L

Service Address

...

Primary Contact/Insured

ENG TECK SENG

BLK 309 SHUNFU ROAD, #03-191, 570309, Singapore
91450810

Claim Handler

TAN Jun Hong

junhong.tan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

--	--

Upload Documents

LKK RESURVEY PHOTO.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

March 7, 2018

LKK SURVEY PHOTO.pdf