



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

General Details

Involving

1 2013 MERCEDES CLA200 (SLN6302Z)

Date of Loss

14 February 2018

Time of Loss

7.40

Loss Description

SLN6302Z (INSD) HIT THE REAR OF GBD6968Z (TP)

Comment

Workshop Details

Total Rebate Amount

62440

Nett Loss Amount

\$47,560.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

22/08/2018



Days of work completion *

189



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SLN6302Z

Registration State

SINGAPORE

Mileage

80930

CATEGORY

Manufacturing Year

POLICY INFORMAT...

2013

ASSESSMENT INFO...

2013

Purchase Date

dd/mm/yyyy



Registration Date *

09/01/2014



Age of Vehicle

4

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LIM GUEK NGOH

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MERCEDES

ASSESSMENT INFO... MERCEDES BENZ

CATEGORY Model

POLICY INFORMAT... CLA200

ASSESSMENT INFO... CLA200 (R18)

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WDD1173432N056175

CATEGORY Date of Birth

FNOL INFORMATI... 21 January 1960

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 58

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 27091030306650

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 30

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 721 YISHUN STREET 71, #05-216,
760721, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1434435G

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

19/02/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

600

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/40R18

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

225/40R18

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
<input type="checkbox"/>	<input type="checkbox"/>	1			FRONT NUMBER PLATE WITH HOUSING			Bent	60				60	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	2			LEFT FRONT FENDER			Bent	646.47				646.47	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	3			RIGHT FRONT FENDER			Bent	646.47				646.47	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	4			FRONT BUMPER			Deformed	1327.24				1327.24	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	5			RADAR SENSOR			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="checkbox"/>	6			RADAR SENSOR FIXTURE			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="checkbox"/>	7			LICENSE PLATE MOLDING			Deformed	89.83				89.83	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	8			IMPACT ABSORBER			Cracked	112.37				112.37	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	9			CTR BASIC MOUNTING FOR BUMPER			Damaged	137.64				137.64	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	10			BUMPER COMPANY SIGN			Cracked	59.73				59.73	Reviewin
<input type="checkbox"/>	<input type="checkbox"/>	11			FRONT BONNET			Bent	1448.71				1448.71	Reviewin

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
<input type="checkbox"/>		12	1			ENGINE HOOD SEAL			Necessary	32.46				32.46	Reviewin
<input type="checkbox"/>		13	1			BONNET LOCK LOWER PART			Bent	117.17				117.17	Reviewin
<input type="checkbox"/>		14	1			BONNET LOCK LIMIT SWITCH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		15	1			BONNET LOCK UPPER PART			Bent	44.92				44.92	Reviewin
<input type="checkbox"/>		16	1			LEFT BONNET ACTUATOR			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		17	1			RIIGHT BONNET ACTUATOR			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		18	1			LEFT BONNET HINGE			Bent	86.81				86.81	Reviewin
<input type="checkbox"/>		19	1			RIGHT BONNET HINGE			Bent	86.81				86.81	Reviewin
<input type="checkbox"/>		20	1			INSULATOR ENGINE HOOD			Deformed	70.47				70.47	Reviewin
<input type="checkbox"/>		21	1			RAD GRILLE			Cracked	648.38				648.38	Reviewin
<input type="checkbox"/>		22	1			RAD GRILLE 2-SPOKE BEAM			Damaged	133.95				133.95	Reviewin
<input type="checkbox"/>		23	1			RAD GRILLE LEFT CHROME TRIM			Cracked	72.6				72.6	Reviewin
<input type="checkbox"/>		24	1			RAD GRILLE RIGHT CHROME TRIM			Necessary	72.6				72.6	Reviewin
<input type="checkbox"/>		25	1			RAD GRILLE STAR HOLDER			Missing	72.06				72.06	Reviewin

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		26	1			RAD GRILLE MERCEDES STAR			Missing	130.65				130.65	Reviewin
		27	1			LEFT AIR FLOW SERRATION			Deformed	54.45				54.45	Reviewin
		28	1			RIGHT AIR FLOW SERRATION			Deformed	54.45				54.45	Reviewin
		29	1			CROSS MEMBER			Serviceable	0	0	0	0	0	Deny
		30	1			CTR TOP CONSOLE BEAM			Cracked	622.03				622.03	Reviewin
		31	1			LEFT HEADLAMP			Cracked	2457.56				2457.56	Reviewin
		32	1			RIGHT HEADLAMP			Cracked	2457.56				2457.56	Reviewin
		33	1			LEFT WATER DEFLECTOR			Cut	331.64				331.64	Reviewin
		34	1			RIGHT WATER DEFLECTOR			Cut	331.64				331.64	Reviewin
		35	1			REFRIGERANT CONDENSER			Dented	1100.15				1100.15	Reviewin
		36	1			RADIATOR			Serviceable	0	0	0	0	0	Deny
		37	1			RIGHT RADIATOR AIR DUCT			Deformed	49.75				49.75	Reviewin
		38	1			LEFT RADIATOR AIR DUCT			Deformed	49.75				49.75	Reviewin

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REM
<input type="checkbox"/> 	1		USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	380	0	0	Reviewing		
<input type="checkbox"/> 	2		RESPRAY FRONT BUMPER, FRONT BONNET, LH/ FRONT FENDER, RH / FRONT FENDER	2400	0	0	Reviewing		
<input type="checkbox"/> 	3		DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	3840	0	0	Reviewing		
<input type="checkbox"/> 	4		TO REMOVE, REPLACE HEADLAMP WITH FOCUS	120	0	0	Reviewing		
<input type="checkbox"/> 	5		REMOVE, REPLACE RADIATOR, CONDENSER SYSTEM & FITTINGS-VACUUM AND REGAS	500	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		1	DAYS OF REPAIR : 8 DAYS	Reviewing			
<input type="checkbox"/>		2	ORNAMENTAL MOLDING CLIP	Reviewing	5.88	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		3	ORNAMENT MOLDING CLIP	Reviewing	5.88	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		4	SUPPORT	Reviewing	14.24	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		5	SUPPORT	Reviewing	14.24	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		6	COVER CROSS MEMBER	Reviewing	66.98	BENT (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		7	COVER CROSS MEMBER	Reviewing	66.98	BENT (SUPPLEMENTARY)	
<input type="checkbox"/>		8	ANTIFREEZE	Reviewing	42.22	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		9	[ALT] CONTROL UNIT	Reviewing	4007.77	BENT (SUPPLEMENTARY)	
<input type="checkbox"/>		10	PENDULAR SUPPORT	Reviewing	256.02	BENT (SUPPLEMENTARY)	
<input type="checkbox"/>		11	FILLING PIPE	Reviewing	56.26	BENT (SUPPLEMENTARY)	
<input type="checkbox"/>		12	AIR INTAKE HOSE	Reviewing	99.5	BENT (SUPPLEMENTARY)	
<input type="checkbox"/>		13	CLAMPING BRACKET	Reviewing	0.73	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		14	ORNAMENTAL MOLDING CLIP	Reviewing	5.88	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		15	CLIP	Reviewing	5.91	NECESSARY (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		16	GUIDE SIGN (2PCS)	Reviewing	11.76	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		17	CLIP	Reviewing	5.91	NECESSARY (SUPPLEMENTARY)	

