

3

DAYS OF REPAIR

Reviewing

7



Reviewing



8

REMOVE & INSTALL (REAR) WINDSCREEN

300

0

0

Reviewing



9

TO REMOVE & REFIX FUEL TANK

200

0

-

Reviewing



4

DISMANTLE & REFIX UNDERCARRIAGE (REAR)
TO FACILITATE REPAIR

300

0

0

Reviewing



5

REMOVE AND REFIX EXHAUST

150

-

22

1

LETTER MK SUBARU

Necessary

43.2

20

34.56

Reviewing



Labour



1

CONDUCT BODYWORK REPAIR (NPA)

0

LH TAIL LAMP

Serviceable

0

20

0

Reviewing



20

1

LABEL TAILGATE

Necessary

Serviceable

0

20

0

Reviewing



17

1

REFLEX AY LH

Serviceable

0

20

necessary

3.6

20

5.76

Reviewing



14

1

MOULDING REAR WINDSCREEN

Necessary

14.4

20

11.52

20

858.24

Reviewing



11

1

TAILGATE GLASS

Necessary

799.2

20

639.36

Reviewing



Reviewing



8

1

REAR BUMPER BEAM

Bent

208.8

20

167.04

Reviewing



MAX



5

1

FLOOR PAN RR 4D

Bent

370.8

20

296.64

Reviewing



6

1

-

2

1

REAR TAIL PIPE CUTTER

Damaged

72

20

57.6

Reviewing



3

1

REAR QTR PNL RH

Handbrake (Serviceable)

Engine Modification

Pre-accident condition

Excellent ▼

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

0

Driver License #

License Type

License Issue Date

License Expiration Date

Address

TBC, Singapore

Address type

Personal Correspondence

ATTACHMENT 1.2

Type

Listed on policy ▼

Type of Paint

Chassis No

MMBSTA13AHH003607

Engine No

3A92UDN9589

Engine Capacity

Sum Insured

0