



SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5576K
Ref. No : BUS/12/17/5022
Reg. Date : 30/09/2016
Vehicle Type : DOUBLE DECK
Make : VOLVO
Model : Volvo B9TL DD
Name of Driver : A Latif Bin Rahmat
Type of Accident : SIDE SWIPE
Date / Time of Accident : 18/12/2017 09:50:00 PM
Accident Reported Date / Time : 19/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : AIG
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093785
Special Instruction to ARC,if any :



FRONT LEFT PORTION
slk3591r (TP) - insured with AIG

Prepared Date : 22/12/2017 11:46:18 AM

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : YV3S4P924GA179515

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,120.00	1,325.00
Total Spray Painting Charges	: 600.00	528.00
Total Material Charges	: 1,401.41	1,401.41
Other Charges	: 0.00	0.00
TOTAL	: 4,121.41	3,254.41
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00	3.00
Prepared / Adjusted By	:	Sebastian - LKK
Arc / Surveyor Sign Off Date	: 27/12/2017 09:15:35 AM	29/12/2017 11:13:38 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/12/2017 09:15:29 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section U - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	2,120.00	1,325.00 /
Total Labour	2,120.00	1,325.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	600.00	528.00 /
Total Spray Painting & Panel Beating	600.00	528.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
ATP-02981			LOWER FRONT DOME CL2	1	8,325.88	100.00	0.00	Repair	Repair <i>R</i>	No
ATP-03155			N/S CORNER BUMPER CL2	1	947.85	10.00	853.06	Replace	Replace <i>/</i>	No <i>CRK</i>
ATP-02807			N/S CORNER DEFLECTOR CL2	1	319.25	10.00	287.32	Replace	Replace <i>/</i>	No <i>CRK</i>
ATP-02812			FRT N/S LIGHT BEZEL CL2	1	290.03	10.00	261.03	Replace	Replace <i>/</i>	No <i>CRK</i>
TOTAL MATERIALS							1,401.42	1,401.41		
TOTAL MATERIALS(Discounted)							1,401.41	1,401.41		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 1401.41 \\
 1325.00 \\
 + \quad 528.00 \\
 \hline
 3254.41
 \end{array}$$

Sebastian
14/2/18