

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC18003186/R1qd3n2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	22-03-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJM 629A	Veh. Inspected SHC 8242E			
	Policy No.	5096669096	Coverage (\$)		0.00	
	Claim No.	MT/0982899-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	19/02/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40 1.7	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2015	
	Chassis No.	KMHLB41UMFU067893	Colou	r	BLUE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	HANKC	OOK	5 mm	
	L/H Front Tyre	205/60 R16	HANKC		5 mm	
	R/H Rear Tyre	205/60 R16	HANKC		5 mm	
	L/H Rear Tyre	205/60 R16	HANKC		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/02/2018	<u> </u>	tion Date	19/02/2018	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					