

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC18003192/R1td3n2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	09-03-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLU 1543R	Veh. Ir	nspected	SHB 2020Z	
	Policy No.	5096186770	Cover	age (\$)	0.00	
	Claim No.	MT/0984190-001	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	19/02/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40 1.7L	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2014	
	Chassis No.	KMHLB41UMEU058015	Colou	r	YELLOW	
	Odometer	578647	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/65 R16	WEST	LAKE	5 mm	
	L/H Front Tyre	205/65 R16	WEST	LAKE	5 mm	
	R/H Rear Tyre	205/65 R16	WEST		5 mm	
	L/H Rear Tyre	205/65 R16	WEST	LAKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	15/02/2018	Inspec	tion Date	19/02/2018	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					