

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALY AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	35	1			REAR WINDSCREEN MOULDING (DISC 25%)			Necessary	99.08		0		99.08	Reviewing	
Labour															
EDIT	SR NO				PART NAME		REPAIR/REPLACE (LABOUR)	LABOUR R&R	LABOUR REPAIR	PAINT		ACTION (LABOUR)	COMMENT		REMOVE
		1			TO REMOVE & REFIT CUSHION.		60	0	0	0		Reviewing			
		2			TO REMOVE & REFIT REAR & CENTRE EXHAUST.		160	0	0	0		Reviewing			
		3			TO REMOVE & REFIT REVERSE SENSOR.		60	0	0	0		Reviewing			
		4			TO REMOVE & REFIT PETROL TANK.		80	0	0	0		Reviewing			
		5			TO REMOVE & REFIT REAR WINDSCREEN.		100	0	0	0		Reviewing			
		6			TO CHECK WIRING.		30	0	0	0		Reviewing			
		7			TOWING FEE.		0	0	0	0		Reviewing			
		8			TUFF KOTE.		50	0	0	0		Reviewing			
		9			PANEL BEATING.		1500	0	0	0		Reviewing			
		10			SPRAY PAINTING.		1400	0	0	0		Reviewing			

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNTY	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	10	1			REAR BOOT LID CENTRE MOULDING (DISC 25%)			Cracked	129.64		0		129.64	Reviewing	
	11	4			REAR BOOT LID CENTRE MOULDING CLIP (DISC 25%)			Necessary	1.87		0		7.48	Reviewing	
	12	2			REAR TAIL LAMP (DISC 25%)			Cracked	211.09		0		422.18	Reviewing	
	13	4			REAR TAIL LAMP CLIP (DISC 25%)			Necessary	6		0		24	Reviewing	
	14	1			REAR TAIL LAMP PANEL (O/S) (DISC 25%)			Dented	142.43		0		142.43	Reviewing	
	15	1			REAR BUMPER (DISC 25%)			Missing	293.55		0		293.55	Reviewing	
	16	10			REAR BUMPER CLIP (DISC 25%)			Necessary	2.25		0		22.5	Reviewing	
	17	2			REAR BUMPER SIDE RETAINER OUTER (DISC 25%)			Necessary	45.75		0		91.5	Reviewing	
	18	2			REAR BUMPER SIDE RETAINER INNER			Serviceable	0		0		0	Reviewing	
	19	2			REAR BUMPER SIDE REFLECTOR (DISC 25%)			Missing	136.69		0		273.38	Reviewing	
	20	2			REAR BUMPER BRACKET (DISC 25%)			Bent	41.85		0		83.7	Reviewing	
	21	2			REAR BUMPER MUD SHIELD			Serviceable	0		0		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Sum Insured	0	0
Market Value	0	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Type		▼
License Issue Date		mm/dd/yyyy
License Expiration Date		mm/dd/yyyy
Address	BLK 15 PUNGOL, FIELD WALK #13-01, 828746, Singapore	
Address type	Personal Correspondence	▼
Gender	Male	▼
Marital status	Unknown	▼
Identification #	50863741E	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
NIKAM Santosh Pandurang	2/20/18 4:20 PM	9135.61	9135.61	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice (with mandate) dated 06.09.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 3, 2018
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 20, 2018
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 20, 2018
TP Estimate Marked.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	September 6, 2018
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 8, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 8, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 8, 2018
SGZ5290B TP GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	February 20, 2018
GBD4056T INSD GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	February 20, 2018
TP - SURVEY REQUEST.msg	Letters and Correspondence	Third Party	NIKAM Santosh Pandurang	February 20, 2018