

INS. CASE OWNER:

CC 6/ATG1800

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

20/1/18

Date / Time:

20/1/18

Registered in Merimen:

21/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 466H

Name of Insured:

SPR REARVIEW PILL

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

12/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: PATRICK UM 500 KHAM

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SNM160008Y6C02

Policy No.:

DMHLSN174341300

Make / Model:

TOWOIA

Place of Accident:

AUE AFTER ALEXANDER RD

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:premium
LMTINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

1/3/18
VIC

YN 1170M - P

SLR 466H - P

policy cancelled

24/1/18 (pk
3:00 pm)

spoke to OI D (M. Lin) at 9139 1843. He confirmed the accident statement. Informed him about the TP claim. OI D agreed to aware the HCD issue. will send letter to OI for reference.

24/01/18

BANK LIABILITY CHECK.

FINALISED.

ORIGINAL - TP LOD

04/12/18

SEND PA TO OI.

TYPE REPORT FOR WANDATE APPROVAL

REPORT DONE

31/01/19

OBER WANDATE APPROVAL TO OI

19/02/19

OI APPROVED WANDATE.

27/02/19

OBER 1ST OFFER TO TP.

11/03/19

ORIG. DV IN. TP ACCEPTED OFFER.

ALL DOCS IN ORDER. TO CLOSE.

PRELIMINARY ADVICE

Date/Time: 04/12/18

Sent By: JK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

LTS

\$S 15,500.00

(14 days)

Reduction:

68

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

\$S 15,500.00

Loss of Rental (LOR):

\$S

(days)

Loss of Use (LOU):

\$S 3,000.00

150 x 20 days

Loss of Income (LOI):

\$S

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$S

7.45

Medical:

\$S

Disbursement:

TOWING

\$S

90.00

(e.g. Tow/ Independent)

Legal Cost

\$S

Total:

\$S 18,597.45

Global Sum \$S:

18,550.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

18,550.00

Name 1:

PREMIUM CARE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 400.00

COPY SENT
14/1/18

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YN9170M Yr Regn: 2015 / SeptType: M.Car / M.Cycle / Bus / Van / (Lorry) / Taxi / Prime Mover /

Truck / Trailer or

Make: Hino XZU60SR cc 4009Colour: White A/C: Insured / Std / NI / NASp. Reading: 94319 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH HACS3H60K00.2734Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/85 R16 BSR: 195/85 R15 Yoko.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 29/02/18Survey held at Premium CarzDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPALG-

Lg & 15,500.00

CRBD: \$ 33,562.42 (68%)

MV: 65K

TV: 31.5K

Net: 33.5K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

2269N.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18003281/Ahb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 21-02-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLQ 466H	Veh. Inspected	YN 9170M
Policy No.		Coverage (\$)	0.00
Claim No.	SNM18D00876C02	Excess (\$)	0.00
Assign From		Assign Date	21/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/02/2018	Inspection Date	20/02/2018
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

forwarded to Admin on 14/2/18

TPchim. Vic.

Date : 19/2/18

TO: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Spingleaf Tower
Singapore 079909

Our Customer : Isoteam Access Pte Ltd

Vehicle No : YN9170M

Model : Hino XZU605R 10FT

Manufacture Year : 2015

Date of Accident : 12/02/2018

Total Estimate Repair Days : 20

Total Page : 3

Attn : Motor Claim Department

Fax : 6224 7478

JH4c53H60k002734

Re: Repair Estimate For Third Party Claim against SLQ466H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper <i>Distorted</i>	1	\$594.00	\$594.00	✓
2	Front bumper bracket RH <i>new</i>	1	\$282.00	\$282.00	x
3	Front bumper bracket LH <i>Bent</i>	1	\$282.00	\$282.00	✓
4	Headlamp RH <i>lt</i>	1	\$1,256.00	\$1,256.00	685
5	Headlamp LH <i>crushed</i>	1	\$1,256.00	\$1,256.00	685
6	Fog lamp RH <i>new</i>	1	\$385.00	\$385.00	x
7	Fog lamp LH <i>crushed</i>	1	\$385.00	\$385.00	✓
8	Front grille <i>crushed</i>	1	\$753.00	\$753.00	✓
9	Front grille "HINO" logo <i>new</i>	1	\$93.00	\$93.00	✓
10	Front grille clip <i>new</i>	8	\$5.00	\$40.00	✓
11	Front corner panel RH <i>new</i>	1	\$542.00	\$542.00	x
12	Front corner panel LH <i>Repair</i>	1	\$542.00	\$542.00	x
13	Front door RH <i>Distorted</i>	1	\$1,895.00	\$1,895.00	1780
14	Front door LH <i>Distorted</i>	1	\$1,895.00	\$1,895.00	1780
15	Front door trimboard RH <i>cracked</i>	1	\$718.00	\$718.00	445
16	Front door trimboard LH <i>cracked</i>	1	\$718.00	\$718.00	445
17	Front door trimboard clip <i>new</i>	20	\$5.00	\$100.00	60
18	Front door lock RH <i>cracked</i>	1	\$450.70	\$450.70	✓
19	Front door lock LH <i>cracked</i>	1	\$450.70	\$450.70	✓
20	Front door power window motor RH <i>new</i>	1	\$569.30	\$569.30	x
21	Front door power window motor LH <i>new</i>	1	\$569.30	\$569.30	x
22	Front door power window regulator RH <i>new</i>	1	\$496.20	\$496.20	x
23	Front door power window regulator LH <i>new</i>	1	\$496.20	\$496.20	x
24	Front door signal lamp RH <i>new</i>	1	\$278.00	\$278.00	x
25	Front door signal lamp LH <i>new</i>	1	\$378.00	\$378.00	x
26	Front door outer moulding RH <i>new</i>	1	\$378.00	\$378.00	x
27	Front door outer moulding LH <i>new</i>	1	\$187.30	\$187.30	x
30	Front door weatherstrip RH <i>Bent</i>	1	\$275.60	\$275.60	✓
31	Front door weatherstrip LH <i>Bent</i>	1	\$275.60	\$275.60	✓
32	Front door hinges RH <i>Bent</i>	1	\$169.50	\$169.50	70
33	Front door hinges LH <i>Bent</i>	1	\$169.50	\$169.50	70
34	Front door check RH <i>new</i>	1	\$196.30	\$196.30	48
35	Front door check LH <i>new</i>	1	\$196.30	\$196.30	48
36	Front door "616" sticker RH <i>new</i>	1	\$98.00	\$98.00	✓



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
37	Front door "616" sticker LH <i>NEC</i>	1	\$98.00	\$98.00	✓
38	Front door chanel RH <i>2</i>	1	\$281.75	\$281.75	✗
39	Front door chanel LH <i>1/2</i>	1	\$281.75	\$281.75	✗
40	Front door lower rubber RH <i>new</i>	1	\$145.50	\$145.50	✗
41	Front door lower rubber LH	1	\$145.50	\$145.50	✗
42	Front door pillar RH <i>Bent</i>	1	\$970.80	\$970.80	✓
43	Front door pillar LH <i>Distorted</i>	1	\$970.80	\$970.80	✓
44	Front door frame RH <i>3 Repairs</i>	1	repair	repair	✗
45	Front door frame LH	1	repair	repair	✗
46	Side mirror RH assy <i>3/4</i>	1	\$1,027.60	\$1,027.60	✗
47	Side mirror LH assy <i>1/2</i>	1	\$1,027.60	\$1,027.60	✗
48	Front step panel RH <i>3 Deformed</i>	1	\$300.00	\$300.00	225
49	Front step panel LH	1	\$300.00	\$300.00	225
50	Front floor panel RH <i>3 Repair</i>	1	\$1,467.75	\$1,467.75	✗
51	Front floor panel LH	1	\$1,467.75	\$1,467.75	✗
52	Air filter housing assy <i>Not new</i>	1		\$0.00	✗
53	Air-con condenser <i>Distorted</i>	1	\$1,285.00	(\$1,285.00)	695
54	Air-con fan blade <i>3/4</i>	1	\$140.00	\$140.00	✗
55	Air-con condenser fan motor <i>1/2</i>	1	\$493.00	\$493.00	✗
56	Air-con cowling <i>crackd</i>	1	\$228.00	\$228.00	✓
57	Rear under run bumper <i>3 Repair</i>	1	\$1,700.00	\$1,700.00	✗
58	Rear under run bumper bracket	2	\$510.00	\$1,020.00	✗
59	Tail lamp RH <i>crackd</i>	1	\$430.00	\$430.00	205
60	Tail lamp LH <i>Smashed</i>	1	\$430.00	\$430.00	205
61	Tail lamp bracket RH <i>Bent</i>	1	\$150.00	\$150.00	90
62	Tail lamp bracket LH <i>Distorted</i>	1	\$150.00	\$150.00	90
63	Rear number plate lamp <i>crackd</i>	1	\$90.00	\$90.00	✓
64	Rear number plate holder <i>Bent</i>	1	\$97.50	\$97.50	✓
65	Rear fender LH <i>Not new</i>	1	\$225.00	\$225.00	✗
			Sub Total	\$32,293.80	
			Less 10%	\$3,229.38	
			Sub-Total 1	\$29,064.42	
B.	Spare Parts (S/Nett)				
1	Front number plate <i>Bent</i>	1	\$35.00	\$35.00	✓
2	Air-con discharge pipe <i>3/4</i>	1	\$310.00	\$310.00	✗
3	Air-con aluminium pipe <i>Not new</i>	1	\$280.00	\$280.00	✗
4	Air-con liquid pipe	1	\$270.00	\$270.00	✗
5	Rear under run bumper sticker <i>New</i>	1	\$80.00	\$80.00	50.
6	Tail facelift torsion reflector sticker <i>NEC</i>	1	\$80.00	\$80.00	50.
7	Hydraulic pump - large LH <i>Bent</i>	2	\$2,500.00	\$5,000.00	2800
8	Hydraulic pump - small <i>3/4</i>	2	\$1,800.00	\$3,600.00	✗
9	Hydraulic pipe <i>1/2</i>	1	\$185.00	\$185.00	✗
10	Rear number plate <i>Bent</i>	1	\$35.00	\$35.00	✓
11	Stow arm RH <i>3 Repair</i>	1	\$168.00	\$168.00	✗
12	Stow arm LH	1	\$168.00	\$168.00	✗
13	Control casing box complete <i>crackd</i>	1	\$575.00	\$575.00	✓
14	Control casing box bracket <i>Not new</i>	1	\$198.00	\$198.00	✗
15	Power pack casing cover <i>crackd</i>	1	\$395.00	\$395.00	✓
16	Power pack cover clip <i>new</i>	1	\$45.00	\$45.00	20

Premium Carz

Sole Agent Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417863

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
17	Side stopper LH (yellow colour) <i>Missing</i>	1	\$69.00	\$69.00	✓
18	Side stopper bracket assy LH <i>BRK</i>	1	\$575.00	\$575.00	✗
19	Retraction cylinder RH <i>He new</i>	1	\$1,700.00	\$1,700.00	✗
20	Retraction cylinder bracket RH	1		\$0.00	✓
21	Retraction cylinder chain safety device	1		\$0.00	✓
22	Eye Retraction cylinder RH	1		\$0.00	✗
23	Torsion bar RH	1	repair	repair	✗
24	Rear End cap RH	1		\$0.00	✗
25	Rear End stopper RH	1		\$0.00	✗
26	Floor mat <i>3 new</i>	1	\$70.00	\$70.00	✗
27	Floor carpet <i>3 new</i>	1	\$110.00	\$110.00	✗
<i>3029</i> Sub-Total 2				\$13,948.00	
Total for Parts				\$43,012.42	
C.	Labour				
1	To check wiring.			\$150.00	60
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$2,400.00	1600
3	Spray painting all affected parts & areas.			\$2,200.00	1400
4	To spray anti-rust undercoat.			\$150.00	80
5	To remove and refit front door glass RH.			\$100.00	80
6	To remove and refit front door glass LH.			\$100.00	80
7	To remove and replace, to cut and weld tail lift damaged parts & areas (including hydraulic pump).			\$650.00	400
8	To remove and replace damaged air-con parts, and to vacuum air-con system and charge up air-con gas.			\$300.00	120
Total Labour				\$6,050.00	
Total Repair Cost				\$49,062.42	

3820.

LKK Auto Consultants hence notify the Repairer of the following:

- Yours faithfully,**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and approved by LKK Auto Consultants
- Aun Teng*
f Premium Carz Services Pte Ltd

Acknowledged By Repairer

Signature:

Date:

Surveyor's Details

Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

total 19,398.33
4/5: 155K
140 days

155K



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI18003281/Ahb3

Date: 04.12.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

YN 9170M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.07.2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	49,062.42
Revised Estimate Amount	: S\$	19,398.33
"Check" Items Amount	: S\$	-
Market Value	: S\$	65,000.00
LTA Reimbursement Value	: S\$	31,500.00
Nett Value	: S\$	33,500.00

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion, N/S & O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 14 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel: 6636 9100 Fax: 6636 9113

✓

SATISFACTION VOUCHER

Our ref.: 0290/YN9170M/TP/PC/0218

To : China Taiping Insurance (Singapore) Pte Ltd

ACCIDENT INVOLVING YN9170M AND SLQ466H ON 12/02/2018
ALONG AYE TUAS NEAR LIP 283

I/We hereby acknowledge having received from Premium Carz Services Pte Ltd, 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883, my/our vehicle number YN9170M which has been repaired to my/our satisfaction and acceptance. I/We admit that the payment of *SGD _____ account for such repairs is in full discharge of my/our claim.

Dated : 9 day of March 2018

Signature : [Signature]

Owners' name: Isoteam Access Pte Ltd

NRIC/Co. Reg.: 200612269N

Address : 8 Changi North St-1

ISOTEAM Building

Singapore 498829





Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Letter of Authority

Date: 13/02/2018

ACCIDENT INVOLVING YN9170M AND SLQ466H ON 12/02/2018
ALONG AYE TUAH NEAR L/P 283

To Whom It May Concern:

This is to certify that I, Isoteam Access Pte Ltd (Owner), NRIC/Passport No:
200612269N Contact No: 6252 9982 the owner of Vehicle No:
YN9170M, hereby authorize Subramanian Ranjith Kumar (driver), NRIC/Passport
No: G6836302R, to:

- i) Drive the above stated vehicle;
- ii) Collect the vehicle upon completion of repair

The authority given herein shall be irrevocable unless notice of revocation is given to us.

Thank you.

Yours sincerely,

(Owner's Signature)



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

INVOICE: 0290

Date : 29/11/2018

Bill To :

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Our Customer

Name : Isoteam Access Pte Ltd

Co.Reg.No. : 200612269N

Address : 8 Changi North St. 1

ISOTEAM Building

Singapore 498829

Vehicle No : **YN9170M**

Date of Accident : 12/2/2018

Model : HINO 300

No.		Qty	Unit Price	Amount
1	To supply labour and materials to repair the above-mentioned vehicle to its pre-accident condition (Lump Sum)	1	-	\$15,500.00
TOTAL				\$15,500.00

For Premium Carz Services Pte Ltd

* All cheque should be crossed and make payable to "Premium Carz Services Pte Ltd"

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18003281/Ahb3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-03-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLQ 466H	Veh. Inspected	YN 9170M
Policy No.	DMHCSN174741700	Coverage (\$)	0.00
Claim No.	SNM18D00876C02/6	Excess (\$)	0.00
Assign From		Assign Date	20/02/2018
2. Vehicle Particulars & Condition			
Make & Model	HINO XZU605R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JHHACS3H60K002734	Colour	WHITE
Odometer	94319	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/85R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/85R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/85R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/85R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/02/2018	Inspection Date	20/02/2018
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 9170M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	594.00	594.00
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	282.00	-
1	FRONT BUMPER BRACKET LH	BENT	282.00	282.00
1	HEADLAMP RH	CUT	1,256.00	685.00
1	HEADLAMP LH	CRACKED	1,256.00	685.00
1	FOG LAMP RH	NOT NECESSARY	385.00	-
1	FOG LAMP LH	CRACKED	385.00	385.00
1	FRONT GRILLE	CRACKED	753.00	753.00
1	FRONT GRILLE "HINO" LOGO	NECESSARY	93.00	93.00
8	FRONT GRILLE CLIP @ \$5.00	NECESSARY	40.00	40.00
1	FRONT CORNER PANEL RH	NOT NECESSARY	542.00	-
1	FRONT CORNER PANEL LH	TO REPAIR SEE LABOUR	542.00	-
1	FRONT DOOR RH	DISTORTED	1,895.00	1,750.00
1	FRONT DOOR LH	DISTORTED	1,895.00	1,750.00
1	FRONT DOOR TRIMBOARD RH	CRACKED	718.00	445.00
1	FRONT DOOR TRIMBOARD LH	CRACKED	718.00	445.00
20	FRONT DOOR TRIMBOARD CLIP @ \$5.00	NECESSARY	100.00	60.00
1	FRONT DOOR LOCK RH	DAMAGED	450.70	450.70
1	FRONT DOOR LOCK LH	DAMAGED	450.70	450.70
1	FRONT DOOR POWER WINDOW MOTOR RH	NOT NECESSARY	569.30	-
1	FRONT DOOR POWER WINDOW MOTOR LH	NOT NECESSARY	569.30	-
1	FRONT DOOR POWER WINDOW REGULATOR RH	NOT NECESSARY	496.20	-
1	FRONT DOOR POWER WINDOW REGULATOR LH	NOT NECESSARY	496.20	-
1	FRONT DOOR SIGNAL LAMP RH	NOT NECESSARY	278.00	-
1	FRONT DOOR SIGNAL LAMP LH	NOT NECESSARY	378.00	-
1	FRONT DOOR OUTER MOULDING RH	NOT NECESSARY	378.00	-
1	FRONT DOOR OUTER MOULDING LH	NOT NECESSARY	187.30	-
1	FRONT DOOR WEATHERSTRIP RH	CUT	275.60	275.60
1	FRONT DOOR WEATHERSTRIP LH	CUT	275.60	275.60
1	FRONT DOOR HINGES RH	BENT	169.50	70.00

Report Ref No. CC6/CTI18003281/Ahb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR HINGES LH	BENT	169.50	70.00
1	FRONT DOOR CHECK RH	BENT	196.30	48.00
1	FRONT DOOR CHECK LH	BENT	196.30	48.00
1	FRONT DOOR "616" STICKER RH	NECESSARY	98.00	98.00
1	FRONT DOOR "616" STICKER LH	NECESSARY	98.00	98.00
1	FRONT DOOR CHANNEL RH	NOT NECESSARY	281.75	-
1	FRONT DOOR CHANNEL LH	NOT NECESSARY	281.75	-
1	FRONT DOOR LOWER RUBBER RH	NOT NECESSARY	145.50	-
1	FRONT DOOR LOWER RUBBER LH	NOT NECESSARY	145.50	-
1	FRONT DOOR PILLAR RH	BENT	970.80	970.80
1	FRONT DOOR PILLAR LH	DISTORTED	970.80	970.80
1	FRONT DOOR FRAME RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR FRAME LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	SIDE MIRROR RH ASSY	NOT NECESSARY	1,027.60	-
1	SIDE MIRROR LH ASSY	NOT NECESSARY	1,027.60	-
1	FRONT STEP PANEL RH	DEFORMED	300.00	225.00
1	FRONT STEP PANEL LH	DEFORMED	300.00	225.00
1	FRONT FLOOR PANEL RH	TO REPAIR SEE LABOUR	1,467.75	-
1	FRONT FLOOR PANEL LH	TO REPAIR SEE LABOUR	1,467.75	-
1	AIR FILTER HOUSING ASSY (NPA)	NOT NECESSARY	-	-
1	AIR-CON CONDENSER	DENTED	1,285.00	695.00
1	AIR-CON FAN BLADE	NOT NECESSARY	140.00	-
1	AIR-CON CONDENSER FAN MOTOR	NOT NECESSARY	493.00	-
1	AIR-CON COWLING	CRACKED	228.00	228.00
1	REAR UNDER RUN BUMPER	TO REPAIR SEE LABOUR	1,700.00	-
2	REAR UNDER RUN BUMPER BRACKET @ \$510.00	TO REPAIR SEE LABOUR	1,020.00	-
1	TAIL LAMP RH	CRACKED	430.00	205.00
1	TAIL LAMP LH	SMASHED	430.00	205.00
1	TAIL LAMP BRACKET RH	BENT	150.00	90.00

Report Ref No. CC6/CTI18003281/Ahb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP BRACKET LH	DISTORTED	150.00	90.00
1	REAR NUMBER PLATE LAMP	CRACKED	90.00	90.00
1	REAR NUMBER PLATE HOLDER	BENT	97.50	97.50
1	REAR FENDER LH	NOT NECESSARY	225.00	-
	LESS 10% DISCOUNT		-3,229.38	-1,394.37
			29,064.42	12,549.33
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	AIR-CON DISCHARGE PIPE (SN)	NOT NECESSARY	310.00	-
1	AIR-CON ALUMINIUM PIPE (SN)	NOT NECESSARY	280.00	-
1	AIRC-CON LIQUID PIPE (SN)	NOT NECESSARY	270.00	-
1	REAR UNDER RUN BUMPER STICKER (SN)	NECESSARY	80.00	50.00
1	TAIL FACELIFT TORSION REFLECTOR STICKER (SN)	NECESSARY	80.00	50.00
2	HYDRAULIC PUMP - LARGE @ \$2,500.00 (SN)	N/S BENT	5,000.00	1,800.00
2	HYDRAULIC PUMP - SMALL @ \$1,800.00 (SN)	NOT NECESSARY	3,600.00	-
1	HYDRAULIC PIPE (SN)	NOT NECESSARY	185.00	-
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
1	STOW ARM RH (SN)	TO REPAIR SEE LABOUR	168.00	-
1	STOW ARM LH (SN)	TO REPAIR SEE LABOUR	168.00	-
1	CONTROL CASING BOX COMPLETE (SN)	CRACKED	575.00	575.00
1	CONTROL CASING BOX BRACKET (SN)	NOT NECESSARY	198.00	-
1	POWER PACK CASING COVER (SN)	CRACKED	395.00	395.00
1	POWER PACK COVER CLIP (SN)	NECESSARY	45.00	20.00
1	SIDE STOPPER LH (YELLOW COLOUR) (SN)	MISSING	69.00	69.00
1	SIDE STOPPER BRACKET ASSY LH (SN)	TO REPAIR SEE LABOUR	575.00	-
1	RETRACTION CYLINDER RH (SN)	NOT NECESSARY	1,700.00	-
1	RETRACTION CYLINDER BRACKET RH (SN) (NPA)	NOT NECESSARY	-	-
1	RETRACTION CYNLINDER CHAIN SAFETY DEVICE (SN) (NPA)	NOT NECESSARY	-	-
1	EYE RETRACTION CYLINDER RH (SN) (NPA)	NOT NECESSARY	-	-
1	TORSION BAR RH (SN) (NPA)	NOT NECESSARY	-	-

Report Ref No. CC6/CT118003281/Ahb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END CAP RH (SN) (NPA)	NOT NECESSARY	-	-
1	REAR END STOPPER RH (SN) (NPA)	NOT NECESSARY	-	-
1	FLOOR MAT (SN)	NOT NECESSARY	70.00	-
1	FLOOR CARPET (SN)	NOT NECESSARY	110.00	-
			13,948.00	3,029.00
	LABOUR			
	TO CHECK WIRING.		150.00	60.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL LH, FRONT DOOR FRAME RH, FRONT DOOR FRAME LH, FRONT FLOOR PANEL RH, FRONT FLOOR PANEL LH, REAR UNDER RUN BUMPER, REAR UNDER RUN BUMPER BRACKET, STOW ARM RH, STOW ARM LH AND SIDE STOPPER BRACKET ASSY LH.		2,400.00	1,600.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		2,200.00	1,400.00
	TO SPRAY ANTI-RUST UNDERCOAT.		150.00	80.00
	TO REMOVE AND REFIT FRONT DOOR GLASS RH.		100.00	80.00
	TO REMOVE AND REFIT FRONT DOOR GLASS LH.		100.00	80.00
	TO REMOVE AND REPLACE, TO CUT AND WELD TAIL LIFT DAMAGED PARTS & AREAS (INCLUDING HYDRAULIC PUMP).		650.00	400.00
	TO REMOVE AND REPLACE DAMAGED AIR-CON PARTS, AND TO VACUUM AIR-CON SYSTEM AND CHARGE UP AIR-CON GAS.		300.00	120.00
			6,050.00	3,820.00
	GRAND TOTAL		49,062.42	19,398.33
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,500.00

Report Ref No. CC6/CTI18003281/Ahb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.