



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0218-6366
Policy No:	A28805625QMX	Date of Loss:	10/02/2018
Vehicle Reg. No.:	SLF349X	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN CHEE KEONG (CHEN ZHIQIANG)	Contact No:	+6590484656
Driver:	TAN CHEE KEONG (CHEN ZHIQIANG)		

Make/Model:	HONDA VEZEL, 1.5 CVT ABS D/AIRBAG 2WD 5DR (A)	Vehicle Reg. Date:	11/08/2016
Vehicle Colour:	WHITE		
Engine No:	LEB5908163	Chassis No:	RU31208154
Odometer:	16163 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **6**

Description of Accident/Loss: REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Remarks: VEHICLE IS NOT IN WORKSHOP

Present Location: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	7,098.30
Miscellaneous Items	140.00
Labour	980.00
Paintwork Labour	800.00
Towing	0.00
	9097.50
Calculated Gross Total (\$\$)	9,018.30
- Excess (\$\$)	500.00
(\$\$)	8,518.30
+ GST 7.00% (\$\$)	596.28
Nett Amount (\$\$)	9,114.58

This claim is handled by: **NG PEI WEN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Feb 2018)**Parts:** 144 HONDA VEZEL 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/SLF349X/13/02/2018 10:01**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET / <i>mc</i>	0.00	0.00	*450.00 F ✓
2	1	NA	*BONNET LOCK / <i>BT</i>	0.00	0.00	*75.00 F ✓
3	1	NA	*BONNET HINGE - LH X <i>} repair</i>	0.00	0.00	*30.00 F X
4	1	NA	*BONNET HINGE - RH X	0.00	0.00	*30.00 F X
5	1	NA	*BONNET INSULATOR / <i>ee</i>	0.00	0.00	*70.00 F ✓
6	9	NA	*BONNET INSULATOR CLIPS / <i>mc</i>	0.00	0.00	*18.00 F ✓
7	2	NA	*BONNET RUBBER - CENTRE - LH; RH / <i>} mc</i>	0.00	0.00	*32.00 F ✓
8	2	NA	*BONNET RUBBER - LONG - LH; RH	0.00	0.00	*46.00 F ✓
9	2	NA	*BONNET RUBBER - CENTRE	0.00	0.00	*32.00 F ✓
10	12	NA	*GRILLE TOP GARNISH CLIP / <i>mc</i>	18 0.00	0.00	*24.00 F ✓
11	2	NA	*AIR DUCT CLIP / <i>} mis</i>	0.00	0.00	*6.00 F ✓
12	2	NA	*GRILLE LOGO CLIP / <i>} mis</i>	0.00	0.00	*6.00 F ✓
13	1	NA	*GRILLE BASE - NO STOCK / <i>CRA</i> <i>558</i>	0.00	0.00	*250.00 F ✓
14	1	NA	*GRILLE OUTER GARNISH / <i>CRA</i>	0.00	0.00	*240.00 F X
15	1	NA	*GRILLE LOWER CHROME / <i>CRA</i>	0.00	0.00	*45.00 F X
16	1	NA	*GRILLE LOGO / <i>mc</i>	0.00	0.00	*17.00 F X
17	1	NA	*FRONT BUMPER / <i>ee</i>	0.00	0.00	*330.00 F ✓
18	10	NA	*FRONT BUMPER CLIPS / <i>mc</i>	0.00	0.00	*20.00 F ✓
19	1	NA	*FRONT BUMPER SIDE HOLDER - LH / <i>} mc</i>	0.00	0.00	*11.00 F ✓
20	1	NA	*FRONT BUMPER SIDE HOLDER - RH	0.00	0.00	*11.00 F ✓
21	1	NA	*FRONT BUMPER CENTRE LOWER GRILLE / <i>CRA</i>	0.00	0.00	*55.00 F ✓
22	1	NA	*FRONT BUMPER REINFORCEMENT / <i>BT</i>	0.00	0.00	*180.00 F ✓
23	1	NA	*FRONT BUMPER LOWER SPOILER; BLACK / <i>X ee NN</i>	0.00	0.00	*240.00 F X
24	1	NA	*FRONT BUMPER FOG LAMP - LH / <i>X</i>	0.00	0.00	*170.00 F X
25	1	NA	*FRONT BUMPER FOG LAMP - RH / <i>X</i>	0.00	0.00	*170.00 F X
26	1	NA	*FRONT BUMPER FOG LAMP COVER - LH / <i>X NN</i>	0.00	0.00	*18.00 F X
27	1	NA	*FRONT BUMPER FOG LAMP COVER - RH / <i>X NN</i>	0.00	0.00	*18.00 F X
28	1	NA	*FRONT FENDER OUTER WHEEL ARCH GARNISH - LH / <i>X ee</i>	0.00	0.00	*110.00 F X
29	1	NA	*FRONT FENDER OUTER WHEEL ARCH GARNISH - RH / <i>X ee</i>	0.00	0.00	*110.00 F X
30	1	NA	*CONDENSER / <i>BT</i>	0.00	0.00	*330.00 F ✓
31	1	NA	*CONDENSER SIDE GARNISH - LH / <i>X ee</i>	0.00	0.00	*25.00 F ✓
32	1	NA	*CONDENSER SIDE GARNISH - RH / <i>X NN</i>	0.00	0.00	*25.00 F X
33	1	NA	*RADIATOR / <i>X cut</i>	0.00	0.00	*760.00 F ✓
34	1	NA	*AIRCON W/RADIATOR FAN COWLING / <i>X NN</i>	0.00	0.00	*65.00 F X
35	1	NA	*AIRCON W/RADIATOR FAN BLADE / <i>X NN</i>	0.00	0.00	*40.00 F X
36	1	NA	*AIRCON W/RADIATOR FAN MOTOR / <i>X NN</i>	0.00	0.00	*185.00 F X
37	1	NA	*SUPPORT PANEL ASSY / <i>BT - photo</i>	0.00	0.00	*310.00 F ✓
38	1	NA	*HEAD LAMP UNIT - LH / <i>ee</i>	0.00	0.00	*820.00 F ✓
39	1	NA	*HEAD LAMP UNIT - RH / <i>X NN</i>	0.00	0.00	*820.00 F X
40	1	NA	*HEAD LAMP LOWER RETAINER - LH / <i>ee</i>	0.00	0.00	*22.00 F ✓
41	1	NA	*HEAD LAMP LOWER RETAINER - RH / <i>X ee</i>	0.00	0.00	*22.00 F ✓
42	1	NA	*FRONT FENDER - LH / <i>X repair</i>	0.00	0.00	*180.00 F X
43	1	NA	*FRONT FENDER HYBRID WORDING - LH / <i>X mc NN</i>	0.00	0.00	*35.00 F X

F=Franchise part.

Sub Total (\$\$)

6,453.00

Progressive Automotive Pte Ltd/SLF349X/13/02/2018 10:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
+ Margin on L,N Items 10.00% (S\$)						645.30
Total Parts (S\$)						7,098.30

Progressive Automotive Pte Ltd/SLF349X/13/02/2018 10:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	COOLANT / <i>nk</i>	20.00
2	1	FRONT FENDER MUGEN WORDING - LH <i>X NN</i>	85.00
3	1	FRONT NUMBER PLATE W/CASING / <i>SLA</i>	35.00
Sub Total (S\$)			140.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New <i>750</i>	800.00
Labour Items			
2	TO KNOCK OUT DENTS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New <i>700</i>	800.00
3	TO CHECK WIRING	New <i>/</i>	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New <i>/</i>	100.00
5	TO RESET CHECK LIGHT	New <i>30</i>	60.00
Gross Labour Cost (S\$)			1,780.00

Progressive Automotive Pte Ltd/SLF349X/13/02/2018 10:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

5 Days.

Not Authorize.

23/2/18.

put by pt.

before print photos.

Excess \$500.

Quo Qia - 82880212.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: