

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
28	09/04/18 08:57	General View	 Load JPG	☒
29	09/04/18 08:57	General View	 Load JPG	☒
30	09/04/18 08:57	General View	 Load JPG	☒
31	09/04/18 08:57	General View	 Load JPG	☒
32	09/04/18 08:57	General View	 Load JPG	☒
33	09/04/18 08:57	General View	 Load JPG	☒
34	09/04/18 08:57	General View	 Load JPG	☒
35	09/04/18 08:57	General View	 Load JPG	☒
36	09/04/18 08:57	General View	 Load JPG	☒
37	09/04/18 08:57	General View	 Load JPG	☒
38	09/04/18 08:57	General View	 Load JPG	☒
39	09/04/18 08:57	General View	 Load JPG	☒
40	09/04/18 08:57	General View	 Load JPG	☒
41	09/04/18 08:57	General View	 Load JPG	☒
42	09/04/18 08:57	General View	 Load JPG	☒
43	09/04/18 08:57	General View	 Load JPG	☒
44	09/04/18 08:57	General View	 Load JPG	☒
45	09/04/18 08:57	General View	 Load JPG	☒
46	09/04/18 08:57	General View	 Load JPG	☒
47	09/04/18 08:57	General View	 Load JPG	☒
48	09/04/18 08:57	General View	 Load JPG	☒
49	09/04/18 08:57	General View	 Load JPG	☒
50	09/04/18 08:57	General View	 Load JPG	☒
51	09/04/18 08:57	General View	 Load JPG	☒
52	09/04/18 08:57	General View	 Load JPG	☒
53	09/04/18 08:57	General View	 Load JPG	☒
54	09/04/18 08:57	General View	 Load JPG	☒
55	09/04/18 08:57	General View	 Load JPG	☒
56	09/04/18 08:57	General View	 Load JPG	☒
57	09/04/18 08:57	General View	 Load JPG	☒
58	09/04/18 08:57	General View	 Load JPG	☒
59	09/04/18 08:57	General View	 Load JPG	☒
60	09/04/18 08:57	General View	 Load JPG	☒
61	09/04/18 08:57	General View	 Load JPG	☒
62	09/04/18 08:57	General View	 Load JPG	☒
63	09/04/18 08:57	General View	 Load JPG	☒
64	09/04/18 08:57	General View	 Load JPG	☒
65	09/04/18 08:57	General View	 Load JPG	☒
66	09/04/18 08:57	General View	 Load JPG	☒
67	09/04/18 08:57	General View	 Load JPG	☒
68	09/04/18 08:57	General View	 Load JPG	☒
69	09/04/18 08:57	General View	 Load JPG	☒
70	09/04/18 08:57	General View	 Load JPG	☒
71	09/04/18 08:57	General View	 Load JPG	☒
72	09/04/18 08:58	Reinspection Photo	 Load JPG	☒
73	09/04/18 08:58	Reinspection Photo	 Load JPG	☒
74	09/04/18 08:58	Reinspection Photo	 Load JPG	☒
75	09/04/18 08:58	Reinspection Photo	 Load JPG	☒
76	09/04/18 08:58	Reinspection Photo	 Load JPG	☒
77	09/04/18 08:58	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
78	09/04/18 08:58	Reinspection Photo	Load JPG	☒
79	09/04/18 08:58	Reinspection Photo	Load JPG	☒
80	09/04/18 08:58	Reinspection Photo	Load JPG	☒
81	09/04/18 08:58	Reinspection Photo	Load JPG	☒
82	09/04/18 08:58	Reinspection Photo	Load JPG	☒
83	09/04/18 08:58	Reinspection Photo	Load JPG	☒
84	09/04/18 08:58	Reinspection Photo	Load JPG	☒
85	09/04/18 08:58	Reinspection Photo	Load JPG	☒
86	09/04/18 08:58	Reinspection Photo	Load JPG	☒
87	09/04/18 08:58	Reinspection Photo	Load JPG	☒
88	09/04/18 08:58	Reinspection Photo	Load JPG	☒
89	09/04/18 08:58	Reinspection Photo	Load JPG	☒
90	09/04/18 08:58	Reinspection Photo	Load JPG	☒
91	09/04/18 08:58	Reinspection Photo	Load JPG	☒
92	09/04/18 08:58	Reinspection Photo	Load JPG	☒
93	09/04/18 08:58	Reinspection Photo	Load JPG	☒
94	09/04/18 08:58	Reinspection Photo	Load JPG	☒
95	09/04/18 08:58	Reinspection Photo	Load JPG	☒
96	09/04/18 08:58	Reinspection Photo	Load JPG	☒
97	09/04/18 08:58	Reinspection Photo	Load JPG	☒
98	09/04/18 08:58	Reinspection Photo	Load JPG	☒
99	09/04/18 08:58	Reinspection Photo	Load JPG	☒
100	09/04/18 08:58	Reinspection Photo	Load JPG	☒
101	09/04/18 08:58	Reinspection Photo	Load JPG	☒
102	09/04/18 08:58	Reinspection Photo	Load JPG	☒
103	09/04/18 08:58	Reinspection Photo	Load JPG	☒
104	09/04/18 08:58	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 09:51	E-filed GIA report	Load PDF	
2	13/02/18 09:51	Certificate of Insurance	Load TIF	
3	13/02/18 09:51	Claimant's NRIC & LICENSE	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 15:49	MARK ESTIMATE	Load PDF	
2	09/04/18 09:23	1ST MARK ESTIMATE	Load PDF	
3	09/04/18 09:23	SUPPLEMENTARY	Load PDF	
4	10/04/18 14:39	Parts Invoice	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	10/02/18 11:52	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	10/02/18 11:32	Accident Photo	Load JPG	☒
2	10/02/18 11:32	Accident Photo	Load JPG	☒
3	10/02/18 11:32	Accident Photo	Load JPG	☒
4	10/02/18 11:32	Accident Photo	Load JPG	☒
5	10/02/18 11:32	Accident Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
				☒
6	10/02/18 11:32	Accident Photo	Load JPG	☒
7	10/02/18 11:32	Accident Photo	Load JPG	☒
8	10/02/18 11:32	Accident Photo	Load JPG	☒
9	10/02/18 11:32	Accident Photo	Load JPG	☒
10	10/02/18 11:32	Accident Photo	Load JPG	☒
11	10/02/18 11:32	Accident Photo	Load JPG	☒
12	10/02/18 11:32	Accident Photo	Load JPG	☒
13	10/02/18 11:32	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	10/02/18 11:51	Sketch Plan	Load JPG	☒
2	10/02/18 11:51	Sketch Plan #2	Load JPG	☒
3	10/02/18 11:51	CI	Load TIF	
4	10/02/18 11:51	DRIVER NRIC & LICENSE	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003289/GVBE2

Date: 10/04/2018

REFERENCE

Insured/Claimant: TAN CHEE KEONG (CHEN ZHIQIANG)
Date of Loss: 10/02/2018

Policy No: A28805625QMX
Nature of Claim: OD

Claim No: 549377

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF349X**
Make & Model: HONDA VEZEL, 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: LEB5908163
Reg. Date: 11/08/2016 (Man. Year: 2015) Chassis No: RU31208154
Colour: White Odometer: 16770 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$84,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40ZR19 Rear Tyre Size: 245/40ZR19
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,177.50	4,706.90	2,470.60	34.42
Miscellaneous Items	140.00	55.00	85.00	60.71
Labour	980.00	850.00	130.00	13.27
Paintwork Labour	800.00	750.00	50.00	6.25
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,097.50	6,361.90	2,735.60	30.07
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	8,597.50	5,861.90	2,735.60	31.82
+ GST 7.00/7.00% (S\$)	601.82	410.33	191.49	31.82
Nett Amount (S\$)	9,199.32	6,272.23	2,927.09	31.82

INSPECTION

Date of Assignment: 21/02/2018 Present Location:
Date Inspected: 23/02/2018 Inspected At:

Progressive Automotive Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
Parts:	144	HONDA VEZEL 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF349X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (WCP)	Buckled	450.00 F	*450.00 F
2	1	NA	*BONNET LOCK (WCP)	Bent	75.00 F	*75.00 F
3	1	NA	*BONNET HINGE - LH (WCP)	Repair	30.00 F	*- F
4	1	NA	*BONNET HINGE - RH (WCP)	Repair	30.00 F	*- F
5	1	NA	*BONNET INSULATOR (WCP)	Deformed	70.00 F	*70.00 F
6	9	NA	*BONNET INSULATOR CLIPS (WCP)	Necessary	18.00 F	*18.00 F
7	2	NA	*BONNET RUBBER - CENTRE - LH; RH (WCP)	Necessary	32.00 F	*32.00 F
8	2	NA	*BONNET RUBBER - LONG - LH; RH (WCP)	Necessary	46.00 F	*46.00 F
9	2	NA	*BONNET RUBBER - CENTRE (WCP)	Necessary	32.00 F	*32.00 F
10	12	NA	*GRILLE TOP GARNISH CLIP (WCP)	Necessary	24.00 F	*18.00 F
11	2	NA	*AIR DUCT CLIP (WCP)	Missing	6.00 F	*6.00 F
12	2	NA	*GRILLE LOGO CLIP (WCP)	Missing	6.00 F	*6.00 F
13	1	NA	*GRILLE BASE - NO STOCK (WCP)	Necessary	250.00 F	*558.00 F
14	1	NA	*GRILLE OUTER GARNISH (WCP)	Cracked	240.00 F	*- F
15	1	NA	*GRILLE LOWER CHROME (WCP)	Cracked	45.00 F	*- F
16	1	NA	*GRILLE LOGO (WCP)	Necessary	17.00 F	*- F
17	1	NA	*FRONT BUMPER (WCP)	Deformed	330.00 F	*330.00 F
18	10	NA	*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
19	1	NA	*FRONT BUMPER SIDE HOLDER - LH (WCP)	Necessary	11.00 F	*11.00 F
20	1	NA	*FRONT BUMPER SIDE HOLDER - RH (WCP)	Necessary	11.00 F	*11.00 F
21	1	NA	*FRONT BUMPER CENTRE LOWER GRILLE (WCP)	Cracked	55.00 F	*55.00 F
22	1	NA	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	180.00 F	*180.00 F
23	1	NA	*FRONT BUMPER LOWER SPOILER; BLACK (WCP)	Not Necessary	240.00 F	*- F
24	1	NA		Not Necessary	170.00 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT BUMPER FOG LAMP - LH (WCP)			
25	1	NA	*FRONT BUMPER FOG LAMP - RH (WCP)	Not Necessary	170.00 F	*- F
26	1	NA	*FRONT BUMPER FOG LAMP COVER - LH (WCP)	Not Necessary	18.00 F	*- F
27	1	NA	*FRONT BUMPER FOG LAMP COVER - RH (WCP)	Not Necessary	18.00 F	*- F
28	1	NA	*FRONT FENDER OUTER WHEEL ARCH GARNISH - LH (WCP)	Not Necessary	110.00 F	*- F
29	1	NA	*FRONT FENDER OUTER WHEEL ARCH GARNISH - RH (WCP)	Not Necessary	110.00 F	*- F
30	1	NA	*CONDENSER (WCP)	Bent	330.00 F	*330.00 F
31	1	NA	*CONDENSER SIDE GARNISH - LH (WCP)	Deformed	25.00 F	*25.00 F
32	1	NA	*CONDENSER SIDE GARNISH - RH (WCP)	Not Necessary	25.00 F	*- F
33	1	NA	*RADIATOR (WCP)	Cut	760.00 F	*760.00 F
34	1	NA	*AIRCON W/RADIATOR FAN COWLING (WCP)	Not Necessary	65.00 F	*- F
35	1	NA	*AIRCON W/RADIATOR FAN BLADE (WCP)	Not Necessary	40.00 F	*- F
36	1	NA	*AIRCON W/RADIATOR FAN MOTOR (WCP)	Not Necessary	185.00 F	*- F
37	1	NA	*SUPPORT PANEL ASSY (WCP)	Bent	310.00 F	*310.00 F
38	1	NA	*HEAD LAMP UNIT - LH (WCP)	Cracked	820.00 F	*820.00 F
39	1	NA	*HEAD LAMP UNIT - RH (WCP)	Not Necessary	820.00 F	*- F
40	1	NA	*HEAD LAMP LOWER RETAINER - LH (WCP)	Deformed	22.00 F	*22.00 F
41	1	NA	*HEAD LAMP LOWER RETAINER - RH (WCP)	Deformed	22.00 F	*22.00 F
42	1	NA	*FRONT FENDER - LH (WCP)	Repair	180.00 F	*- F
43	1	NA	*FRONT FENDER HYBRID WORDING - LH (WCP)	Not Necessary	35.00 F	*- F
Supplementary #1						
44	1		*GRILLE TOP BRACKET (WCP)	Broken	25.00 F	*25.00 F
45	1		*FRONT BUMPER FOGLAMP INNER BRACKET - LH (WCP)	Broken	18.00 F	*18.00 F
46	1		*HEADLAMP TOP BRACKET - LH (WCP)	Broken	16.00 F	*16.00 F
47	1		*AMBIENT SENSOR BRACKET - FRONT (WCP)	Broken	13.00 F	*13.00 F

F=Franchise part.

Sub Total (S\$)	6,525.00	4,279.00
+ Margin on L,N Items 10.00/10.00% (S\$)	652.50	427.90
Total Parts (S\$)	7,177.50	4,706.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	COOLANT (NECESSARY)	20.00	20.00
2	1	FRONT FENDER MUGEN WORDING - LH (NOT NECESSARY)	85.00	0.00
3	1	FRONT NUMBER PLATE W/CASING (SCRATCHED)	35.00	35.00
Sub Total (S\$)			140.00	55.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	750.00
<u>Labour Items</u>				
2	TO KNOCK OUT DENTS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	800.00	700.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
5	TO RESET CHECK LIGHT	New	60.00	30.00
Gross Labour Cost (S\$)			1,780.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >