

ASS. REC. BY:

REF: CS/MSG18003309/R1 v.bj

Special Instruction:

 ASSIGNMENT (Office)
 From (Person): Rasul of MSIG

 Date/Time: 21/2 10:29

Estimated Cost: _____ Bill to: _____

 OD / WS / TP RES / OD RES / EVA / INV / MV / CS

 To Inspect Vehicle No: SLP 1977Z Insured: SKX140Y

 at Workshop m/s Kah motor Tel: 68465671

 of Ismbi Road 4

 Policy No: 29053197QMY Claim No: _____

Sum Insured: _____ Excess: _____

 Make of Veh: _____ D.O.A. 17/2/18
 (Client's Record)

CA / REV / REP. / REV 24 HRS

 Date/Time: 21/2/18 Person Contacted: Geran chui H.O.D. Endorsement: _____

 Vehicle IN OUT

| Date/Time | Action/Instruction |
|-----------|--|
| | <input checked="" type="checkbox"/> Estimate |
| | <u>SLP 1977Z-X</u> |
| | <u>SKX 140Y-X</u> |
| | <u>Sent preli thru meimen</u> |
| | <u>Confirm \$5814.40, 7 days (Red: \$3385.23, 37'1.)</u> |

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|-------------|--------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 19 Feb 2018 | | 21 Feb 2018 10:29 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|---|-------------------------------|--|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | LEE KIEN BOON, ID: S7247417A | | | | | | | | |
| Main Claimant: | PECK KENG YEOW, ID: S7818750F | | | | | | | | |
| Vehicle Reg. No.: | SLP1977Z | Date of Loss: | 17/02/2018 09:00 - :59 | | | | | | |
| Claim Type: | TP | Policy/Cover Note No.: | 29053197QMY Coverage: 25/11/2017 - 24/11/2018 | | | | | | |
| Vehicle Reg. No. (Insured): | SKX140Y | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/02/2018] | | | | | | | | |
| Driver/Custodian (Insured): | LEE KIEN BOON (), NRIC: S7247417A | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Rasm1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003309/R1rb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-02-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|--------------|----------------------|----------------|------------|
| Insured Veh. | SKX 140Y | Veh. Inspected | SLP 1977Z |
| Policy No. | 29053197QMY | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | MERIMEN (ELAINE NGU) | Assign Date | 21/02/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 17/02/2018 | Inspection Date | 21/02/2018 |
| Survey held at | KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610 | | |

5a. Remarks

| |
|---|
| <p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p> |
|---|

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 12 Apr 2018

Preliminary Advice

Insured Vehicle : SKX140Y

No

TP Vehicle No : SLP1977Z

Make : HONDA JAZZ

Date of : 21/02/2018

Inspection

Inspection At : KAH MOTOR CO SDN BHD (UBI)
15 UBI ROAD 4
SINGAPORE 408610

Accident Date : 17/02/2018

Assignment Date : 21/02/2018

Est. Duration of
Repair : 7.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 8,940.06 |
| Revised Amount | :S\$ | 5,814.40 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 5,814.40 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---------------------------|
| Date Of Report | 19/02/2018 16:11 |
| Date Of Accident | 17/02/2018 09:40 |
| Exact Location Of Accident | WOODLANDS CAUSEWAY BRIDGE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|--------------------------------------|
| Vehicle Registration Number | SLP1977Z |
| Insured/Policyholder | |
| Name Of Registered Owner | PECK KENG YEOW |
| NRIC No | S7818750F |
| Email Address | KY.PECK@GMAIL.COM |
| Mobile Phone No | (LOCAL) +65-97978342 |
| Alternative Phone No | OFFICE-97978342 |
| Vehicle Particulars | |
| Manufacturer | HONDA |
| Model | JAZZ-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | LEISURE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 17-MU006204-R00 |
| Cover Note Number | |
| Driver | |
| Name of Driver | PECK KENG YEOW |
| NRIC No | S7818750F |
| Date Of Birth | 30/06/1978 |
| Occupation | INDOOR |
| Date Of Driving Pass | 04/07/2001 |
| Driving Experience | 16 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97978342 |
| Fax Number | |
| Contact Number | OFFICE-97978342 |
| Email Address | KY.PECK@GMAIL.COM |

| | |
|---|-----------------------------------|
| Address | BLK721 TAMPINES STREET 71 #05-218 |
| Postcode | 520721 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 4 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER REPORT ATTACHED

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---------------|
| Vehicle Registration Number | SKX140Y |
| Vehicle Make/Model/Colour | MITSHIBISHI |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | LEE KIEN BOON |
| NRIC/Passport Number | S7247417A |
| Contact Number | 91199883 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Vehicle No SLP 1977 Z

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
17/02/18
15:10 hr




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue to Annex E.

Vehicle No SLP 1977 Z

Annex E

Describe Circumstances of the Accident

On 17/2/2018 at approximately 9.38 am, I was on the woodlands
canopy bridge towards Malaysia. Car was moving slowly at less than 10 km/hr.
SKX140Y driver claim that he stopped on the accelerator instead of the
brake and ran into the back of my car.

Declaration

We declare the foregoing particulars are true in every respect.

 17/02/18
15:10hr

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7818750F



Name
PECK KENG YEOW
(BAI QINGYAO)
白庆耀
Race
CHINESE
Date of birth 30-06-1978 Sex M
Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7818750F
Name
PECK KENG YEOW
(BAI QINGYAO)
Date of Birth 30 Jun 1978
Issue Date 28 Apr 2005



0004319580



425328



NRIC No. S7818750F
Date of Issue
28-07-2008

APT BLK 721 TAMPINES STREET 71 #05-218
SINGAPORE 520721
S7818750F 11/01/2014

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

| Class | Description | Valid Until |
|---------|--|-------------|
| Class 3 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 04 Jul 2011 |



License No. S7818750F

NP 423A



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | |
|--|--|-----------------|
| Customer : MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581 | Document No. : SQT18000727 | Page : 1 |
| Registration No : SLP1977Z | Date : 19. Feb 2018 | |
| Chassis No : JHMGK5850HX201395 | Customer No. : WZM003 | |
| Model : JAZZ 1.5VTIR CVT 17YM | Svc Advisor : | |
| Owner's Name : PECK KENG YEOW | Engine No : L15B31191023 | |
| Ins Policy No. : | Date Time : 19. Feb 2018 4:37:13 PM | |
| Date of Accident : 17/2/2018 | Surveyor Name : | |
| | Survey Date : | |
| | Authorisation Date : | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount Includ GST |
|-----------------|---|-----|-----------------|--------|----------------|---------------|-------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER:PECK KENG YEOW OWNER INSURER:TOKIO MARINE ACC DATE:17/02/2018 SURVEYED BY: DATE: REF NO: TP INSURER:MSIG INS TP VEH:SKX140Y | | | | | | |
| 68100-TAS-Z50ZZ | TAILGATE COMP | 1 | 716.30 | 25 | 537.22 | 37.61 | 574.83 |
| 75722-T5L-T01 | EMBLEMRR. | 1 | 10.50 | 25 | 7.87 | 0.55 | 8.42 |
| 04715-T5B-000ZZ | FACERR.BUMPER | 1 | 492.60 | 25 | 369.45 | 25.86 | 395.31 |
| 71598-T5A-000 | SPACERL.RR.BUMPER | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 |
| 71593-T5A-000 | SPACERR.RR.BUMPER | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 |
| 71507-T5A-000 | GARNISHL.RR.BUMPER | 1 | 14.00 | 25 | 10.50 | 0.74 | 11.24 |
| 71502-T5A-000 | GARNISHR.RR.BUMPER | 1 | 14.00 | 25 | 10.50 | 0.74 | 11.24 |
| 84640-T5A-003ZA | LINING ASSYRR.PANEL | 1 | 60.80 | 25 | 45.60 | 3.19 | 48.79 |
| 84651-TAR-Z03ZA | LINING ASSYL.TRUNK | 1 | 165.60 | 25 | 124.20 | 8.89 | 132.89 |
| 84640-T5A-003ZA | LINING ASSYRR.PANEL | 1 | 60.80 | 25 | 45.60 | 3.19 | 48.79 |
| 33550-T5A-J02 | TAILLIGHT ASSYL | 1 | 217.40 | 25 | 163.05 | 11.41 | 174.46 |
| 33500-T5A-J02 | TAILLIGHT ASSYR. | 1 | 217.40 | 25 | 163.05 | 11.41 | 174.46 |
| 34155-T5A-J01 | LIGHT ASSYL.LID | 1 | 79.30 | 25 | 59.47 | 4.16 | 63.63 |
| 34150-T5A-J01 | LIGHT ASSYR.LID | 1 | 79.30 | 25 | 59.47 | 4.16 | 63.63 |
| 74890-T5B-911 | GARNISH ASSYRR.LICENSE | 1 | 194.70 | 25 | 146.02 | 10.22 | 156.24 |
| 39530-T5A-003 | CAMERA ASSYRR.VIEW | 1 | 1041.10 | 25 | 780.82 | 54.66 | 835.48 |
| | | | Sum Item | | 2540.05 | 177.79 | 2,717.85 |
| BOSUN | SUNDRIES | 1 | 100.00 | 30 | 100.00 | 7.00 | 107.00 |
| BOJSE | BODY JOINT SEALANT. | 1 | 100.00 | TAU | 100.00 | 7.00 | 107.00 |
| BG02D | REMOVE & INSTALL RR. WINDSCREEN.(N) | 1 | 280.00 | | 280.00 | 19.60 | 299.60 |



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581
 Registration No : SLP1977Z
 Chassis No : JHMGK5850HX201395
 Model : JAZZ 1.5VTIR CVT 17YM
 Owner's Name : PECK KENG YEOW
 Ins Policy No. :
 Date of Accident : 17/2/2018

Document No. : SQT18000727 Page 2
 Date : 19. Feb 2018
 Customer No. : WZM003
 Svc Advisor :
 Engine No : L15B31191023
 Date | Time : 19. Feb 2018 4:37:13 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|------------------|--|-----|-------------------------|--------|----------------|---------------|------------------|
| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BKRP02M | CUT OFF & RENEW RR PANEL. STRAIGHTEN BOTH FENDER | 1 | 3000.00 1680 | | 3000.00 | 210.00 | 3210.00 |
| BP06R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1 | 2800.00 1250 | | 2800.00 | 196.00 | 2996.00 |
| Sum Labor | | | | | 6400.00 | 448.00 | 6,848.00 |

Survey By RASUL - HP 90010068
 Date & Time 21/02/18 @ 1430
 Excess _____
 Status _____
 Signature Ru

9199.68
Total Amount 8,940.06 625.79 9,565.85
Total (Inclusive of GST) 9,565.85

7 days
 Refy by part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLP1977Z

Chassis No : JHMGK5850HX201395

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : PECK KENG YEOW

Ins Policy No. :

Date of Accident :

Document No. : SQT18000957 Page 1

Date : 6. Mar 2018

Customer No. : WZM003

Svc Advisor :

Engine No : L15B31191023

Date | Time : 6. Mar 2018 1:24:44 PM

Surveyor Name :

Survey Date :

Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount Includ GST |
|-----------------|---|-----|------------|----------|---------------|---------------|---------------------------|
| | TP DIRECT SETTLEMENT (J/NO: OWNER:PECK KENG YEOW OWNER INSURER:TOKIO MARINE ACC DATE:17/02/2018 SURVEYED BY:RASUL(LKK) DATE:21/02/2018 TP INSURER:MSIG INS TP VEH:SKX140Y SUPPLEMENTARY LABOURS & PARTS | | | | | | |
| 73127-TY0-000 | RUBBER CWINDOWSHIELD DAMPER | 1 | 11.20 | 25 | 8.40 | 0.59 | 8.99 <i>Handwritten</i> |
| 73214-T5A-013 | RUBBERWINDOWSHIELD DAMPER | 2 | 6.30 | 25 | 9.45 | 0.66 | 10.11 <i>Handwritten</i> |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 6.30 | 25 | 6.22 | 0.44 | 6.66 <i>Handwritten</i> |
| 66100-TAR-T10ZZ | PANEL COMPRR. | 1 | 314.00 | 25 | 235.50 | 16.49 | 251.99 <i>Handwritten</i> |
| | | | | Sum Item | 259.57 | 18.18 | 277.75 |

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 259.57 18.18 277.75

Total (Inclusive of GST) **277.75**

Printed on 6/3/2018 1:32:24 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Janice Lee (LKKAuto)

From: Steven Chui <stevenchui@honda.com.sg>
Sent: Tuesday, March 06, 2018 1:39 PM
To: SUR; Rasul (LKKAuto)
Subject: SLP1977Z FINAL BILL
Attachments: SLP1977Z FB.pdf

Dear Rasul & Veron,

Attached the final bills for SLP1977Z

Steven Chui
Bodyshop Service Advisor
Kah Motor Co. Sdn Bhd
15 Ubi Road 4
Singapore 408610
E-mail: stevenchui@honda.com.sg

Contact : 68465672
H/phone:90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G*Final*

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMGK5850HX201395
License No: SLP1977Z
Mileage: 9627
Engine No: L15B31191023

Document No: SVO18010228
Printed By: FSCHUI
Order Date: 21. February 2018
Order Time: 3:02:33 PM
Service Advisor: STEVEN CHUI FOOK SENG

| ITEM | DESCRIPTION | QTY | UNIT | DISC % | AMOUNT | 7% GST Amount | incld GST |
|-----------------|---|-----|----------|--------|-----------------|---------------|-----------------|
| | TP DIRECT SETTLEMENT (J/NO: OWNER:PECK KENG YEOW OWNER INSURER:TOKIO MARINE ACC DATE:17/02/2018 SURVEYED BY:RASUL(LKK) DATE:21/02/2018 REF NO: TP INSURER:MSIG INS TP VEH:SKX140Y | | | | | | |
| 68100-TAS-Z50ZZ | TAILGATE COMP | 1 | 716.30 | 25 | 537.22 | 37.61 | 574.83 |
| 75722-T5L-T01 | EMBLEMRR. | 1 | 10.50 | 25 | 7.87 | 0.55 | 8.42 |
| 71501-T5B-000ZN | FACERR.BUMPER | 1 | 492.70 | 25 | 369.52 | 25.87 | 395.39 |
| 71598-T5A-000 | SPACERL.RR.BUMPER | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 |
| 71593-T5A-000 | SPACERR.RR.BUMPER | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 |
| 33550-T5A-J02 | TAILLIGHT ASSYL. | 1 | 217.40 | 25 | 163.05 | 11.41 | 174.46 |
| 73127-TY0-000 | RUBBER CWINDSHIELD DAMPER | 1 | 11.20 | 25 | 8.40 | 0.59 | 8.99 |
| 73214-T5A-013 | RUBBERWINDSHIELD DAMPER | 2 | 6.30 | 25 | 9.45 | 0.66 | 10.11 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 8.30 | 25 | 6.22 | 0.44 | 6.66 |
| 66100-TAR-T10ZZ | PANEL COMPRR. | 1 | 314.00 | 25 | 235.50 | 16.49 | 251.99 |
| | SUM PARTS: | | | | 1,354.47 | 94.82 | 1,449.29 |
| BOSUN | 0672 SUNDRIES | 1 | 30.00 | | 30.00 | 2.10 | 32.10 |
| BOJSE | 0672 BODY JOINT SEALANT. | 1 | 100.00 | | 100.00 | 7.00 | 107.00 |
| BG02D | EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N) | 1 | 280.00 | | 280.00 | 19.60 | 299.60 |
| BA02R | EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BKRP02M | EXT-YJ CUT OFF & RENEW RR PANEL STRAIGHTEN BOTH FENDER ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS. | 1 | 1,680.00 | | 1,680.00 | 117.60 | 1,797.60 |
| BP06R | EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1 | 2,250.00 | | 2,250.00 | 157.50 | 2,407.50 |
| | SUM LABOUR: | | | | 4,460.00 | 312.20 | 4,772.20 |
| | TOTAL SGD | | | | 5,814.47 | 407.02 | 6,221.49 |
| | Total Payable (SGD) | | | | | | 6,221.49 |

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 19 Feb 2018 | | 21 Feb 2018 10:29 Edit Adj Rpt | S\$5,814.40 Edit Estimates | S\$5,814.40 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | LEE KIEN BOON , ID: S7247417A | | | | | | | | |
| Main Claimant: | PECK KENG YEOW , ID: S7818750F | | | | | | | | |
| Vehicle Reg. No.: | SLP1977Z | Date of Loss: | 17/02/2018 09:00 - :59 [8 Months and 19 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 550123 | Policy/Cover Note No.: | A29053197QMY (Comprehensive) Coverage: 25/11/2017 - 24/11/2018 | | | | | | |
| Vehicle Reg. No. (Insured): | SKX140Y | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$600.00 | | | | | | |
| Repairer: | Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/03/2018] | | | | | | | | |
| Driver/Custodian (Insured): | LEE KIEN BOON (), NRIC: S7247417A | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLP1977Z (550123)
[SKX140Y]
TP
PECK KENG YEOW
Feb 17 2018 9:00AM
[LEE KIEN BOON]
Kah Motor Co Sdn Bhd

| Upload Documents | | | Upload Photos | | | Compose New Letter | | | View View in Browser | |
|---------------------------|-----------------|-----------------------------------|---------------|--|--|--------------------|-----------|----------|---|-------------------------------------|
| Assessment Reports | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | | | | Thumbnail | Print | | |
| 1 | 12/04/18 10:22 | Adjuster Immediate Advice | | | | | | Load HTM | | |
| Photos/Images | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | Thumbnail | Print | | |
| 1 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 32 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 33 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 34 | 12/04/18 10:01 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|---|------------|--|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail Print |
| | | | | <input checked="" type="checkbox"/> |
| 35 | 12/04/18 10:01 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 36 | 12/04/18 10:02 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 37 | 12/04/18 10:02 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 38 | 12/04/18 10:02 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 39 | 12/04/18 10:02 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 40 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 41 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 42 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 43 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 44 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 45 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 46 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 47 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 48 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 49 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| 50 | 12/04/18 10:02 | Reinspection Photo | | Load JPG <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail Print |
| 1 | 21/02/18 09:55 | SLP1977Z E-FILE REPORT | | Load PDF |
| 2 | 21/02/18 09:56 | SKX140Y E-FILE REPORT | | Load PDF |
| 3 | 21/02/18 09:57 | TP email PRI Request | | Load PDF |
| 4 | 21/02/18 10:25 | SLP1977Z estimate | | Load PDF |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail Print |
| 1 | 16/04/18 09:24 | SUPPLEMENTARY PART | | Load PDF |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003309/R1RBQ2

Date: 16/04/2018

REFERENCE

| | | |
|--|---------------------|--|
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | A29053197QMY |
| Claimant Vehicle No: SLP1977Z | Insured Vehicle No: | SKX140Y |
| Date of Loss: 17/02/2018 | Nature of Claim: | TP Claim No: 550123 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | |
|--|-------------------------------|
| Reg No: SLP1977Z | Engine No: L15B31191023 |
| Make & Model: HONDA JAZZ, 1.5 VTIR CVT (A) | Chassis No: JHMGK5850HX201395 |
| Reg. Date: 29/05/2017 (Man. Year: 2016) | Odometer: 10888 km |
| Colour: Black | |
| Engine Capacity: 1498 cc | |
| Market Value/New Car Price: N/A | |
| Sum Insured (S\$): Market Value/New Car Price | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/55 R16 | Rear Tyre Size: | 195/55 R16 |
| Front Left Side: | Dunlop 5 mm | Rear Left Side: | Dunlop 5 mm |
| Front Right Side: | Dunlop 5 mm | Rear Right Side: | Dunlop 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 2,999.63 | 1,484.40 | 1,515.23 | 50.51 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,200.00 | 4,330.00 | 1,870.00 | 30.16 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 9,199.63 | 5,814.40 | 3,385.23 | 36.80 |
| + GST 7.00/7.00% (S\$) | 643.97 | 407.01 | 236.96 | 36.80 |
| Nett Amount (S\$) | 9,843.60 | 6,221.41 | 3,622.19 | 36.80 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 21/02/2018 | | |
| Date Inspected: | 21/02/2018 | Inspected At: | Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610 |
| Estimated Period of Repair: | 7.0 days | | |

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 16 Apr 2018) |
| Parts: 144 | HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SLP1977Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk * |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------------|-----|----------|------------------------------|-------------|-----------------|-----------------|
| 1 | 1 | | *TAILGATE COMP | Buckled | 537.22 FS | *537.22 FS |
| 2 | 1 | | *EMBLEMRR | Necessary | 7.87 FS | *7.87 FS |
| 3 | 1 | | *FACERR.BUMPER | Deformed | 369.45 FS | *369.45 FS |
| 4 | 1 | | *SPACERL.RR.BUMPER | Necessary | 8.62 FS | *8.62 FS |
| 5 | 1 | | *SPACERR.RR.BUMPER | Necessary | 8.62 FS | *8.62 FS |
| 6 | 1 | | *GARNISHL.RR.BUMPER | Serviceable | 10.50 FS | *- FS |
| 7 | 1 | | *GARNISHR.RR.BUMPER | Serviceable | 10.50 FS | *- FS |
| 8 | 1 | | *LINING ASSYRR.PANEL | Serviceable | 45.60 FS | *- FS |
| 9 | 1 | | *LINING ASSYRL.TRUNK | Serviceable | 124.20 FS | *- FS |
| 10 | 1 | | *LINING ASSYRR.PANEL | Serviceable | 45.60 FS | *- FS |
| 11 | 1 | | *TAILLIGHT ASSYL | Cracked | 163.05 FS | *163.05 FS |
| 12 | 1 | | *TAILLIGHT ASSYR | Serviceable | 163.05 FS | *- FS |
| 13 | 1 | | *LIGHT ASSYL.LID | Serviceable | 59.47 FS | *- FS |
| 14 | 1 | | *LIGHT ASSYR.LID | Serviceable | 59.47 FS | *- FS |
| 15 | 1 | | *GARNISH ASSYRR.LICENSE | Serviceable | 146.02 FS | *- FS |
| 16 | 1 | | *CAMERA ASSYRR.VIEW | Serviceable | 780.82 FS | *- FS |
| 17 | 1 | | *SUNDRIES | Necessary | 100.00 FS | *30.00 FS |
| 18 | 1 | | *BODY JOINT SEALANT | Necessary | 100.00 FS | *100.00 FS |
| 19 | 1 | | *RUBBER CWINDOWSHIELD DAMPER | Necessary | 8.40 FS | *8.40 FS |
| 20 | 1 | | *RUBBERWINDOWSHIELD DAMPER | Necessary | 9.45 FS | *9.45 FS |
| 21 | 1 | | *DAMPERSTD 5X5 | Necessary | 6.22 FS | *6.22 FS |
| 22 | 1 | | *PANEL COMP RR | Bent | 235.50 FS | *235.50 FS |
| Total Parts (S\$) | | | | | 2,999.63 | 1,484.40 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | REMOVE & INSTALL RR.WINDSCREEN | New | 280.00 | 280.00 |
| 2 | REMOVE & RENEW REVERSE SENSORS | New | 120.00 | 120.00 |
| 3 | CUT OFF & RENEW RR PANEL .STRAIGHTEN BOTH FENDER | New | 3,000.00 | 1,680.00 |
| 4 | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS | New | 2,800.00 | 2,250.00 |
| Gross Labour Cost (S\$) | | | 6,200.00 | 4,330.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >