

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BG 3562**
Date Estimated : **20/02/2018**
Prepared By : **Mohamed Shabir Abdul Hamid**

Page No. : **1 of 2**

- ESTIMATE REPAIR FOR -

Ng Kee Chong
Blk 336 Bukit Batok St 32
#04-303

Singapore 650336

- ACCOUNT - **2000**

CASH - Sale service

.

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT1692U	WF0EXXGBBECC12812	20/02/2013	MON TTN 5DR	0

DESCRIPTION	VALUE
SUNDRIES	150.00
ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)	150.00
TO REMOVE AND REFIX REAR BUMPER REVERSE SENSORS (NETT)	150.00
TO REMOVE AND REPLACE/ REFIX REAR WINDSCREEN (NETT)	600.00
SEALANT FOR REAR WINDSCREEN (NETT)	60.00
INNER SEAL FOR REAR WINDSCREEN (NETT)	50.00
TO SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN (NETT)	350.00
TO TRANSFER REAR BOOT MECHANISMS, COMPONENTS, LOCKS, TRIMS, CLIPS (NETT)	300.00
TUFF KOTE - BODY CAVITY PRESERVATION (NETT) @ \$60.00 PER PANEL	180.00
SEALANT FOR BODY PANELS (NETT) @ \$90.00 PER PANEL	180.00
TO REPAIR, REPLACE REAR BOOT, REAR WINDSCREEN, REAR BUMPER REAR END PANEL, BUMPER BRACKET TAIL LAMPS, 3RD BRAKE LIGHT REINFORCEMENT, REAR BUMPER SIDE RETAINER AND ALL OTHER AFFECTED PARTS AND AREAS	3,600.00
TO SPRAY PAINT REAR BUMPER, REAR END PANEL, REAR BOOT, REAR FENDER, TAIL LAMP PANEL, AND ALL OTHER AFFECTED AREAS	3,000.00
TO SUPPLY AND INSTALL REAR NUMBER PLATE WITH HOLDER (NETT)	70.00

Total Labour 1: **8,840.00**

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
-------------	-------------	-----	-------	------	-------

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BG 3562**
Date Estimated : **20/02/2018**
Prepared By : **Mohamed Shabir Abdul Hamid**

Page No. : **2 of 2**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT1692U	WF0EXXGBBECC12812	20/02/2013	MON TTN 5DR	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
PBS71A40410A	TAILGATE ASSY	1	2,650.00	10.00	2,385.00
A					
BS7117A881AD	RHR BUMPER BRACKET	1	85.00	10.00	76.50
BS7117A882AD	LHR BUMPER BRACKET	1	85.00	10.00	76.50
BS71A43400AC	BOOT LID HANDLE,PRIMED - M07	1	328.00	10.00	295.20
XWAA					
BS71A423A40B	BOOT LID LWR PANEL,PRIMED - M07	1	401.00	10.00	360.90
AXWAA					
7S71A404A06B	TAILGATE WEATHERSTRIP - M07	1	295.00	10.00	265.50
C					
BS71A42004AD	REAR WINDSCREEN - MON. 2.0L ECO 5DR	1	720.00	10.00	648.00
6M21R29760AA	WINDSCREEN SPACER	1	10.00	10.00	9.00
97BBA29760AA	SPACER	1	0.00	0.00	0.00
7U5A19H250AB	FRT & RR FORD BADGE	1	138.00	10.00	124.20
1S7142528AA	RR EMBLEM MONDEO - M07	1	130.00	10.00	117.00
BS7113A601AE	THIRD BRAKE LAMP ASSY	1	195.00	10.00	175.50
7S7113550AB	LAMP-LIC.PLATE	2	110.00	10.00	198.00
BS7113A602AE	RHR INNER LAMP ASSY	1	570.00	10.00	513.00
BS7113A603AE	LHR INNER LAMP ASSY - M07	1	570.00	10.00	513.00
BS7113404AE	LAMP ASSY RHR OUTER	1	620.00	10.00	558.00
BS7113405AE	LAMP ASSY - REAR, LH - OUTER	1	600.00	10.00	540.00
BS71A17906BB	BUMPER-REAR	1	1,562.00	10.00	1,405.80
XWAA					
7S71A17E850A	RHR BUMPER SIDE BRACKET	1	110.00	10.00	99.00
N					
7S71A17E851A	LHR BUMPER SIDE BRACKET	1	110.00	10.00	99.00
N					
BS7117A894BD	RR BPR EXTENSION DUAL EXH - M07	1	380.00	10.00	342.00
6M2117F902AD	RHR BPR REINF.BRACKET - M07	1	184.00	10.00	165.60
6M2117F903AC	LHR BPR REINF.BRACKET - M07	1	186.00	10.00	167.40
6M2117970AF5	RR BUMPER REINFORCEMENT - M07	1	1,095.00	10.00	985.50
ZCT					
7S7117B918AD	RR BUMPER LWR MTG BRACKET	2	54.00	10.00	97.20
96FG16K262AA	CLIP - F08,M07	4	8.00	10.00	28.80
AM5T15K870BB	RR PARKING AID BRACKET,UNPRIMED	4	48.00	10.00	172.80
XUAA					

Total Parts : **10,418.40**

Labour 1	:	8,840.00
Parts	:	10,418.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,348.09
Grand Total	:	20,606.49

Customer Service Officer

Contact

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.