



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9357X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,202.00	-
1	FRONT BUMPER LOWER ABSORBER (CONSISTENT)	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	356.00	-
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	SERVICEABLE	78.00	-
1	FRONT BUMPER LOWER STIFFENER (CONSISTENT)	TO REPAIR SEE LABOUR	134.37	-
1	BUMPER FOG LAMP COVER RH (CONSISTENT)	SERVICEABLE	32.40	-
1	FRONT HEADLAMP RH (CONSISTENT)	SERVICEABLE	816.00	-
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	837.60	-
1	FRONT FENDER LINER RH (CONSISTENT)	SERVICEABLE	47.00	-
1	FRONT DOOR RH (CONSISTENT)	SERVICEABLE	1,133.00	-
1	FRONT SIDE VIEW MIRROR RH (CONSISTENT)	SERVICEABLE	939.00	-
	LESS 10% DISCOUNT		-585.74	-
			5,271.63	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER FASTENER CLIP (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER LINER CLIP RH (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT WHEEL RIM HUB CAP RH (SN) (CONSISTENT)	SERVICEABLE	166.30	-
1	FRONT TYRE RH (SN) (CONSISTENT)	SERVICEABLE	180.00	-
1	FRONT TYRE RIM RH (SN) (CONSISTENT)	SERVICEABLE	126.00	-
1	DOOR STICKER "TRANS-CAB" RH (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			612.30	-
<b><u>LABOUR</u></b>				
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT BUMPER LOWER STIFFENER		1,350.00	150.00

Report Ref No. CC4/ASM18003325/Kps3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	220.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	400.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			3,650.00	550.00
<b>GRAND TOTAL</b>			<b>9,533.93</b>	<b>550.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>550.00</b>
------------------------------------	--	--	---------------

Report Ref No. CC4/ASM18003325/Kps3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.