

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

AXA-CP(P)

TS

VEHICLE NO : SHD 3542S

DATE 21/2/2018

MAKE :

MODEL : HYUNDAI i40

1030

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear No. Plate ✓			\$ 25.00	Nett
	License Plate Cover ✓			\$ 100.00	Nett
	Rubber Mat - \$50				
				\$ 260.70	
	Labour Charge				
	Panel Beating			\$ 380.00 200	
	Spray Painting Charge			\$ 200.00 180	
	R/Refix Reverse Sensor			\$ 120.00 20	
	TOTAL LABOUR			\$ 700.00	
	ESTIMATE TOTAL			\$ 2,486.58	
	<p>Kalvin CKK</p> <p>M 21/2/18 1130L</p> <p>2 DYS</p> <p>PIP</p> <p>Before Part of LH</p>				
	<div> <p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				