

22/02/2018

ASS. REC. BY:

REF: CS3 / M6617008552 / Caber-1
CS3 / M6617008552 / J. Jones
Special Instructions: 710 - 8.5 k

Surveyor: R. Jones ASSIGNMENT (Office)
From (Person): Tere Ton of MSLH Date/Time: 21/2/17 11:30pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G8D 1192H Insured: SKK 61528

at Workshop m/s TwinCar. Automotive Tel: 6817 0051

of 2 Kaky Bukit Ave) # 01-17

Policy No: 82007069 Claim No: 512850

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27 04 2017

(Client's Record)


CA / REV / REP. / REV 24 HRS w/p 03/05/2017 H.O.D. Endorsement: _____

Date/Time: 02/05/2017 11:30pm Person Contacted: Elynn Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	G8D 1192H - X
	SKK 61528 - X
	Disassembly Pad : 08-05-2017
	After repair : 09-05-2017
13/05/17 11:41am	Email to Tere Ton thru Maximan

22/2/18 submit LS \$ 6700, 6 days.
(red \$ 7800, 54%)

RECEIVED 2018


22/2/2018.

\$20.00

Celine Fong (LKKAuto)

From: Irene Tan <irene_tan@sg.msig-asia.com>
Sent: Wednesday, 21 February 2018 1:27 PM
To: Admin-D (LKKAuto); KKLau; Veron Chen (LKKAuto); Shiau Chan (LKKAuto)
Cc: assignments
Subject: Your surveyor's inspection of GBD4192H; Our claim no.: 512850/IT
Attachments: 20180214123602.pdf

Importance: High

URGENT

Good afternoon Catherine,

We refer to your PRI report dated 22.5.17.

The 3rd party lawyers have submitted their final total repair cost claim and your surveyor had completed a post-repair survey of the subject vehicle. Please see attached self-explanatory letter from the repairer and email below.

Please let us have your final survey report uploaded in the Merimen **asap or within the next 7 days by Tuesday, 27.2.18.**

Best Regards

Irene Tan
Senior Executive, Claims Services (Motor)
Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Anna Tan [mailto:annatan@visionlawllc.com]
Sent: Wednesday, 14 February, 2018 12:32 PM
To: Irene Tan <irene_tan@sg.msig-asia.com>
Subject: YOUR REF: 512850/IT - ACCIDENT INVOLVING GBD 4192 H AND SKK 6152 S ON 27-APR-17

URGENT

Without prejudice
OUR REF: AKN-atv-INS-T140-105419-17

Dear Irene,

Refer to the above matter and your email dated 12 December 2017.

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Koryo Trading Pte Ltd
c/o 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub
Singapore 417921

Date : 11/12/2017
Reference No : CAS/17-12/027

General Information

Registration No. : GBD 4192H
Accident Date : 27/04/2017

Particulars of Damaged Vehicle

Colour	: Silver	Make & Model	: Toyota Hiace
Engine Capacity	: 2982 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 103790	Engine No.	: 1KD2444192
Chassis No.	: JTFHT02P600149962	Steering	: In Order
Registration Date	: 16/10/2014	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195R15	NEXEN	90%
L/H Front Tyre	195R15	NEXEN	90%
R/H Rear Tyre	195R15	MAXTREK	40%
L/H Rear Tyre	195R15	BRIDGESTONE	90%

Inspection

Repairer : Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$20,883.98
Revised Amount : \$14,500.00
Less Excess : -
Nett Total : \$14,500.00

Remarks

- (A) Survey was done on 03/05/2017
- (B) Re-survey was done on 04/05/2017 & 08/05/2017
- (C) Re-survey after repair was done on 09/05/2017
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Text size

Enquire Transfer Fee

Vehicle Details

Vehicle No. : GBD4192H
 Vehicle Type : A50 - Goods (Closed) Van/Van Panel (Delivery)
 Vehicle Attachment 1 : No Attachment
 Vehicle Scheme : Normal
 Vehicle Make : TOYOTA
 Vehicle Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL
 Chassis No : JTFHT02P600149962
 Propellant : Diesel
 Engine No : 1KD2444192
 Engine Capacity : 2982 cc
 Maximum Power Output : -
 Maximum Laden Weight : 2800 kg
 Unladen Weight : 1740 kg
 Year Of Manufacture : 2014
 Original Registration Date : 16 Oct 2014
 Lifespan Expiry Date : 15 Oct 2034
 COE Category : C - Goods Vehicle & Bus
 Quota Premium : \$49,901.00
 COE Expiry Date : 15 Oct 2024
 Road Tax Expiry Date : 15 Oct 2017
 Inspection Due Date : 15 Oct 2017
 Intended Transfer Date : 03 May 2017
 CO2 Emission : 216.00 (g/km)
 CEVS Rebate Utilised Amount : -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00
Total Amount Payable :			11.00

You may print this page for reference.



Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Constant Appraiser Services

Vehicle No : GBD 4192H

Our ref : CAS/17-12/027

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Front bonnet 'logo' emblem	Necessary	72.60	72.60
2	2pcs	Front bonnet rubber guide stopper L/R @ \$43.75	Necessary	87.50	87.50 X NN
3	1pc	Front bumper	Dented/Broken	681.90	681.90
4	2pcs	Front bumper foglamp cover L/R @ \$45.90	N/S Deformed	99.00	45.90
5	1pc	Front bumper lower center grille	Deformed	155.70	155.70 X NN
6	1pc	Front bumper reinforcement	Dented/Bent	381.75	381.75 X R
7	2pcs	Front bumper side retainer L/R @ \$70.00	Necessary LH	140.00	70 140.00
8	1pc	Front bumper top beam	Repair	267.90	-
9	2pcs	Front bumper tow hook cover L/R @ \$43.75	Serviceable	87.50	-
10	1pc	Front corner LH side panel	Dented	195.10	195.10
11	1pc	Front corner LH side panel bracket	Bent	45.70	45.70 X NC
12	3pcs	Front corner LH side panel clips @ \$6.50	Necessary	19.50	19.50
13	1pc	Front grille	Broken	696.80	696.80 X NT
14	1pc	Front grille outer garnish 'lower'	Broken	295.10	295.10 X NT
15	1pc	Front grille outer garnish 'top'	Broken	165.30	165.30 X NT
16	1pc	Front LH door	Dented/Buckled	1,632.50	1,632.50
17	1pc	Front LH door checker	Bent	185.70	185.70
18	1pc	Front LH door front pillar 'inner'	Repair	635.10	-
19	1pc	Front LH door front pillar 'outer'	Dented/Twisted	785.30	785.30 X R
20	1pc	Front LH door glass inner moulding	Necessary	93.30	93.30
21	1pc	Front LH door glass outer moulding	Necessary	172.25	172.25
22	2pcs	Front LH door hinges (top & lower) @ \$90.70	Bent lower	181.40	90.70 181.40
23	1pc	Front LH door inner garnish	Serviceable	131.10	-
24	1pc	Front LH door inner handle	Serviceable	95.30	-
25	1pc	Front LH door inner trim board	Broken	781.10	781.10 X NN
26	1pc	Front LH door lower rubber seal	Necessary	108.60	108.60
27	1pc	Front LH door mechanism lock	Bent/Jammed	554.40	554.40
28	1pc	Front LH door outer key lock	Serviceable	110.95	-
29	1pc	Front LH door outer lock handle	Serviceable	161.60	-
30	1pc	Front LH door outer lock handle cover	Serviceable	35.10	-
31	1pc	Front LH door power window channel bracket	Bent	195.10	195.10 X SUC
32	1pc	Front LH door power window channel bracket weather strip	Necessary	133.20	133.20 X SUC

Constant Appraiser Services

Vehicle No : GBD 4192H

Our ref : CAS/17-12/027

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS (CONT'D)</u>					
33	1pc	Front LH door power window control switch	Damaged	298.00	298.00 XNN
34	1pc	Front LH door power window motor	Damaged	768.80	768.80 XNN
35	1pc	Front LH door power window regulator	Bent	281.75	281.75 XNN
36	2pcs	Front LH door rubber guide stopper @ \$43.75	Necessary	87.50	87.50
37	1pc	Front LH door side mirror	Grazed	450.20	450.20
38	1pc	Front LH door side mirror inner garnish	Serviceable	65.70	-
39	1pc	Front LH door step panel	Dented/Twisted	378.85	378.85
40	1pc	Front LH door step panel garnish	Deformed	74.10	74.10
41	1pc	Front LH door weather strip	Necessary	272.45	272.45
42	1pc	Front LH door wire harness	Serviceable	274.40	-
43	1pc	Front LH headlamp	Broken	781.40	781.40
44	1pc	Front LH headlamp clips	Necessary	6.50	6.50
45	1pc	Front RH ABS sensor	Damaged	372.85	372.85 XNN
46	1pc	Front RH knuckle arm	Bent	430.00	430.00
47	1pc	Front RH lower arm	Bent	350.95	350.95 XNI
48	1pc	Front RH lower ball joint	Bent	372.40	372.40
49	1pc	Front RH power steering rack end	Bent	181.90	181.90
50	1pc	Front RH shock absorber	Bent	283.40	283.40
51	1pc	Front RH stabilizer bar link	Bent	261.10	261.10
52	1pc	Front RH strut bar	Bent	334.50	334.50
53	1pc	Front RH wheel hub bearing	Necessary	485.30	485.30 DM
54	1pc	Front support panel	Repair	981.45	-
55	1pc	Front windscreen moulding	Necessary	172.45	172.45
				17,349.30	14,450.10
Less 25%				(4,337.33)	(3,612.53)
Sub total				13,011.98	10,837.58
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	1set	Front bumper clips - set	Necessary	30.00	30.00
2	1pc	Front bumper number plate	Serviceable	25.00	-
3	1set	Front grille clips - set	Necessary	30.00	30.00 XNI
4	1pc	Front LH door 'company detail' sticker	Necessary	180.00	50.00 20
5	1pc	Front LH door advertisement & art work	Necessary	500.00	300.00 1PC

Constant Appraiser Services

Vehicle No : GBD 4192H

Our ref : CAS/17-12/027

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS (CONT'D)</u>					
6	1set	Front LH door inner trim board clips - set	Necessary	30.00	30.00
7	1pc	Front LH door speaker	Broken	180.00	180.00
8	1pc	Front LH door sun visor	Necessary	180.00	180.00
9	1pc	Front LH headlamp high beam bulb	Broken	40.00	40.00
10	1pc	Front LH headlamp signal bulb	Broken	12.00	12.00
11	1pc	Front RH 15" rim	Dented/Grazed	280.00	280.00
12	1pc	Front RH 195R15 tyre	Cut (90%)	250 380.00	200 342.00
13	1pc	Front windscreen E.R.P bracket	Not Necessary	50.00	-
14	1pc	Front windscreen E.R.P bracket striker	Not Necessary	15.00	-
15	1pc	Front windscreen sealant	Necessary	100.00	100.00
16	1bot	Radiator coolant - bot	Not Necessary	80.00	-
Sub total				15,123.98	12,411.58
<u>LABOUR & MISC. CHARGES</u>					
1		To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)		180.00	140.00
2		To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)		120.00	80.00
3		To remove, reinstall windscreen. (to FR)		150.00	140.00
4		To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion		400.00	300.00
5		To road test driving, check and resetting wheel alignments system		180.00	120.00
6		To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		150.00	100.00
7		To remove, reinstall dashboard fascia, meter reading and etc. (to FR)		400.00	300.00
8		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		1,400.00	1,200.00
9		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		2,700.00	2,200.00

Constant Appraiser Services

Vehicle No : GBD 4192H

Our ref : CAS/17-12/027

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
10		<u>LABOUR & MISC. CHARGES (CONT'D)</u> To apply anti-rust chemical on repaired and replaced panel		80.00	80.00
			Grand total	20,883.98	17,071.58
Recommended cost of lump sum repair (To its pre-accident condition)					14,500.00

60 days

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

- The repairer has agreed to undertake the job at a lump sum of **\$14,500.00** on a contractual basis. Under normal circumstances, the repair period would be about 7 (Seven) working days.

Yours faithfully,
Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Apr 2017		02 May 2017 16:17 Edit Adj Rpt	\$6,700.00 Edit Estimates	\$6,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	FARADIANA BINTE MOHAMED JALAL, ID: S9214404F, Tel: +6585864374, Email: fara.diana@hotmail.com			
Main Claimant:	KORYO TRADING PTE LTD, Co. Reg. No.: 197902267Z			
Vehicle Reg. No.:	GBD4192H	Date of Loss:	27/04/2017 18:00 - :59	
Claim Type:	TP / 512850	Policy/Cover Note No.:	82009069 (Comprehensive) Coverage: 07/11/2016 - 06/11/2017	
Vehicle Reg. No. (Insured):	SKK6152S	Policy No. (Claimant):		
		Excess:		
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 23/02/2018]			
Driver/Custodian (Insured):	FARADIANA BINTE MOHAMED JALAL (24 / Female), NRIC: S9214404F, Tel: +6585864374			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_SG (21/02/2018): Report Send Back Alerts - GBD4192H (TP) MSIG_SG (21/02/2018): Report Send Back Alerts - GBD4192H (TP) 		

ALL ASSOCIATED TASKS <input type="checkbox"/>											View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

Claim Documents

***GBD4192H (512850)**
[SKK6152S]
TP
KORYO TRADING PTE LTD
Apr 27 2017 6:00PM
[FARADIANA BINTE MOHAMED JALAL]
Twincar Automotive Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/17 11:10	Accident Statement From:SC - Reg. No: SKK6152S, Claimant: FARADIANA BINTE MOHAMED JALAL	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/05/17 11:36	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/05/17 11:36	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
4	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
16	13/05/17 11:36	Front View Right	Load JPG	<input checked="" type="checkbox"/>
17	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
18	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
19	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
20	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
21	13/05/17 11:36	General View	Load JPG	<input checked="" type="checkbox"/>
22	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	13/05/17 11:37	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

31	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
34	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
35	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
36	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
37	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
38	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
39	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
42	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
43	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
44	13/05/17 11:37	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
45	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
46	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
47	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
48	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
49	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
50	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
51	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
52	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
53	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
58	13/05/17 11:38	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
59	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
60	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
61	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
62	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
63	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
64	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
65	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
66	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
67	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
68	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
69	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
70	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
71	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
72	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
73	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
74	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
75	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
76	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
77	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
78	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

79	13/05/17 11:39	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/05/17 11:12	TP GBD 4192H GIA RPT From:SC - Reg. No: SKK6152S, Claimant: FARADIANA BINTE MOHAMED JALAL		Load PDF	
2	02/05/17 11:19	EMAIL TO CONDUCT PRE-REPAIR INSPECTION		Load PDF	
3	02/05/17 16:29	PRI email		Load PDF	
4	02/11/17 15:29	CRM 512463		Load HTM	
5	20/02/18 09:21	LOD		Load PDF	
6	20/02/18 09:21	Final Repair Bill, Rental Invoice, Survey fee, LTA Fee		Load PDF	
7	20/02/18 09:21	Survey Report (1)		Load PDF	
8	20/02/18 09:24	Survey Report (2)		Load PDF	
9	20/02/18 09:24	Survey Report (3)		Load PDF	
10	21/02/18 13:28	our instruction to LKK to prepare final survey report		Load PDF	
11	21/02/18 13:29	Post repair survey letter from Twin Car		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 08:22	Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

//

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17008552/CQBE2-1
Date: 26/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. **Policy No:** 82009069
Claimant Vehicle No : GBD4192H **Insured Vehicle No :** SKK6152S
Date of Loss: 27/04/2017 **Nature of Claim:** TP **Claim No:** 512850

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD4192H** **Engine No:** 1KD2444192
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) **Chassis No:** JTFHT02P600149962
Reg. Date: 16/10/2014 (Man. Year: 2014) **Odometer:** 103790 km
Colour: Silver
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195 R15C **Rear Tyre Size:** 195 R15
Front Left Side: Nexen 6 mm **Rear Left Side:** Maxtrek 6 mm
Front Right Side: Nexen 6 mm **Rear Right Side:** Maxtrek 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,123.97	5,745.40	9,378.57	62.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,760.00	2,630.00	3,130.00	54.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,883.97	8,375.40	12,508.57	59.90
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	20,883.97	6,700.00	14,183.97	67.92
+ GST 7.00/7.00% (S\$)	1,461.88	469.00	992.88	67.92
Nett Amount (S\$)	22,345.85	7,169.00	15,176.85	67.92

INSPECTION

Date of Assignment: 02/05/2017
Date Inspected: 03/05/2017 **Inspected At:** TWINCAR AUTOMOTIVE PTE LTD
 2 KAKI BUKIT AVE 2
 #01-17 KAKI BUKIT AUTOHUB
 SINGAPORE 417921
Estimated Period of Repair: 6.0 days

Adjuster: Richard Harjanto**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2018)**Parts:** 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBD4192H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOGO EMBLEM	Necessary	72.60 FL	*72.60 FL
2	2		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Not Necessary	87.50 FL	*- FL
3	1		*FRONT BUMPER	Dented / Broken	681.90 FL	*681.90 FL
4	1		*FRONT BUMPER FOGLAMP COVER L/R	N/S Deformed	99.00 FL	*45.90 FL
5	1		*FRONT BUMPER LOWER CENTER GRILLE	Not Necessary	155.70 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	381.75 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Necessary	140.00 FL	*70.00 FL
8	1		*FRONT BUMPER TOP BEAM	Repair	267.90 FL	*- FL
9	2		*FRONT BUMPER TOW HOOK COVER L/R	Serviceable	87.50 FL	*- FL
10	1		*FRONT CORNER LH SIDE PANEL	Dented	195.10 FL	*195.10 FL
11	1		*FRONT CORNER LH SIDE PANEL BRACKET	Serviceable	45.70 FL	*- FL
12	3		*FRONT CORNER LH SIDE PANEL CLIPS	Necessary	19.50 FL	*19.50 FL
13	1		*FRONT GRILLE	Not Necessary	696.80 FL	*- FL
14	1		*FRONT GRILLE OUTER GARNISH LOWER	Not Necessary	295.10 FL	*- FL
15	1		*FRONT GRILLE OUTER GARNISH TOP	Not Necessary	165.30 FL	*- FL
16	1		*FRONT LH DOOR	Dented / Buckled	1,632.50 FL	*1,632.50 FL
17	1		*FRONT LH DOOR CHECKER	Bent	185.70 FL	*185.70 FL
18	1		*FRONT LH DOOR FRONT PILLAR INNER	Repair	635.10 FL	*- FL
19	1		*FRONT LH DOOR FRONT PILLAR OUTER	Repair	785.30 FL	*- FL
20	1		*FRONT LH DOOR GLASS INNER MOULDING	Necessary	93.30 FL	*93.30 FL
21	1		*FRONT LH DOOR GLASS OUTER MOULDING	Necessary	172.25 FL	*172.25 FL
22	1		*FRONT LH DOOR HINGES (TOP & LOWER)	Lower Bent	181.40 FL	*90.70 FL
23	1		*FRONT LH DOOR INNER GARNISH	Serviceable	131.10 FL	*- FL
24	1		*FRONT LH DOOR INNER HANDLE	Serviceable	95.30 FL	*- FL
25	1		*FRONT LH DOOR INNER TRIM BOARD	Not Necessary	781.10 FL	*- FL
26	1		*FRONT LH DOOR LOWER RUBBER SEAL	Necessary	108.60 FL	*108.60 FL
27	1		*FRONT LH DOOR MECHANISM LOCK	Bent / Jammed	554.40 FL	*554.40 FL
28	1		*FRONT LH DOOR OUTER KEY LOCK	Serviceable	110.95 FL	*- FL
29	1		*FRONT LH DOOR OUTER LOCK HANDLE	Serviceable	161.60 FL	*- FL
30	1		*FRONT LH DOOR OUTER LOCK HANDLE COVER	Serviceable	35.10 FL	*- FL
31	1		*FRONT LH DOOR POWER WINDOW CHANNEL BRACKET	Serviceable	195.10 FL	*- FL
32	1		*FRONT LH DOOR POWER WINDOW CHANNEL BRACKET WEATHER STRIP	Serviceable	133.20 FL	*- FL
33	1		*FRONT LH DOOR POWER WINDOW CONTROL SWICTH	Not Necessary	298.00 FL	*- FL
34	1		*FRONT LH DOOR POWER WINDOW MOTOR	Not Necessary	768.80 FL	*- FL
35	1		*FRONT LH DOOR POWER WINDOW REGULATOR	Not Necessary	281.75 FL	*- FL
36	2		*FRONT LH DOOR RUBBER GUIDE STOPPER	Necessary	87.50 FL	*87.50 FL
37	1		*FRONT LH DOOR SIDE MIRROR	Grazed	450.20 FL	*450.20 FL
38	1		*FRONT LH DOOR SIDE MIRROR INNER GARNISH	Serviceable	65.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*FRPMT LH DOOR STEP PANEL	Dented / Twisted	378.85 FL	*378.85 FL
40	1		*FRONT LH DOOR STEP PANEL GARNISH	Deformed	74.10 FL	*74.10 FL
41	1		*FRONT LH DOOR WEATHERSTRIP	Necessary	272.45 FL	*272.45 FL
42	1		*FRONT LH DOOR WIRE HARNESS	Serviceable	274.40 FL	*- FL
43	1		*FRONT LH HEADLAMP	Broken	781.40 FL	*781.40 FL
44	1		*FRONT LH HEADLAMP CLIPS	Necessary	6.50 FL	*6.50 FL
45	1		*FRONT RH ABS SENSOR	Not Necessary	372.85 FL	*- FL
46	1		*FRONT RH KNUCKLE ARM	Not Necessary	430.00 FL	*- FL
47	1		*FRONT RH LOWER ARM	Not Necessary	350.95 FL	*- FL
48	1		*FRONT RH LOWER BALL JOINT	Not Necessary	372.40 FL	*- FL
49	1		*FRONT RH POWER STEERING RACK END	Not Necessary	181.90 FL	*- FL
50	1		*FRONT RH SHOCK ABSORBER	Not Necessary	283.40 FL	*- FL
51	1		*FRONT RH STABILIZER BAR LINK	Not Necessary	261.10 FL	*- FL
52	1		*FRONT RH STRUT BAR	Not Necessary	334.50 FL	*- FL
53	1		*FRONT RH WHEEL HUB BEARING	Damaged	485.30 FL	*485.30 FL
54	1		*FRONT SUPPORT PANEL	Repair	981.45 FL	*- FL
55	1		*FRONT WINDSCREEN MOULDING	Necessary	172.45 FL	*172.45 FL
56	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
57	1		*FRONT BUMPER NUMBER PLATE	Serviceable	25.00 FS	*- FS
58	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
59	1		*FRONT LH DOOR COMPANY DETAIL STICKER	Necessary	180.00 FS	*20.00 FS
60	1		*FRONT LH DOOR ADVERTISEMENT & ART WORK	Necessary	500.00 FS	*180.00 FS
61	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
62	1		*FRONT LH DOOR SPEAKER	Broken	180.00 FS	*180.00 FS
63	1		*FRONT LH DOOR SUN VISOR	Necessary	180.00 FS	*80.00 FS
64	1		*FRONT LH HEADLAMP HIGH BEAM BULB	Broken	40.00 FS	*40.00 FS
65	1		*FRONT LH HEADLAMP SIGNAL BULB	Broken	12.00 FS	*12.00 FS
66	1		*FRONT RH 15 RIM	Repair	280.00 FS	*- FS
67	1		*FRONT RH 195R15 TYRE	Cut	380.00 FS	*200.00 FS
68	1		*FRONT WINDSCREEN E.R.P BRACKET	Not Necessary	50.00 FS	*- FS
69	1		*FRONT WINDSCREEN E.R.P BRACKET STRIKER	Not Necessary	15.00 FS	*- FS
70	1		*FRONT WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
71	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,461.30	7,403.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,337.33	1,657.80
Total Parts (\$\$)	15,123.97	5,745.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL AIR CON PARTS, VACUUMS, REFILL AIR CON GAS (TO FR)	New	180.00	0.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING . (TO FR)	New	120.00	30.00
3	TO REMOVE, REINSTALL WINDSCREEN (TO FR)	New	150.00	0.00
4	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	400.00	120.00
5	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	180.00	60.00
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	150.00	60.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	900.00
8	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,700.00	1,200.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
10	TO REMOVE, REINSTALL DASHBOARD FASCIA, METER READING AND ETC (TO FR)	New	400.00	200.00
Gross Labour Cost (\$\$)			5,760.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >