









SERVICE REQUESTS    MESSAGES    CLAIMS

|                                  |    | PART NAME | PART NUMBER             | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE    | DEPR/ BTR% | DISC COUNT      | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE |
|----------------------------------|----|-----------|-------------------------|------------------------|-------------|---------------|------------|-----------------|-----------|-----------------|----------------|--------|
| REAR BUMPER SIDE RETAINERS (N/S) |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 15 | 1         |                         |                        | Damaged     | 95            |            | 20              |           | 22.8            | Reviewing      |        |
| SET REAR BUMPER CLIPS            |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 16 | 1         |                         |                        | Necessary   | 40            |            | 20              |           | 32              | Reviewing      |        |
| REAR BUMPER BEAM                 |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 17 | 1         |                         |                        | Serviceable | 0             |            | 20              |           | 0               | Reviewing      |        |
| REAR AIR VENT N/S                |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 18 | 1         |                         |                        | Serviceable | 0             |            | 20              |           | 0               | Reviewing      |        |
| REAR END PANEL                   |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 19 | 1         |                         |                        | Repair      | 0             |            | 20              |           | 0               | Reviewing      |        |
| REAR END PANEL TOP GARNISH       |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 20 | 1         |                         |                        | Serviceable | 0             |            | 20              |           | 0               | Reviewing      |        |
| REAR FENDER N/S                  |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 21 | 1         |                         |                        | Bent        | 975           |            | 20              |           | 780             | Reviewing      |        |
| REAR FENDER QUARTER GLASS N/S    |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 22 | 1         |                         |                        | Necessary   | 465.3         |            | 20              |           | 372.24          | Reviewing      |        |
| REAR FENDER INNER TRIM           |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 23 | 1         |                         |                        | Serviceable | 0             |            | 20              |           | 0               | Reviewing      |        |
| REAR WINDSCREEN MOULDING         |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 24 | 1         |                         |                        | Necessary   | 82.3          |            | 20              |           | 65.84           | Reviewing      |        |
| REAR SHOCK ABSORBER N/S          |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 25 | 1         |                         |                        | Serviceable | 0             |            | 20              |           | 0               | Reviewing      |        |
| REAR TRAILING ARM N/S            |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 26 | 1         |                         |                        | Serviceable | 0             |            | 20              |           | 0               | Reviewing      |        |
| REAR WHEEL HUB N/S               |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
|                                  | 27 | 1         |                         |                        | Serviceable | 0             |            | 20              |           | 0               | Reviewing      |        |
| Labour                           |    |           |                         |                        |             |               |            |                 |           |                 |                |        |
| EDIT                             |    | SIR NO    | REPAIR/REPLACE (LABOUR) | PART NAME              | LABOUR RER  | LABOUR REPAIR | PAINT      | ACTION (LABOUR) | COMMENT   | REMOVE          |                |        |
|                                  |    | 1         |                         | TO CHECK WIRING.       | 30          | 0             | 0          | Reviewing       |           |                 |                |        |



ASSESSMENT INFORMATION

0

Claim Portal

CATEGORY

License Expiration Date

mm/dd/yyyy

END INFORMATION

POST SURVEY INFORMATION

Address

Singapore

Address type

Personal Correspondence

Gender

Female

Marital status

Unknown

Identification #

S1711870F



|                                                                                                                        | TYPE                       | SUB-TYPE                 | AUTHOR                            | DATE UPLOADED     |
|------------------------------------------------------------------------------------------------------------------------|----------------------------|--------------------------|-----------------------------------|-------------------|
|  Immediate Advice- SLM 7775R.pdf    | Reports & Statement        | Others                   | LKK AUTO CONSULTANTS PTE LTD (TP) | October 17, 2018  |
|  LETTER TO OI.pdf                   | Letters and Correspondence | Policy Holders / Insured | LKK AUTO CONSULTANTS PTE LTD (TP) | May 18, 2018      |
|  GIA SEARCH.pdf                     | Forms / Claim Documents    | Others                   | LKK AUTO CONSULTANTS PTE LTD (TP) | May 18, 2018      |
|  RENTAL RECEIPT.pdf                 | Invoice                    | Other Service            | LKK AUTO CONSULTANTS PTE LTD (TP) | May 18, 2018      |
|  Preliminary Advice.pdf             | Reports & Statement        | Others                   | LKK AUTO CONSULTANTS PTE LTD (TP) | March 28, 2018    |
|  TP GIA Report (SLM7775R).pdf       | Reports & Statement        | GIA Report               | LKK AUTO CONSULTANTS PTE LTD (TP) | March 28, 2018    |
|  TP ESTIMATE + TP GIA REPORT.pdf    | Reports & Statement        | Estimate / Quotation     | LKK AUTO CONSULTANTS PTE LTD (TP) | March 28, 2018    |
|  TP ESTIMATE - MARKED.pdf          | Reports & Statement        | GIA Report               | LKK AUTO CONSULTANTS PTE LTD (TP) | March 28, 2018    |
|  EMAIL TO WORKSHOP.pdf            | Other                      | Other                    | DHIWAR Namrata                    | February 21, 2018 |
|  EMAIL RECEIVED FROM WORKSHOP.msg | Other                      | Other                    | DHIWAR Namrata                    | February 21, 2018 |