

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18003372/M1EA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MC0M0015
Claimant		
Vehicle No : GV5985B	Insured Vehicle No :	SHC2193C
Date of Loss: 18/02/2018	Nature of Claim: TP	Claim No: MCT18020549

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GV5985B	Engine No:	4JG2880241
Make & Model:	ISUZU TFS69H-29(T), 3.1 D (M)	Chassis No:	JAATFS69H27102351
Reg. Date:	23/08/2002 (Man. Year: 2002)	Odometer:	307794 km
Colour:	Black		
Engine Capacity:	3059 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	10.50 R15	Rear Tyre Size:	10.50 R15
Front Left Side:	Silverstone 5 mm	Rear Left Side:	Silverstone 7 mm
Front Right Side:	Silverstone 5 mm	Rear Right Side:	Silverstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,561.25	4,561.25	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,730.00	180.00	9.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,471.25	6,291.25	180.00	2.78
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	6,471.25	5,650.00	821.25	12.69
+ GST 7.00/7.00% (S\$)	452.99	395.50	57.49	12.69
Nett Amount (S\$)	6,924.24	6,045.50	878.74	12.69
+ Loss of Use (15.0 x S\$80.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,252.95		

INSPECTION

Date of Assignment: 21/02/2018

Date Inspected: 22/02/2018 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd
(Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 12.0 days

Adjuster: MA CHIN FOOK**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE : \$10,000

LTA REBATE : \$614

NETT VALUE : \$9,386

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Apr 2020)	
Parts:	N/A	ISUZU TFS69H-29(T) 3.1 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GV5985B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	600.00 FL	*600.00 FL
2	1		*FRONT BUMPER BEAM LH	Bent	200.00 FL	*200.00 FL
3	1		*FRONT BUMPER BEAM RH	Bent	200.00 FL	*200.00 FL
4	1		*FRONT BUMPER BRACKET LH	Bent	90.00 FL	*90.00 FL
5	1		*FRONT BUMPER BRACKET RH	Bent	90.00 FL	*90.00 FL
6	1		*FRONT BUMPER SIGNAL LAMP	Cracked	90.00 FL	*90.00 FL
7	1		*FRONT BUMPER RETAINER LH	Distorted	35.00 FL	*35.00 FL
8	1		*FRONT BUMPER RETAINER RH	Distorted	35.00 FL	*35.00 FL
9	1		*FRONT BUMPER RETAINER ,CENTRE	Bent	45.00 FL	*45.00 FL
10	1		*RADIOATOR GRILLE	Missing	720.00 FL	*720.00 FL
11	1		*RADIOATOR GRILLE LOGO	Missing	90.00 FL	*90.00 FL
12	1		*FRONT HEADLAMP WITH BRACKET LH	Bent	250.00 FL	*250.00 FL
13	1		*FRONT HEADLAMP WITH BRACKET RH	Bent	250.00 FL	*250.00 FL
14	1		*FRONT SIDE LAMP LH	Cracked	90.00 FL	*90.00 FL
15	1		*FRONT SIDE LAMP RH	Cracked	90.00 FL	*90.00 FL
16	1		*AIR CON CONDENSER	Bent	200.00 FL	*200.00 FL
17	1		*FRONT BRACE PANEL	Bent	50.00 FL	*50.00 FL
18	1		*RADIATOR	Bent	1,150.00 FL	*1,150.00 FL
19	1		*RADIATOR FAN CLUTCH	Necessary	400.00 FL	*400.00 FL
20	1		*RADIATOR FAN BLADE	Cracked	35.00 FL	*35.00 FL
21	3		*RADIATOR FAN CLUTCH SILICON	Necessary	15.00 FL	*15.00 FL
22	1		*FRONT SUPPORT PANEL	Bent	600.00 FL	*600.00 FL
23	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,360.00	5,360.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	798.75	798.75
Total Parts (\$\$)	4,561.25	4,561.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	180.00	120.00
2	TO DISMANTLE +RENEW AIR CON CONDENSER AND REFILL GAS	New	120.00	100.00
3	TO DISMANTLE +RENEW RADIATOR FAN CLUTCH + BLADE,ETC	New	60.00	60.00
4	TO STRAIGHTEN FRONT BODY INCLUDING CUTTING AND WELDING ,TO KNOCK DENTS ON FRONT FENDER RH AND RENEW OF PARTS	New	700.00	650.00
5	TO SPRAY PAINT	New	600.00	550.00
6	TO KNOCK DENTS ON FRONT CHASSIS PANEL RH	New	250.00	250.00
Gross Labour Cost (\$)			1,910.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >