



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 481E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	880.00	880.00
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER -LH & RH	NOT NECESSARY	49.00	-
1	REAR SIDE BUMPER -RH	DEFORMED	195.00	195.00
1	REAR BUMPER REFLECTOR -RH	NOT NECESSARY	95.00	-
1	TAILLAMP -RH	NOT NECESSARY	460.60	-
1	REAR FENDER ARC GARNISH -RH	DEFORMED	165.90	165.90
1	SET REAR FENDER ARC GARNISH CLIPS	NECESSARY	20.00	20.00
	LESS 20% DISCOUNT		-379.10	-258.18
			1,516.40	1,032.72
	<u>LABOUR</u>			
	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS.		400.00	250.00
	TO PUTTY & SPRAY UP PAINT WORKS.		300.00	150.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
			850.00	480.00
	GRAND TOTAL		2,366.40	1,512.72
	RECOMMENDED COST OF REPAIRS			1,512.72

Report Ref No. CC4/DAI18003381/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.