

ASSIGNMENT (Office)

From (Person): Lionel Tan

of MS16

Date/Time: 20/Feb/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 6975 L

Insured: SJN 3081 D

at Workshop m/s cheng Hoe Motor Pte Ltd (AMK)

Tel: 6481 2001

of 10 Ang Mo Kio Ind Park 2A #01-04

Policy No: 29068594 QMX

Claim No: 55 0012

Sum Insured:

Excess: \$ 500/-

Make of Veh:
(Client's Record)

D.O.A. 13/2/18 21:00

CA / REV / REP. / REV 24 HRS

lwp?

Date/Time: 16:14 on 21/2/18

Person Contacted: Dunlyn

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction
	<u>SLM 6975 L-x</u>
	<u>SJN 3081 D-x</u>
<u>13/3/18</u>	<u>Rece file from assignment Team</u>
<u>13/3/18</u>	<u>Send preli revised by merimen</u>
<u>5/4/18</u>	<u>Final fig \$ 3419.98 (Red 818.48, 1990) Confirmed with Effield</u>
<u>@ 1129 am</u>	

ASS. REC. BY:

REF: *ms61*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

4-5 days

Res.: Yes or No

Lum Sum: _____

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *S2M 6975L*Yr Regn: *04, 17*Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: *Honda Vezel*c.c. *1496*Colour: *M. Red*

A/C: _____

Insured / Std / NI / NA

Sp. Reading: *16790*

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: *BUI*

1207198

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

*215/60R16*BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. *8*

mm

R/Bal. *8*

mm

L/Bal. *8*

mm

L/Bal. *8*

mm

D.O.A. *13/2/18*D.O.I. *5/3/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*13 Rm pass to Catherine, est not ready**5/4/18*

RECEIVED 06 APR 2018

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

slu-typist

Report Format: _____

merimen

Lump Sum / I.B.I. (\$) _____

*3419.96*Days Of Repair: *5*Resurvey No. of Trip: *1*Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL

*200**10**210*

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/800 3409/Kvel3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 5/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003409/Kvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 3081D	Veh. Inspected	SLM 6975L
Policy No.	29068594QMX	Coverage (\$)	0.00
Claim No.	550012	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/02/2018	Inspection Date
Survey held at	CHENG HOE MOTOR SERVICE 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018		20 Feb 2018 14:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM HAO, ID: S8631870I		
Main Claimant:	LOW FATT CHYE (LUI FAZAI), ID: S7218884E		
Vehicle Reg. No.:	SLM6975L	Date of Loss:	13/02/2018 21:00 - :59
Claim Type:	TP / 550012	Policy/Cover Note No.:	29068594QMX (Comprehensive) Coverage: 15/01/2018 - 10/02/2019
Vehicle Reg. No. (Insured):	SJN3081D	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/02/2018]		
Driver/Custodian (Insured):	LIM HAO (31 / Male), NRIC: S8631870I		
Adj Asg. Remarks:	Please contact MS DORLYN LI @ 6481 2001 to arrange for survey.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Lionel Tan Tian Pei	Date: 13 Mar 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SJN3081D	Accident Date	: 13/02/2018
TP Vehicle No	: SLM6975L	Assignment Date	: 20/02/2018
Make	: HONDA VEZEL	Est. Duration of Repair	: 5.00
Date of Inspection	: 05/03/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,238.44
Revised Amount	:S\$	3,419.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,419.96
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8884E
Vehicle Details	
Vehicle No.:	SLM6975L
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B4407191
Chassis No.:	RU11207194
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,322.00
Original Registration Date:	07 Apr 2017
First Registration Date:	07 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$13,251.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2027
PARF Rebate Amount:	\$9,938.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$41,412.00
Total Rebate Amount:	\$51,350.00

The information contained herein is correct as at 14 Feb 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO.201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES1890213/AMK

Date: 02 Mar 2018

Policy No: D17MTPV01005523

Veh Reg No: SLM6975L

Make/Model: HONDA VEZEL 1.5X
 CVT A

Chassis No: RU11207194

Engine No: L15B4407191

Reg. Date: 07/04/2017

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 13/02/2018

TP Veh Reg No: SJN3081D

Estimate Repair Cost to Vehicle No :SLM6975L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	762.70	1 PC	762.70	—
2 REAR BUMPER CLIP	3.90	4 PC	15.60	—
3 REAR TAILGATE	1,100.90	1 PC	1,100.90	—
4 TAILGATE INNER RUBBER	98.50	1 PC	98.50	—
5 TAILGATE EMBLEM 'VEZEL'	39.80	1 PC	39.80	—
6 TAILGATE WINDSCREEN GLASS MOULDING	158.10	1 PC	158.10	—
7 REAR END PANEL	415.60	1 PC	415.60	X
8 REAR END PANEL INNER TOP GARNISH	92.80	1 PC	92.80	—
9 REAR END PANEL OUTER BUZZER SENSOR	95.00	1 PC	95.00	X
10 TOOL SPONGE	225.30	1 PC	225.30	—
			3,004.30	
		Less 20%	600.86	2,403.44
Special Net				
11 REAR NUMBER PLATE	35.00	1 PC	35.00	—
12 REVERSE SENSOR	200.00	1 SET	200.00	—
13 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	—
			275.00	275.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.0000	1 LA	120.00	—
15 REMOVE & REFIX REAR BUMPER, SIDE BUMPERS, TAILGATE, SPOILER & ATTACHMENTS, TAIL LAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	700.0000	1 LA	700.00	950
16 PUTTY & RESPRAY REAR SIDE BUMPERS, TAILGATE, NUMBER PLATE LAMP GARNISH, REAR END PANEL & ALL AFFECTED AREAS	600.0000	1 LA	600.00	500
17 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	80.0000	1 PC	80.00	50
18 RUSTPROOFING	60.0000	1 LA	60.00	30
			1,560.00	1,560.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO.201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 13/02/2018
TP Veh Reg No: SJN3081D

Estimate No: ES1890213/AMK
Date: 02 Mar 2018
Policy No: D17MTPV01005523
Veh Reg No: SLM6975L
Make/Model: HONDA VEZEL 1.5X
CVT A
Chassis No: RU11207194
Engine No: L15B4407191
Reg. Date: 07/04/2017

Estimate Repair Cost to Vehicle No :SLM6975L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 4,238.44
			Add GST @ 7%	296.69
			Total Amount Payable	SS 4,535.13

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003409/KVD3N2

Date: 06/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29068594QMX
Claimant Vehicle No :	SLM6975L	Insured Vehicle No :	SJN3081D
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	550012

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6975L	Engine No:	L15B4407191
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11207194
Reg. Date:	07/04/2017 (Man. Year: 2016)	Odometer:	16790 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,678.44	2,269.96	408.48	15.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,150.00	410.00	26.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,238.44	3,419.96	818.48	19.31
+ GST 7.00/7.00% (S\$)	296.69	239.40	57.29	19.31
Nett Amount (S\$)	4,535.13	3,659.36	875.77	19.31

INSPECTION

Date of Assignment:	20/02/2018	
Date Inspected:	05/03/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM6975L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	762.70 FL	*762.70 FL
2	4		*REAR BUMPER CLIP	Necessary	15.60 FL	*15.60 FL
3	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
4	1		*TAILGATE INNER RUBBER	Cut	98.50 FL	*98.50 FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	39.80 FL	*39.80 FL
6	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	158.10 FL	*158.10 FL
7	1		*REAR END PANEL	Repair	415.60 FL	*- FL
8	1		*REAR END PANEL INNER TOP GARNISH	Mtg Distorted	92.80 FL	*92.80 FL
9	1		*REAR END PANEL OUTER BUZZER SENSOR	Serviceable	95.00 FL	*- FL
10	1		*TOOL SPONGE	Cracked	225.30 FL	*225.30 FL
11	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
12	1		*SET REVERSE SENSOR	Shorted/Dented	200.00 FS	*200.00 FS
13	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
					Sub Total (\$\$)	3,279.30 2,768.70
					- List Item Discount on L Items 20.00/20.00% (\$\$)	600.86 498.74
					Total Parts (\$\$)	2,678.44 2,269.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER,SIDE BUMPERS,TAILGATE,SPOILER & ATTACHMENTS,TAILLAMPS,TO CUT,WELD & RENEW REAR END PANEL;KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	New	700.00	450.00
3	PUTTY & RESPRAY REAR SIDE BUMPERS,TAILGATE,NUMBER PLATE LAMP GARNISH,REAR END PANEL & ALL AFFECTED AREAS	New	600.00	500.00
4	REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	New	80.00	50.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (S\$)			1,560.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >