

12/03/2002

ASS. REC. BY:

REF: CS/FCI18003451/Aqd3ⁿ²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

CWS

From (Person):

May Chuen

of

FCI

Date/Time: 2/2/18 @ 12:25pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 3566S

Insured:

SHD 4800R

at Workshop m/s

Reliable Carz

Tel:

81669797

of

8 Keki Bkt Ave 4 #05-50

Policy No:

Claim No:

D18001494MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time: 11:51am @ 22/2/18

Person Contacted:

jason

Vehicle IN (OUT)

Date/Time

Action/Instruction

(✓)

Estimate

SLT 3566S - NA / INC18003220 / r3

D.O.A: 17/2/18

SHD 4800R - NA / INC18003220 / r3

D.O.A: 17/2/18

02/3/18 @ 1:44pm informed May Chuen, we are pending estimate from repairer.

03/4/18 @ 4:24pm revised to May Chuen by email.

Final tag @ 3211.68, 4 days. (Red \$4171.92, 57%)

Signature

Adrian

REF:

FCL

ASSIGNMENT

From:

Date:

27/02/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLT 3566S

at Workshop m/s:

Reliable Carz

of:

8 Kaki Bukit Ave 4 #05-50

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

After 12pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLT3566S

Yr Regn:

2007 oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle Hybrid 1496

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

41436

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP71120736

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60 R15

R:

185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

27/02/18

Survey held at:

Reliable

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 04 APR 2018

Date/Time File Pass to?

☐

Preli. Report

10/3/4 tyris

☐

Final Report

Date/Time File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

)) 3 + RS 5

) Photo

) Others

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Invs \$

☐

Weekend \$

Report Format:

7P

Lump Sum / I.B.I. (\$) :

3211.68

150

50

50

23

233



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003451/Aqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4800R	Veh. Inspected	SLT 3566S
Policy No.		Coverage (\$)	0.00
Claim No.	D18001494MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	23/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/02/2018	Inspection Date	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001494MFSH

Date: 03 April 2018

Our Ref: CS/FCI18003451/Aqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 3566S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/02/2018 at the premises of M/s RELIABLE CARZ, and have the following to report:-

Workshop Estimate Amount	: S\$ 7,383.60 .
Revised Estimate Amount	: S\$ 3,211.68 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	20-02-2018	Our Ref No. D18001494MFSH
Accident Date	17-02-2018	Claim Type. Third Party
Insured Vehicle	SHD4800R	Third Party Vehicle. SLT3566S
Survey Location	8 KAKI BUKIT AVENUE 4#05-50	
Contact Person.	JASON LEE	
Contact No.	0/ 81669797	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RELIABLE CARZ PTE LTD	Attention. NIL
Cc : TP Solicitor	CROSSBORDERS LLC	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235176)



PRI Documents



Close



PRI Header Details

Claim No	D18001494MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CROSSBO
Workshop Name	RELIABLE CARZ PTE LTD (Contact Person : JASON LEE)	Survey Location & Contact Details	8 KAKI BUKIT AVENUE 4#05-50 Mobile: 81669797 , Phone: 0 , Fax: 0 EmailId: HUITING@CROSSBORDERSLLC.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4800R	TP Vehicle No	SLT3566S
PRI Recieved Date	20-02-2018 10:00:45 PM	Surveyor Appointed Date	21-02-2018 12:24:27 PM	Surveyor Accept Date	23-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-02-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--------------------------------------------

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 3 April 2018 4:24 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001494MFSH/1
Attachments: CSFCI18003451Aqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SLT 3566S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 2 March 2018 1:44 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001494MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SLT 3566S on 27/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 22 February 2018 4:42 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001494MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 2 March 2018 1:44 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001494MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SLT 3566S on 27/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 22 February 2018 4:42 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001494MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 21 February 2018 12:25 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001494MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1627542E



PATRICK ANG KIAN PING

洪建平

Race
CHINESE

Date of birth
29-08-1964

Country/Place of birth
SINGAPORE

Sex
M

REPUBLIC OF SINGAPORE DRIVING LICENCE

S1627542E



PATRICK ANG KIAN PING

Birth Date 29 Aug 1964

Issue Date 16 Dec 2002



5185855



NRIC No. S1627542E



Date of issue
25-06-2013

APT BLK 254 ANG MO KIO AVENUE 4 #03-145
SINGAPORE 560254

NRIC No: S1627542E

Date: 24/08/2017

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

PASS DATE
21 Jul 1982



18A

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5095300089

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle

: SLT35665

Chassis Number

: GP71120736

2. Name of Policyholder

: RELIABLE RIDES PTE LTD

3. Effective Date of Insurance

: 26 Oct 2017

4. Expiry Date of Insurance

: 25 Oct 2018

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use for the carriage of goods (other than samples) in connection with any trade or business.

(c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)

: S\$1,000

EXCESS (SECTION 2)

: S\$1,500

WINDSCREEN EXCESS

: S\$100

ADDITIONAL EXCESS

: N/A

UNNAMED DRIVER EXCESS

: PLEASE REFER OVERLEAF

REPAIR AT OWNER'S PREFERRED WORKSHOP

: NO

INSURE WITH COE

: YES

NCD PROTECTION

: NO

TRANSPORT ALLOWANCE

: NO

EXCESS WAIVER

: NO

PRIMARY DRIVER

: N/A

NAMED DRIVER (1)

: N/A

NAMED DRIVER (2)

: N/A

HIRE PURCHASE COMPANY

: LAKE-VIEW CREDIT PTE LTD

SUM INSURED

: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TAN INSURANCE BROKERS PTE LTD (00000690287)

Date of Issue : 24 Oct 2017 11:24 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875
Contact No.: +65 8166 9797 Fax No.: +65 6385 1751

Vehicle No.: SLT 3566S

Model: HONDA SHUTTLE

GP71120736

TP 1st Cap
Xiao Chun

QTY DESCRIPTION

List Items:

- | | |
|---|------------------------------------------------|
| 1 | Front bumper <i>Debonded</i> |
| 1 | Front bumper lower grille <i>me in</i> |
| 1 | Front bumper fog lamp cover LH <i>Debonded</i> |
| 1 | Head lamp LH <i>at</i> |
| 1 | Head lamp panel LH <i>Repair</i> |
| 1 | Front fender LH <i>Repair</i> |
| 1 | Front fender liner LH <i>me in</i> |
| 1 | Front fender emblem LH <i>me in</i> |
| 1 | Head lamp lower bracket LH <i>me in</i> |
| 1 | Front bumper reinforcement <i>get</i> |
| 1 | Front grille <i>me in</i> |
| 1 | Front grille chrome moulding <i>me in</i> |
| 1 | Head lamp chrome moulding (top) <i>me in</i> |
| 1 | Front bumper lower moulding <i>me in</i> |

AMOUNT (S\$)

1380
1740.00 ✓
132.30 +.
111.40 ✓
987.40 ✓
897.30 +.
685.60 x
193.40 x
92.40 ✓
88.30 +
493.40 ✓
545.30 +
382.40 +
285.40 +
182.40 +

3064.60

2451.68

Less 20 % (1363.40)
Subtotal 5453.60

Special Nett Items:

- Front bumper clip (1 set) *me in*
Front fender liner clip (1 set) *me in*

30

80.00 - 30
50.00 +.
Subtotal 130.00

Labour Charges:

- To check wiring system
To apply undercoating on affected area
To remove and replace above parts
To spray painting on affected area

730

80.00 - 30
120.00 x
800.00 - 300
800.00 - 400
Subtotal 1800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

7383.60

Adrian Ling
P/P # 27/02/18
04 days
total 3211.68
(P/P)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003451/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4800R	Veh. Inspected	SLT 3566S	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001494MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	21/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GP71120736	Colour	BLACK	
Odometer	41436	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/02/2018	Inspection Date	27/02/2018	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3566S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,740.00	1,380.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	132.30	-
1	FRONT BUMPER FOG LAMP COVER LH	DEFORMED	111.40	111.40
1	HEAD LAMP LH	CUT	987.40	987.40
1	HEAD LAMP PANEL LH	TO REPAIR SEE LABOUR	897.30	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	685.60	-
1	FRONT FENDER LINER LH	NOT NECESSARY	193.40	-
1	FRONT FENDER EMBLEM LH	NECESSARY	92.40	92.40
1	HEAD LAMP LOWER BRACKET LH	NOT NECESSARY	88.30	-
1	FRONT BUMPER REINFORCEMENT	BENT	493.40	493.40
1	FRONT GRILLE	NOT NECESSARY	545.30	-
1	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	382.40	-
1	HEAD LAMP CHROME MOULDING (TOP)	NOT NECESSARY	285.40	-
1	FRONT BUMPER LOWER MOULDING	NOT NECESSARY	182.40	-
	LESS 20% DISCOUNT		-1,363.40	-612.92
			5,453.60	2,451.68
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	50.00	-
			130.00	30.00
LABOUR				
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO APPLY UNDERCOATING ON AFFECTED AREA.	NOT NECESSARY	120.00	-
	TO REMOVE AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF HEAD LAMP PANEL LH AND FRONT FENDER LH.		800.00	300.00
	TO SPRAY PAINTING ON AFFECTED AREA.		800.00	400.00
			1,800.00	730.00
GRAND TOTAL			7,383.60	3,211.68

Report Ref No. CS/FCI18003451/Aqd3n2



RECOMMENDED COST OF REPAIRS			3,211.68
-----------------------------	--	--	----------

Report Ref No. CS/FCI18003451/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.