

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003501/T1VD3E2
Date: 26/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No : SLJ7858B	Insured Vehicle No :	SDQ7647B
Date of Loss: 02/02/2018	Nature of Claim:	TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ7858B		
Make & Model:	TOYOTA COROLLA, AXIO 1.5 X (A)	Engine No:	2NR8481876
Reg. Date:	27/12/2016 (Man. Year: 2015)	Chassis No:	NRE1610005514
Colour:	Black	Odometer:	20471 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,670.25	270.25	1,400.00	83.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	700.00	2,500.00	78.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,870.25	970.25	3,900.00	80.08
+ GST 7.00/7.00% (S\$)	340.92	67.92	273.00	80.08
Nett Amount (S\$)	5,211.17	1,038.17	4,173.00	80.08

INSPECTION

Date of Assignment:	23/02/2018 Present Location:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected:	23/02/2018 Inspected At:	No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2018)
Parts: 143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLJ7858B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper (WCP)	Deformed	220.00 F	*220.00 F
2	10		*Rear bumper clips (WCP)	Necessary	15.00 F	*15.00 F
3	2		*Rear bumper retainer outer LH/RH (WCP)	Not Necessary	70.00 F	*- F
4	2		*Rear bumper retainer inner LH/RH (WCP)	Not Necessary	70.00 F	*- F
5	2		*Rear bumper reflector lamp LH/RH (WCP)	Not Necessary	50.00 F	*- F
6	1		*End panel (WCP)	Repair	230.00 F	*- F
7	1		*End panel garnish (WCP)	Not Necessary	100.00 F	*- F
8	1		*Reverse sensor	Not Necessary	250.00 FS	*- FS
9	2		*Taillamp LH/RH (WCP)	Not Necessary	400.00 F	*- F
10	1		*Bootlid weatherstripe (WCP)	Not Necessary	80.00 F	*- F
11	1		*Bootlid (WCP)	Not Necessary	-	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,485.00	235.00
+ Margin on L,N Items 15.00/15.00% (S\$)	185.25	35.25
Total Parts (S\$)	1,670.25	270.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	1,200.00	300.00
2	Putty, blend and paint affected area	New	1,200.00	300.00
3	Check Wiring, re-align and ensure proper function	New	80.00	30.00
4	Remove & reinstall bumper sensors	New	120.00	30.00
5	Cavity Treatment on New Parts	New	100.00	0.00
6	Remove & reinstall Rear reverse camera	New	120.00	0.00
7	Remove and refix bootlid lock & mechanism to facilitate repair	New	150.00	0.00
8	Conduct water seepage test	New	80.00	0.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	150.00	40.00
Gross Labour Cost (\$\$)			3,200.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >