

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Christina Wong	Date:	27 Feb 2018
<b><u>Preliminary Advice</u></b>			

Insured Vehicle No	: SDQ7647B	Accident Date	: 02/02/2018
TP Vehicle No	: SLJ7858B	Assignment Date	: 23/02/2018
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 3.00
Date of Inspection	: 23/02/2018		
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

<b><u>Point of Impact / General Description of Damages</u></b>			
The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.			
	Repairer's Estimate (Gross)	:S\$	4,870.25
	Revised Amount	:S\$	970.25
	Check Items (Estimated)	:S\$	250.00
	Total	:S\$	1,220.25
	Lump Sum Repair	:S\$	
<b><u>Total Loss Consideration</u></b>			
	New for Old Value	:S\$	
	Pre-Accident Value	:S\$	
	COE / PARF Rebate	:S\$	
	Salvage Value	:S\$	
	Margin for Repair	:S\$	

<b><u>Remarks</u></b>	
<input type="checkbox"/>	The vehicle is economical/not economical for repair.
<input checked="" type="checkbox"/>	The above survey was conducted on a 'without prejudice' basis.