

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18003526/GEA3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994850

Claimant
Vehicle No : SLB9212T **Insured Vehicle No :** SLS2167Y

Date of Loss: 20/02/2018 Nature of Claim: TP Claim No: 1740896522SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB9212T		
Make & Model:	NISSAN NOTE, 1.2 DIG-S CVT (A)	Engine No:	HR12183822B
Reg. Date:	27/04/2016 (Man. Year: 2016)	Chassis No:	JN1TBAE12Z0982436
Colour:	Blue	Odometer:	6129 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,435.00	5,401.50	12,033.50	69.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	2,070.00	1,990.00	49.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	21,495.00	7,471.50	14,023.50	65.24
+ GST 7.00/7.00% (\$\$)	1,504.65	523.01	981.64	65.24
Nett Amount (\$\$)	22,999.65	7,994.51	15,005.14	65.24
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 22/02/2018

Date Inspected: 23/02/2018 Inspected At:

Jack Cars Enterprise Pte Ltd - Ubi
(HQ)
BLK 3007 UBI ROAD 1 #01-450
Singapore 408701

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	756.00 F	*673.00 FL
2	1		*FRONT BUMPER BRACKET -LEFT	Deformed	108.00 F	*22.00 FL
3	1		*BONNET	Bent	1,235.00 F	*750.00 FL
4	1		*BONNET HINGE -LEFT & RIGHT	Bent	216.00 F	*136.00 FL
5	1		*HEADLAMP LOWER BRACKET -LEFT	Not Necessary	220.00 F	*- FL
6	1		*FRONT LEFT FENDER	Buckled	845.00 F	*538.10 FL
7	1		*FRONT LEFT MUDGUARD	Deformed	144.00 F	*68.60 FL
8	1		*LEFT SIDESKIRT	Cut	504.00 F	*504.00 FL
9	1		*FRONT BUMPER GRILLE	Not Necessary	396.00 F	*- FN
10	1		*FRONT BUMPER GRILLE CHROME GARNISH	Not Necessary	110.00 F	*- FN
11	1		*FRONT BUMPER GRILLE TOP COVER	Not Necessary	378.00 F	*- FN
12	1		*FRONT BUMPER LOWER LIPS	Cracked	810.00 FS	*300.00 FS
13	1		*FRONT BUMPER LOWER LIPS RUBBER	Cut	54.00 FS	*20.00 FS
14	1		*HEADLAMP -LEFT	Cut	2,850.00 F	*434.50 FN
15	1		*FRONT LEFT DOOR	Buckled	1,782.00 F	*871.20 FN
16	1		*REAR LEFT DOOR	Repair	1,782.00 F	*- FN
17	1		*ANTI ROLL BAR	Not Necessary	685.00 F	*- FN
18	1		*ANTI ROLL BAR LINK	Not Necessary	76.00 F	*- FN
19	1		*KNUCKLE	Bent	532.00 F	*382.20 FN
20	1		*LEFT ABSORBER BEARING	Necessary	102.00 F	*77.00 FN
21	1		*LEFT ABSORBER MOUNTING	Necessary	57.00 F	*38.60 FN
22	1		*LEFT ABSORBER	Bent	663.00 F	*410.36 FN
23	1		*WHEEL BEARING	Necessary	209.00 F	*139.48 FN
24	1		*TIE ROD	Bent	228.00 F	*136.00 FN
25	1		*TIE ROD END	Bent	228.00 F	*136.00 FN
26	1		*LOWER ARM -LEFT	Bent	425.00 F	*255.00 FN
27	1		*LEFT RIMS & FRONT & REAR	Cut	1,400.00 FS	*360.00 FS
28	1		*TYRE-FRONT LEFT	Cut	340.00 FS	*150.00 FS
29	1		*CLIPS (60 PCS)	Necessary	85.00 FS	*20.00 FS
30	1		*OFF PEAK CAR TAG	Necessary	180.00 FS	*40.00 FS
31	1		*NUMBER PLATE -FRONT	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	17,435.00	6,497.04
- List Item Discount on L Items 0.00/30.00% (S\$)	0.00	807.51
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	288.03

Total Parts (S\$)	17,435.00	5,401.50
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,400.00	1,200.00
2	TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS KNOCK ,JACK ,WELD ,RESHAPE AND ALIGN ALL AFFECTED PORTIONS	New	1,520.00	600.00
3	TO CHECK WIRING & REWIRING	New	80.00	30.00
4	WHEEL BALANCING & ALIGNMENT	New	140.00	60.00
5	TO REMOVE & REPLACE TYRE	New	50.00	20.00
6	TO REMOVE & INSTALL WEEKEND PLATE	New	100.00	40.00
7	TO REMOVE AND REINSTALL FRONT BONNET & DOOR	New	350.00	60.00
8	TO CHECK LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	0.00
9	TO REMOVE & REPACE ALL AFFECTED PARTS WITH MECHANICAL & ELECTRICAL CHECKS	New	180.00	0.00
10	ANTI RUST TREATMENT	New	120.00	60.00
Gross Labour Cost (S\$)			4,060.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >