

ASSIGNMENT

Surveyor:

KENNETH

DOI:

14/08/13

Date / Time:

14/08/13

Registered in Merimen:

18/08/13

Pre-assign / CCU / FTE

Insured Vehicle No.:

GX 3727 H

Claim No.:

800676705

Name of Insured:

MAO SHENG QUANJI CONSTRUCTION PTG LTD

Policy No.:

200127293-04000

Insured Tel No.:

HP:

Make / Model:

MITSUBISHI LORRY

Excess Sec II :SS

D.O.A:

7/8/13

Place of Accident:

BUKIT TIMAH ROAD / UPPER
BUKIT TIMAH ROAD

Is driver the owner? (YES / NO)

Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age:

CHIA SOON SENG

Driver Tel No. : 9478342 / 62852300 (V/L: YES / NO Insured Liability:

% Final ? Yes / No

SFH 1998 B

INSRS:
WSP: P Kim Han
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Does driver got his/her owned vehicle? : (YES / NO)

Driver's Own Vehicle Number:

Insurance Company:

SFH 1998B - CS/CA113014693/Kg, D.O.A. 7/8/13

GX 3727 H - X

STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA:

Medical Bill:

Approval Email:

Payment Breakdown Form:

Others:

27/8/13

called OI spoke to Mr Chai. Inform about the claim. Confirm the accident. OI came out from residence, lands towards main road and was hit by TP on drive way.

Inform OI liability may not be in his favour.

As such we will proceed to settle the claim. OI aware of and will be affected.

Letter out.

07/11/14

File pass to typist to close.

workshop could not finalize. As per AIG instruction, submit

w/p report.

settle G/S.

FINAL SETTLEMENT

Date:

Confirm with

Repair Cost:

SS

Final Liability

100 % (Agreed / Assessed)

BOLA S/N No.:

N/A

Loss of Rental:

SS

(days)

If NO or B 28, Ass. Lia:

Loss of Use:

SS

(\$ x days)

Disbursement:

Legal Cost

SS

Total:

SS

Global Sum: SS

\$ 250

[Home](#) | [About Us](#) | [Services](#)[Driving Licence Enquiry](#)[Outstanding Traffic Offence](#)[About Driving In Singapore](#)[Singapore Police Force Website](#)[Home](#) > [Driving Licence Information](#)
> [Licence Enquiry Options](#) > [Status of Driving Licence](#)[Terms and Conditions](#) | [FAQs](#) | [Help](#)

Status of Driving Licence

Licence Number: S7869077A
Status of Driving Licence: Valid
Classes of Licence: 2B,3
Expiry Date: Valid for life unless revoked, suspended or disqualified.

The above information is accurate as at 16/08/2013 12:01 AM

[Print Licence Status](#)

Please do not use the Back or Forward button on your browser or double-click a hyperlink as this may end your transactions.

Rate this e-Service.

If you encounter any problems with this e-Service, please contact us at http://www.spf.gov.sg/contactus/contactus_index.htm.
You may also give us your comments at <http://www.spf.gov.sg/feedback.htm>.

Last updated/reviewed on 03/08/2007.

@ 2007 Government of Singapore

[Privacy Statement](#)

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
Tel: 6452 7018 (5 Lines) Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 25387

Vehicle Insured : GX 3727 H
Accident Date : 07-Aug-2013

Date : 13-Aug-2013

Our Ref : 130483 (AIG ASIA) / LYN

PAGE : 1

MDM LIM SEOW LING
Singapore

*Not Attached
L.S. & ?*

ESTIMATED COST OF REPAIR FOR HONDA ODYSSEY 2.4A SFH1998B

1 pc front bumper		<i>B/LM</i> 734.30 ✓
1 pc front bumper reinforcement		<i>B</i> 243.10 ✓
2 pcs front bumper side retainer (LH+RH)	1	<i>e SS</i> 18.70 <i>CMA</i> 37.40 ✓
12 pcs front bumper clips		<i>e SS</i> 3.90 <i>Neu</i> 46.80 ✓
1 pc front bumper centre lower grille	1	<i>D</i> 93.40 ✓
2 pcs front bumper fog lamp (LH+RH)		<i>e SS</i> 254.60 509.20 ?
1 pc bonnet		<i>B</i> 729.40 ✓
1 pc bonnet stand		<i>B</i> 32.90 ✓
1 pc bonnet stand clip holder		<i>M</i> 4.80 ✓
1 pc bonnet stand base clip holder		<i>M</i> 4.50 ✓
1 pc bonnet lock		<i>B</i> 97.20 ✓
1 pc bonnet pull lock cable		35.20 ?
1 pc bonnet stand clips holder bracket	1	<i>D</i> 22.30 ✓
1 pc bonnet insulation		<i>Debra</i> 81.80 ✓
8 pcs bonnet insulation clips	<i>e SS</i> 3.50	<i>M</i> 28.00 ✓
2 pcs bonnet hinges (LH+RH)	<i>e SS</i> 47.40	<i>B</i> 94.80 ✓
2 pcs bonnet outer rubber (LH+RH)	<i>e SS</i> 32.50	<i>C</i> 65.00 ✓
1 pc bonnet outer centre rubber		<i>C</i> 32.50 ✓
1 pc bonnet inner rubber - center		<i>C</i> 32.50 ✓
1 pc o/s bonnet inner rubber		<i>M</i> 32.50 ✓
1 pc front grille net		<i>M</i> 210.30 ✓
2 pcs front grille center chrome	<i>e SS</i> 194.50	<i>M</i> 389.00 ✓
1 pc front grille upper chrome		<i>M</i> 136.40 ✓
1 pc front grille "H" logo		<i>M</i> 35.50 ✓
10 pcs front grille clips	<i>e SS</i> 3.90	<i>M</i> 39.00 ✓
2 pcs headlamp assy HID (LH+RH) <i>elica</i>	<i>e SS</i> 625.60	1,251.20 <i>N.S. B</i> ✓
2 pcs n/s headlamp back cover	<i>e SS</i> 18.00	<i>CMA</i> 36.00 ✓

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : GX 3727 H
Our Ref : 130483

Page : 2
No. : 25387

2 pcs headlamp lower beam (LH+RH)	@ S\$ 36.50	Bt	73.00	✓
2 pcs headlamp HID bulb (LH+RH) <i>ALIAN</i>	@ S\$ 324.90		649.80	✓
2 pcs headlamp ballast control unit (LH+RH)	@ S\$ 361.60	<i>NS</i>	723.20	<i>dim</i>
1 pc n/s headlamp light bulb (big)		Bt	18.60	✓
1 pc n/s headlamp light bulb (small)		Bt	15.60	✓
1 pc n/s headlamp signal bulb		Bt	20.50	✓
1 pc n/s front fender		Bt	559.20	✓
1 pc n/s front fender top garnish		<i>CM</i>	35.70	✓
3 pcs n/s front fender top garnish clips	@ S\$ 3.50	<i>NS</i>	10.50	✓
1 pc n/s front fender inner panel top		Bt	145.20	✓
1 pc n/s front fender inner shield		<i>NS</i>	85.10	✓
8 pcs n/s front fender inner shield clips	@ S\$ 3.50	<i>NS</i>	28.00	✓
1 pc n/s front fender inner panel extension		Bt	48.70	✓
1 pc n/s front fender lower chrome moulding		<i>NS</i>	22.10	✓
1 pc n/s front fender wheel housing panel		Bt	588.40	✓
1 pc o/s front fender		Bt	559.20	✓
1 pc o/s front fender top garnish		<i>NS</i>	35.70	X
3 pcs o/s front fender top garnish clips	@ S\$ 3.50	<i>NS</i>	10.50	X
1 pc o/s front fender inner shield		<i>CM</i>	85.10	✓
8 pcs o/s front fender inner shield clips	@ S\$ 3.50	<i>NS</i>	28.00	✓
1 pc o/s front fender lower chrome moulding		<i>NS</i>	22.10	✓
1 pc n/s front chassis member		Bt	830.90	✓
1 pc front windscreen glass		<i>CM</i>	1,638.20	✓
1 pc front windscreen glass moulding		<i>NS</i>	42.60	✓
1 pc n/s roof top side moulding		<i>NS</i>	128.00	✓

Con't Page 3 ...

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
Tel: 6452 7018 (5 Lines) Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H
Our Ref : 130483

Page : 3
No. : 25387

1 pc	wiper panel garnish - big			229.00 ✓
2 pcs	wiper panel garnish - side (LH+RH)	@ SS 28.70	28.70	57.40 ✓
10 pcs	wiper panel garnish clips	@ SS 4.50	4.50	45.00 ✓
1 pc	n/s wiper panel inner garnish (NPA) wv			
1 pc	wiper washer tank			70.10 ✓
2 pcs	wiper washer tank motor	@ SS 78.50	78.50	157.00 ?
1 pc	front support panel			449.20 ✓
2 pcs	front support panel rubber stopper	@ SS 24.50	24.50	49.00 ✓
1 pc	aircon condenser			753.70 ✓
1 pc	aircon fan cowling			88.70 ?
1 pc	aircon fan blade			58.30 ?
1 pc	aircon fan motor			303.80 ?
2 pcs	aircon lower bushing (LH+RH)	@ SS 18.20	18.20	36.40 ?
2 pcs	aircon top bracket (LH+RH)	@ SS 12.00	12.00	24.00 ?
2 pcs	aircon top rubber bushing (LH+RH)	@ SS 4.20	4.20	8.40 ?
1 pc	aircon suction hose			187.00 ?
1 pc	radiator assy			1,495.70 ✓
2 pcs	radiator top mounting bracket (LH+RH)	@ SS 18.80	18.80	37.60 ✓
2 pcs	radiator top mounting bushing (LH+RH)	@ SS 6.00	6.00	12.00 ✓
1 pc	radiator spare tank			56.30 ✓
1 pc	radiator top hose			24.20 ✓
1 pc	radiator lower hose			26.70 ?
1 pc	radiator spare tank bypass hose			12.00 ?
2 pcs	radiator lower bushing (LH+RH)	@ SS 13.80	13.80	27.60 ?
1 pc	radiator fan cowling			111.85 ✓
1 pc	radiator fan blade			58.30 ?
1 pc	radiator fan motor			303.80 ?
1 pc	radiator pressure cap cover			24.30 ✓
2 pcs	radiator air guide (LH+RH)	@ SS 8.50	8.50	17.00 ✓
1 pc	air intake duct			91.20 ✓
2 pcs	air intake duct clips	@ SS 3.90	3.90	7.80 ✓

Con't Page 4 ...



AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H

Our Ref : 130483

Page : 4

No. : 25387

1 pc	air resonator		192.30 X
1 pc	air cleaner box - top		71.90 ?
1 pc	air cleaner box - lower		141.50 ✓
1 pc	air cleaner box inner hose		68.80 ?
1 pc	air cleaner box air		48.60 ?
	temperature sensor	]	
1 pc	throttle body		1,057.60 ?
1 pc	throttle position sensor		185.20 ?
1 pc	battery cover		37.00 ✓
1 pc	battery bracket		28.00 ✓
1 pc	battery base tray		27.00 ✓
1 pc	battery base plate		95.00 ?
1 pc	battery terminal positive		64.20 ✓
	cover - red	]	
1 pc	fuse box bracket		18.00 ✓
1 pc	fuse box top c/w lower and		756.40 ✓
	center	]	
1 pc	horn		48.00 X
1 pc	air intake manifold		391.70 ?
1 pc	aircon discharge pipe		263.60 ?
1 pc	n/s front upper arm		218.00 ?
1 pc	n/s front lower arm		316.00 ?
1 pc	n/s front shock absorber		310.40 ?
1 pc	n/s front shock absorber		45.00 ?
	mounting	]	
1 pc	n/s front knuckle arm		303.80 ?
1 pc	n/s front knuckle arm bearing		121.60 ?
1 pc	engine under cover		93.40 ✓
1 pc	engine lower sub frame		1,168.50 ?
1 pc	engine mounting - LH		145.90 ?
1 pc	engine mounting - RH		198.60 ?
1 pc	engine mounting - rear		245.40 ?
1 pc	engine mounting - front		137.70 ?
1 pc	thermostat		65.00 ?
1 pc	thermostat housing		47.90 ?
1 pc	water pump		181.90 ?
1 pc	gearbox solenoid valve (1)		338.00 ?

Con't Page 5 ...

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H
Our Ref : 130483

Page : 5
No. : 25387

1 pc gearbox solenoid valve (2)

386.90 ?

24,101.05

Less 20% : -4,820.21

19,280.84

- 1 pc front number plate
- 1 pc front fog lamp wireharness (local repair) 1
- 1 pc front bumper lower spoiler
- 1 pc front windscreen glass sealant
- 1 pc front windscreen glass damping seal 1
- 1 pc front windscreen glass solar film 1
- 1 pc ERP bracket
- 1 pc radiator coolant
- 1 pc battery
- 1 pc n/s front sports rim

40.00 sn ✓
Ta 300.00 sn 200sn
Ta 780.00 sn ✓
Nu 40.00 sn ✓
Nu 20.00 sn ✓
Nu 180.00 sn ✓
Nu 26.00 sn ✓
Nu 48.00 sn 502sn
Nu 180.00 sn ✓
Nu 480.00 sn ✓

To tow accident vehicle to workshop by normal towing

50.00 ✓

To remove and renew front windscreen glass and conduct water leak test.

120.00 ✓

To remove aircon condenser, pipes and driers. Vacuum and recharge gas

120.00 1000

To remove and refit engine assy in order to facilitate repairing works

350.00 2800

To apply undersealing

180.00 1500

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : GX 3727 H
Our Ref : 130483

Page : 6
No. : 25387

To dismantle and check front under-carriages. To replace affected portions.

280.00 *200*

To conduct front wheel alignment test.

80.00 *60*

To check and realignment on chassis member.

350.00 *250*

To remove front instrument panel assy and rewiring to facilitate repair works.

250.00 *220*

To putty and respray on affected portions.

1400
1,700.00 *1200*

To focus headlamps. To check front wiring and lighting operation.

50.00 *30*

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

2,400.00 *1800*

Total : S\$27,304.84
=====

Singapore Dollars Twenty Seven Thousand Three Hundred and Four and Cents Eighty Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Supplementary Hours 14/5/13

1pc Fuses box - Top (Small) ?
1pc Fuses box - Lower (Small) ?
1pc Fuses box - Centre (Small) ?

Zayyer

From: Zayyer
Sent: Tuesday, 27 August, 2013 5:31 PM
To: 'service@kkimhin.com.sg'
Cc: Ashley Chong
Subject: ACCIDENT INVOLVING GX 3727H & SFH 1998B ON 07/08/2013

Your Ref: SFH 1998B

WITHOUT PREJUDICE

Our Ref: CC6/AIG13014849/Kg2a3

Dear Sir/Madam,

ACCIDENT INVOLVING GX 3727H & SFH 1998B ON 07/08/2013

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly take note that case handler in charge is Ashley and she can be contacted at DID: 6841 2360.

Thanks and Best regards,

Zayer

LKK Auto Consultants Pte Ltd

DID: 6749 9635

Fax: 6741 4108

Zayyer

From: Zayyer
Sent: Friday, 7 November, 2014 1:34 PM
To: Pillai, Sherini; 'Syed-Yusoff, Saliha'; 'Elaine Chia'
Cc: CS A Team
Subject: Your Ref: 800676705 Our Ref: CC6/AIG13014849/Kza3 Date of accident on 7/08/2013 accident involving GX 3727H & SFH 1998B

Your Ref: 800676705

Our Ref: CC6/AIG13014849/Kza3

Dear Sir / Madam,

Date of accident on 7/08/2013 accident involving GX 3727H & SFH 1998B

Refer to the above matter and our discussion on 4/11/2014.

Above matter is clear for liability. However, workshop had not finalized with our surveyor until now.

In view of the above, we are intending to temporary close the file and submit our report to your good office. If there are any new developments in future, kindly inform us and we will follow up if necessary.

Thanks and Best Regards

Zayer

LKK Auto Consultants Pte Ltd

51 Ubi Avenue 1

#01-25

Paya Ubi Industrial Park

Singapore 408933

DID: 6841 2409

Fax: 6741 4108



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG13014849/Kg2a3

27 August 2013

MAO SHENG QUANJI CONSTRUCTION PTE LTD
165 Mapherson Road
Singapore 348533

Dear Sir/Madam,

ACCIDENT INVOLVING GX 3727H & SFH 1998B ON 07/08/2013

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Zayer

DID: 6749 9635

FAX: 6741 4108

Email: zayyer@lkkauto.com

Case Handler

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2013 Edit Reg		14 Aug 2013 00:00 Edit Adj Rpt	S\$14,550.00 Edit Estimates	S\$14,550.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	Mao Sheng Quanji Construction Pte Ltd, NRIC: A02470/1988G			[Created by adjuster]	
Main Claimant:	LIM SEOW LING, NRIC: S7311622H				
Vehicle Reg. No.:	SFH1998B	Date of Loss:	07/08/2013 09:00 - :59		
Claim Type:	TP / 800676705	Policy/Cover Note No.:	2100127293 (Comprehensive) Coverage: 15/04/2013 - 14/04/2014		
Vehicle Reg. No. (Insured):	GX3727H	Policy No. (Claimant):	DMPCSN3014131302		
Repairer:	K Kim Hin Auto Pte Ltd (HQ) Bk 34, #01-114, Sin Ming Drive, 575708 Sin Ming - Tel: 64527018				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tan, Jamie-BL - 6419 1969]				
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/08/2013]				

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Complete
No results.								

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Claim Documents

*SFH1998B (800676705)
[GX3727H]
TP
LIM SEOW LING
Aug 7 2013 9:00AM
[Mao Sheng Quanji Construction Pte Ltd]

Upload Documents			Upload Photos		Compose New Letter		View Use Viewer	
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail			Print	
1	15/08/13 17:03	Chassis Number		Load JPG			☒	
2	15/08/13 17:03	General View		Load JPG			☒	
3	15/08/13 17:03	General View		Load JPG			☒	
4	15/08/13 17:03	General View		Load JPG			☒	
5	15/08/13 17:03	General View		Load JPG			☒	
6	15/08/13 17:03	General View		Load JPG			☒	
7	15/08/13 17:03	General View		Load JPG			☒	
8	15/08/13 17:03	General View		Load JPG			☒	
9	15/08/13 17:03	General View		Load JPG			☒	
10	15/08/13 17:03	General View		Load JPG			☒	
11	15/08/13 17:03	General View		Load JPG			☒	
12	15/08/13 17:03	General View		Load JPG			☒	
13	15/08/13 17:03	General View		Load JPG			☒	
14	15/08/13 17:03	General View		Load JPG			☒	
15	15/08/13 17:03	General View		Load JPG			☒	
16	15/08/13 17:03	General View		Load JPG			☒	
17	15/08/13 17:03	General View		Load JPG			☒	
18	15/08/13 17:03	General View		Load JPG			☒	
19	15/08/13 17:03	General View		Load JPG			☒	
20	15/08/13 17:03	General View		Load JPG			☒	
21	15/08/13 17:03	General View		Load JPG			☒	
22	15/08/13 17:03	General View		Load JPG			☒	
23	15/08/13 17:03	General View		Load JPG			☒	
24	15/08/13 17:03	General View		Load JPG			☒	
25	15/08/13 17:03	General View		Load JPG			☒	
26	15/08/13 17:03	General View		Load JPG			☒	
27	15/08/13 17:03	General View		Load JPG			☒	
28	15/08/13 17:03	General View		Load JPG			☒	
29	15/08/13 17:03	General View		Load JPG			☒	
30	15/08/13 17:03	General View		Load JPG			☒	
31	15/08/13 17:03	General View		Load JPG			☒	
32	15/08/13 17:03	General View		Load JPG			☒	
33	15/08/13 17:03	General View		Load JPG			☒	
34	15/08/13 17:03	General View		Load JPG			☒	
35	15/08/13 17:03	General View		Load JPG			☒	
36	15/08/13 17:03	General View		Load JPG			☒	
37	15/08/13 17:03	General View		Load JPG			☒	
38	15/08/13 17:03	General View		Load JPG			☒	
39	15/08/13 17:03	General View		Load JPG			☒	

40	15/08/13 17:03	General View	1	Load JPG	☒
41	15/08/13 17:04	General View	1	Load JPG	☒
42	15/08/13 17:04	General View	1	Load JPG	☒
43	15/08/13 17:04	General View	1	Load JPG	☒
44	15/08/13 17:04	General View	1	Load JPG	☒
45	15/08/13 17:04	General View	1	Load JPG	☒
46	15/08/13 17:04	General View	1	Load JPG	☒
47	15/08/13 17:04	General View	1	Load JPG	☒
48	15/08/13 17:04	General View	1	Load JPG	☒
49	15/08/13 17:04	General View	1	Load JPG	☒
Documentation					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1 per page	☒	
1	15/08/13 19:40	TP ESTIMATE	Thumbnail	Print	
2	15/08/13 19:40	TP GIA REPORT	1	Load PDF	
3	07/11/14 13:37	email to AIG	1	Load PDF	
4	17/11/14 11:14	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1	Load PDF	
1	16/08/13 09:12	OI GIA REPORT	Thumbnail	Print	
			1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#) [Save](#) [Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: account@lkkauto.com; admin-
 c@lkkauto.com; sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG13014849/KZA3Q2
 Date: 17/11/2014

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100127293
 Claimant Vehicle No: SFH1998B Insured Vehicle No: GX3727H
 Date of Loss: 07/08/2013 Nature of Claim: TP Claim No: 800676705

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFH1998B
 Make & Model: HONDA ODYSSEY, 2.4 (A)
 Reg. Date: 02/04/2007 (Man. Year: 2006)
 Colour: Metallic Silver
 Engine Capacity: 2354 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price
 Engine No: K24A64003690
 Chassis No: JHMRB18507C203689
 Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17
 Front Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm
 Rear Tyre Size: 215/55 R17
 Rear Left Side: Yokohama 8 mm
 Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	21,374.84	13,527.96	7,846.88	36.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	4,660.00	1,270.00	21.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,304.84	18,187.96	9,116.88	33.39
Approved Total (Overridden) (\$\$)		14,550.00		
(\$\$)	27,304.84	14,550.00	12,754.84	46.71
+ GST 7.00/7.00% (\$\$)	1,911.34	1,018.50	892.84	46.71
Nett Amount (\$\$)	29,216.18	15,568.50	13,647.68	46.71
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 14/08/2013
 Date Inspected: 14/08/2013 Inspected At: K Kim Hin Auto Pte Ltd (HQ)
 Est Repair Period: 18.0 days Blk 34, #01-114, Sin Ming Drive
 Singapore 575708

Adjuster: KENNETH KONG

Manager: ZAY YER LYNN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Cracked	734.30 FL	*734.30 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	243.10 FL	*243.10 FL
3	2		*FRONT BUMPER SIDE RETAINER (LH+RH)	Cracked	37.40 FL	*37.40 FL
4	12		*FRONT BUMPER CLIPS	Necessary	46.80 FL	*46.80 FL
5	1		*FRONT BUMPER CENTRE LOWER GRILLE	Distorted	93.40 FL	*93.40 FL
6	2		*FRONT BUMPER FOG LAMP (LH+RH)	*Check	509.20 FL	*- FL
7	1		*BONNET	Bent	729.40 FL	*729.40 FL
8	1		*BONNET STAND	Bent	32.90 FL	*32.90 FL
9	1		*BONNET STAND CLIP HOLDER	Missing	4.80 FL	*4.80 FL
10	1		*BONNET STAND BASE CLIP HOLDER	Missing	4.50 FL	*4.50 FL
11	1		*BONNET LOCK	Bent	97.20 FL	*97.20 FL
12	1		*BONNET PULL LOCK CABLE	*Check	35.20 FL	*- FL
13	1		*BONNET STAND CLIPS HOLDER BRACKET	Distorted	22.30 FL	*22.30 FL
14	1		*BONNET INSULATION	Deformed	81.80 FL	*81.80 FL
15	8		*BONNET INSULATION CLIPS	Missing	28.00 FL	*28.00 FL
16	2		*BONNET HINGES (LH+RH)	Bent	94.80 FL	*94.80 FL
17	2		*BONNET OUTER RUBBER (LH+RH)	Cut	65.00 FL	*65.00 FL
18	1		*BONNET OUTER CENTRE RUBBER	Cut	32.50 FL	*32.50 FL
19	1		*BONNET INNER RUBBER -CENTER	Cut	32.50 FL	*32.50 FL
20	1		*O/S BONNET INNER RUBBER	Missing	32.50 FL	*32.50 FL
21	1		*FRONT GRILLE NET	Missing	210.30 FL	*210.30 FL
22	2		*FRONT GRILLE CENTER CHROME	Missing	389.00 FL	*389.00 FL
23	1		*FRONT GRILLE UPPER CHROME	Missing	136.40 FL	*136.40 FL
24	1		*FRONT GRILLE H LOGO	Missing	35.50 FL	*35.50 FL
25	10		*FRONT GRILLE CLIPS	Necessary	39.00 FL	*39.00 FL
26	2		*HEADLAMP ASSY HID (LH+RH)	O/S Cracked / N/S Broken	1,251.20 FL	*1,251.20 FL
27	1		*N/S HEADLAMP BACK COVER	Cracked (1 PCS ONLY)	36.00 FL	*18.00 FL
28	2		*HEADLAMP LOWER BEAM (LH+RH)	Necessary	73.00 FL	*73.00 FL
29	1		*HEADLAMP HID BULB (LH+RH)	N/S Broken	649.80 FL	*324.90 FL
30	2		*HEADLAMP BALLAST CONTROL UNIT (LH+RH)	N/S *Check / O/S Serviceable	723.20 FL	*- FL
31	1		*N/S HEADLAMP LIGHT BULB (BIG)	Broken	18.60 FL	*18.60 FL
32	1		*N/S HEADLAMP LIGHT BULB (SMALL)	Broken	15.60 FL	*15.60 FL
33	1		*N/S HEADLAMP SIGNAL BULB	Broken	20.50 FL	*20.50 FL
34	1		*N/S FRONT FENDER	Broken	559.20 FL	*559.20 FL
35	1		*N/S FRONT FENDER TOP GARNISH	Cracked	35.70 FL	*35.70 FL
36	3		*N/S FRONT FENDER TOP GARNISH CLIPS	Necessary	10.50 FL	*10.50 FL
37	1		*N/S FRONT FENDER INNER PANEL TOP	Bent	145.20 FL	*145.20 FL
38	1		*N/S FRONT FENDER INNER SHIELD	Distorted	85.10 FL	*85.10 FL
39	8		*N/S FRONT FENDER INNER SHIELD CLIPS	Necessary	28.00 FL	*28.00 FL
40	1		*N/S FRONT FENDER INNER PANEL EXTENSION	Bent	48.70 FL	*48.70 FL
41	1		*N/S FRONT FENDER LOWER CHROME MOULDING	Necessary	22.10 FL	*22.10 FL
42	1		*N/S FRONT FENDER WHEEL HOUSING PANEL	Bent	588.40 FL	*588.40 FL
43	1		*O/S FRONT FENDER	Buckled	559.20 FL	*559.20 FL
44	1		*O/S FRONT FENDER TOP GARNISH	Serviceable	35.70 FL	*- FL
45	3		*O/S FRONT FENDER TOP GARNISH CLIPS	Not Necessary	10.50 FL	*- FL
46	1		*O/S FRONT FENDER INNER SHIELD	Cracked	85.10 FL	*85.10 FL
47	8		*O/S FRONT FENDER INNER SHIELD CLIPS	Necessary	28.00 FL	*28.00 FL
48	1		*O/S FRONT FENDER LOWER CHROME	Necessary	22.10 FL	*22.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
MOULDING						
49	1		*N/S FRONT CHASSIS MEMBER	Bent	830.90 FL	*830.90 FL
50	1		*FRONT WINDSCREEN GLASS	Cracked	1,638.20 FL	*1,638.20 FL
51	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	42.60 FL	*42.60 FL
52	1		*N/S ROOF TOP SIDE MOULDING	Dented	128.00 FL	*128.00 FL
53	1		*WIPER PANEL GARNISH -BIG	Cracked	229.00 FL	*229.00 FL
54	2		*WIPER PANEL GARNISH -SIDE (LH+RH)	Dented / Cut	57.40 FL	*57.40 FL
55	10		*WIPER PANEL GARNISH CLIPS	Necessary	45.00 FL	*45.00 FL
56	1		*N/S WIPER PANEL INNE GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
57	1		*WIPER WASHER TANK	Dented	70.10 FL	*70.10 FL
58	1		*WIPER WASHER TANK MOTOR	*Check	157.00 FL	*- FL
59	1		*FRONT SUPPORT PANEL	Bent	449.20 FL	*449.20 FL
60	2		*FRONT SUPPORT PANEL RUBBER STOPPER	Cracked	49.00 FL	*49.00 FL
61	1		*AIRCON CONDENSER	Bent	753.70 FL	*753.70 FL
62	1		*AIRCON FAN COWLING	*Check	88.70 FL	*- FL
63	1		*AIRCON FAN BLADE	*Check	58.30 FL	*- FL
64	1		*AIRCON FAN MOTOR	*Check	303.80 FL	*- FL
65	2		*AIRCON LOWER BUSHING (LH+RH)	*Check	36.40 FL	*- FL
66	2		*AIRCON TOP BRACKET (LH+RH)	*Check	24.00 FL	*- FL
67	2		*AIRCON TOP RUBBER BUSHING (LH+RH)	*Check	8.40 FL	*- FL
68	1		*AIRCON SUCTION HOSE	*Check	187.00 FL	*- FL
69	1		*RADIATOR ASSY	Broken	1,495.70 FL	*1,495.70 FL
70	1		*RADIATOR TOP MOULDING BRACKET (LH+RH)	N/S Distorted	37.60 FL	*18.80 FL
71	2		*RADIATOR TOP MOULDING BUSHING (LH+RH)	Necessary	12.00 FL	*12.00 FL
72	1		*RADIATOR SPARE TANK	Dented	56.30 FL	*56.30 FL
73	1		*RADIATOR TOP HOSE	Punctured	24.20 FL	*24.20 FL
74	1		*RADIATOR LOWER HOSE	*Check	26.70 FL	*- FL
75	1		*RADIATOR SPARE TANK BYPASS HOSE	*Check	12.00 FL	*- FL
76	2		*RADIATOR LOWER BUSHING (LH+RH)	*Check	27.60 FL	*- FL
77	1		*RADIATOR FAN COWLING	Cracked	111.85 FL	*111.85 FL
78	1		*RADIATOR FAN BLADE	*Check	58.30 FL	*- FL
79	1		*RADIATOR FAN MOTOR	*Check	303.80 FL	*- FL
80	1		*RADIATOR PRESSURE CAP COVER	Serviceable	24.30 FL	*- FL
81	1		*RADIATOR AIR GUIDE (LH/RH)	N/S Cracked	17.00 FL	*8.50 FL
82	1		*AIR INTAKE DUCT	Distorted	91.20 FL	*91.20 FL
83	2		*AIR INTAKE DUCT CLIPS	Necessary	7.80 FL	*7.80 FL
84	1		*AIR RESONATOR	Serviceable	192.30 FL	*- FL
85	1		*AIR CLEANER BOX-TOP	*Check	71.90 FL	*- FL
86	1		*AIR CLEANER BOX-LOWER	Mtg Cracked	141.50 FL	*141.50 FL
87	1		*AIR CLEANER BOX INNER HOSE	*Check	68.80 FL	*- FL
88	1		*AIR CLEANER BOX AIR TEMPERATURE SENSOR	*Check	48.60 FL	*- FL
89	1		*THROTTLE BODY	*Check	1,057.60 FL	*- FL
90	1		*THROTTLE POSITION SENSOR	*Check	185.20 FL	*- FL
91	1		*BATTERY COVER	Dented	37.00 FL	*37.00 FL
92	1		*BATTERY BRACKET	Bent	28.00 FL	*28.00 FL
93	1		*BATTERY BASE TRAY	Dented	27.00 FL	*27.00 FL
94	1		*BATTERY BASE PLATE	*Check	95.00 FL	*- FL
95	1		*BATTERY TERMINAL POSITIVE COVER - RED	Cracked	64.20 FL	*64.20 FL
96	1		*FUSE BOX BRACKET	Bent	18.00 FL	*18.00 FL
97	1		*FUSE BOX TOP C/W LOWER AND CENTER	Mtg Cracked	756.40 FL	*756.40 FL
98	1		*HORN	Serviceable	48.00 FL	*- FL
99	1		*AIR INTAKE MANIFOLD	*Check	391.70 FL	*- FL
100	1		*AIRCON DISCHARGE PIPE	*Check	263.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
101	1		*N/S FRONT UPPER ARM	*Check		
102	1		*N/S FRONT LOWER ARM	*Check	218.00 FL	*- FL
103	1		*N/S FRONT SHOCK ABSORBER	*Check	316.00 FL	*- FL
104	1		*N/S FRONT SHOCK ABSORBER MOUNTING	*Check	310.40 FL	*- FL
					45.00 FL	*- FL
105	1		*N/S FRONT KNUCKLE ARM	*Check		
106	1		*N/S FRONT KNUCKLE ARM BEARING	*Check	303.80 FL	*- FL
107	1		*ENGINE UNDER COVER	Cracked	121.60 FL	*- FL
108	1		*ENGINE LOWER SUB FRAME	*Check	93.40 FL	*93.40 FL
109	1		*ENGINE MOUNTING-LH	*Check	1,168.50 FL	*- FL
110	1		*ENGINE MOUNTING-RH	*Check	145.90 FL	*- FL
111	1		*ENGINE MOUNTING-REAR	*Check	198.60 FL	*- FL
112	1		*ENGINE MOUNTING-FRONT	*Check	245.40 FL	*- FL
113	1		*THERMOSTAT	*Check	137.70 FL	*- FL
114	1		*THERMOSTAT HOUSING	*Check	65.00 FL	*- FL
115	1		*WATER PUMP	*Check	47.90 FL	*- FL
116	1		*GEARBOX SOLENOID VALVE (1)	*Check	181.90 FL	*- FL
117	1		*GEARBOX SOLENOID VALVE (2)	*Check	338.00 FL	*- FL
118	1		*FRONT NUMBER PLATE	Missing	386.90 FL	*- FL
119	1		*FRONT FOG LAMP WIREHARNES (LOCAL REPAIR)	Torn	40.00 FS	*40.00 FS
					300.00 FS	*200.00 FS
120	1		*FRONT BUMPER LOWER SPOILER	Torn		
121	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	780.00 FS	*780.00 FS
122	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	Necessary	40.00 FS	*40.00 FS
					20.00 FS	*20.00 FS
123	1		*FRONT WINDSCREEN GLASS SOLAR FILM	Necessary		
124	1		*ERP BRACKET	Necessary	180.00 FS	*180.00 FS
125	1		*RADIATOR COOLANT (50%)	Necessary	26.00 FS	*26.00 FS
126	1		*BATTERY	Necessary	48.00 FS	*24.00 FS
127	1		*N/S FRONT SPORTS RIM	Dented	180.00 FS	*180.00 FS
				Dented	480.00 FS	*480.00 FS

F=Franchise part. S=SpocNett. L=ListItemDisc.

Sub Total (S\$) 26,195.05 16,417.45
 - List Item Discount on L Items 20.00/20.00% (S\$) 4,820.21 2,889.49

Total Parts (S\$) 21,374.84 13,527.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING	New	50.00	50.00
2	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
3	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS, VACUUM AND RECHARGE GAS	New	120.00	100.00
4	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS	New	350.00	280.00
5	TO APPLY UNDERSEALING	New	180.00	150.00
6	TO DISMANTLE AND CHECK FRONT UNDERCARRIAGE .TO REPLACE AFFECTED PORTIONS	New	280.00	200.00
7	TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	80.00	60.00
8	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER	New	350.00	250.00
9	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS	New	250.00	220.00
10	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,700.00	1,400.00
11	TO FOCUS HEADLAMPS .TO CHECK FRONT WIRING AND LIGHTING OPERATION	New	50.00	30.00
12	TO REMOVE,CUT OUT DAMAGED PARTS ,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	2,400.00	1,800.00
Gross Labour Cost (\$\$)			5,930.00	4,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >