

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Feb 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/23/02/2018 20:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	*380.00 F BT
2	2		*Bonnet hinge	0.00	0.00	*70.00 F BT
3	1		*Bonnet lock	0.00	0.00	*65.00 F BT
4	1		*Bonnet insulator	0.00	0.00	*90.00 F BT
5	8		*Bonnet insulator clips	0.00	0.00	*12.00 F nee
6	2		*Bonnet stopper	0.00	0.00	*20.00 F nee
7	1		*Bonnet lock cable	0.00	0.00	*30.00 F ?
8	1		*Front grille base garnish	0.00	0.00	*165.00 F CR
9	1		*Front grille logo	0.00	0.00	*15.00 F nee
10	2		*Front grille chrome moulding LH/RH	0.00	0.00	*56.00 F nee
11	1		*Front grille outer	0.00	0.00	*140.00 F CR
12	2		*Headlamp LH/RH	0.00	0.00	*1,560.00 F BRO
13	2		*Headlamp top bracket	0.00	0.00	*20.00 F BRO
14	2		*Headlamp lower bracket	0.00	0.00	*40.00 F BRO
15	1		*Front bumper	0.00	0.00	*185.00 F TBS
16	10		*Front bumper clips	0.00	0.00	*15.00 F nee
17	2		*Front bumper side retainer outer	0.00	0.00	*20.00 F nee
18	1		*Front bumper center lower grille	0.00	0.00	*40.00 F BRO
19	1		*Front number plate with casing	0	0.00	35 *35.00 FS nee
20	1		*Front towing cover	0.00	0.00	*10.00 F X
21	2		*Front fog lamp cover - LH/RH-?	0.00	0.00	15 *36.00 F CR (LH)
22	2		*Front fog lamp - LH/RH-?	0.00	0.00	130 *260.00 F BRO (LH)
23	1		*Front bumper lower spoiler	0.00	0.00	*110.00 F DE
24	1		*Front reinforcement	0.00	0.00	*180.00 F BT
25	2		*Front reinforcement garnish LH/RH	0.00	0.00	*30.00 F DE
26	2		*Support side top garnish LH/RH	0.00	0.00	-
27	2		*Support side center garnish LH/RH	0.00	0.00	*40.00 F DE
28	1		*Support panel	0.00	0.00	*350.00 F BT
29	1		*Support panel top center cover bracket	0.00	0.00	*15.00 F BT
30	1		*Support panel top garnish	0.00	0.00	*30.00 F DE
31	8		*Support panel top garnish clips	0.00	0.00	*12.00 F nee
32	1		*Wiper hose to bonnet	0.00	0.00	- ?
33	2		*Horn	0.00	0.00	*60.00 F ?
34	1		*Aircon condensor	0.00	0.00	*300.00 F BT
35	1		*Radiator	0.00	0.00	*700.00 F CR
36	1		*Airduct	0.00	0.00	*60.00 F CR
37	1		*Airduct hose	0.00	0.00	*30.00 F CR
38	1		*Airduct resonator box	0.00	0.00	*55.00 F CR
39	1		*Wiper tank	0.00	0.00	*50.00 F ?
40	1		*Wiper tank motor	0.00	0.00	*30.00 F ?
41	1		*Radiator spare tank	0.00	0.00	*25.00 F nee
42	2		*Radiator top bracket with bush	0.00	0.00	*30.00 F nee

Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/23/02/2018 20:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	2		*Radiator bottom bush	0.00	0.00	*24.00 F ^{Act}
44	2		*Front fender LH/RH	0.00	0.00	*360.00 F ^{Act}
45	21		*Front fender shield LH/RH-X	0.00	0.00	55 *110.00 F ^{DE} (LH)
46	20/10		*Front fender shield clip *	0.00	0.00	15 *30.00 F ^{Act}
47	1		*Coolant	0	0.00	60 *80.00 F ^{Act}
48	2		*Engine undercover LH/RH-?	0.00	0.00	35 *70.00 F ^{Act} (LH)
49	10		*Engine undercover clips	0.00	0.00	*15.00 F ^{Act}
50	1		*Engine undercover center	0.00	0.00	*75.00 F [?]
51	21		*Front wheel arch garnish LH/RH-X	0.00	0.00	35 *70.00 F ^{DE} (LH)
52	1		*Front fender inner panel outer LH	0.00	0.00	*110.00 F ^{Act}
53	1		*Front fender inner panel LH	0.00	0.00	*60.00 F ^R
54	1		*Front chassis side extension LH	0.00	0.00	*65.00 F ^{Act}
55	1		*Front chassis side extension bracket LH	0.00	0.00	*25.00 F ^{Act}
56	1		*Wire harness LH set	0.00	0.00	*600.00 F [?]
57	1		*Front levelling sensor LH	0.00	0.00	*180.00 F [?]
58	1		*Fuse cover top LH	0.00	0.00	*20.00 F [?]
59	1		*ECU unit	0.00	0.00	*1,400.00 F [?]
60	1		*Main fuse set	0.00	0.00	- ?
61	1		*Radiator fan motor	0.00	0.00	*230.00 F [?]
62	1		*Radiator fan blade	0.00	0.00	*40.00 F [?]
63	1		*Radiator fan cowling	0.00	0.00	*65.00 F [?]
64	1		*Aircon fan motor	0.00	0.00	*150.00 F [?]
65	1		*Aircon fan blade	0.00	0.00	*40.00 F [?]
66	1		*Aircon fan cowling	0.00	0.00	*70.00 F [?]
67	1		*Air intake housing top	0.00	0.00	*30.00 F ^{DE}
68	1		*Air intake housing bottom	0.00	0.00	*75.00 F [?]
69	1		*Radiator top hose	0.00	0.00	*25.00 F ^{Act}
70	1		*Radiator bottom hose	0.00	0.00	*20.00 F [?]
71	1		*Radiator cap	0.00	0.00	*30.00 F ^X
72	1		*Front door LH Repair	0.00	0.00	-
73	1		*Front original RIM LH	0.00	0.00	- X 266
74	1		*Front tyre LH	0	0.00	70.2 *380.00 FS ^{purchased}
75	1		*Front shock absorber LH	0.00	0.00	*200.00 F [?]
76	1		*Front shock absorber top mount LH	0.00	0.00	*20.00 F [?]
77	1		*Front knuckle arm LH	0.00	0.00	*165.00 F [?]
78	1		*Front wheel bearing LH	0.00	0.00	*80.00 F [?]
79	1		*Front wheel hub LH	0.00	0.00	*120.00 F [?]
80	1		*Front lower arm LH	0.00	0.00	*160.00 F [?]
81	1		*Front lower arm ball joint LH	0.00	0.00	*40.00 F [?]
82	1		*Front stabilizer link LH	0.00	0.00	*40.00 F [?]
83	1		*Front Steering crossmember with bush	0.00	0.00	*550.00 F [?]
84	1		*Front engine crossmember	0.00	0.00	*550.00 F [?]
85	1		*Steering rack assembly	0.00	0.00	*820.00 F [?]
86	1		*Front tie rod LH	0.00	0.00	*55.00 F [?]
87	1		*Front tie rod end LH	0.00	0.00	*45.00 F [?]
88	1		*Front stabilizer bar	0.00	0.00	*90.00 F [?]
89	2		*Front stabilizer bar bush	0.00	0.00	*18.00 F [?]
90	1		*Front drive shaft LH	0.00	0.00	*550.00 F [?]
91	2		*Front drive shaft oil seal LH/RH	0.00	0.00	*30.00 F [?]
92	1		*Auto transmission fluid	0	0.00	*120.00 FS [?]
93	1		*Front fender shield mudflap LH	0.00	0.00	- ?
94	2		*Front impact sensor	0.00	0.00	*200.00 F [?]
95	1		*Driver airbag	0.00	0.00	*720.00 F ^{Act}
96	1		*Driver airbag coil sensor set	0.00	0.00	*170.00 F ^{Act}
97	1		*Passenger airbag	0.00	0.00	*1,250.00 F ^{Act}

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
98	1		*Dashboard assembly	0.00	0.00	*650.00 F Boa ?
99	1		*Airbag control unit	0.00	0.00	Δ *600.00 F ACT ?
100	1		*Airbag G sensor	0.00	0.00	- ACT ?
101	1		*Driver seatbelt	0.00	0.00	*450.00 F ACT ?
102	1		*Driver seatbelt buckle	0.00	0.00	Δ *90.00 F ACT ? X
103	1		*Passenger seatbelt	0.00	0.00	*450.00 F ACT ? X
104	1		*Passenger seatbelt buckle	0.00	0.00	Δ *90.00 F ACT ? X
105	1		*Wiper garnish	0.00	0.00	*140.00 F ?
106	1		*Battery top bracket	0.00	0.00	*10.00 F PA ?
107	1		*Battery base panel	0.00	0.00	*60.00 F PA ?
108	1		*Battery base garnish	0.00	0.00	*10.00 F DE ?
109	1		*Battery	0	0.00	120 *380.00 F SCA ?
110	1		*Engine mounting set assembly \$95/\$130/\$75	0.00	0.00	*300.00 F ?
111	1		*Engine mounting bracket LH	0.00	0.00	- ?
112	1		*Gearbox assembly Sell separate (TBA)	0.00	0.00	- ?
113	1		*Gearbox oil sump	0.00	0.00	*200.00 F ?
114	1		*Gearbox oil level dipstick	0.00	0.00	- ?
115	1		*Aircon suction pipe	0.00	0.00	*90.00 F ?
116	1		*Aircon discharge pipe	0.00	0.00	*110.00 F ?
117	1		*Aircon pressure pipe	0.00	0.00	*100.00 F ?
118	1		*Front chassis LH	0.00	0.00	*360.00 F PA ?
119	1		*Front chassis bracket LH	0.00	0.00	- PA ?
120	1		*Front suspension top panel LH	0.00	0.00	*380.00 F ?

F=Franchise part. S=SpecNett.

Sub Total (S\$)	20,263.00
+ Margin on L,N Items 10.00% (S\$)	1,928.80
Total Parts (S\$)	22,191.80

Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/23/02/2018 20:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,400.00 1400
2	Putty, blend and paint affected area	New	2,400.00 1600
3	Check Wiring, re-align and ensure proper function	New	100.00 30
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 120
5	Conduct four wheel alignment / side slip test	New	180.00 60
6	Realign chassis member	New	600.00 400
7	Remove, replace & balance rim / tire	New	60.00 30
8	Remove, replace & re-install undercarriage parts	New	400.00 150?
9	Diagnostic Check & Reset Engine system	New	280.00 150?
10	Remove and replace Dashboard assembly	New	350.00 150
11	Remove and replace Airbag full set and seatbelt assembly	New	280.00 150
12	Diagnose, reset and programming Airbag full system	New	380.00 150
13	Remove, lift up and refit engine and gearbox assembly to facilitate repair work	New	350.00 200?
14	Dismantle, remove and replace gearbox unit, reset auto transmission system	New	400.00 200?
Gross Labour Cost (S\$)			8,360.00

Hitachi Capital Asia Pacific Pte. Ltd./SKX926Y/23/02/2018 20:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Rasul

Hp 90010068

14 days

P/P

27/04/18 @ 0940


EXCESS: 500

Repeat

Resurvey 64 paint

2/3/18

ブロック(B) : ATM-1 トルクコンバーターケース




FR.

T7A1AD100A

部品明細(P) :


ブロック(B) : ATM- 2 トランスミッションケース



T7A1A0200A

部品明細(P) :

177 (D) - [A]m



177

品明細(P)

177A1A0300

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	A80422333QMX	Date of Loss:	16/02/2018
Vehicle Reg. No.:	SKX926Y	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG HOE KHENG	Contact No:	+6596974997
Driver:	ANG HOE KHENG		
Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	30/12/2015
Vehicle Colour:	White	Chassis No:	RU11108643
Engine No:	L15B4028645		
Odometer:	30000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30		
Description of Accident/Loss PLEASE REFER TO ATTACHED SKETCH PLAN			
Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)			

COST OF CLAIMS	Amount
Parts	13,750.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,750.00
+ GST 7.00% (S\$)	962.50
Nett Amount (S\$)	14,712.50
+ Previous Estimates (S\$)	32,155.43
Claim Total (S\$)	46,867.93

HITACHI
 Inspire the Next

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80422333QMX	Date of Loss:	16/02/2018
Vehicle Reg. No.:	SKX926Y	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG HOE KHENG	Contact No:	+6596974997
Driver:	ANG HOE KHENG		
Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	30/12/2015
Vehicle Colour:	WHITE		
Engine No:	L15B4028645	Chassis No:	RU11108643
Odometer:	30000 KM		

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 30

Description of Accident/Loss: PLEASE REFER TO ATTACHED SKETCH PLAN
 Remarks: CAR IN FOR SURVEY @ NO.8 FOURTH LOK YANG ROAD SINGAPORE 629705 HITACHI CAPITAL ASIA PACIFIC PTE LTD

Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

COST OF CLAIMS	Amount
Parts	22,191.80
Miscellaneous Items	0.00
Labour	8,360.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	30,551.80
- Excess (S\$)	500.00
(S\$)	30,051.80
+ GST 7.00% (S\$)	2,103.63
Nett Amount (S\$)	32,155.43

This claim is handled by: GRANT CHONG KEAN YAP

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Feb 2018)
 Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/23/02/2018 20:56
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	*380.00 F <i>Bl</i>
2	2		*Bonnet hinge	0.00	0.00	*70.00 F <i>Bl</i>
3	1		*Bonnet lock	0.00	0.00	*65.00 F <i>Bl</i>
4	1		*Bonnet insulator	0.00	0.00	*90.00 F <i>Bl</i>
5	8		*Bonnet insulator clips	0.00	0.00	*12.00 F <i>Bl</i>
6	2		*Bonnet stopper	0.00	0.00	*20.00 F <i>Bl</i>
7	1		*Bonnet lock cable	0.00	0.00	*30.00 F <i>Bl</i>
8	1		*Front grille base garnish	0.00	0.00	*165.00 F <i>Bl</i>
9	1		*Front grille logo	0.00	0.00	*15.00 F <i>Bl</i>
10	2		*Front grille chrome moulding LH/RH	0.00	0.00	*58.00 F <i>Bl</i>
11	1		*Front grille outer	0.00	0.00	*140.00 F <i>Bl</i>
12	2		*Headlamp LH/RH	0.00	0.00	*1,560.00 F <i>Bl</i>
13	2		*Headlamp top bracket	0.00	0.00	*20.00 F <i>Bl</i>
14	2		*Headlamp lower bracket	0.00	0.00	*40.00 F <i>Bl</i>
15	1		*Front bumper	0.00	0.00	*185.00 F <i>Bl</i>
16	10		*Front bumper clips	0.00	0.00	*15.00 F <i>Bl</i>
17	2		*Front bumper side retainer outer	0.00	0.00	*20.00 F <i>Bl</i>
18	1		*Front bumper center lower grille	0.00	0.00	*40.00 F <i>Bl</i>
19	1		*Front number plate with casing	0	0.00	35 *45.00 FS <i>Bl</i>
20	1		*Front towing cover	0.00	0.00	*10.00 F <i>Bl</i>
21	2		*Front fog lamp cover - LH/RH-?	0.00	0.00	*36.00 F <i>Bl</i>
22	2		*Front fog lamp - LH/RH-?	0.00	0.00	*260.00 F <i>Bl</i>
23	1		*Front bumper lower spoiler	0.00	0.00	*110.00 F <i>Bl</i>
24	1		*Front reinforcement	0.00	0.00	*180.00 F <i>Bl</i>
25	2		*Front reinforcement garnish LH/RH	0.00	0.00	*30.00 F <i>Bl</i>
26	2		*Support side top garnish LH/RH	0.00	0.00	*40.00 F <i>Bl</i>
27	2		*Support side center garnish LH/RH	0.00	0.00	*350.00 F <i>Bl</i>
28	1		*Support panel	0.00	0.00	*15.00 F <i>Bl</i>
29	1		*Support panel top center cover bracket	0.00	0.00	*30.00 F <i>Bl</i>
30	1		*Support panel top garnish	0.00	0.00	*12.00 F <i>Bl</i>
31	8		*Support panel top garnish clips	0.00	0.00	*30.00 F <i>Bl</i>
32	1		*Wiper hose to bonnet	0.00	0.00	*60.00 F <i>Bl</i>
33	2		*Horn	0.00	0.00	*300.00 F <i>Bl</i>
34	1		*Aircon condensor	0.00	0.00	*700.00 F <i>Bl</i>
35	1		*Radiator	0.00	0.00	*60.00 F <i>Bl</i>
36	1		*Airduct	0.00	0.00	*30.00 F <i>Bl</i>
37	1		*Airduct hose	0.00	0.00	*55.00 F <i>Bl</i>
38	1		*Airduct resonator box	0.00	0.00	*50.00 F <i>Bl</i>
39	1		*Wiper tank	0.00	0.00	*30.00 F <i>Bl</i>
40	1		*Wiper tank motor	0.00	0.00	*25.00 F <i>Bl</i>
41	1		*Radiator spare tank	0.00	0.00	*30.00 F <i>Bl</i>
42	2		*Radiator top bracket with bush	0.00	0.00	

Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/23/02/2018 20:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	2		*Radiator bottom bush	0.00	0.00	*24.00 FAL
44	2		*Front fender LH/RH	0.00	0.00	*360.00 FBH
45	21		*Front fender shield LH/RH-X	0.00	0.00	*110.00 FDE (LH)
46	20/10		*Front fender shield clip	0.00	0.00	*30.00 FAL
47	1		*Coolant	0	0.00	60 *80.00 FS
48	2		*Engine undercover LH/RH-?	0.00	0.00	*70.00 FCRAL (LH)
49	10		*Engine undercover clips	0.00	0.00	*15.00 FAL
50	1		*Engine undercover center	0.00	0.00	*75.00 F? (LH)
51	21		*Front wheel arch garnish LH/RH-X	0.00	0.00	*70.00 FDE (LH)
52	1		*Front fender inner panel outer LH	0.00	0.00	*110.00 FBH
53	1		*Front fender inner panel LH	0.00	0.00	*60.00 FR
54	1		*Front chassis side extension LH	0.00	0.00	*65.00 FBH
55	1		*Front chassis side extension bracket LH	0.00	0.00	*25.00 FBH
56	1		*Wire harness LH set	0.00	0.00	*600.00 F? cut
57	1		*Front levelling sensor LH	0.00	0.00	*180.00 F?
58	1		*Fuse cover top LH	0.00	0.00	*20.00 F?
59	1		*ECU unit	0.00	0.00	*1,400.00 F?
60	1		*Main fuse set	0.00	0.00	?
61	1		*Radiator fan motor	0.00	0.00	*230.00 F? 3mm
62	1		*Radiator fan blade	0.00	0.00	*40.00 F? cap
63	1		*Radiator fan cowling	0.00	0.00	*65.00 F? cap
64	1		*Aircon fan motor	0.00	0.00	*150.00 F? 3mm
65	1		*Aircon fan blade	0.00	0.00	*40.00 F? cut
66	1		*Aircon fan cowling	0.00	0.00	*70.00 F? at
67	1		*Air intake housing top	0.00	0.00	*30.00 FDE
68	1		*Air intake housing bottom	0.00	0.00	*75.00 F? (RA)
69	1		*Radiator top hose	0.00	0.00	*25.00 FFW
70	1		*Radiator bottom hose	0.00	0.00	*20.00 F? 2mm
71	1		*Radiator cap	0.00	0.00	*30.00 FX
72	1		*Front door LH Repair	0.00	0.00	
73	1		*Front original RIM LH	0.00	0.00	- X
74	1		*Front tyre LH	0	0.00	7.2 *380.00 FS Purchased
75	1		*Front shock absorber LH	0.00	0.00	*200.00 F?
76	1		*Front shock absorber top mount LH	0.00	0.00	*20.00 F?
77	1		*Front knuckle arm LH	0.00	0.00	*165.00 F?
78	1		*Front wheel bearing LH	0.00	0.00	*80.00 F?
79	1		*Front wheel hub LH	0.00	0.00	*120.00 F?
80	1		*Front lower arm LH	0.00	0.00	*160.00 F?
81	1		*Front lower arm ball joint LH	0.00	0.00	*40.00 F?
82	1		*Front stabilizer link LH	0.00	0.00	*40.00 F?
83	1		*Front Steering crossmember with bush	0.00	0.00	*550.00 F? 2mm
84	1		*Front engine crossmember	0.00	0.00	*550.00 F?
85	1		*Steering rack assembly	0.00	0.00	*820.00 F?
86	1		*Front tie rod LH	0.00	0.00	*55.00 F?
87	1		*Front tie rod end LH	0.00	0.00	*45.00 F?
88	1		*Front stabilizer bar	0.00	0.00	*90.00 F?
89	2		*Front stabilizer bar bush	0.00	0.00	*18.00 F?
90	1		*Front drive shaft LH	0.00	0.00	*550.00 F?
91	2		*Front drive shaft oil seal LH/RH	0.00	0.00	*30.00 F?
92	1		*Auto transmission fluid	0	0.00	*120.00 FS ? Am
93	1		*Front fender shield mudflap LH	0.00	0.00	*? cut ? Am
94	2		*Front impact sensor	0.00	0.00	*200.00 F
95	1		*Driver airbag	0.00	0.00	*720.00 FAL
96	1		*Driver airbag coil sensor set	0.00	0.00	*170.00 FAL
97	1		*Passenger airbag	0.00	0.00	*1,250.00 FAL

Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/23/02/2018 20:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
98	1		*Dashboard assembly	0.00	0.00	*650.00 F <i>RA</i>
99	1		*Airbag control unit	0.00	0.00	*600.00 F <i>RA</i>
100	1		*Airbag G sensor	0.00	0.00	<i>RA</i>
101	1		*Driver seatbelt	0.00	0.00	*450.00 F <i>RA</i>
102	1		*Driver seatbelt buckle ←	0.00	0.00	*90.00 F <i>RA</i> <i>? Jan</i>
103	1		*Passenger seatbelt	0.00	0.00	*450.00 F <i>RA</i> <i>?</i>
104	1		*Passenger seatbelt buckle	0.00	0.00	*90.00 F <i>RA</i> <i>?</i>
105	1		*Wiper garnish ←	0.00	0.00	*140.00 F <i>RA</i> <i>?</i>
106	1		*Battery top bracket	0.00	0.00	*10.00 F <i>RA</i>
107	1		*Battery base panel	0.00	0.00	*60.00 F <i>RA</i>
108	1		*Battery base garnish	0.00	0.00	*10.00 F <i>RA</i>
109	1		*Battery ←	0	0.00	120 *260.00 F <i>RA</i>
110	1		*Engine mounting set assembly ← \$95/\$130/\$75	0.00	0.00	*300.00 F <i>?</i>
111	1		*Engine mounting bracket LH ←	0.00	0.00	<i>?</i> <i>RA</i>
112	1		*Gearbox assembly ← <i>(Supplementary)</i> Sell separate (TBA)	0.00	0.00	<i>?</i> <i>RA</i>
113	1		*Gearbox oil sump	0.00	0.00	*200.00 F <i>?</i>
114	1		*Gearbox oil level dipstick	0.00	0.00	<i>?</i>
115	1		*Aircon suction pipe	0.00	0.00	*90.00 F <i>?</i>
116	1		*Aircon discharge pipe ←	0.00	0.00	*110.00 F <i>?</i> <i>RA</i>
117	1		*Aircon pressure pipe ←	0.00	0.00	*100.00 F <i>?</i> <i>RA</i>
118	1		*Front chassis LH	0.00	0.00	*360.00 F <i>RA</i>
119	1		*Front chassis bracket LH	0.00	0.00	<i>?</i> <i>RA</i>
120	1		*Front suspension top panel LH	0.00	0.00	*380.00 F <i>?</i>

F=Franchise part. S=SpotNet.

Sub Total (S\$)	20,263.00
+ Margin on L,N Items 10.00% (S\$)	1,928.80
Total Parts (S\$)	22,191.80

Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/23/02/2018 20:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

*Supplementary**ATF oil cooler**wire harness RH & L**starter motor**gearbox assembly*

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2400.00 1400
2	Putty, blend and paint affected area	New	1500 2400.00 1600
3	Check Wiring, re-align and ensure proper function	New	100.00 30
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 120
5	Conduct four wheel alignment / side slip test	New	180.00 60
6	Realign chassis member	New	600.00 400
7	Remove, replace & balance rim / tire	New	80.00 30
8	Remove, replace & re-install undercarriage parts	New	400.00 150?
9	Diagnostic Check & Reset Engine system	New	280.00 150?
10	Remove and replace Dashboard assembly	New	350.00 150
11	Remove and replace Airbag full set and seatbelt assembly	New	280.00 150
12	Diagnose, reset and programming Airbag full system	New	380.00 150
13	Remove, lift up and refit engine and gearbox assembly to facilitate repair work	New	350.00 200? photo
14	Dismantle, remove and replace gearbox unit, reset auto transmission system	New	400.00 220? photo
Gross Labour Cost (S\$)			8,360.00

Hitachi Capital Asia Pacific Pte. Ltd./SKX926Y/23/02/2018 20:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

14 days

P/P

27/02/18 @ 0940

EXCESS: 500

Revert

Resurvey for paint

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/09/03/2018 17:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Gearbox assembly include Programming and resetting	0.00	0.00	*6,500.00 F
2	1		*Miscellaneous item to replace (ATF Cooler, Wire Harness RH set, Starter motor and ETC.....) All item will list out and provide invoice after confirm	0.00	0.00	*6,000.00 F

F=Franchise part.

Sub Total (S\$)	12,500.00
+ Margin on L,N Items 10.00% (S\$)	1,250.00
Total Parts (S\$)	13,750.00

Hitachi Capital Asia Pacific Pte. Ltd/SKX926Y/09/03/2018 17:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Hitachi Capital Asia Pacific Pte. Ltd./SKX926Y/09/03/2018 17:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80422333QMX	Date of Loss:	16/02/2018
Vehicle Reg. No.:	SKX926Y	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG HOE KHENG	Contact No:	+6596974997
Driver:	ANG HOE KHENG		

Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	30/12/2015
Vehicle Colour:	WHITE		
Engine No:	L15B4028645	Chassis No:	RU11108643
Odometer:	5 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair 1
(day)

Description of Accident/Loss	REFER TO SKETCH PLAN
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS	Amount
Parts	17,209.30
Miscellaneous Items	0.00
Labour	4,850.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	22,059.30
+ GST 7.00% (S\$)	1,544.15
Nett Amount (S\$)	23,603.45

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	*35.00 FSS
2	1		*FRT BUMPER	0.00	0.00	*200.00 F
3	1		*FRT BUMPER LOWER	0.00	0.00	*120.00 F
4	10		*FRT BUMPER CLIPS	0.00	0.00	*25.00 F
5	2		*FRT BUMPER SIDE RETAINER	0.00	0.00	*20.00 F
6	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*180.00 F
7	2		*FRT BUMPER REINFORCEMENT TOP MOULDING L/R	0.00	0.00	*20.00 F
8	2		*FRT HEADLAMP LOWER BRACKET	0.00	0.00	*40.00 F
9	1		*FRT GRILLE	0.00	0.00	*180.00 F
10	1		*FRT GRILLE OUTER GARNISH	0.00	0.00	*140.00 F
11	2		*FRT GRILLE SIDE BRACKET L/R	0.00	0.00	*20.00 F
12	1		*FRT GRILLE CENTER BRACKET	0.00	0.00	*20.00 F
13	2		*FRT GRILLE CHROME L/R	0.00	0.00	*40.00 F
14	1		*FRT GRILLE EMBLEM	0.00	0.00	*15.00 F
15	6		*FRT GRILLE CLIPS	0.00	0.00	*40.00 F
16	1		*FRT SUPPORT TOP GARNISH	0.00	0.00	*15.00 F
17	5		*FRT SUPPORT TOP GARNISH CLIPS	0.00	0.00	*45.00 F
18	1		*FRT LOWER GRILLE	0.00	0.00	*280.00 F
19	2		*FRT FOG LAMP	0.00	0.00	*20.00 F
20	2		*FRT FOG LAMP BRACKET L/R	0.00	0.00	*30.00 F
21	2		*FRT FOG LAMP COVER L/R	0.00	0.00	*35.00 F
22	1		*FRT A/C TEMPERATURE SENSOR	0.00	0.00	*10.00 F
23	1		*FRT A/C TEMPERATURE SENSOR BRACKET	0.00	0.00	*65.00 F
24	1		*FRT ENGINE UNDERCOVER CTR	0.00	0.00	*70.00 F
25	2		*FRT ENGINE UNDERCOVER L/R	0.00	0.00	*25.00 F
26	10		*FRT ENGINE UNDERCOVER CLIPS	0.00	0.00	*360.00 F
27	2		*FRT FENDER L/R	0.00	0.00	*100.00 F
28	2		*FRT FENDER PROTECTOR L/R	0.00	0.00	*140.00 F
29	2		*FRT FENDER INNER SHIELD L/R	0.00	0.00	*40.00 F
30	16		*FRT FENDER INNER SHIELD CLIPS L/R	0.00	0.00	*85.00 F
31	1		*FRT FENDER INNER PANEL (INNER)LH.	0.00	0.00	*75.00 F
32	1		*FRT FENDER INNER PANEL (OUTER)LH.	0.00	0.00	*380.00 F
33	1		*FRT CHASSIS LH	0.00	0.00	*45.00 F
34	1		*FRT CHASSIS SIDE MEMBER SUPPORT BRACKET LH	0.00	0.00	*380.00 F
35	1		*FRT BONNET	0.00	0.00	*56.00 F
36	2		*FRT BONNET HINGE L/R	0.00	0.00	*65.00 F
37	1		*FRT BONNET INSULATOR	0.00	0.00	*20.00 F
38	8		*FRT BONNET INSULATOR CLIPS	0.00	0.00	*30.00 F
39	2		*FRT BONNET SIDE SEAL L/R	0.00	0.00	*30.00 F
40	2		*FRT BONNET CTR SEAL L/R	0.00	0.00	*30.00 F
41	2		*FRT BONNET RUBBER PAD L/R	0.00	0.00	*30.00 F
42	1		*FRT BONNET STOPPER@SUPPORT LH	0.00	0.00	*10.00 F

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*FRT BONNET LOCK	0.00	0.00	*65.00 FPA
44	1		*FRT BONNET LOCK CABLE	0.00	0.00	*18.00 F ? BPT
45	1		*FRT WIPER GARNISH	0.00	0.00	*140.00 F ? BPT
46	1		*FRT SUPPORT PANEL CPL	0.00	0.00	*300.00 F PA
47	1		*FRT HORN LH	0.00	0.00	*30.00 F ? CBA
48	1		*FRT GEAR BOX CORNER	0.00	0.00	*160.00 F ? BPT
49	1		*FRT GEAR BOX PICK UP SENSOR LH	0.00	0.00	*65.00 F ? BPT
50	1		*BATTERY	0	0.00	*180.00 FS CBA
51	1		*BATTERY BASE PANEL	0.00	0.00	*50.00 FPA
52	1		*BATTERY TRAY	0.00	0.00	*15.00 F ? CBA
53	1		*BATTERY TERMINAL + COVER	0.00	0.00	*55.00 F ? CBA
54	1		*BATTERY TOP BRACKET	0.00	0.00	*15.00 FPA
55	2		*BATTERY TOP BRACKET SUPPORT BAR	0.00	0.00	*16.00 FR
56	1		*AIR RESONATOR	0.00	0.00	*75.00 FPA
57	1		*AIR INTAKE DUCT	0.00	0.00	*45.00 FPA
58	2		*AIR INTAKE DUCT CLIPS	0.00	0.00	*5.00 FPA
59	1		*AIR INTAKE HOSE	0.00	0.00	*45.00 FPA
60	1		*AIR FLOW SENSOR HOSE	0.00	0.00	*18.00 F ? XSVL
61	1		*AIR CLEANER BOX ASSY	0.00	0.00	*150.00 F ? CBA
62	1		*FRT LH RELAY BOX TOP COVER	0.00	0.00	*10.00 F ?
63	1		*FRT LH RELAY BOX LOWER COVER TYPO: FRT LH RELAY BOX HOUSING	0.00	0.00	*650.00 F ? XSVL
64	1		*FRT ECU BRACKET	0.00	0.00	*40.00 F ?
65	1		*FRT WIRE HARNESS CTR	0.00	0.00	*650.00 F ? CBA
66	1		*FRT STARTER ASSY	0.00	0.00	*850.00 F ? CBA
67	1		*FRT ENGINE MOUNTING LH	0.00	0.00	*150.00 F ? CBA
68	1		*FRT ENGINE MOUNTING RH	0.00	0.00	*95.00 F ? CBA
69	1		*FRT ENGINE MOUNTING RR	0.00	0.00	*70.00 F ? XSVL
70	1		*FRT THROTTLE ASSY	0.00	0.00	*850.00 F ?
71	1		*A/C CONDENSER	0.00	0.00	*310.00 F ? CBA
72	2		*A/C CONDENSER AIR GUIDE L/R	0.00	0.00	*40.00 F ? XSVL
73	1		*A/C HIGH PRESSURE	0.00	0.00	*100.00 F ? BPT
74	1		*A/C CONDENSER TOP BRACKET LH	0.00	0.00	*10.00 F ?
75	1		*A/C FAN COWLING	0.00	0.00	*60.00 FPA
76	1		*A/C FAN BLADE	0.00	0.00	*30.00 F ? BPT
77	1		*A/C FAN MOTOR	0.00	0.00	*150.00 F ? BPT
78	1		*RADIATOR	0.00	0.00	*680.00 FPA
79	1		*COOLANT	0	0.00	*40.00 FS
80	2		*RADIATOR TOP BRACKET L/R	0.00	0.00	*20.00 FPA
81	2		*RADIATOR TOP MOUNTING BUSH L/R	0.00	0.00	*12.00 FPA
82	2		*RADIATOR LOWER MOUNTING BUSH L/R	0.00	0.00	*20.00 FPA
83	1		*RADIATOR SPARE TANK	0.00	0.00	*30.00 F ? DE
84	1		*RADIATOR SPARE TANK HOSE	0.00	0.00	*10.00 F ? XSVL
85	1		*RADIATOR FAN COWLING	0.00	0.00	*70.00 FPA
86	1		*RADIATOR FAN BLADE	0.00	0.00	*38.00 FPA
87	1		*RADIATOR FAN MOTOR	0.00	0.00	*210.00 F ? BPT
88	1		*RADIATOR TOP HOSE	0.00	0.00	*15.00 FPA
89	2		*FRT AIR BAG IMPACT SENSOR L/R	0.00	0.00	*240.00 FPA
90	1		*FRT AIR BAG AT STEERING	0.00	0.00	*900.00 FPA
91	1		*FRT AIR BAG AT LH	0.00	0.00	*850.00 FPA
92	1		*FRT AIR BAG CONTROL UNIT	0.00	0.00	*580.00 F ? BPT
93	1		*FRT AIR BAG STEERING CLOCK SPRING	0.00	0.00	*95.00 FPA
94	2		*FRT SEAT BELT L/R	0.00	0.00	*500.00 FPA
95	2		*FRT SEAT BELT BUCKLE L/R	0.00	0.00	*220.00 FX
96	1		*FRT DASHBOARD ASSY	0.00	0.00	*450.00 F ? BPT
97	1		*FRT DASHBOARD LH A/C AIR VENT COVER (ROUND)	0.00	0.00	*45.00 F ? BPT
98	2		*FRT HEADLAMP	0.00	0.00	*1,580.00 FPA

F=Franchise part. S=SpcNett.

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Sub Total (S\$)						15,668.00
+ Margin on L,N Items 10.00% (S\$)						1,541.30
Total Parts (S\$)						17,209.30

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00 ✓
2	TO REMOVE AND REFIT FRT DASHBOARD	New	220.00 150 ✓
3	TO REMOVE AND REFIT FRT WIRE HARNESS	New	200.00 100 ✓
4	TO RESET AND DIAGNOSE FAULT CODE	New	100.00 ✓
5	TO REMOVE ,REPLACE & REFIT AIR BAG SYSTEM	New	400.00 200 ✓
6	TO TOP UP AIR CON GAS	New	100.00 ✓
7	TO KNOCK FRT WHEEL HOUSE PANEL LH, FRT CHASSIS, WELD,REMOVE AND REFIT ABOVE PARTS	New	2,200.00 1500 ✓
8	TO PUTTY & RESPRAY ON FRT BUMPER, FRT FENDER x2, FRT BONNET, FRT SUPPORT PANEL, FRT PANEL INNER PANEL LH, FRT WHEEL HOUSE PANEL LH,FRT DOOR x2 & ACCIDENT AREAS	New	1,600.00 1300 ✓
Gross Labour Cost (S\$)			4,850.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resme

Hp 90010068

14 days

P/P

27/02/18 @ 0940

EXCESS : 500

Resurvey 54 paint

28/3/18

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80422333QMX	Date of Loss:	16/02/2018
Vehicle Reg. No.:	SKX926Y	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG HOE KHENG	Contact No:	+6596974997
Driver:	ANG HOE KHENG		

Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	30/12/2015
Vehicle Colour:	WHITE	Chassis No:	RU11108643
Engine No:	L15B4028645		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	1

Description of Accident/Loss	REFER TO SKETCH PLAN
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

Parts	1,093.40
Miscellaneous Items	0.00
Labour	80.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,173.40
+ GST 7.00% (S\$)	82.14
Nett Amount (S\$)	1,255.54
+ Previous Estimates (S\$)	23,603.45
Claim Total (S\$)	24,858.99

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 May 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/04/05/2018 11:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No. Particulars	%Disc	%Depr	Amount
1	1	*FRONT WIRE HARNESS LH	0.00	0.00	*650.00 F <i>ad</i>
2	1	*FRONT CHASSIS SIDE MEMBER SUPPORT (INNER) LH H69044-T7A-300Z	0.00	0.00	*35.00 F <i>bt</i>
3	1	*SENSOR OIL PRESSURE SWITCH(missing item)	0.00	0.00	*130.00 F <i>ms</i>
4	1	*O RING OIL PRESSURE SWITCH(item missing)	0.00	0.00	*3.00 F <i>ms</i>
5	1	*AIR CLEANER BOX TOP	0.00	0.00	*50.00 F <i>DE</i>
6	1	*FRONT BONNET STAND CLIP (missing item)	0.00	0.00	*3.00 F <i>ms</i>
7	1	*ATF FLUID 4L	0.00	0.00	*63.00 F <i>ms</i>
8	1	*FRONT BUMPER LOWER RUBBER (missing item)	0.00	0.00	*45.00 F <i>ms</i>
9	1	*FRONT FENDER INNER GARNISH	0.00	0.00	*15.00 F <i>DE</i>
Sub Total (S\$)					994.00
+ Margin on L,N Items 10.00% (S\$)					99.40
Total Parts (S\$)					1,093.40

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/04/05/2018 11:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WHEEL ALIGNMENT	New	80.00
Gross Labour Cost (\$\$)			80.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/04/05/2018 11:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2018)
 Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	4735 SN	*FRT NUMBER PLATE	0	0.00	*35.00 RS
2	1	47200	*FRT BUMPER	0.00	0.00	*200.00 F Ben
3	1	47120	*FRT BUMPER LOWER	0.00	0.00	*120.00 F 06
4	10	10X42-4720	*FRT BUMPER CLIPS	0.00	0.00	*25.00 FAN
5	2	2X410-4720	*FRT BUMPER SIDE RETAINER	0.00	0.00	*20.00 FAN
6	1	4780	*FRT BUMPER REINFORCEMENT	0.00	0.00	*180.00 FTH
7	2	2X410-4720	*FRT BUMPER REINFORCEMENT TOP MOULDING L/R	0.00	0.00	*20.00 FAN
8	2	2X4720-4740	*FRT HEADLAMP LOWER BRACKET	0.00	0.00	*40.00 F 20
9	1	47180	*FRT GRILLE	0.00	0.00	*180.00 F 02
10	1	47140	*FRT GRILLE OUTER GARNISH	0.00	0.00	*140.00 F 04
11	2	2X410-4720	*FRT GRILLE SIDE BRACKET L/R	0.00	0.00	*20.00 F 04
12	1	4720	*FRT GRILLE CENTER BRACKET	0.00	0.00	*20.00 F 04
13	2	2X4720-4740	*FRT GRILLE CHROME L/R	0.00	0.00	*40.00 F 04
14	1	4715	*FRT GRILLE EMBLEM	0.00	0.00	*15.00 FAN
15	6	6X42-4720	*FRT GRILLE CLIPS	0.00	0.00	*15.00 FAN
16	1	4740	*FRT SUPPORT TOP GARNISH	0.00	0.00	*40.00 F 05
17	6	6X42-4720	*FRT SUPPORT TOP GARNISH CLIPS	0.00	0.00	*15.00 FAN
18	1	4745	*FRT LOWER GRILLE	0.00	0.00	*45.00 F 04
19	2	2X4720-4740	*FRT FOG LAMP	0.00	0.00	*280.00 FLH-04/RH-X04
20	2	4710	*FRT FOG LAMP BRACKET L/R	0.00	0.00	*20.00 FLH-04/RH-X04
21	2	2X4720-4740	*FRT FOG LAMP COVER L/R	0.00	0.00	*30.00 FLH-04/RH-X04
22	1	4735	*FRT A/C TEMPERATURE SENSOR	0.00	0.00	*35.00 F 04
23	1	4710	*FRT A/C TEMPERATURE SENSOR BRACKET	0.00	0.00	*10.00 F 04
24	1	4715	*FRT ENGINE UNDERCOVER CTR	0.00	0.00	*85.00 F 04
25	2	2X4720-4740	*FRT ENGINE UNDERCOVER L/R	0.00	0.00	*70.00 FLH-04/RH-X04
26	10	10X42-4720	*FRT ENGINE UNDERCOVER CLIPS	0.00	0.00	*25.00 FAN
27	2	2X4720-4740	*FRT FENDER L/R	0.00	0.00	*360.00 F 04
28	2	2X4720-4740	*FRT FENDER PROTECTOR L/R	0.00	0.00	*100.00 FLH-04/RH-X04
29	2	4730	*FRT FENDER INNER SHIELD L/R	0.00	0.00	*140.00 FLH-04/RH-X04
30	16	16X42-4720	*FRT FENDER INNER SHIELD CLIPS L/R	0.00	0.00	*40.00 FAN
31	1	4715	*FRT FENDER INNER PANEL (INNER) LH	0.00	0.00	*85.00 F 04
32	1	4715	*FRT FENDER INNER PANEL (OUTER) LH	0.00	0.00	*75.00 F 04
33	1	4730	*FRT CHASSIS LH	0.00	0.00	*380.00 F 04
34	1	4730	*FRT CHASSIS SIDE MEMBER SUPPORT BRACKET LH	0.00	0.00	*45.00 F 04
35	1	4730	*FRT BONNET	0.00	0.00	*380.00 F 04
36	2	2X4720-4740	*FRT BONNET HINGE L/R	0.00	0.00	*56.00 F 04
37	1	4715	*FRT BONNET INSULATOR	0.00	0.00	*65.00 F 04
38	8	8X42-4720	*FRT BONNET INSULATOR CLIPS	0.00	0.00	*20.00 FAN
39	2	2X415-4740	*FRT BONNET SIDE SEAL L/R	0.00	0.00	*30.00 FAN
40	2	2X415-4740	*FRT BONNET CTR SEAL L/R	0.00	0.00	*30.00 FAN
41	2	2X4720-4740	*FRT BONNET RUBBER PAD L/R	0.00	0.00	*30.00 FAN
42	1	4715	*FRT BONNET STOPPER@SUPPORT LH	0.00	0.00	*10.00 FAN

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1	945	*FRT BONNET LOCK ✓	0.00	0.00	*65.00 FRT ✓
44	1	948	*FRT BONNET LOCK CABLE ✓	0.00	0.00	*18.00 FRT ✓
45	1	940	*FRT WIPER GARNISH ✓	0.00	0.00	*140.00 FRT ✓
46	1	9290	*FRT SUPPORT PANEL CPL ✓	0.00	0.00	*300.00 FRT ✓
47	1	930	*FRT HORN LH ✓	0.00	0.00	*30.00 FRT ✓
48	1	945	*FRT GEAR BOX CORNER cooler ✓	0.00	0.00	*180.00 FRT ✓
49	1	945	*FRT GEAR BOX PICK UP SENSOR LH ✓	0.00	0.00	*65.00 FRT ✓
50	1	9150	*BATTERY ✓	0	0.00	*180.00 FS (RT) ✓
51	1	950	*BATTERY BASE PANEL ✓	0.00	0.00	*50.00 FRT ✓
52	1	910	*BATTERY TRAY F15 ✓	0.00	0.00	*15.00 FRT ✓
53	1	910	*BATTERY TERMINAL + COVER ✓	0.00	0.00	*55.00 FRT ✓
54	1	910	*BATTERY TOP BRACKET ✓	0.00	0.00	*15.00 FRT ✓
55	2		*BATTERY TOP BRACKET SUPPORT BAR ✓	0.00	0.00	*16.00 FRT ✓
56	1	975	*AIR RESONATOR ✓	0.00	0.00	*75.00 FRT ✓
57	1	945	*AIR INTAKE DUCT ✓	0.00	0.00	*45.00 FRT ✓
58	2	9220	*AIR INTAKE DUCT CLIPS ✓	0.00	0.00	*5.00 FRT ✓
59	1	945	*AIR INTAKE HOSE ✓	0.00	0.00	*45.00 FRT ✓
60	1		*AIR FLOW SENSOR HOSE ✓	0.00	0.00	*18.00 FRT ✓
61	1	910	*AIR CLEANER BOX ASSY (Lower) ✓	0.00	0.00	*150.00 FRT ✓
62	1		*FRT LH RELAY BOX TOP COVER ✓	0.00	0.00	*10.00 FRT ✓
63	1		*FRT LH RELAY BOX LOWER COVER c/w wire harness LH ✓	0.00	0.00	*650.00 FRT ✓
64	1		*FRT ECU BRACKET ✓	0.00	0.00	*40.00 FRT ✓
65	1		*FRT WIRE HARNESS CTR ✓	0.00	0.00	*650.00 FRT ✓
66	1	9450	*FRT STARTER ASSY ✓	0.00	0.00	*850.00 FRT ✓
67	1	9150	*FRT ENGINE MOUNTING LH ✓	0.00	0.00	*150.00 FRT ✓
68	1	945	*FRT ENGINE MOUNTING RH ✓	0.00	0.00	*85.00 FRT ✓
69	1	970	*FRT ENGINE MOUNTING RR ✓	0.00	0.00	*70.00 FRT ✓
70	1		*FRT THROTTLE ASSY ✓	0.00	0.00	*850.00 FRT ✓
71	1	9300	*A/C CONDENSER ✓	0.00	0.00	*310.00 FRT ✓
72	2	9220	*A/C CONDENSER AIR GUIDE L/R ✓	0.00	0.00	*40.00 FRT ✓
73	1		*A/C HIGH PRESSURE ✓	0.00	0.00	*100.00 FRT ✓
74	1	910	*A/C CONDENSER TOP BRACKET LH ✓	0.00	0.00	*10.00 FRT ✓
75	1	960	*A/C FAN COWLING ✓	0.00	0.00	*80.00 FRT ✓
76	1	930	*A/C FAN BLADE ✓	0.00	0.00	*30.00 FRT ✓
77	1	9150	*A/C FAN MOTOR ✓	0.00	0.00	*150.00 FRT ✓
78	1	9680	*RADIATOR ✓	0.00	0.00	*880.00 FRT ✓
79	1	9400	*COOLANT ✓	0	0.00	*40.00 FRT ✓
80	2	9220	*RADIATOR TOP BRACKET L/R ✓	0.00	0.00	*20.00 FRT ✓
81	2	9220	*RADIATOR TOP MOUNTING BUSH L/R ✓	0.00	0.00	*12.00 FRT ✓
82	2	9220	*RADIATOR LOWER MOUNTING BUSH L/R ✓	0.00	0.00	*20.00 FRT ✓
83	1	930	*RADIATOR SPARE TANK ✓	0.00	0.00	*30.00 FRT ✓
84	1		*RADIATOR SPARE TANK HOSE ✓	0.00	0.00	*10.00 FRT ✓
85	1	970	*RADIATOR FAN COWLING ✓	0.00	0.00	*70.00 FRT ✓
86	1	930	*RADIATOR FAN BLADE ✓	0.00	0.00	*38.00 FRT ✓
87	1	910	*RADIATOR FAN MOTOR ✓	0.00	0.00	*210.00 FRT ✓
88	1	915	*RADIATOR TOP HOSE ✓	0.00	0.00	*15.00 FRT ✓
89	2	9120	*FRT AIR BAG IMPACT SENSOR L/R ✓	0.00	0.00	*240.00 FRT ✓
90	1	9120	*FRT AIR BAG AT STEERING ✓	0.00	0.00	*900.00 FRT ✓
91	1	9120	*FRT AIR BAG AT LH ✓	0.00	0.00	*850.00 FRT ✓
92	1	9120	*FRT AIR BAG CONTROL UNIT ✓	0.00	0.00	*580.00 FRT ✓
93	1	945	*FRT AIR BAG STEERING CLOCK SPRING ✓	0.00	0.00	*95.00 FRT ✓
94	2	9120	*FRT SEAT BELT L/R ✓	0.00	0.00	*500.00 FRT ✓
95	2		*FRT SEAT BELT BUCKLE L/R ✓	0.00	0.00	*220.00 FRT ✓
96	1	9450	*FRT DASHBOARD ASSY ✓	0.00	0.00	*450.00 FRT ✓
97	1	9120	*FRT DASHBOARD LH A/C AIR VENT COVER (ROUND) ✓	0.00	0.00	*45.00 FRT ✓
98	2	9120	*FRT HEADLAMP ✓	0.00	0.00	*1,580.00 FRT ✓

F=Franchise part. S=SpocNet

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS