

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile							
	LONPAC INSURAN	NCE BHD	Ref:	CC4/LPC18003579/Kyb3q2			
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	02/07/2021			
			Code:	LPC2			
1.		Policy Particulars :	- THIRD PARTY CLAIF	И			
	Insured Veh.	SKR 1594X	Veh. Inspected	SJN 8028B			
	Policy No.	Z18VP05016941	Coverage (\$)	0.00			
	Claim No.	18/18/18/VP05/020391	Excess (\$)	0.00			
	Assign From	GERALD	Assign Date	22/02/2018			
2.		Vehicle Partic	ulars & Condition				
	Make & Model	B.M.W. X3 (A)	c.c	1997			
	Engine No.	HIDDEN	Year of Reg.	2016			
	Chassis No.	WBAWY920000R99723	Colour	METALLIC SILVER			
	Odometer	36666 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM			
	General	GOOD					
3.		Condition	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	245/50 R18	PIRELLI	5 mm			
	L/H Front Tyre	245/50 R18	PIRELLI	5 mm			
	R/H Rear Tyre	245/50 R18	PIRELLI	6 mm			
	L/H Rear Tyre	245/50 R18	PIRELLI	6 mm			
4.		Description	on of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.						
	DAMAGES SEE DETAILS.						
5.		General	Information				
	Accident Date	08/02/2018	Inspection Date	22/02/2018			
	Survey held at	SIONG LEE MOTOR					
		SIN MING INDUSTRIAL ESTATE BLOCK 12 SECTOR B #01-73 SINGAPORE 575656.					
5a.			emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.		Estimate I	Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days						



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 8028B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	MTG DISTORTED	1,509.45	1,509.45
2	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	738.05	-
1	REAR BUMPER PAD	DENTED / CUT	480.20	480.20
1	REAR BUMPER LOWER GARNISH	SERVICEABLE	369.70	-
1	SIDE GARNISH RIVERT (ADDITIONAL)	NECESSARY	70.00	70.00
	LESS 10% DISCOUNT		-316.74	-205.97
			2,850.66	1,853.68
	SPECIAL NETT ITEMS			
2	REVERSE SENSOR (SN) (ADDITIONAL)	SHORTED	350.00	350.00
			350.00	350.00
	<u>LABOUR</u>			
	LABOUR TO SPRAY PAINT.		400.00	280.00
	LABOUR TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		350.00	250.00
			750.00	530.00
	GRAND TOTAL		3,950.66	2,733.68

RECOMMENDED COST OF LUMP SUM REPAIRS		2.150.00
(TO ITS PRE-ACCIDENT CONDITION)		,

Report Ref No. CC4/LPC18003579/Kyb3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJN 8028B

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJN 8028B

RE-INSPECTION









