

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

Not Admin
d/s #2550/2
Hdy.
16/10/18
Take up the rep

YP5138Z Mitsubishi Canter

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 1,290.00
2	2	Front bumper bracket	\$ 246.00
3	1	Front bumper reinforcement	\$ 337.00
4	1	Front grille assy	\$ 287.00
5	1	Front grille centre emblem	\$ 83.00
6	1	Front grille canter emblem	\$ 80.00
7	1	Front left headlamp	\$ 786.00
8	1	Front left signal lamp	\$ 107.00
9	1	Front left side lamp	\$ 124.00
10	1	Front panel assy	\$ 823.00
11	1	Front left corner panel	\$ 284.00
12	1	Front right corner panel	\$ 284.00
13	1	Front wiper garnish (center)	\$ 394.00
14	1	Front windscreen glass moulding	\$ 286.00
15	1	Front left wing mirror assy	\$ 693.00
16	1	Front right wing mirror assy	\$ 493.00
17	1	Front right headlamp	\$ 786.00
18	1	Front right signal lamp	\$ 107.00
19	1	Front right side lamp	\$ 124.00
20	2	Front wiper arm	\$ 138.00
21	2	Front wiper blade	\$ 88.00
22	1	Front wiper linkage	\$ 179.00
23	1	Front wiper motor	\$ 283.00
24	1	Front dashboard assy	\$ 986.00
25	1	Front glove compartment assy	\$ 163.00
26	1	Front air con evaporator assy	\$ 1,634.00
27	1	Front air con evaporator coil temperature sensor	\$ 162.00
28	1	Front air con blower motor	\$ 698.00
29	2	Front engine mounting	\$ 885.00
			\$ 12,830.00
Less 25% (502)			\$ 3,207.50
			\$ 9,622.50

Special Nett Items

1	6	Front grille clips	\$ 30.00
2	6	Front wiper garnish clips (center)	\$ 30.00
3	1	Front grille company sticker	\$ 150.00
4	1	Front windscreen glass sealant	\$ 80.00
5	1	Front no plate	\$ 80.00
			\$ 370.00

Total parts

\$ 9,992.50

150

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

YP5138Z Mitsubishi Canter

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,200.00 600
2	To putty and spray painting front portion.	\$ 1,200.00 600
3	To check wiring and focus front headlamp.	\$ 50.00 20
4	To remove and install air con system including evaporator assy to facilitate the repair and refill gas.	\$ 1300.00 X
5	To apply anti rust proofing to front affected area.	\$ 120.00 X
6	To remove and install front dashboard assy.	\$ 300.00 X
7	To repair, straighten and align both front door panel assy.	\$ 350.00 X
8	Towing service.	\$ 120.00 X
		<u>\$ 3,640.00</u>
		1220

Total parts : \$ 9,992.50

Total labour : \$ 3,640.00

Total repair cost : \$ 13,632.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-2375.42
 Less 502
 P+1187.56
 S.N+ 150.00
 Labor+ 1220.00
 2557.56