

REPAIR ESTIMATE*

VEHICLE NO : SHA 6924U

MAKE :

MODEL : HYUNDAI i40


Aig Asia - LK Sum

DATE 26/2/2018

IS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Grille (RH)			\$ 40.30
	Front Bumper Bracket (RH)			\$ 24.60
	Front RH Fender		\$619	\$ 627.20
	Front RH Headlamp		\$125.44	\$ 125.44
	DISCOUNTED TOTAL			\$ 501.76
	Labour Charge			
	Panel Beating- Repair FRT RH Fender			\$ 300
	Spray Painting Charge			\$ 500.00
				\$ 400.00
				360
	TOTAL LABOUR			\$ 900.00
	ESTIMATE TOTAL			\$ 1,401.76
<p>Kalvin (1/6/14)</p> <p>26/2/18 1435h</p> <p>2 Pys.</p> <p>4/5</p> <p>Atta Rymph</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

[illegible]

[illegible]