

22/03/2002

ASS. REC. BY:

REF: CS/FCI18003694/MT-103

n2

Special Instruction:

Surveyor:

Ma

ASSIGNMENT (Office)

CWS

From (Person):

Eileen Lee

of

FCI

Date/Time:

23/2/18 @ 3pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 8470X

Insured:

SH 7268G

at Workshop m/s

Motor Image

Tel:

9090 3323

of

19 Loring & Ton Payoh

Policy No:

Claim No:

D18001474MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/02/18

01/03/18 @ After 10am

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

10:29am 26/2/18

Person Contacted:

oliver

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SKW 8470X - X

SH 7268G - CS/FCI12004308/Ay/n

D.O.A: 28/2/12

5B-

Revert preli advise

Part by Part \$5905.28 (Red: 55/1696: 48%)

REF:

FCL

ASSIGNMENT

From: _____ Date: 01032018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 8970X

at Workshop m/s: Motor Image
of 17 Loring & Tou Payoh

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

after 10am

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW 8970X Vtr Regn: 11 ? 15
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUZUKI XV. 1600

Colour: Red A/C Insured / Std / NI / NA

Sp. Reading: 25743. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1GP3KC5FG159036.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 225/55/17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 8 mm

R/Bal: 8 mm

L/Bal: 8 mm

L/Bal: 8 mm

D.O.A: 19/02/2018.

D.O.I: 11/3/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 27 AUG 2018

Date/Time: File Pass to?

24/8 Typist ☐ Preli. Report

Date/Time: File Return to?

☒ Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1 - E - RS - \$

Phone:

Others:

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Invs \$☐ Weekend \$

Report Format: TP

Lump Sum / I.B.I.: \$ 5905.28

170+15

50

50

32

317



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003694/M1td3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7268G	Veh. Inspected	SKW 8970X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001474MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/02/2018	Inspection Date		
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001474MESH

Date: 5/3/2018

Our Ref: CS/FCI18003694/M1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKW 8970X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 5/3/2018 at the premises of M/s Motor Image, and have the following to report: -


Workshop Estimate Amount	: S\$ <u>10,891.04</u>
Revised Estimate Amount	: S\$ <u>5,374.08</u>
"Check" Items Amount	: S\$ <u>5.76</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u></u>
Nett Value	: S\$ <u></u>

Description of Damage:

The vehicle sustained damages at the rear.

Comments/ Present Status:

Damages Consistent.



Yours faithfully

Ma CF

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-02-2018	Our Ref No.	D18001474MFSH
Accident Date	19-02-2018	Claim Type.	Third Party
Insured Vehicle	SH7268G	Third Party Vehicle.	SKW8970X
Survey Location	19 LORONG 8 TOA PAYOH		
Contact Person.	OLIVER ZUBIRI		
Contact No.	01 90903323	Fax No.	0
Survey Type			
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOTOR IMAGE ENTERPRISES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235150)



PRI Documents



Close



PRI Header Details

Claim No	D18001474MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & MOTOR IM
Workshop Name	MOTOR IMAGE ENTERPRISES PTE LTD (Contact Person : OLIVER ZUBIRI)	Survey Location & Contact Details	19 LORONG 8 TOA PAYOH Mobile: 90903323 , Phone: 0 , Fax: 0 EmailId: OLIVERGRACILLA@MOTORIMAGE.NET		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor			
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7268G	TP Vehicle No	SKW8970X
PRI Recieved Date	23-02-2018 03:23:43 PM	Surveyor Appointed Date	23-02-2018 02:59:49 PM	Surveyor Accept Date	27-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 5 March 2018 4:55 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001474MFSH/1
Attachments: PRELI ADVISED SKW 8970X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKW 8970X**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 26 February 2018 10:33 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001474MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 01/03/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 23 February 2018 3:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001474MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0640/2018
DATE : 19-FEB-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : HOPE DAVID ANTHONY
ADDRESS : 20 BUKIT CHERMIN ROAD

S(109919)
TELEPHONE NO : 9367 7114 MS ALEX

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100438927-02
VEHICLE NO : SKW8970X
MODEL CODE : GP3DKDC
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT
ENGINE NO : FB16Y065887
CHASSIS NO : JF1GP3KC5FG159036
MILEAGE : 1 KM
DATE IN : 19/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 19/02/2018

Print Date : 21/02/2018
Print Time : 10:16:24

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW8970X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL LOCATION:DOVER ROAD OUTSIDE ALS SCHOOL DATE:19/02/2018 TIME:0805HRS		
3	ZZ/002	REMOVE/REPLACE RR BUMPER,END PANEL,FLOOR PAN, TAILGATE	2240.00 2160	✓
4	ZZ/003	RESPRAY RR BUMPER,END PANEL,FLOOR PAN,TAILGATE	1680.00 1260	✓
5	ZZ/004	DISMENTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	900.00	X
6	ZZ/005	REMOVE AND REFIX EXHAUST	150.00	✓
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	X
8	ZZ/007	TRANSFER(TAILGATE)MECHANISM	150.00	X
9	ZZ/008	WHEEL ALIGNMENT	200.00	X
10	ZZ/009	REMOVE&REFIX CARPET,SEATS TO FACILITATE REPAIRS	550.00 350	✓
11	ZZ/011	TO CONDUCT(REAR)LIGHTING TEST	50.00	✓
12	ZZ/012	TO CONDUCT(REAR) ANTI-RUST COATING	580.00 350	✓
13	ZZ/013	TO SUPPLY & INSTALL REVERSE SENSOR-2 EYES	300.00	✓ shw
14	ZZ/014	SUNDRIES	100.00	X
15	ZZ/10	TO REMOVE & REFIX FUEL TANK	200.00	X
TOTAL LABOUR CHARGES			7200.00	

Not Authorized
P19 Repair
Believe paint job
Lab Auto (M)
1/3/2018
6w/days

Signature
5/3/18

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW8970X

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	FLOOR PAN R	CKD-XV 52129FJ0009P	X 540.00	R	X	
2	SKIRT COMPL R 5D	52401FJ0209P	X 244.80	NSP.	X	
3	BUMPER FACE R XUV	57704FJ041	✓ 594.00	def.	✓	
4	BRKT RRH BUMP CORN	57707FJ080	✓ 28.80	dis	✓	
5	BRKT RLH BUMP CORN	57707FJ090	✓ 28.80	dis	✓	
6	BRKT RRH BUMP	57707FJ160	✓ 14.40	dis	✓	
7	BRKT RLH BUMP	57707FJ170	✓ 14.40	dis	✓	
8	BRKT BUMP R LWR	57707FJ201	? 7.20	X nn		
9	COVER-REAR BUMPER	57731FG010TQ	X 14.40	QVC	X	
10	PANEL-REAR GATE	60809FJ0019P	X 720.00	R.	X	
11	GLASS ASSY R G	63019FJ000	X 799.20	NK.	X	
12	LAT & ACT AY RG	63032FG111	X 176.40	nn	X	
13	STRIKER R/G	63264AG100	X 21.60	NK	X	
14	WEATHER STRIP-REAR GATE	63516FJ000	✓ 85.00	dis	✓	
15	DAM RUBBER R WIND	65245SC000	X 21.60	NK.	X	
16	REFLEX AY RH	84281FG000	X 21.60	nn	X	
17	REFLEX ASSY LH	84281FG010	X 21.60	QVC	X	
18	LENS & BODY-R COMBI LAMP RH	84912FJ040	X 377.40	nn	X	
19	LENS & BODY-R COMBI LAMP LH	84912FJ050	X 377.40	QVC	X	
20	GARNISH ASSY-REAR GATE,B	91111FJ190WU	X 238.00	nn	X	
21	ORNAMENT ASSY F SIX	91174SA181	/ 68.40	nn	✓	
22	LETTER MARK-REAR	93079FJ060	/ 68.00	nn	✓	
23	LETTER MARK-REAR	93079FJ100	/ 40.80	nn	✓	
24	TRIM PNL R SKIRT	94026FJ000VH	X 90.00	nn	X	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW8970X

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
SUB TOTAL		4613.80	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		922.76	0.00	0.00	0.00
GRAND TOTAL		3691.04	0.00	0.00	0.00
OVERALL TOTAL		3691.04			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW8970X

TOTAL LABOUR CHARGES 7200.00
TOTAL SPARE PARTS CHARGES 3691.04

GRAND TOTAL 10891.04 *

11472-24

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0640/2018
DATE : 19-FEB-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : HOPE DAVID ANTHONY
ADDRESS : 20 BUKIT CHERMIN ROAD

S(109919)
TELEPHONE NO : 9367 7114 MS ALEX

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100438927-02
VEHICLE NO : SKW8970X
MODEL CODE : GP3DKDC
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT
ENGINE NO : FB16Y065887
CHASSIS NO : JF1GP3KC5FG159036
MILEAGE : 25750 KM
DATE IN : 19/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 19/02/2018

Print Date : 20/06/2018
Print Time : 12:29:52

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW8970X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL LOCATION:DOVER ROAD OUTSIDE ALS SCHOOL DATE:19/02/2018 TIME:0805HRS		
3	ZZ/002	REMOVE/REPLACE RR BUMPER,END PANEL,FLOOR PAN, TAILGATE	2240.00	2160.00
4	ZZ/003	RESPRAY RR BUMPER,END PANEL,FLOOR PAN,TAILGATE	1680.00	1260.00
5	ZZ/004	DISMENTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	900.00	.00
6	ZZ/005	REMOVE AND REFIX EXHAUST	150.00	150.00
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	.00
8	ZZ/007	TRANSFER(TAILGATE)MECHANISM	150.00	.00
9	ZZ/008	WHEEL ALIGNMENT	200.00	.00
10	ZZ/009	REMOVE&REFIX CARPET,SEATS TO FACILITATE REPAIRS	550.00	350.00
11	ZZ/011	TO CONDUCT(REAR)LIGHTING TEST	50.00	50.00
12	ZZ/012	TO CONDUCT(REAR) ANTI-RUST COATING	580.00	350.00
13	ZZ/013	TO SUPPLY & INSTALL REVERSE SENSOR-2 EYES	300.00	300.00
14	ZZ/014	SUNDRIES	100.00	.00
15	ZZ/10	TO REMOVE & REFIX FUEL TANK	200.00	.00
TOTAL LABOUR CHARGES			7200.00	4620.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKJ8970X

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26 LETTER MARK-REAR	93079FJ100	40.80			OK
27 TRIM PNL R SKIRT	94026FJ000VH	90.00			X
SUB TOTAL		1606.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		321.32	0.00	0.00	0.00
GRAND TOTAL		1285.28	0.00	0.00	0.00
OVERALL TOTAL		1285.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW8970X

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 GASKET RM	44011AE010 44011AE01A	16.00	(A) nec		OK
2 MUFFLER AY <i>Desal</i>	(SUPP) 44300FJ040	576.00	(A)		OK
3 FLOOR PAN R	CKD-XV 52129FJ0009P	540.00			X
4 SKIRT COMPL R 5D	52401FJ0209P	244.80			X
5 BUMPER FACE R XUV	57704FJ041	594.00			OK
6 BRKT RRH BUMP CORN	57707FJ080	28.80			OK
7 BRKT RLH BUMP CORN	57707FJ090	28.80			OK
8 BRKT RRH BUMP	57707FJ160	14.40			OK
9 BRKT RLH BUMP	57707FJ170	14.40			OK
10 BRKT BUMP R LWR	57707FJ201	7.20			X
11 COVER-REAR BUMPER	57731FG010TQ	14.40			X
12 COVER EXH R (SUPP) <i>Her</i>	59024FJ000	72.00	(A)		OK
13 PANEL-REAR GATE	60809FJ0019P	720.00			X
14 GLASS ASSY R G	63019FJ000	799.20			X
15 LAT & ACT AY RG	63032FG111	176.40			X
16 STRIKER R/G	63264AG100	21.60			X
17 WEATHER STRIP-REAR GATE	63516FJ000	85.00			OK
18 DAM RUBBER R WIND	65245SC000	21.60			X
19 REFLEX AY RH	84281FG000	21.60			X
20 REFLEX ASSY LH	84281FG010	21.60			X
21 LENS & BODY-R COMBI LAMP RH	84912FJ040	377.40			X
22 LENS & BODY-R COMBI LAMP LH	84912FJ050	377.40			X
23 GARNISH ASSY-REAR GATE,B	91111FJ190WU	238.00			X
24 ORNAMENT ASSY F SIX	91174SA181	68.40			OK
25 LETTER MARK-REAR	93079FJ060	68.00			OK

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKWB970X

NETT ITEM	1606.60
LESS 20 %	-321.32
NETT AMOUNT	1285.28

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	4620.00
TOTAL SPARE PARTS CHARGES	1285.28

TOTAL CHARGES	5905.28
ADD 7 % GST	413.37

GRAND TOTAL	6318.65
-------------	---------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003694/Dtd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7268G	Veh. Inspected	SKW 8970X
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001474MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	SUBARU XV	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JF1GP3KC5FG159036	Colour	RED
Odometer	25743	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	8 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	8 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	8 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/02/2018	Inspection Date	01/03/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 8970X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FLOOR PAN R (N)	TO REPAIR SEE LABOUR	540.00	-
1	SKIRT COMPL R 5D (N)	NO SUCH PARTS	244.80	-
1	BUMPER FACE R XUV (N)	DEFORMED	594.00	594.00
1	BRKT RRH BUMP CORN (N)	DISTORTED	28.80	28.80
1	BRKT RLH BUMP CORN (N)	DISTORTED	28.80	28.80
1	BRKT RRH BUMP (N)	DISTORTED	14.40	14.40
1	BRKT RLH BUMP (N)	DISTORTED	14.40	14.40
1	BRKT BUMP R LWR (N)	NOT NECESSARY	7.20	-
1	COVER-REAR BUMPER (N)	SERVICEABLE	14.40	-
1	PANEL-REAR GATE (N)	TO REPAIR SEE LABOUR	720.00	-
1	GLASS ASSY R G (N)	NOT NECESSARY	799.20	-
1	LAT & ACT AY RC (N)	SERVICEABLE	176.40	-
1	STRIKER R/G (N)	NOT NECESSARY	21.60	-
1	WEATHER STRIP-REAR GATE (N)	DISTORTED	85.00	85.00
1	DAM RUBBER R WIND (N)	NOT NECESSARY	21.60	-
1	REFLEX AY RH (N)	SERVICEABLE	21.60	-
1	REFLEX ASSY LH (N)	SERVICEABLE	21.60	-
1	LENS & BODY-R COMBI LAMP RH (N)	SERVICEABLE	377.40	-
1	LENS & BODY-R COMBI LAMP LH (N)	SERVICEABLE	377.40	-
1	GARNISH ASSY-REAR GATE,B (N)	SERVICEABLE	238.00	-
1	ORNAMENT ASSY F SIX (N)	NECESSARY	68.40	68.40
1	LETTER MARK-REAR (N)	NECESSARY	68.00	68.00
1	LETTER MARK-REAR (N)	NECESSARY	40.80	40.80
1	TRIM PNL & SKIRT (N)	SERVICEABLE	90.00	-
1	GASKET RM (N)(ADDITIONAL)	NECESSARY	16.00	16.00
1	MUFFLER AY (N)(ADDITIONAL)	DENTED	576.00	576.00
1	COVER EXH R (N)(ADDITIONAL)	NECESSARY	72.00	72.00
	LESS 20% DISCOUNT		-1,055.56	-321.32
			4,222.24	1,285.28

Report Ref No. CS/FCI18003694/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	REVERSE SENSOR-2 EYES (SN)	SHORTED	300.00	300.00
			400.00	300.00
	LABOUR			
	REMOVE/REPLACE RR BUMPER,END PANEL,FLOOR PAN,TAILGATE.INCLUSIVE OF THE REPAIR OF FLOOR PAN R AND PANEL-REAR GATE.		2,240.00	2,160.00
	RESPRAY RR BUMPER,END PANEL,FLOOR PAN,TAILGATE.		1,680.00	1,260.00
	DISMENTLE &REFIX UNDERCARRIAGE (REAR) TO FACILITATE REPAIR.	NOT NECESSARY	900.00	-
	REMOVE AND REFIX EXHAUST.		150.00	150.00
	TO CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	100.00	-
	TRANSFER (TAILGATE) MECHANISM.	NOT NECESSARY	150.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	200.00	-
	REMOVE & REFIX CARPET,SEATS TO FACILITATE REPAIRS.		550.00	350.00
	TO CONDUCT (REAR) LIGHTING TEST.		50.00	50.00
	TO CONDUCT (REAR) ANTI-RUST COATING.		580.00	350.00
	TO REMOVE & REFIX FUEL TANK.	NOT NECESSARY	200.00	-
			6,800.00	4,320.00
	GRAND TOTAL		11,422.24	5,905.28
	RECOMMENDED COST OF REPAIRS			5,905.28

Report Ref No. CS/FCI18003694/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.