

ASS. REC. BY:

REF: CS/FCI18003695/Krd3ez

Special Instruction:

Surveyor: Kenneth  
CWS

## ASSIGNMENT (Office)

From (Person): Serene Ter

of

FCI

Date/Time: 26/2/18 @ 2:34pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC5589A

Insured:

SHC8019J

at Workshop m/s

Trans-Cab

Tel:

6287 6666

of

No. 2 AMK St 63

Policy No:

Claim No:

D18001620 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/2/18

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 3:50pm 26/2/18

Person Contacted:

Condy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC5589A - CS/FCI17013692/Krh3n2

D.O.A: 12/7/17

SHC8019J - CC3/ALG18001894/Klj63

D.O.A: 27/1/18

27/2/18

Email preli revised to FCI

14/5/18

11 By 818,500 (Red 53,530.13, 741)

ASS. REC. BY:

REF: 10021

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 5589A Yr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour: M. White 1A A/C: Insured / Std / NI / NA

Sp. Reading: 395198 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VIFIABL 15AUC 279381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size: Prime well 215/60R16

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 23/2/18

Survey held at

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 26/2/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/2 File pass to Catherine

RECEIVED 14 MAY 2010

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 14/5 - typist

Report Format:

Lump Sum / I.B.I. (\$) 18,500

CWS

Days Of Repair: 15

Resurvey No. of Trlp: -

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

) 038

) 14/5/18

62x15: 930

170+930

50

28

1178

## Survey Department Check List (Case Handler)

Reference No. : **CS** | **FCI 18003695** | **Kvd3**  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

### (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

### (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: **VERON** | **14/5/18**  
 Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003695/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-02-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 8019J	Veh. Inspected	SHC 5589A
Policy No.		Coverage (\$)	0.00
Claim No.	D18001620MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	27/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	23/02/2018	Inspection Date	26/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	26-02-2018	<b>Our Ref No.</b> D18001620MFSH
<b>Accident Date</b>	23-02-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC8019J	<b>Third Party Vehicle.</b> SHC5589A
<b>Survey Location</b>	NO. 2 ANG MO KIO STREET 63	
<b>Contact Person.</b>	CANDY KONG	
<b>Contact No.</b>	62876666/ 0	<b>Fax No.</b> 62571330
<b>Survey Type</b>	WITHOUT PREJUDICE: EST. COR - \$72,030.13	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	TRANS-CAB AUTO SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235334)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18001620MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & TRANS C/
<b>Workshop Name</b>	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	<b>Survey Location &amp; Contact Details</b>	NO. 2 ANG MO KIO STREET 63 <b>Mobile:</b> 0 , <b>Phone:</b> 62876666 , <b>Fax:</b> 62571330 <b>EmailId:</b> CANDY.KONG@TRANSCAB.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: EST. COR - \$72,030.13		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHC8019J	<b>TP Vehicle No</b>	SHC5589A
<b>PRI Recieved Date</b>	26-02-2018 04:44:12 PM	<b>Surveyor Appointed Date</b>	26-02-2018 02:33:24 PM	<b>Surveyor Accept Date</b>	27-02-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	27-02-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	Please Select Make ▾	<b>Model</b>	Please Select Model ▾	<b>Year</b>	Select Year ▾
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 27 February 2018 4:33 PM  
**To:** 'Claim Workflow System'  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18001620MFSH/1, SHC 5589A  
**Attachments:** SHC 5589A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 5589A  
Date of survey: 26/2/2018  
Number of days:15 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Monday, 26 February 2018 3:16 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18001620MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Monday, 26 February 2018 2:34 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SERENELER@MSFIRSTCAPITAL.COM.SG](mailto:SERENELER@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001620MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

• Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001620MFSH

Our ref: CS/FCI18003695/Kvd3

Date : 27/2/2018

The Motor Claims Department  
M/s First Capital Insurance Ltd

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5589A**


We thank for your instruction on 26/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/2/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$72,030.13
Revised Estimate Amount	: S\$23,109.56
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear n/s portion



**Comments/Present Status:**  
Damages Consistent

Yours faithfully,

Kenneth Kong  
Licensed Appraiser

## Enquire PARF/COE Rebate for Registered Vehicle

---

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

### Vehicle Details

Vehicle No.: SHC5589A

Vehicle to be Exported: Yes

Intended De-registration Date: 23 Feb 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001946

Chassis No.: VF1ABL15AUC279381

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 30 Sep 2014

First Registration Date: 30 Sep 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Sep 2022

PARF Rebate Amount: \$9,373.00

### Intended COE Rebate Details

COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$29,154.00
<b>Total Rebate Amount:</b>	<b>\$38,527.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Feb 2018

**OK**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/02/2018 13:23
Date Of Accident	23/02/2018 09:30
Exact Location Of Accident	NORTH BUONA VISTA ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5589A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	CHANG TING CHIA
NRIC No	S0140603E
Date Of Birth	20/02/1954
Occupation	OUTDOOR
Date Of Driving Pass	23/12/1971
Driving Experience	46 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94742254
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 6 TELOK BLANGAH CRESCENT #10-424
Postcode	090006
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 23.02.2018 at about 0930hours, I was travelling straight on the Centre lane along North Buona Vista Road when Vehicle in front of me slow down and made a stop due to congestions ahead so I follow suit. Suddenly I felt an impact. Vehicle B (SHC8019J) hit onto my taxi's left rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8019J
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SIMON CHIEN YOA SAN
NRIC/Passport Number	S2595075E
Contact Number	90619003
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Sketch Plan #2 Pg. 1**

### SKETCH PLAN

North Buena Vista  
Road

A- SHC 5589A  
B- SHC 8019J

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

ps see attach GIA Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_



**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5589A - FCIL****AAD1802-227***Not Authorised*  
*1/1/8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC5589A - FCIL**

VF1ABL15AUC279381

RENAULT

LATITUDE

23.02.2018

60411.05

**FCIL****PART****LIST**

1	1	BUMPER COVER REAR	\$	71	1,108.46	✓
2	1	BUMPER LOWER REAR	\$	m1 Re	768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	cm	113.47	✓
4	1	BUMEPR BRACKET SIDE LH REAR	\$	cm	135.97	✓
5	1	BUMEPR BRACKET CTR LH REAR	\$	cm	44.99	✓
6	1	BUMEPR BRACKET SIDE RH REAR	\$	sn	135.97	X
7	1	BUMEPR BRACKET CTR RH REAR	\$	sn	44.99	X
8	1	BUMPER BEAM REAR	\$	R1	777.52	✓
9	1	BUMPER BEAM BRACKET LH REAR	\$	R1	225.95	✓
10	1	BUMPER BEAM BRACKET RH REAR	\$	R	225.95	X
11	1	BUMPER REFLECTOR LH	\$	R10	43.61	✓
12	1	BUMPER REFLECTOR RH	\$	R	43.61	X
13	1	BOOT REAR	\$	M1	2,872.68	✓
14	2	BOOT RUBBER PLUG	\$	sn	221.81	X
15	1	BOOT FINISHER	\$	wap	470.06	✓
16	1	BOOT SWITCH	\$	sn	168.13	X
17	1	BOOT TRIM BOARD	\$	netolan	914.87	✓
18	1	BOOT LOCK	\$	m1	202.67	✓
19	1	BOOT LOCK CATCH	\$	R	74.40	X
20	1	BOOT LOCK LINKAGE	\$	sn	34.53	X
21	1	BOOT LOCK LINKAGE HOLDER	\$	sn	154.52	X
22	1	BOOT LOCK CATCH TRIM BOARD	\$	sn	249.24	X
23	1	BOOT WHEATERSTRIP	\$	netolan	323.05	✓
24	1	BOOT REFLECTOR LAMP LH	\$	cm	493.35	✓
25	1	BOOT REFLECTOR LAMP RH	\$	cm	493.35	✓
26	1	BOOT BADGE 'RENAULT'	\$	na	225.36	✓
27	1	BOOT BADGE	\$	na	225.36	✓
28	1	BOOT STRUT LH	\$	sn	276.08	} X
29	1	BOOT STRUT RH	\$	sn	276.08	
30	1	BOOT HINGE LH	\$	R	367.84	
31	1	BOOT HINGE RH	\$	R	367.84	
32	2	LICENCE PLATE LAMP	\$	sn	50.52	
33	1	WINDSCREEN REAR	\$	sn	1,463.28	} X
34	1	WINDSCREEN GARNISH INNER LH	\$	sn	263.74	

13858.09

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1802-227**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5589A - FCIL**

35	1	WINDSCREEN GARNISH INNER RH	\$	Sn	263.74	X
36	1	TAILLAMP LH	\$	Bn	552.55	✓
37	1	TAILLAMP PANEL LH	\$	Bn	986.70	✓
38	1	TAILLAMP RH	\$	Sn	552.55	X
39	1	TAILLAMP PANEL RH	\$	N	986.70	X
40	1	CHASSIS PANEL REAR LH	\$	N Bn	3,766.43	<del>✓</del> X
41	1	FENDER PANEL REAR LH	\$	Bn	3,299.13	✓
42	1	FENDER PANEL REAR RH	\$	N	3,299.13	X
43	1	WHEELARCH REAR LH	\$	Sn	543.47	X
44	1	FENDER PANEL INNER TRIM REAR LH	\$	Return	671.45	✓
45	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	N	3,039.04	X
46	1	LOWER ARM REAR LH	\$	Sn	905.99	} X
47	1	KUCKLE ARM REAR LH	\$	Sn	736.67	
48	1	ABSORBER REAR LH	\$	Sn	389.75	
49	1	ABSORBER BOLT REAR LH	\$	Sn	52.10	
50	1	ABSORBER DUST COVER REAR LH	\$	Sn	92.16	
51	1	REAR AXLE	\$	Sn	4,167.03	
52	1	AXLE ARM ROD	\$	Sn	117.22	
53	1	AXLE ARM LH	\$	Sn	117.22	
54	1	AXLE ARM RH	\$	Sn	117.22	
55	1	AXLE ARM SHIELD LH	\$	N	9.08	
56	1	AXLE ARM SHIELD RH	\$	N	9.08	
57	1	AXLE SPRING ARM LH	\$	Sn	376.92	} 24676.41
58	1	AXLE SPRING ARM RH	\$	Sn	376.92	
59	1	STABILIZER BAR REAR	\$	Sn	604.65	
60	1	STABILIZER LINK REAR LH	\$	Sn	92.36	
61	1	STABILIZER LINK REAR RH	\$	Sn	92.36	
62	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bn	2,189.88	✓
63	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	CM	612.21	✓
64	1	SPARE WHEEL PANEL BRACKET LH	\$	N	123.73	X
65	1	SPARE WHEEL PANEL BRACKET RH	\$	N	121.36	X
66	1	OUTER PANEL REAR (End Panel)	\$	Bn	1,471.77	✓
67	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	401.02	✓
68	1	EXHAUST REAR	\$	N	7,489.05	X
69	1	EXHAUST CAP REAR	\$	N	230.49	X
70	1	EXHAUST MOUNTING REAR	\$	Bn	31.97	X
71	1	EXHAUST BRACKET REAR	\$	N	39.86	X
72	1	EXHAUST HEAT SHIELD REAR	\$	N	99.06	X
73	1	SHIELD - HEAT - TUNNEL	\$	Sn	225.16	X
74	1	FUEL FLAP	\$	Sn	343.57	X
75	1	FUEL TANK NECK	\$	Sn	684.77	X
76	1	FUEL CAP	\$	Bn	233.02	✓

15860.13

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1802-227**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5589A - FCIL**

77	1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	<i>X</i>
78	1	DOOR SEAL REAR LH	\$	<i>Sn</i> 187.08	<i>X</i>
79	1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66	<i>X</i>
80	1	DOOR SEAL REAR RH	\$	<i>Sn</i> 162.02	<i>X</i>

*6038 02*

<b>TOTAL</b>	<b>\$</b>	<b>60,411.06</b>
<b>10%</b>	<b>\$</b>	<b>6,041.11</b>
	<b>\$</b>	<b>54,369.95</b>

**Specical Nett**

1	1SET	BUMPER RR CLIP	\$	<i>na</i> 66.00	<i>—</i>
2	1SET	BUMPER BEAM BOLT	\$	<i>Sn na</i> 22.22	<i>X</i>
3	1SET	PARKING AID	\$	<i>na</i> 600.00	<i>—</i>
4	1	BUMPER BRACKET CLIP CTR REAR	\$	<i>na</i> 15.00	<i>X</i>
5	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	<i>na</i> 12.00	
6	1	BUMEPR RETAINER CLIP LH REAR	\$	<i>na</i> 10.40	
7	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	<i>na</i> 12.00	
8	1	BUMEPR RETAINER CLIP RH REAR	\$	<i>na</i> 10.40	
9	1	CAP HUB LH RR	\$	<i>Sn</i> 35.00	
10	1	RIM LH RR	\$	<i>Sn</i> 385.00	
11	1	TYRE LH RR	\$	<i>Sn</i> 330.00	
12	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i> 385.00	<i>X</i>
13	1	SPARE TYRE	\$	<i>Sn</i> 330.00	
14	1SET	BOOT FINISHER CLIP	\$	<i>na</i> 25.10	<i>—</i>
15	1	Rear boots sticker "trans-cab"	\$	<i>na</i> 30.00	<i>—</i>
16	1	Rear boots sticker "6555-3333"	\$	<i>na</i> 30.00	<i>—</i>
17	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	<i>na</i> 22.00	<i>—</i>
18	1SET	WHEELARCH CLIP LH RR	\$	<i>na</i> 32.34	<i>X</i>
19	2	Rear windscreen sealant	\$	<i>na</i> 80.00	<i>4000</i>
20	1	Windscreen moulding	\$	<i>na</i> 100.00	<i>—</i>
21	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i> 100.00	<i>3000</i>
22	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i> 65.50	<i>X</i>
23	1	EXHAUST BRACKET REAR	\$	<i>R</i> 22.22	<i>X</i>
24	1SET	Rear licence plate with holder	\$	<i>Sn</i> 80.00	<i>X</i>
25	1	DOOR STICKER "6555-3333" LH	\$	<i>na</i> 80.00	<i>X</i>
26	1	DOOR STICKER "6555-3333" RH	\$	<i>na</i> 80.00	<i>X</i>

<b>TOTAL</b>	<b>\$</b>	<b>2,960.18</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>57,330.13</b>

Towing Fees.

\$ 120.00 *500*

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1802-227**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5589A - FCIL**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2000 4,200.00
To apply paint protection system (PPS) maintain and enhancement	\$	~ 380.00 X
Putty and spray painting of the affected portion.	\$	4,500.00 1320
To rust-proofing of the affected areas.	\$	170.00 120
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00 120
To check steering geometry and computer wheel alignment	\$	220.00 60
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 } 250
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 } X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 80
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To reinstall rear bumper parking sensor.	\$	170.00 60

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1802-227**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5589A - FCIL**

To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	12 q
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	} 6 q
To repair and realign rear exhaust pipe.	\$	170.00	
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00	X
To drop rear axle assy, remove and renewal of the necessary parts	\$	380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>14,700.00</b>	14820
<b>Over All Total</b>	<b>\$</b>	<b>72,030.13</b>	72150.12

&lt; parts by parts &gt; Repair Days

**15 DAYS** ✓

LKK Auto Care Centre hence notify the Repairs of the following:

- To repair and repaint
- To repair and repaint during resurvey
- Parts prices must be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation must be allowed
- Supplemental survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairs

Signature

Date




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003695/Kvd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-05-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8019J	Veh. Inspected	SHC 5589A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001620MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	26/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279381	Colour	METALLIC WHITE / RED	
Odometer	395198	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	PRIMEWELL	7 mm	
L/H Front Tyre	215/60 R16	PRIMEWELL	7 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/02/2018	Inspection Date	26/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5589A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR	TORN	1,108.46	1,108.46
1	BUMPER LOWER REAR	MISSING	768.84	768.84
1	BUMPER BRACKET CTR REAR	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE LH REAR	CRACKED	135.97	135.97
1	BUMPER BRACKET CTR LH REAR	CRACKED	44.99	44.99
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER BRACKET CTR RH REAR	SERVICEABLE	44.99	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER REFLECTOR LH	BROKEN	43.61	43.61
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BOOT REAR	BENT	2,872.68	2,872.68
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	BOOT FINISHER	WARPED	470.06	470.06
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT TRIM BOARD	DEFORMED	914.87	914.87
1	BOOT LOCK	DENTED	202.67	202.67
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
1	BOOT LOCK LINKAGE	SERVICEABLE	34.53	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	154.52	-
1	BOOT LOCK CATCH TRIM BOARD	SERVICEABLE	249.24	-
1	BOOT WEATHERSTRIP	DENTED / CUT	323.05	323.05
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-

Report Ref No. CS/FCI18003695/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
1	WINDSCREEN REAR	SERVICEABLE	1,463.28	-
1	WINDSCREEN GARNISH INNER LH	SERVICEABLE	263.74	-
1	WINDSCREEN GARNISH INNER RH	SERVICEABLE	263.74	-
1	TAILLAMP LH	BROKEN	552.55	552.55
1	TAILLAMP PANEL LH	BENT	986.70	986.70
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	CHASSIS PANEL REAR LH	TO REPAIR SEE LABOUR	3,766.43	-
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR LH	DEFORMED	671.45	671.45
1	FENDER WHEEL HOUSE PANEL REAR LH	TO REPAIR SEE LABOUR	3,039.04	-
1	LOWER ARM REAR LH	SERVICEABLE	905.99	-
1	KNUCKLE ARM REAR LH	SERVICEABLE	736.67	-
1	ABSORBER REAR LH	SERVICEABLE	389.75	-
1	ABSORBER BOLT REAR LH	SERVICEABLE	52.10	-
1	ABSORBER DUST COVER REAR LH	SERVICEABLE	92.16	-
1	REAR AXLE	SERVICEABLE	4,167.03	-
1	AXLE ARM ROD	SERVICEABLE	117.22	-
1	AXLE ARM LH	SERVICEABLE	117.22	-
1	AXLE ARM RH	SERVICEABLE	117.22	-
1	AXLE ARM SHIELD LH	NOT NECESSARY	9.08	-
1	AXLE ARM SHIELD RH	NOT NECESSARY	9.08	-
1	AXLE SPRING ARM LH	SERVICEABLE	376.92	-
1	AXLE SPRING ARM RH	SERVICEABLE	376.92	-

Report Ref No. CS/FCI18003695/Kvd3e2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STABILIZER BAR REAR	SERVICEABLE	604.65	-
1	STABILIZER LINK REAR LH	SERVICEABLE	92.36	-
1	STABILIZER LINK REAR RH	SERVICEABLE	92.36	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	BENT	2,189.88	2,189.88
1	SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL)	CRACKED	612.21	612.21
1	SPARE WHEEL PANEL BRACKET LH	TO REPAIR SEE LABOUR	123.73	-
1	SPARE WHEEL PANEL BRACKET RH	TO REPAIR SEE LABOUR	121.36	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	401.02	401.02
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	EXHAUST MOUNTING REAR	SERVICEABLE	31.97	-
1	EXHAUST BRACKET REAR	TO REPAIR SEE LABOUR	39.86	-
1	EXHAUST HEAT SHIELD REAR	TO REPAIR SEE LABOUR	99.06	-
1	SHIELD - HEAT - TUNNEL	SERVICEABLE	225.16	-
1	FUEL FLAP	SERVICEABLE	343.57	-
1	FUEL TANK NECK	SERVICEABLE	684.77	-
1	FUEL CAP	BUCKLED	233.02	233.02
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	187.08	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
	LESS 10% DISCOUNT		-6,041.11	-1,985.73
			54,369.94	17,871.56
	<b>SPECIAL NETT ITEMS</b>			
1	SET BUMPER RR CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BEAM BOLT (SN)	SERVICEABLE	22.22	-

Report Ref No. CS/FC118003695/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET PARKING AID (SN)	TORN	600.00	600.00
1	BUMPER BRACKET CLIP CTR REAR (SN)	NOT NECESSARY	15.00	-
1	BUMPER BRACKET SIDE CLIP LH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP LH REAR (SN)	NOT NECESSARY	10.40	-
1	BUMPER BRACKET SIDE CLIP RH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP RH REAR (SN)	NOT NECESSARY	10.40	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	25.10	-
1	REAR BOOTS STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOTS STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	FENDER PANEL INNER TRIM CLIP REAR LH (SN)	NECESSARY	22.00	22.00
1	SET WHEELARCH CLIP LH RR (SN)	NOT NECESSARY	32.34	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	65.50	-
1	EXHAUST BRACKET REAR (SN)	TO REPAIR SEE LABOUR	22.22	-
1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER "6555-3333" LH (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "6555-3333" RH (SN)	NOT NECESSARY	80.00	-
			2,960.18	918.00
	<b>LABOUR</b>			
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TOWING FEES.		120.00	50.00

Report Ref No. CS/FCI18003695/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET RH REAR, BOOT LOCK CATCH, BOOT HINGE LH, BOOT HINGE RH, TAILLAMP PANEL RH, CHASSIS PANEL REAR LH, FENDER PANEL REAR RH, FENDER WHEEL HOUSE PANEL REAR LH, SPARE WHEEL PANEL BRACKET LH, SPARE WHEEL PANEL BRACKET RH, EXHAUST REAR, EXHAUST CAP REAR, EXHAUST BRACKET REAR, EXHAUST HEAT SHIELD REAR, DOOR PANEL REAR LH, } DOOR PANEL REAR RH AND EXHAUST BRACKET REAR . }		4,200.00	2,000.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,320.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. }		380.00	250.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. }		380.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI18003695/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WIDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	120.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		280.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DROP REAR AXLE ASSY, REMOVE AND RENEWAL OF THE NECESSARY PARTS.	NOT NECESSARY	380.00	-
			14,820.00	4,320.00
GRAND TOTAL			72,150.12	23,109.56

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,500.00
--	--	--	-----------

Report Ref No. CS/FCI18003695/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.