

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1449Y

DATE 26/2/2018 16:04

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Bracket Top (RH) ✓			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Headlamp (RH) ✓			\$ 1,388.00
	Front Fender (RH) ✓			\$ 619.00
	Front Fender Shield (RH) X			\$ 169.80
	Front Fender Retainer X			\$ 9.20
	Front Windscreen Moulding X			\$ 60.00
	Front Windscreen Pillar Outer(RH) X			\$ 1,843.10
	Frt Wheel Hub Cap X			\$ 150.70
	SUB TOTAL			\$ 4,833.70
	LESS 20%			\$ 966.74
	DISCOUNTED TOTAL			\$ 3,866.96
	Front Windscreen Sealant X			\$ 46.00 Nett
	Labour Charge			
	Panel Beating			\$ 1,000.00 ³⁰⁰
	Spray Painting Charge			\$ 600.00 ³⁶⁰
	Wiring Charge			\$ 50.00 ²⁰
	Tuff Kote			\$ 50.00 ²⁰
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,780.00
	ESTIMATE TOTAL			\$ 5,692.96
<i>Ka Lian 1449Y</i> <i>26/2/18 1620L.</i> <i>2 Day,</i> <i>P/P</i> <i>Before Paint photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary demand must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				