

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2018 20:39
Date Of Accident	15/02/2018 09:30
Exact Location Of Accident	SIN MENG AVE TWDS BISHAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR8708B
Insured/Policyholder	
Name Of Registered Owner	TAN PENG YIAM
NRIC No	S1549113B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81212655
Alternative Phone No	OFFICE-81212655

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3076671701
Cover Note Number	

Driver

Name of Driver	TAN PENG YIAM
NRIC No	S1549113B
Date Of Birth	30/09/1962
Occupation	INDOOR
Date Of Driving Pass	23/05/1994
Driving Experience	23 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81212655
Fax Number	
Contact Number	OFFICE-81212655
Email Address	NOEMAIL

Address	BLK 504A YISHUN STREET 51 #04-84
Postcode	761504
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH3388U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/Fin No:

Accident Sketch Plan

SKETCH PLAN



Vehicle A → 57R870785

Vehicle B → 5H55884

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Sir Moly Ave towards Bishan on the left lane. While I was travelling straight, I was distracted and never notice that vehicle B was stationary. I was unable to stopped in time and hit off vehicle B rear portion.

DECLARATION


I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/ID No.:


Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 8 Raffles Quay #18-00 Singapore 048580
 Tel: (65) 6224 0000 Fax: (65) 6224 0040
 Operating hours: Monday to Friday 09:00 - 17:00
 UEN: S46540290 / GST Reg. No. 04000017755

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MAA 11 P02486 Vehicle Registration No: SJR 8708B
 Name (as shown on NRIC): Tan Peng Yiam NRIC/FIN/Passport No: S1549113B
 (* Vehicle Driver / Vehicle Owner) (* Please delete as appropriate)
 Address: Blk 524A Yishun Street 51 #04-84 Singapore: 711614
 Contact (Tel): 9122655 Mobile No.: 9658131266
 Email Address: _____
 Date of Accident: 14/2/2018 Time of Accident: 19:30 approx
 Place of Accident: SIN MENG AVE TOWARDS BISHAN
 Insurance Company: CHINA TAIPEI INSURANCE (SINGAPORE) PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I was trying to avoid the truck vehicle, I swerve to the left,
but unable to, causing the damages to the front and front right
portion of my vehicle SJR 8708B

[Signature]
 Policyholder / Driver's Signature
 Date: 03.03.2018

[Signature]
 Reporting Centre Personnel's Signature
 Name: _____
 NRIC/FIN No: _____
 Date: _____

**SMRT AUTOMOTIVE
SERVICES PTE LTD
60 WOODLANDS
INDUSTRIAL PARK E4
757705**

Claim Reference: MAC/FEB2018/001
Assessment Number: CTI10129
Version: SMRTAUTO/3
Date Calculated: 26/02/2018 03:33

Full Report - V1
Registration: SJR8708B
Printed: 26/02/2018 11:35

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Eng Hock Peh	Date of Incident:	15/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pte	Repairs Authorised:	TBA
Claim Reference:	MAC/FEB2018/001	Estimated Repair Time:	10 day(s)
Policy Number:	DMPCSN3076671701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YCA 01
Registration:	SJR8708B
Registration Month:	November
Registration Year:	2009
VIN Number:	MR053BK4107049767
Manufacture Year:	2009
Odometer:	145040
Colour:	Green
Engine Number:	1AZE149757
Fuel Level:	90%

Model Specs

FROM 12/2009	AUTO AIR CON
CHROME DOOR HANDLES	S/MOULding CHROMED
MIRROR W/NDICATOR	2COMP GLASS ADHESIVE
RADIO WITH CD	REARVIEW CAMERA
FOG LAMPS	EXHAUST TRIM CHROMED
PARKING BRAKE FOOT	LEATHER SEATS
S-WHEEL RADIO CONT	ANTI THEFT ALARM
LEATHER/WOOD S-WHEEL	RR PARK DIST CONTROL
2.0 LTR 108 KW	4-SPEED AUTOMATIC
ELECT POWER STEERING	CRUISE CONTROL
TYRES 215/60 YR 16	WHEELS 6.5J X 16 ALU
VERSION THAILAND	PRODUCT THAILAND
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:		Severity of Impact:	Light Structural
Steering:		Vehicle Status on	Unroadworthy
		Inspection:	Mobile
Brakes Pedal Travel:		Date of Inspection:	18/01/2018
Place of Inspection:	Assessor		
Pre-Accident Damage:			
Tyres Condition:	Fair		
Tread Depth LHF:		Tread Depth RHF:	
Tread Depth LHR:		Tread Depth RHR:	
Damage Areas:		Direction of Impact:	

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001
Assessment Number: CTI10129
Version: SMRTAUTO/3
Date Calculated: 26/02/2018 03:33

Full Report - V1
Registration: SJR8708B
Printed: 26/02/2018 11:35



Primary Impact
Secondary Impact

Addresses

Cost Summary

Total Labour	\$3,247.60
Total Paint/Material	\$300.23
Total Parts	\$9,515.67
Excess:	TBA
Grand Total Exc GST:	\$13,063.50
7 % GST:	\$914.45
Grand Total Inc GST:	\$13,977.95

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	DIAGNOSIS WITHOUT CHASSIS JIG	2.0	9.20
NO NUMBER	CONVERT CHASSIS JIG	10.0	46.00
043233C	ADD: ADJUST FRONT TOE	1.0	4.60
043233	ALIGN VEHICLE CPL	12.0	55.20
043233D	ADJUST FRONT CAMBER (ADD/WORK)	5.0	23.00
043233F	ADD: ADJUST REAR TOE	2.0	9.20
M030ZAX	R + R L/F AXLE HALF (ADD/WORK)	11.0	50.60
NO NUMBER	R + R ENGINE WITH GEARBOX	4.0	18.40
B140	RENEW FRONT PANEL	22.0	101.20
NO NUMBER	RENEW R/R LOWER SIDEMEMBER	36.0	165.60
B170)	RENEW R/F SIDE MEMBER	23.0	105.80
B110	RENEW L/FRT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	5.0	23.00
B110	RENEW R/FRT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)	5.0	23.00
B100	R + R LEFT SILL RAIL	3.0	13.80
B100	R + R RIGHT SILL RAIL	3.0	13.80
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	15.0	69.00
B040	RENEW BOTH HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS	7.0	32.20

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001

Assessment Number: CTI10129

Version: SMRTAUTO/3

Date Calculated: 26/02/2018 03:33

Full Report - V1

Registration: SJR8708B

Printed: 26/02/2018 11:35

B070	RENEW BONNET	6.0	27.60
B080	R + R BONNET HINGES	1.0	4.60
530121)	R + R BONNET OPENER CABLE	2.0	9.20
190011	R + R BATTERY	3.0	13.80
851091)	R + R WASHER RESERVOIR	4.0	18.40
851061	R + R WASHER NOZZLES	2.0	9.20
B085)	R + R WATER BOX CLOSING PANEL	4.0	18.40
M010)	RENEW CONDENSER (REMOVED)	1.0	4.60
883401)	R + R AIR CONDITIONING COMPRESSOR	1.0	4.60
NO NUMBER	R + R AIR CONDITIONING PIPE	4.0	18.40
NO NUMBER	R + R AIR CONDITIONING PIPE	5.0	23.00
NO NUMBER	R + R AIR CONDITIONING HOSE	4.0	18.40
NO NUMBER	R + R ENGINE ROOM WIRING	19.0	87.40
NO NUMBER	R + R ENGINE WIRING	10.0	46.00
895011	R + R ENGINE CONTROL UNIT	3.0	13.80
NO NUMBER	R + R FAN RELAY	2.0	9.20
M010	R + R RADIATOR AND CONDENSER (FRONT BUMPER REMOVED)	16.0	73.60
	INCLUDES: BLEED COOLING SYSTEM		
M010)	RENEW RADIATOR	3.0	13.80
160111)	R + R LOWER RADIATOR HOSE	2.0	9.20
160101)	R + R UPPER RADIATOR HOSE	2.0	9.20
NO NUMBER	R + R ENGINE COVER	1.0	4.60
NO NUMBER	R + R AIR FILTER HOSE	1.0	4.60
160251)	R + R DRIVE BELT	2.0	9.20
271011)	R + R ALTERNATOR	2.0	9.20
444401)	R + R POWER STEERING	6.0	27.60
	INCLUDES: BLEED POWER STEERING		
420091)	R + R R/F WHEEL/TYRE	3.0	13.80
473011)	R + R L/FRT BRAKE DISC	1.0	4.60
473011A)	R + R FRONT BRAKE DISC/S	2.0	9.20
896081)	R + R R/F ABS SENSOR	1.0	4.60
NO NUMBER	R + R R/R AXLE CARRIER BRACKET	2.0	9.20
NN	LIQUID GAS SYSTEM R&R / NEW PARTS	10.0*	46.00
0250	VEHICLE TRANSPORT	20.0*	92.00
4475	DRAIN AND REFILL AIR CONDITIONING	30.0*	138.00
9732	REMOVE AND REFIT R/F AXLE HALF	40.0*	184.00
9790	AXLE REMOVED R/F AXLE HALF	40.0*	184.00
9947	ADJUST HEADLAMP	20.0*	92.00
9973	CARRY OUT TEST DRIVE	10.0*	46.00
1117	REPAIR L/F WHEELHOUSE CPL	30.0*	138.00
1118	REPAIR R/F WHEELHOUSE CPL	30.0*	138.00
1124	REPAIR R/F WHEELHOUSE	30.0*	138.00
9831	CHECK ENGINE	10.0*	46.00
9901	ALIGN W/OUT ADJUST COMPL VEH BEFORE REP	30.0*	138.00

LABOUR COST

Total Work Units	581.0	
Panel / Mechanical Labour	53.1HRS	\$2,442.60
Visual Alignment Labour	5.0HRS	\$230.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	58.1HRS	\$2,672.60
Paint Labour	12.5HRS	\$575.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001
 Assessment Number: CTI10129
 Version: SMRTAUTO/3
 Date Calculated: 26/02/2018 03:33

Full Report - V1
 Registration: SJR8708B
 Printed: 26/02/2018 11:35

Total Labour	70.6HRS	\$3,247.60
---------------------	----------------	-------------------

PAINT WORK

Guide Number Description Time Basis 10 WU = 1 HR. Price = \$46.00/HR

		WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	26.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
988	LOCK CARRIER STRUT SURFACE PAINT	4.0	
1009	FRONT PANEL SURFACE PAINT	7.0	
1208	R/F OUT S-MEMBER PNLSURFACE PAINT	5.0	
1214	R/F S-MEMB RR REINF SURFACE PAINT	5.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	3.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	

LABOUR COST - PAINT

TIME(PAINT)	95.0	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	125.0	
Total Paintwork Labour	12.5HRS	\$575.00

MATERIAL COST - PAINT

New Part Painting	\$129.00
New Part Painting - Plastic K1R	\$68.39
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$65.24
Material-Const Main Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$300.23
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$300.23

X- N N

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
8391	1	AIR FILTER ASSY ✓ Defect X	17700 0H121		0%		225.00*
8389	1	AIR INTAKE HOSE X	17881 0H100		0%		60.00*
8375	1	AIR INTAKE HOSE ✓ BT X	17750 0H070		0%		90.00*
3011	1	BADGE "VVT-I" L ✓ NGC X	75443 06260		0%		28.00*
3012	1	BADGE "VVT-I" R ✓ NTC	75443 06540		0%		28.00*
471	1	BONNET ✓ DT	53301 06110		0%		430.00*
527	1	BONNET FRONT SEAL ✓ NEC	53381 06060		0%		38.00*
481	1	BONNET INSULATION ✓ NEC	53341 06160		0%		180.00*
340	1	BUMPER SUPPORT ✓ DT X	52021 06060		0%		150.00*
4481	1	COMPR/CONDENSER TUBE ? X	88711 06280		0%		48.00*
4482	1	COND/EVAPORATOR PIPE ? X	88710 06211		0%		95.00*
4465	1	CONDENSER ✓ DT	88460 06170		0%		380.00*
500	1	CONTROL CABLE ? X	53630 06110		0%		45.00*
412	1	CTR BUMPER GRILLE ✓ CKK	53112 06120		0%		85.00*
9585	1	ENGINE COMP HARNESS X	82111 06S60		0%		0.00
9588	1	ENGINE HARNESS X	82121 06A73		0%		0.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001

Assessment Number: CTI10129

Version: SMRTAUTO/3

Date Calculated: 26/02/2018 03:33

Full Report - V1

Registration: SJR8708B

Printed: 26/02/2018 11:35

7757	1	FAN RELAY 1 ✓ DMG X	90987 02027	0%	76.47U
7758	1	FAN RELAY 2 X	90987 04004	0%	59.53U
283	1	FRONT BUMPER ✓ Defect	52119 06960	0%	260.00*
1000	1	FRONT GRILLE EMBLEM ✓ NGC Renew		0%	30.00*
257	1	FRONT NUMBER PLATE ✓ BT KNPL3		0%	35.00* (SN)
1009	1	FRONT PANEL ✓ BT	53201 06171	0%	380.00*
344	1	FRT BUMPER ABSORBER ✓ CRK	52611 06160	0%	75.00*
1000	1	FRT BUMPER TOW COVER ✓ CRK Renew		0%	20.00*
260	1	FRT NO PLATE BRKT ✓ CRK	52114 06100	0%	65.00*
258	1	FRT NO PLATE REINF ✓ CRK X	KNPL0	0%	15.00*
4485	1	FRT PIPE COMPR/COND ✓ BT	88715 06050	0%	35.00*
410	1	GRILLE ✓ CRK	53111 06280	0%	185.00*
7793	1	L/BLOWER FAN ? CRK X	16361 0H210	0%	55.00*
497	1	L/BONNET DAMPER BT X	53450 0W090	0%	160.00*
475	1	L/BONNET HINGE BT ✓ BT	53420 06130	0%	35.00*
8781	1	L/ENGINE COVER X	51442 06110	0%	85.00*
637	1	L/F FOG LAMP CPL ? X	81220 02121	0%	115.00*
317	1	L/F UPP BUMPER BRKT ? X	52536 06090	0%	48.00*
741	1	L/F WING ✓ BT X	53802 06140	0%	225.00*
7789	1	L/FAN MOTOR ? CRK X	16363 0H130	0%	180.00*
297	1	L/FOG LAMP COVER CRK X	52040 06080	0%	60.00*
9645	1	L/HORN ✓ DMG	86510 06110	0%	65.00*
7771	1	L/LWR RADIATOR BRKT ✓	16535 0H060	0%	0.00
1169	1	L/RADIATOR AIR GUIDE ✓ CRK	53294 06100 X	0%	55.00*
7769	1	L/UPP RADIATOR BRKT ? X	16523 0H050	0%	40.00*
843	1	L/WING COVER PANEL X	53883 06030	0%	45.00*
561	1	LEFT HEADLAMP ASSY ? ✓ CRK	81150 06530 X	0%	380.00*
9951	1	LIQUID GAS SYSTEM ✓ NGC	NO NUMBER X	0%	60.00*
988	1	LOCK CARRIER STRUT ✓ DMG	53208 06040	0%	60.00*
493	1	LOWER BONNET LOCK ✓ Jm	53510 06101	0%	50.00*
7773	1	LWR RADIATOR HOSE ? ✓ CRK	16572 0H100 X	0%	35.00*
7300	1	POWER STEERING CPL ? X	44250 06310	0%	155.00*
7794	1	R/BLOWER FAN ? ✓ CRK	16361 0H220	0%	55.00*
498	1	R/BONNET DAMPER ✓ DMG	53440 0W110	0%	160.00*
476	1	R/BONNET HINGE ✓ BT	53410 06130	0%	35.00*
7066	1	R/CARRIER JOINT X	43330 09580	0%	85.00*
7036	1	R/DRIVE SHAFT CPL X	43410 06590	0%	155.00*
8782	1	R/ENGINE COVER X	51441 06120	0%	85.00*
638	1	R/F FOG LAMP CPL ? ✓ CRK	81210 02121	0%	115.00*
1208	1	R/F OUT S-MEMBER PNL X	57025 06030	0%	0.00
1214	1	R/F S-MEMB RR REINF X	57016 06120	0%	0.00
7272	1	R/F STABI ROD ✓ BT	48820 33070	0%	85.00*
7082	1	R/F STEERING KNUCKLE ✓ BT	43211 06210	0%	65.00*
318	1	R/F UPP BUMPER BRKT X	52535 06100	0%	48.00*
7202	1	R/F WHEEL	42611 06571	0%	450.00*
7118	1	R/F WHEEL BEARING ✓ BT	90369 T0007	0%	60.00*
7218	5	R/F WHEEL BOLT SET X	90942 01033	0%	30.00*
7132	1	R/F WHEEL HUB ✓ DMG	43502 06120	0%	85.00*
742	1	R/F WING ✓ BT	53801 06130	0%	225.00*
7790	1	R/FAN MOTOR ? ✓ CRK	16363 0H140	0%	180.00*
298	1	R/FOG LAMP COVER ✓ CRK	52030 06080	0%	60.00*
9646	1	R/HORN ✓ DMG	86520 06100	0%	65.00*
1166	1	R/INN W-HOUSE COVER R	53736 06090	0%	55.00*
7054	1	R/LWR AXLE STEERING X	48068 33070	0%	145.00*

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: MAC/FEB2018/001
 Assessment Number: CTI10129
 Version: SMRTAUTO/3
 Date Calculated: 26/02/2018 03:33

Full Report - V1
 Registration: SJR8708B
 Printed: 26/02/2018 11:35

7772	1	R/LWR RADIATOR BRKT X	16535 0H060	0%	0.00
7026	1	R/R BUFFER ✓ NEC	52216 06080 X	0%	35.00*
7030	1	R/R CONTROL ARM BUSH ✓ NEC	52217 06060 X	0%	25.00*
7024	1	R/R FRONT AXLE BRKT X	51023 06020	0%	45.00*
1170	1	R/RADIATOR AIR GUIDE ✓ CRK	53293 06110	0%	55.00*
7770	1	R/UPP RADIATOR BRKT ✓ BT	16523 0H050	0%	40.00*
842	1	R/WHEELHOUSE SHELL X	53875 06081	0%	75.00*
844	1	R/WING COVER PANEL ? ✓ CRK	53882 06030	0%	45.00*
768	1	R/WING MOULDING ? ✓ BT	53825 06040	0%	55.00*
7761	1	RADIATOR ✓ Linking / BT	16400 0H250	0%	485.00*
7767	1	RADIATOR SHROUD ? X	16711 0H170	0%	105.00*
562	1	RIGHT HEADLAMP ASSY ✓ CRK	81110 06530	0%	380.00*
413	2	SCREW ✓ NEC X	53119 20120	0%	16.22U
7776	1	UPPER RADIATOR HOSE ? X	16571 0H110	0%	35.00*
1444	1	WASHER CONT SENSOR ? X	85397 33230	0%	62.08U
1436	1	WASHER CONTAINER ✓ Deform	85315 06160 X	0%	75.00*
1437	1	WASHER PUMP ? ✓ BMC	85330 21010 X	0%	150.00*
1443	1	WASHER RESERVOIR CAP X	85386 60050	0%	15.00*
f: OEM Parts				Sub Total	\$8,967.30
g: Original				Mark Up From Cost (5 %)	\$448.37
h: Secondhand				Sundry Parts (Fixed)	\$100.00
p: Parallel				Total Parts	\$9,515.67
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$9,515.67
Labour	
Total Panel/Mechanical	\$2,442.60 754.40
Total Paintwork	\$575.00 556.60
Total Visual Alignment work	\$230.00 97
Total Labour	\$3,247.60
Total Paint/Material Costs	\$300.23 274.21
Grand Total Excludes GST	\$13,063.50
GST @ 7 %	\$914.45
Grand Total Includes GST	\$13,977.95

Assessment Notes

8 days.

Sebastian.
 26/2/18.

- Lwp Sm Repair.
- Chassis Mark Item
- Photo
- Photo After Paint
- EXCESS: \$250
- Revert
- 90036121

sebastian.yong@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Finalise

Claim Reference: SNM18D00938C01
Assessment Number: CTI10129
Version: CHINATAI/3
Date Calculated: 02/05/2018 07:55

Full Report - V1
Registration: SJR8708B
Printed: 02/05/2018 14:55

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	15/02/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00938C01	Estimated Repair Time:	10 day(s)
Policy Number:	DMPCSN3076671701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YCA 01
Registration:	SJR8708B
Registration Month:	November
Registration Year:	2009
VIN Number:	MR053BK4107049767
Manufacture Year:	2009
Odometer:	145040
Colour:	Green
Engine Number:	1AZE149757
Fuel Level:	90%



Model Specs

FROM 12/2009	AUTO AIR CON
CHROME DOOR HANDLES	S/MOULDING CHROMED
MIRROR W/INDICATOR	2COMP GLASS ADHESIVE
RADIO WITH CD	REARVIEW CAMERA
FOG LAMPS	EXHAUST TRIM CHROMED
PARKING BRAKE FOOT	LEATHER SEATS
S-WHEEL RADIO CONT	ANTI THEFT ALARM
LEATHER/WOOD S-WHEEL	RR PARK DIST CONTROL
2.0 LTR 108 KW	4-SPEED AUTOMATIC
ELECT POWER STEERING	CRUISE CONTROL
TYRES 215/60 YR 16	WHEELS 6.5J X 16 ALU
VERSION THAILAND	PRODUCT THAILAND
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	Light Structural
Steering:	Vehicle Status on	Unroadworthy
	Inspection:	Mobile
Brakes Pedal Travel:	Date of Inspection:	18/01/2018
Place of Inspection:	Assessor	
Pre-Accident Damage:		
Tyres Condition:	Fair	
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Primary Impact
Secondary Impact

Addresses

Cost Summary

Total Labour	\$1,403.00
Total Paint/Material	\$277.21
Total Parts	\$4,642.30
Total of Additional Costs	\$35.00
Repair Cost Exc GST:	\$6,357.51
Overall Discount (0.0%):	- \$0.00
Excess:	-\$250.00
After Deduction -	
Grand Total Exc GST:	\$6,107.51
7 % GST:	\$427.53
Grand Total Inc GST:	\$6,535.04

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
043233C	ADD: ADJUST FRONT TOE	1.0	4.60
043233	ALIGN VEHICLE CPL	12.0	55.20
043233D	ADJUST FRONT CAMBER (ADD/WORK)	5.0	23.00
043233F	ADD: ADJUST REAR TOE	2.0	9.20
B100	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0	18.40
B140	RENEW FRONT PANEL	22.0	101.20
B110	RENEW R/FRT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)	5.0	23.00
B100	R + R LEFT SILL RAIL	3.0	13.80
B100	R + R RIGHT SILL RAIL	3.0	13.80
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	15.0	69.00
B040)	RENEW R/HEADLAMP (REMOVED)	2.0	9.20
B040	R + R HEADLAMPS (BUMPER REMOVED)	4.0	18.40
B070	RENEW BONNET	6.0	27.60
B080	R + R BONNET HINGES	1.0	4.60
851061	R + R WASHER NOZZLES	2.0	9.20
B085)	R + R WATER BOX CLOSING PANEL	4.0	18.40
M010)	RENEW CONDENSER (REMOVED)	1.0	4.60

NO NUMBER	R + R AIR CONDITIONING HOSE	4.0	18.40
895011	R + R ENGINE CONTROL UNIT	3.0	13.80
M010	R + R RADIATOR AND CONDENSER (FRONT BUMPER REMOVED)	16.0	73.60
	INCLUDES: BLEED COOLING SYSTEM		
M010)	RENEW RADIATOR	3.0	13.80
NO NUMBER	R + R ENGINE COVER	1.0	4.60
0481	REMOVE&REFIT BONNET INSULATION	2.0*	9.20
7757	REMOVE&REFIT FAN RELAY 1	1.0*	4.60
7769	REMOVE&REFIT L/UPP RADIATOR BRKT	1.0*	4.60
7773	REMOVE&REFIT LWR RADIATOR HOSE	2.0*	9.20
1001	REPAIR FRONT CROSSMEMBER	5.0*	23.00
1019	REPAIR L/F PANEL STRUT	3.0*	13.80
1021	REPAIR L/F RADIATOR BRACKET	5.0*	23.00
1027	REPAIR L/F PANEL REINF	3.0*	13.80
1117	REPAIR L/F WHEELHOUSE CPL	3.0*	13.80
1118	REPAIR R/F WHEELHOUSE CPL	10.0*	46.00
1124	REPAIR R/F WHEELHOUSE	30.0*	138.00
1436	CHECK WASHER CONTAINER		
1437	CHECK WASHER PUMP		
7310	CHECK R/F TIE ROD		
7312	CHECK R/TIE ROD BALL JOINT		

LABOUR COST

Total Work Units	184.0	
Panel / Mechanical Labour	16.4HRS	\$754.40
Visual Alignment Labour	2.0HRS	\$92.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	18.4HRS	\$846.40
Paint Labour	12.1HRS	\$556.60
Total Labour	30.5HRS	\$1,403.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
471	BONNET NEW PART PAINTING	26.0	
742	R/F WING NEW PART PAINTING	10.0	
988	LOCK CARRIER STRUT SURFACE PAINT	4.0	
1009	FRONT PANEL SURFACE PAINT	7.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	3.0	
741	L/F WING REPAIR PAINTING >50%	16.0	
1117	L/F WHEELHOUSE CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	

LABOUR COST - PAINT

TIME(PAINT)	91.0
Preparation Main Work Plastic	5.0
Preparation Main Work Metal	25.0
Preparation Work Multi Layer Paint	0.0
Total Work Units (10WU/HR)	121.0

Total Paintwork Labour	12.1HRS	\$556.60
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$108.36
New Part Painting - Plastic K1R		\$68.39
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$47.06
Repair Painting		\$15.80
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$277.21
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$277.21

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3012	1	BADGE "VVT-I" R	75443 06540		0%	28.00*
471	1	BONNET	53301 06110		0%	430.00*
527	1	BONNET FRONT SEAL	53381 06060		0%	38.00*
340	1	BUMPER SUPPORT	52021 06060		0%	150.00*
4465	1	CONDENSER	88460 06170		0%	380.00*
412	1	CTR BUMPER GRILLE	53112 06120		0%	85.00*
283	1	FRONT BUMPER	52119 06960		0%	260.00*
1000	1	FRONT GRILLE EMBLEM	Renew		0%	30.00*
1009	1	FRONT PANEL	53201 06171		0%	380.00*
344	1	FRT BUMPER ABSORBER	52611 06160		0%	75.00*
1000	1	FRT BUMPER TOW COVER	Renew		0%	20.00*
260	1	FRT NO PLATE BRKT	52114 06100		0%	65.00*
4485	1	FRT PIPE COMPR/COND	88715 06050		0%	35.00*
410	1	GRILLE	53111 06280		0%	185.00*
475	1	L/BONNET HINGE	53420 06130		0%	35.00*
9645	1	L/HORN	86510 06110		0%	65.00*
988	1	LOCK CARRIER STRUT	53208 06040		0%	60.00*
493	1	LOWER BONNET LOCK	53510 06101		0%	50.00*
7794	1	R/BLOWER FAN	16361 0H220		0%	55.00*
498	1	R/BONNET DAMPER	53440 0W110		0%	160.00*
476	1	R/BONNET HINGE	53410 06130		0%	35.00*
638	1	R/F FOG LAMP CPL	81210 02121		0%	115.00*
742	1	R/F WING	53801 06130		0%	225.00*
7790	1	R/FAN MOTOR	16363 0H140		0%	180.00*
298	1	R/FOG LAMP COVER	52030 06080		0%	60.00*
9646	1	R/HORN	86520 06100		0%	65.00*
1170	1	R/RADIATOR AIR GUIDE	53293 06110		0%	55.00*
7770	1	R/UPP RADIATOR BRKT	16523 0H050		0%	40.00*
844	1	R/WING COVER PANEL	53882 06030		0%	45.00*
768	1	R/WING MOULDING	53825 06040		0%	55.00*
7761	1	RADIATOR	16400 0H250		0%	485.00*
562	1	RIGHT HEADLAMP ASSY	81110 06530		0%	380.00*
f: OEM Parts			Sub Total			\$4,326.00
g: Original			Mark Up From Cost	(5 %)		\$216.30
h: Secondhand			Sundry Parts	(Fixed)		\$100.00
p: Parallel			Total Parts			\$4,642.30
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	FRY NO. PLATE	0%	\$35.00
	SPECIALIST		
		Total Extras	\$35.00

Final Calculation

Total Parts		\$4,642.30
Labour		
	Total Panel/Mechanical	\$754.40
	Total Paintwork	\$556.60
	Total Visual Alignment work	\$92.00
Total Labour		\$1,403.00
Additional Costs		
	Corr Prot Materials External	\$0.00
	Corr Prot Materials Internal	\$0.00
	Cost of Specialist	\$35.00
Total of Additional Costs		\$35.00
Total Paint/Material Costs		\$277.21
Repair Costs Excludes GST		\$6,357.51
Deductions		
	Deduction for Excess (Fixed)	-\$250.00
Total Deductions		-\$250.00
Grand Total Excludes GST (After Deduction)		\$6,107.51
	GST @ 7 %	\$427.53
Grand Total Includes GST (After Deduction)		\$6,535.04

Assessment Notes

Veron Chen (LKKAuto)

From: Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
<TanSohChern@smrt.com.sg>
Sent: Thursday, 3 May 2018 9:29 AM
To: Veron Chen (LKKAuto)
Cc: SUR
Subject: RE: SJR 8708B-DOA: 15/2/2018 (CHINA TAIPING OD)

Dear Veron

Thank you for your offer.

We accept your given offer of lump sum \$5,050 (excess \$250).

Regards
Susan

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 2 May, 2018 3:59 PM
To: Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TanSohChern@smrt.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJR 8708B-DOA: 15/2/2018 (CHINA TAIPING OD)

Dear Susan,

Offer Lump Sum \$5,050 before excess \$250.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 2 March 2018 4:52 PM
To: Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TanSohChern@smrt.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SJR 8708B-DOA: 15/2/2018 (CHINA TAIPING OD)

Dear Susan,

As instructed by our client , please proceed to repair the insured vehicle **SJR 8708B (Excess \$250/-), Except RH front portion and undercarriage.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Please refer adjust revised from China TaiPing.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018 Sendback Est	26 Feb 2018 14:06 S\$13,068.50	27 Feb 2018 11:41 Edit Adj Rpt	S\$5,050.00 Edit Estimates	S\$5,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TAN PENG YIAM , ID: S15491138									
Vehicle Reg. No.: SJR8708B		Date of Loss: 15/02/2018 00:00 - :59 [98 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D00938C01		Policy/Cover Note No.: DMPCSN3076671701 (Comprehensive)							
		Excess: S\$250.00							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 08/03/2018]									
Driver/Custodian: TAN PENG YIAM (/ Male), NRIC: S15491138									
Adj Asg. Remarks: OD SURVEY AND REVERT. EXCESS \$250.00 AFTER WAIVER									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPIING (02/03/2018): Alert - Adj Mandate Approved (S\$5900.00) - SJR8708B - Claim Handler: Joel Goh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJR8708B (SNM18D00938C01)
 OD
 Feb 15 2018 12:00AM
 [TAN PENG YIAM]
 SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)		Thumbnail	Print
1	26/02/18 14:06	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 14:49	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 14:50	SURVEY PHOTOS	1	Load PDF	
2	03/05/18 10:21	Reinspection Photo	1	Load PDF	
Documentation				1 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)		Thumbnail	Print
1	26/02/18 14:50	Copy of Insured's IC	1	Load PDF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/03/18 13:13	Revised Estimate	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 14:49	MARK ESTIMATE	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18003716/SVD3E2

Date: 11/05/2018

REFERENCE

Insured/Claimant: TAN PENG YIAM Policy No: DMPCSN3076671701

Date of Loss: 15/02/2018 Nature of Claim: OD Claim No: SNM18D00938C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR8708B**

Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A)

Engine No: 1AZE149757

Reg. Date: 25/11/2009 (Man. Year: 2009)

Chassis No: MR053BK4107049767

Colour: Silver

Odometer: 145041 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$31,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,520.67	4,677.30	4,843.37	50.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,547.83	1,680.21	1,867.62	52.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,068.50	6,357.51	6,710.99	51.35
Approved Total (Overridden) (S\$)		5,050.00		
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	13,068.50	4,800.00	8,268.50	63.27
+ GST 7.00/7.00% (S\$)	914.80	336.00	578.80	63.27
Nett Amount (S\$)	13,983.30	5,136.00	8,847.30	63.27

INSPECTION

Date of Assignment: 27/02/2018 Present Location:

SMRT Automotive Services Pte Ltd
(Woodlands)

Date Inspected: 27/02/2018 Inspected At:

60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 8.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2018)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR8708B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Sundry Parts	Necessary	-	*100.00 FS
2	1	NA	*AIR FILTER ASSY	Not Necessary	225.00 F	*- F
3	1	NA	*AIR INTAKE HOSE	Not Necessary	90.00 F	*- F
4	1	NA	*AIR INTAKE HOSE	Not Necessary	60.00 F	*- F
5	1	NA	*BADGE "VVT-I" L	Not Necessary	28.00 F	*- F
6	1	NA	*BADGE "VVT-I" R	Necessary	28.00 F	*28.00 F
7	1	NA	*BONNET	Dented	430.00 F	*430.00 F
8	1	NA	*BONNET FRONT SEAL	Necessary	38.00 F	*38.00 F
9	1	NA	*BONNET INSULATION	Necessary	180.00 F	*- F
10	1	NA	*BUMPER SUPPORT	Dented	150.00 F	*150.00 F
11	1	NA	*COMPR/CONDENSER TUBE	Not Necessary	48.00 F	*- F
12	1	NA	*COND/EVAPORATOR PIPE	Not Necessary	95.00 F	*- F
13	1	NA	*CONDENSER	Dented	380.00 F	*380.00 F
14	1	NA	*CONTROL CABLE	Not Necessary	45.00 F	*- F
15	1	NA	*CTR BUMPER GRILLE	Cracked	85.00 F	*85.00 F
16	1	NA	*ENGINE COMP HARNESS (NPA)	Not Necessary	0.00 F	*- F
17	1	NA	*ENGINE HARNESS (NPA)	Not Necessary	0.00 F	*- F
18	1	NA	*FAN RELAY 1	Not Necessary	76.47 F	*- F
19	1	NA	*FAN RELAY 2	Not Necessary	59.53 F	*- F
20	1	NA	*FRONT BUMPER	Deformed	260.00 F	*260.00 F
21	1	NA	*FRONT GRILLE EMBLEM	Necessary	30.00 F	*30.00 F
22	1	NA	*FRONT NUMBER PLATE	Dented	35.00 F	*35.00 FS
23	1	NA	*FRONT PANEL	Bent	380.00 F	*380.00 F
24	1	NA	*FRT BUMPER ABSORBER	Cracked	75.00 F	*75.00 F
25	1	NA	*FRT BUMPER TOW COVER	Cut	20.00 F	*20.00 F
26	1	NA	*FRT NO PLATE BRKT	Cracked	65.00 F	*65.00 F
27	1	NA	*FRT NO PLATE REINF	Not Necessary	15.00 F	*- F
28	1	NA	*FRT PIPE COMPR/COND	Bent	35.00 F	*35.00 F
29	1	NA	*GRILLE	Cracked	185.00 F	*185.00 F
30	1	NA	*L/BLOWER FAN	Not Necessary	55.00 F	*- F
31	1	NA	*L/BONNET DAMPER	Not Necessary	160.00 F	*- F
32	1	NA	*L/BONNET HINGE	Bent	35.00 F	*35.00 F
33	1	NA	*L/ENGINE COVER	Not Necessary	85.00 F	*- F
34	1	NA	*L/F FOG LAMP CPL	Not Necessary	115.00 F	*- F
35	1	NA	*L/F UPP BUMPER BRKT	Not Necessary	48.00 F	*- F
36	1	NA	*L/F WING	Not Necessary	225.00 F	*- F
37	1	NA	*L/FAN MOTOR	Not Necessary	180.00 F	*- F
38	1	NA	*L/FOG LAMP COVER	Not Necessary	60.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1	NA	*L/HORN	Damaged	65.00 F	*65.00 F
40	1	NA	*L/LWR RADIATOR BRKT	Not Necessary	0.00 F	*- F
41	1	NA	*L/RADIATOR AIR GUIDE	Not Necessary	55.00 F	*- F
42	1	NA	*L/UPP RADIATOR BRKT	Not Necessary	40.00 F	*- F
43	1	NA	*L/WING COVER PANEL	Not Necessary	45.00 F	*- F
44	1	NA	*LEFT HEADLAMP ASSY	Not Necessary	380.00 F	*- F
45	1	NA	*LIQUID GAS SYSTEM	Not Necessary	60.00 F	*- F
46	1	NA	*LOCK CARRIER STRUT	Damaged	60.00 F	*60.00 F
47	1	NA	*LOWER BONNET LOCK	Jammed	50.00 F	*50.00 F
48	1	NA	*LWR RADIATOR HOSE	Not Necessary	35.00 F	*- F
49	1	NA	*POWER STEERING CPL	Not Necessary	155.00 F	*- F
50	1	NA	*R/BLOWER FAN	Cracked	55.00 F	*55.00 F
51	1	NA	*R/BONNET DAMPER	Damaged	160.00 F	*160.00 F
52	1	NA	*R/BONNET HINGE	Bent	35.00 F	*35.00 F
53	1	NA	*R/CARRIER JOINT	Not Necessary	85.00 F	*- F
54	1	NA	*R/DRIVE SHAFT CPL	Not Necessary	155.00 F	*- F
55	1	NA	*R/ENGINE COVER	Not Necessary	85.00 F	*- F
56	1	NA	*R/F FOG LAMP CPL	Cracked	115.00 F	*115.00 F
57	1	NA	*R/F OUT S-MEMBER PNL (NPA)	Not Necessary	0.00 F	*- F
58	1	NA	*R/F S-MEMB RR REINF (NPA)	Not Necessary	0.00 F	*- F
59	1	NA	*R/F STABI ROD	Not Necessary	85.00 F	*- F
60	1	NA	*R/F STEERING KNUCKLE	Not Necessary	65.00 F	*- F
61	1	NA	*R/F UPP BUMPER BRKT	Not Necessary	48.00 F	*- F
62	1	NA	*R/F WHEEL	Not Necessary	450.00 F	*- F
63	1	NA	*R/F WHEEL BEARING	Not Necessary	60.00 F	*- F
64	1	NA	*R/F WHEEL BOLT SET	Not Necessary	30.00 F	*- F
65	1	NA	*R/F WHEEL HUB	Not Necessary	85.00 F	*- F
66	1	NA	*R/F WING	Dented	225.00 F	*225.00 F
67	1	NA	*R/FAN MOTOR	Cracked	180.00 F	*180.00 F
68	1	NA	*R/FOG LAMP COVER	Cracked	60.00 F	*60.00 F
69	1	NA	*R/HORN	Damaged	65.00 F	*65.00 F
70	1	NA	*R/INN W-HOUSE COVER	Repair	55.00 F	*- F
71	1	NA	*R/LWR AXLE STEERING	Not Necessary	145.00 F	*- F
72	1	NA	*R/LWR RADIATOR BRKT (NPA)	Not Necessary	0.00 F	*- F
73	1	NA	*R/R BUFFER	Not Necessary	35.00 F	*- F
74	1	NA	*R/R CONTROL ARM BUSH	Not Necessary	25.00 F	*- F
75	1	NA	*R/R FRONT AXLE BRKT	Not Necessary	45.00 F	*- F
76	1	NA	*R/RADIATOR AIR GUIDE	Cracked	55.00 F	*55.00 F
77	1	NA	*R/UPP RADIATOR BRKT	Bent	40.00 F	*40.00 F
78	1	NA	*R/WHEELHOUSE SHELL	Not Necessary	75.00 F	*- F
79	1	NA	*R/WING COVER PANEL	Cracked	45.00 F	*45.00 F
80	1	NA	*R/WING MOULDING	Torn	55.00 F	*55.00 F
81	1	NA	*RADIATOR	Leaking / Bent	485.00 F	*485.00 F
82	1	NA	*RADIATOR SHROUD	Not Necessary	105.00 F	*- F
83	1	NA	*RIGHT HEADLAMP ASSY	Cracked	380.00 F	*380.00 F
84	1	NA	*SCREW	Not Necessary	16.22 F	*- F
85	1	NA	*SUNDRY PARTS	Not Necessary	100.00 F	*- F
86	1	NA	*UPPER RADIATOR HOSE	Not Necessary	35.00 F	*- F
87	1	NA	*WASHER CONT SENSOR	Not Necessary	62.08 F	*- F
88	1	NA	*WASHER CONTAINER	Not Necessary	75.00 F	*- F
89	1	NA	*WASHER PUMP	Not Necessary	150.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
90	1	NA	*WASHER RESERVOIR CAP	Not Necessary	15.00 F	*- F
					Sub Total (S\$)	9,067.30 4,461.00
					+ Margin on L,N Items 5.00/5.00% (S\$)	453.37 216.30
					Total Parts (S\$)	9,520.67 4,677.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	575.00	556.60
2	Total Paint Materials	New	300.23	92.00
3	Total Panel/Mechanical Labour	New	2,672.60	754.40
4	Total Paint / Material Costs	New	-	277.21
Gross Labour Cost (S\$)			3,547.83	1,680.21

Report was unsubmitted during this print-out.

< END OF ESTIMATES >