

ASS. REC. BY:

REF: CS/FCI18003782/Kvd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

27/2/18 @ 9.34am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 631ST

Insured:

SHC1218Y

at Workshop m/s

Wei Lee Motor

Tel:

64569830

of

Bikq, Sin Min Ind. Est. #01-32

Policy No:

Claim No:

D18001301MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/02/18

CA / REV / REP. / REV 24 HRS

lwp

28/02/2018

H.O.D. Endorsement:

Date/Time:

1.31pm @ 27/2/18

Person Contacted:

Karen

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLH 631ST - NS/INC18002727/Klvbn2 D.O.A.: 5/2/18
	SHC1218Y - NS/INC18002727/Klvbn2 D.O.A.: 8/2/18
1/3/18	Email preli revised to FCI

REF: FEL

ASSIGNMENT

From: Date: 28/02/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 6315T

at Workshop m/s

Wei Lee

of: Blk 9 Sin Ming #0132

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$11k

IDAO Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lump Sum: 70 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLH 6315T Page: 09 of 08

Type: M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jan 200 1335

Colour: White A/C Insured / Std / NI / NA

Sp. Reading: 91053 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMGD18508S216613

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: Dun 195/55R15

R: B.S

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 2 mm

L/Bal. 8 mm

L/Bal. 2 mm

D.O.A. 8/2/18

D.O.A. 28/2/18

Survey held at: ✓

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

1/3 File pass to Catherine

13/18 11pm 8650 confirmed with Kiren (Red 1248.56, 667)

@415pm

mv: \$11k (EST) LTA: \$7705 NV: \$3295

RECEIVED 02 MAR 2018

Date/Time File Pass to:

☐

Prel. Report

Days Of Repair: 2

1)

☐

Final Report

Resurvey No. of Trip: -

Survey Fee

Date/Time File Return to:

Transportation

1/3 - typist

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech Insp \$

☐

Weekend \$

Report Format:

CWS

Lump Sum / I.B. 113

650/2

100

50

9

159



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001301MFSH

Our ref: CS/FCI18003782/Kvd3

Date : 1/3/2018

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 6315T


We thank for your instruction on 27/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28/2/2018 at the premises of M/s WEILEE MOTOR WORKS and have the following to report:-

Workshop Estimate Amount	: S\$1,898.56
Revised Estimate Amount	: S\$650.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No. : CS | FC1 | 800 3782 | Kvd3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **)**: Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (_____ **)**: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 13/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003782/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1218Y	Veh. Inspected	SLH 6315T
Policy No.		Coverage (\$)	0.00
Claim No.	D18001301MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/02/2018	Inspection Date	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	12-02-2018	Our Ref No. D18001301MFSH
Accident Date	08-02-2018	Claim Type. Third Party
Insured Vehicle	SHC1218Y	Third Party Vehicle. SLH6315T
Survey Location	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32	
Contact Person.	KAREN SEAH	
Contact No.	64569830/ 0	Fax No. 64580128
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEI LEE MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234938)



PRI Documents



Close



PRI Header Details

Claim No	D18001301MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WEI LEE T
Workshop Name	WEI LEE MOTOR WORKS (Contact Person : KAREN SEAH)	Survey Location & Contact Details	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Mobile: 0 , Phone: 64569830 , Fax: 64580128 EmailId: WEILEEMOTORWORKS@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1218Y	TP Vehicle No	SLH6315T
PRI Recieved Date	23-02-2018 06:29:21 PM	Surveyor Appointed Date	27-02-2018 09:33:45 AM	Surveyor Accept Date	27-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-02-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 1 March 2018 5:21 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001301MFSH/1, SLH 6315T
Attachments: SLH 6315T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLH 6315T
Date of survey: 28/2/2018
Number of days: 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 February 2018 1:54 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001301MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 28/02/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 February 2018 9:34 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001301MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	SLH6315T
Vehicle to be Exported:	No
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A55001152
Chassis No.:	JHMGD18508S216613
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,951.00
Original Registration Date:	01 Sep 2008
First Registration Date:	01 Sep 2008
Transfer Count:	4
Actual ARF Paid:	\$13,951.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Aug 2018
PARF Rebate Amount:	\$6,975.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,685.00
COE Rebate Amount:	\$730.00
Total Rebate Amount:	\$7,705.00

The information contained herein is correct as at 01 Mar 2018

OK

威利摩多
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455-3986

Business Regn No : 269436/00J

23, Feb 2018

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House S 068877

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SHC1218Y
Accident involving vehicle No: SLH6315T/SHC1218Y
DOA: 08/02/2018 AT Church St beside Citibank Capital square branch

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SLH6315T

To supply—

Description	Qty	Amount
Front bumper	1	523.50
Bumper retainer, RH	1	13.00
Bumper clip		38.00
Headlamp, RH	1	486.20
Total		1,060.70
Parts less 20%		212.14
		848.56

To remove damaged parts and attachments.

Repair/reshape dented areas.

Replace/align above parts.

Painting.

550.00

500.00

1898.56

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003782/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1218Y	Veh. Inspected	SLH 6315T	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001301MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMGD18508S216613	Colour	WHITE	
Odometer	91053	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	DUNLOP	8 mm	
L/H Front Tyre	195/55 R15	DUNLOP	8 mm	
R/H Rear Tyre	195/55 R15	BRIDGESTONE	2 mm	
L/H Rear Tyre	195/55 R15	BRIDGESTONE	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	28/02/2018	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 6315T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED / CRACKED	523.50	523.50
1	BUMPER RETAINER,RH	DISTORTED	13.00	13.00
1	BUMPER CLIP	NECESSARY	38.00	38.00
1	HEADLAMP,RH	SERVICEABLE	486.20	-
	LESS 20% DISCOUNT		-212.14	-114.90
			848.56	459.60
	<u>LABOUR</u>			
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DENTED AREAS.REPLACE/ALIGN ABOVE PARTS. PAINTING.		550.00	200.00
			500.00	200.00
			1,050.00	400.00
	GRAND TOTAL		1,898.56	859.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			650.00
---	--	--	---------------

Report Ref No. CS/FCI18003782/Kvd3n2

MARKET VALUE: \$11,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$7,705.00=NETT VALUE: \$3,295.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.