

22/03/2003

ASS. REC. BY:

REF: CS/FCI18003789/Kqd3

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

27/2/18 @ 9.32am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 9886Y

Insured:

SHA 6046D

at Workshop m/s

Hui Yung Motor

Tel:

64515752

of

Blk 176, Sin Ming Drive # 04-02

Policy No:

D-15072701MFSH

Claim No:

D18021635MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/2017

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

1106am 27/2/18

Person Contacted:

Belle

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

GBA 9886Y-NA/AIC08028029/r

D.O.A: 15/10/2008

SHA 6046D-CS3/FCI/5001769/Rpk3

D.O.A: 27/1/15

01/2/18 @ 9.32am verified to Karen Tan by email.

23/3 11pm 824501 email & confirm (Red 8750, 23/3)

ASS. REC. BY:

REF:

PCZ /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBA 9886 Y

Yr Regn:

08 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Me Vito

c.c.

2143

Colour multi

white

A/C: Insured / Std / NI / NA

Sp. Reading

20853

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDI-8396052-3894758

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Continental

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

20/11/17

D.O.I.

21/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S on body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/2

File pass to Continental

RECEIVED 27 MAR 2018

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

130

50

50

17

247

Report Format:

Lump Sum / I.B.I. (\$

78

7450

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003789/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 6046D	Veh. Inspected	GBA 9886Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18001635MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/11/2017	Inspection Date	27/02/2018
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001635MFSH

Date: 01 March 2018

Our Ref: CS/FCI18003789/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBA 9886Y.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/02/2018 at the premises of M/s HUI YANG, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,155.00</u> .
Revised Estimate Amount	: S\$ <u>2,545.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the n/s front body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-02-2018	Our Ref No. D18001635MFSH
Accident Date	20-11-2017	Claim Type. Third Party
Insured Vehicle	SHA6046D	Third Party Vehicle. GBA9886Y
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	SANDRA	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235351)



PRI Documents



Close



PRI Header Details

Claim No	D18001635MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & HUI YANG
Workshop Name	HUI YANG MOTOR PTE LTD (Contact Person : SANDRA)	Survey Location & Contact Details	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE Mobile: 0 , Phone: 6451 5752 , Fax: 6451 4658 EmailId: HUI_YANG_MOTOR@HOTMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA6046D	TP Vehicle No	GBA9886Y
PRI Recieved Date	26-02-2018 07:27:57 PM	Surveyor Appointed Date	27-02-2018 09:31:42 AM	Surveyor Accept Date	27-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-02-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 March 2018 9:33 AM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001635MFSH/1
Attachments: CSFCI18003789Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of GBA 9886Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 February 2018 11:08 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001635MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 February 2018 9:32 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001635MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

First capital
26/02 or 27/02

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

20/11/2017

Owner: WILDLIFE END VETERINARY SUPPLIES

*Not authorized
C/Py @ 2450/-
Running After Prim
4 days*

ESTIMATE TO REPAIR MERCEDES VITO 116 CDI - GBA9886Y

1pc front LH door
1pc front LH door protector

Bj \$ 1,100.00 ✓
dd \$ 250.00 —

less 10%

\$ 1,350.00
\$ 135.00
\$ 1,215.00

commercial sticker

900.00 ✓
s.nett \$ ~~450.00~~ *300* nec

tuffkote
wiring
spray painting
labour charges
Total

\$ 60.00 *300*
\$ 80.00 *200*
\$ 700.00 *500*
\$ 650.00 *400*
\$ 3,155.00
3605



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before *C* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed *and* is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003789/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6046D	Veh. Inspected	GBA 9886Y	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D18001635MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES VITO	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDF63960523894758	Colour	MULTI	
Odometer	209653	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R16	CONTINENTAL	8 mm	
L/H Front Tyre	225/60 R16	CONTINENTAL	8 mm	
R/H Rear Tyre	225/60 R16	CONTINENTAL	8 mm	
L/H Rear Tyre	225/60 R16	CONTINENTAL	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2017	Inspection Date	27/02/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 9886Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LH DOOR	BENT	1,100.00	1,100.00
1	FRONT LH DOOR PROTECTOR	DENTED	250.00	250.00
	LESS 10% DISCOUNT		-135.00	-135.00
			1,215.00	1,215.00
	<u>SPECIAL NETT ITEMS</u>			
1	COMMERCIAL STICKER (SN)	NECESSARY	900.00	900.00
			900.00	900.00
	<u>LABOUR</u>			
	TUFFKOTE.		60.00	30.00
	WIRING.		80.00	20.00
	SPRAY PAINTING.		700.00	500.00
	LABOUR CHARGES.		650.00	400.00
			1,490.00	950.00
	GRAND TOTAL		3,605.00	3,065.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00

Report Ref No. CS/FCI18003789/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.