

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| NTU | TUC INCOME INSURANCE CO-OPERATIVE LTD | | | Ref: NS/INC18003801/K1tbn2 | | |
|--|---|-------------------|---------|----------------------------|--------------------|--|
| | | | | | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE | | | | 08-03-2018 | | |
| #05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 08-03-2018 | | | | | | |
| | | | Code: | INC4 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | GBA 3707X | Veh. Ir | nspected | SHC 8951S | |
| | Policy No. | 5076969791-02 | Cover | age (\$) | 0.00 | |
| | Claim No. | MT/0984841-001 | Exces | s (\$) | 0.00 | |
| | Assign From | | Assig | n Date | 27/02/2018 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HYUNDAI 140 | c.c | | 1685 | |
| | Engine No. | HIDDEN | Year o | f Reg. | 2016 | |
| | Chassis No. | KMHLB41UMGU087652 | Colou | r | BLUE | |
| | Odometer | 222896 | Steeri | ng | IN ORDER | |
| | Brakes | IN ORDER | Modifi | cation | STANDARD ALLOY RIM | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/60 R16 | WEST | LAKE | 7 mm | |
| | L/H Front Tyre | 205/60 R16 | WEST | LAKE | 7 mm | |
| | R/H Rear Tyre | 205/60 R16 | WEST | LAKE | 7 mm | |
| | L/H Rear Tyre | 205/60 R16 | WEST | LAKE | 7 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 25/02/2018 | Inspec | tion Date | 27/02/2018 | |
| | Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | | | | |
| | | | | | | |
| 5a. Remarks | | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | · · | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | |