

ASS. REC. BY:

REF:

TP / Independent

CS/TP18003826/Kvber

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

12772%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 3959R Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude C.C. 1995

Colour

N-White / Red

A/C: Insured / Std / NI / NA

Sp. Reading

407728

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VFI ABL 15AUC 281245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

Pmm well mm

Rear

R/Bal.

8

mm

L/Bal.

9

Giti mm

L/Bal.

8

mm

D.O.A.

13/2/18

D.O.I.

19/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S &amp; U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/2

Frt pass to lite

SHC 3959R - TC3 / ATG 13007393 / Kptg 2

DCA: 110513

23/10/18

LS \$ 10,400 (Red 118,894.50, 92h)

RECEIVED 23 OCT 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

23/10 typist

Days Of Repair:

5

Resurvey No. of Trip:

-

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Photos:

Others:

OSP

TOTAL

119 x 15 =

170 + 1785

50

28

2033

Report Format:

TP

Lump Sum / I.B.I. (\$

10,400/2

# Survey Department Check List (Case Handler)

Reference No.: CS/TP/18003826/Kvb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 23/10/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18003826/Kvb		
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 27-02-2018		
		Code : TP378		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	Veh. Inspected		SHC 5959R	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		19/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	13/02/2018	Inspection Date	19/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5959R
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002366
Chassis No.:	VF1ABL15AUC281245
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	16 Mar 2015
First Registration Date:	16 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2023
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	15 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$32,481.00
<b>Total Rebate Amount:</b>	<b>\$41,854.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Feb 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/02/2018 13:26
Date Of Accident	13/02/2018 07:50
Exact Location Of Accident	ANCHORVALE CRES TOWARDS ANCHORVALE ST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5959R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	POH KHENG
NRIC No	S0030072A
Date Of Birth	18/01/1953
Occupation	OUTDOOR
Date Of Driving Pass	20/02/1976
Driving Experience	41 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98397793
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 116B RIVERVALE DRIVE #10-26
Postcode	542116
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : MOTHER GENDER: : FEMALE
Passenger 2	NAME: : SON GENDER: : MALE
Passenger 3	NAME: : DAUGHTER GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT : T/20180213/2080

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	ANDREW YAP
Phone Number	98510055
Email Address	YJP_SURV@SINGNET.COM.SG



**Details of Witness 2**

Name  
Phone Number 96702999  
Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLL209K  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number 96702999  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SKT5926K  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver ANDREW YAP  
NRIC/Passport Number  
Contact Number 98510055  
Address 10 GENTING ROAD, #05-00, THE BLUE BUILDING  
Postcode 349473  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name POH KHENG  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SHC5959R  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN

SKETCH PLAN

A hand-drawn sketch plan on graph paper. The plan shows a path starting from the top left, moving down and to the right. There is a break in the line, indicated by a gap. The gap is labeled 'NHL'. After the gap, the path continues down and to the right again.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to police report -

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature: \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180213/2080

1 of 3

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

Report No. T/20180213/2080

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 13/02/2018 14:31	Vide Report No.:	Station Diary No.: 91
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: POH KHENG			Address: APT BLK 116B RIVERVALE DRIVE #10-26 SINGAPORE 542116	
ID Type / ID No.: NRIC NO / S0030072A			Contact No.: Home/Office:	Mobile: 98397793
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 65	Date of Birth: 18/01/1953	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 3 Date of Expiry:	

**General Information of the Accident**

General Information				
Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 13/02/2018 07:50	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 ANCHORVALE CRESCENT ANCHORVALE STREET Along Anchorvale Crescent towards Anchorvale Street.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHC5959R	TAXI				Seriously Damaged	3

POLICE REPORT Pg. 1



SINGAPORE  
POLICE FORCE



T/20180213/2080

2 of 3

Report No. T/20180213/2080

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

CONTINUATION OF REPORT

Brief Details.

On the 13/02/2018 at about 0750hrs, I was driving my taxi bearing registration plate number of SHC5959R along Anchorvale Crescent and was heading towards Anchorvale Street.

As I was travelling along Anchorvale Crescent, I heard a sound coming from below my taxi but I did not think much about it at that moment. After I had turned into Anchorvale Street, my taxi could not move anymore. I went down to make a check and I discovered that my front right tyre was punctured, the front right tyre rim was spoilt and oil was leaking from below my taxi.

The 3 passengers in my taxi were unharmed and they took another taxi thereafter. Another uncle came and told me that another car had mounted on the same kerb located at Anchorvale Crescent.

I went to take a look and saw another white car bearing registration plate number of SLL209K had mounted on the kerb. I want to state that there was no kerb there previously as I had drive through Anchorvale Crescent multiple times. Traffic Police and SCDF were at scene as well.

I was also given 3 days MC from 13/02/2018 - 15/02/2018  
by clinic Lifeline Medical Group Sengkang Pte Ltd.

Ang Mo Kio North  
51 Ang Mo Kio Ave 9  
Singapore 569784  
Tel: 4849999

*[Signature]*  
Sgt C/T14086  
Yeo Jun Bin



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999



T/20180213/2080

3 of 3

Report No. T/20180213/2080

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /  
Sgt 1 YEO JUN BIN

Signature Of Interpreter:  
Not applicable

Signature Of Informant:

Date/Time:  
13/02/2018 14:31

Officer In Charge Of Case: SN 085

HAIRIE /  
S. DZUL HAIRIE BIN RAMLI  
Contact No: 68476220

Classification Of Case:

Authentication Stamp  
Singapore Police Force

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5959R -****AAD1802-142***Not Authored*  
*1/1/8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC5959R - JHOW**

VF1ABL15AUC281245

RENAULT

LATITUDE

13.02.2018

**LTA**

<b>PART</b>			<b>LIST</b>	
1	1	BUMPER COVER FRT	\$	<i>CM</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>10.1</i> <i>Sh</i> 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>Sh</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>Sh</i> 151.41
5	1	BUMPER SUPPORT FRT	\$	<i>Sh</i> 123.88
6	1	BUMPER RETAINER FRT RH	\$	<i>Sh</i> 150.77
7	1	BUMPER SUPPORT FRT	\$	<i>Sh</i> 123.88
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sh</i> 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sh</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sh</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sh</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>N</i> 914.08
13	1	TOW COVER FRT	\$	<i>Sh</i> 28.61
14	1	RADAIOR GRILLE	\$	<i>Sh</i> 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sh</i> 225.36
16	1	RADAIOR GRILLE FRAME	\$	<i>Sh</i> 1,353.75
17	1	FRAME FULL SUPPORT PANEL	\$	<i>N</i> 615.90 X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79
19	1	FRONT BRACE PANEL	\$	<i>N</i> 177.22
20	1	HORN	\$	<i>Sh</i> 314.17
21	1	HORN BRACKET	\$	<i>N</i> 40.45
22	1	HEADLALMP LH	\$	<i>Sh</i> 1,184.43
23	1	HEADLALMP RH	\$	<i>Sh</i> 1,184.43
24	1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15
25	1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15
26	1	BONNET	\$	<i>N</i> 1,941.63
27	1	BONNET INSULATOR	\$	<i>Sh</i> 405.73
28	1	BONNET STRUT LH	\$	<i>Sh</i> 88.61
29	1	BONNET STRUT RH	\$	<i>Sh</i> 88.61
30	1	BONNET HINGE LH	\$	<i>R</i> 348.31
31	1	BONNET HINGE RH	\$	<i>N</i> 348.31
32	1	BONNET LOCK	\$	<i>N</i> 305.48
33	1	BONNET CABLE	\$	<i>Sh</i> 119.19
34	1	BONNET CABLE COVER	\$	<i>Sh</i> 161.03

# TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5959R -

AAD1802-142

35	1	BONNET SEAL OUTER	\$	92.36	X
36	1	BONNET SEAL INNER	\$	157.28	X
37	1	FENDER PANEL FRT LH	\$	783.83	X
38	1	FENDER PANEL FRT RH	\$	783.83	X
39	1	WHEELARCH FRT LH	\$	278.84	X
40	1	WHEELARCH FRT RH	\$	278.84	X
41	1	FENDER BRACKET LOWER LH	\$	15.79	X
42	1	FENDER BRACKET LOWER RH	\$	15.79	X
43	1	FENDER INSULATOR LH	\$	130.84	X
44	1	FENDER INSULATOR RH	\$	130.84	X
45	1	WIPER RESERVOIR	\$	348.25	X
46	1	WIPER RESERVOIR NECK	\$	136.11	X
47	1	WIPER RESERVOIR MOTOR	\$	270.06	X
48	1	AIR CLEANER LOWER	\$	271.26	X
49	1	AIR CLEANER HOSE	\$	76.14	X
50	1	AUTO GEARBOX <i>P-?</i>	\$	41,101.58	X
51	1	AUTO COMPUTER	\$	5,032.17	X
52	1	STEERING PUMP ELECTRIC	\$	2,306.90	X
53	1	STEERING PINION RACK	\$	4,413.11	X
54	1	ENGINE HARNESS	\$	4,084.54	X
55	1	SUBFRAME OUTER FRT	\$	2,652.45	X
56	1	SUBFRAME BRACKET OUTER LH	\$	92.36	X
57	1	SUBFRAME BRACKET OUTER RH	\$	92.36	X
58	1	ENGINE UNDERTRAY	\$	564.98	X
59	1	A/C CONDENSER	\$	2,020.37	X
60	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	X
61	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	X
62	1	A/C CONDENSER GARNISH LH	\$	58.81	X
63	1	A/C CONDENSER GARNISH RH	\$	59.60	X
64	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39	X
65	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72	X
66	1	A/C PIPE COMPRESSOR	\$	334.29	X
67	1	A/C PIPE	\$	658.72	X
68	1	A/C COMRPRESSOR	\$	2,684.61	X
69	1	AIR COOLER	\$	792.60	X
70	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	X
71	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	X
72	1	TRANSMISSION COOLER	\$	1,219.30	X
73	1	TRANSMISSION COOLER PAD	\$	17.96	X
74	1	RADIATOR	\$	1,202.20	X
75	2	RADIATOR STUD UPPER	\$	14.41	X
76	2	RADIATOR BUSH UPPER	\$	50.12	X



**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1802-142

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5959R -

77	2	RADIATOR MTG LOWER	\$	55.85	
78	1	RADAI TOR FAN COWLING	\$	820.54	
79	1	RADIATOR FAN MOTOR LH	\$	967.36	
80	1	RADIATOR FAN MOTOR RH	\$	1,479.46	
81	1	RADIATOR TANK	\$	324.62	
82	1	RADIATOR HOSE UPPER	\$	240.56	
83	1	RADIATOR HOSE LOWER	\$	491.18	
84	1	RADIATOR TANK HOSE	\$	61.18	
85	1	WINDSCREEN FRT	\$	1,364.06	
86	1	SEATBELT LH	\$	2,937.80	
87	1	SEATBELT RH	\$	2,925.37	
88	1	SEATBELT BUCKLE LH	\$	984.13	
89	1	SEATBELT BUCKLE RH	\$	949.80	
90	1	PASSENGER AIRBAG	\$	3,412.40	
91	1	STEERING AIRBAG	\$	2,525.75	
92	1	AIRBAG COMPUTER	\$	1,259.82	
93	1	AIRBAG SENSOR	\$	724.63	
94	1	AIRBAG SENSOR	\$	289.30	
95	1	ROTARY SWITCH	\$	1,253.11	
96	1	DASHBOARD	\$	4,900.54	X
97	1	LOWER ARM LH	\$	685.76	✓
98	1	KUNCKLE ARM LH	\$	846.98	✓
99	1	KUNCKLE HUB+BEARING LH	\$	497.69	X
100	1	ABSORBER FRT LH	\$	360.54	✓
101	1	LOWER ARM RH	\$	685.76	✓
102	1	KUNCKLE ARM RH	\$	846.98	✓
103	1	KUNCKLE HUB+BEARING RH	\$	497.69	✓
104	1	ABSORBER FRT RH	\$	360.54	✓
105	1	DRIVESHAFT LH	\$	1,914.79	✓
106	1	DRIVESHAFT RH	\$	1,747.45	X

<b>TOTAL</b>	<b>\$</b>	<b>127,457.88</b>
<b>10%</b>	<b>\$</b>	<b>12,745.79</b>
	<b>\$</b>	<b>114,712.10</b>

**Specical Nett**

1	1SET	RADAI TOR GRILLE FRAME CLIP	\$	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5959R -****AAD1802-142**

7	1	TOW COVER FRT	\$	Sn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	
14	1SET	WHEELARCH CLIP FRT RH	\$	nn	29.40	
15	1	CAP HUB LH FRT	\$	Sn	35.00	
16	1	RIM LH FRT	\$	Sn	385.00	
17	1	TYRE LH FRT	\$	Sn	330.00	
18	1	CAP HUB RH FRT	\$	Sn	35.00	
19	1	RIM RH FRT	\$	B	385.00	
20	1	TYRE RH FRT	\$	297 Sn	330.00	Polish
21	1SET	Front licence plate with holder	\$	Sn	80.00	X
22	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
23	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

<b>TOTAL</b>	<b>\$</b>	<b>2,182.40</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>116,894.50</b>

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 <sup>300/</sup>

Towing Fees.

\$ 120.00 <sup>50/</sup>

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 4,500.00 <sup>220/</sup>

To rust-proofing of the affected areas.

\$ nn 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 <sup>60/</sup>

To transfer of tire, rim and on wheel balancing.

\$ 170.00 <sup>20/</sup>

To Check Electrical Lighting Concerned.

\$ 170.00 <sup>15/</sup>

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5959R -****AAD1802-142**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 <i>30d</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>10d</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>5d</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 <i>5d</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>

<b>TOTAL</b>	<b>\$</b>	<b>12,400.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>129,294.50</b>

&lt; parts by parts &gt; Repair Days

~~15 DAYS~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP18003826/Kvbe2

NO.2 ANG MO KIO STREET 63SINGAPORE 569111

Date : 12-11-2018



Code : TP378

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHC 5959R
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	19/02/2018

## 2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281245	Colour	METALLIC WHITE / RED
Odometer	407728	Steering	JAMMED
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	PRIMEWELL	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	13/02/2018	Inspection Date	19/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5959R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	DISTORTED	181.75	181.75
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	TO REPAIR SEE LABOUR	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-

Report Ref No. CS/TP18003826/Kvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	WHEELARCH FRT RH	TORN	278.84	278.84
1	FENDER BRACKET LOWER LH	TO REPAIR SEE LABOUR	15.79	-
1	FENDER BRACKET LOWER RH	TO REPAIR SEE LABOUR	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	STEERING PUMP ELECTRIC	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK	TO REPAIR SEE LABOUR	4,413.11	-
1	ENGINE HARNESS	SERVICEABLE	4,084.54	-
1	SUBFRAME OUTER FRT	BENT	2,652.45	2,652.45
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH	BENT	92.36	92.36
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-

Report Ref No. CS/TP18003826/Kvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TOP COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	BENT / PUNCTURE	1,219.30	1,219.30
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	WINDSCREEN FRT	SERVICEABLE	1,364.06	-
1	SEATBELT LH	SERVICEABLE	2,937.80	-
1	SEATBELT RH	SERVICEABLE	2,925.37	-
1	SEATBELT BUCKLE LH	SERVICEABLE	984.13	-
1	SEATBELT BUCKLE RH	SERVICEABLE	949.80	-
1	PASSENGER AIRBAG	SERVICEABLE	3,412.40	-
1	STEERING AIRBAG	SERVICEABLE	2,525.75	-
1	AIRBAG COMPUTER	SERVICEABLE	1,259.82	-
1	AIRBAG SENSOR	SERVICEABLE	724.63	-
1	AIRBAG SENSOR	SERVICEABLE	289.30	-
1	ROTARY SWITCH	SERVICEABLE	1,253.11	-

Report Ref No. CS/TP18003826/Kvbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DASHBOARD	SERVICEABLE	4,900.54	-
1	LOWER ARM LH	SERVICEABLE	685.76	-
1	KUNCKLE ARM LH	SERVICEABLE	846.98	-
1	KUNCKLE HUB + BEARING LH	SERVICEABLE	497.69	-
1	ABSORBER FRT LH	BENT	360.54	360.54
1	LOWER ARM RH	BENT	685.76	685.76
1	KUNCKLE ARM RH	BENT	846.98	846.98
1	KUNCKLE HUB+BEARING RH	NECESSARY	497.69	497.69
1	ABSORBER FRT RH	BENT	360.54	360.54
1	DRIVESHAFT LH	TO REPAIR SEE LABOUR	1,914.79	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
	LESS 10% DISCOUNT		-8,635.63	-843.56
			77,720.66	7,592.07
1	AUTO GEARBOX (LOCAL REPAIR) (SN)	HOUSING CRACKED	41,101.58	3,500.00
	LESS 10% DISCOUNT		-4,110.16	-
			36,991.42	3,500.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	29.40	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-

Report Ref No. CS/TP18003826/Kvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH FRT (SN)	SERVICEABLE	35.00	-
1	RIM RH FRT (SN)	BENT	385.00	385.00
1	TYRE RH FRT (90%) (SN)	PUNCTURE	330.00	297.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER "6555-3333" LH (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "6555-3333" RH (SN)	NOT NECESSARY	80.00	-
			2,182.40	748.00
	<b>LABOUR</b>			
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, FRAME FULL SUPPORT PANEL, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, HEADLAMP PANEL FRT LH, HEADLAMP PANEL FRT RH, BONNET, } BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK, FENDER PANEL FRT LH, FENDER PANEL FRT RH, FENDER BRACKET LOWER LH, FENDER BRACKET LOWER RH, STEERING PINION RACK, SUBFRAME BRACKET OUTER LH, DRIVESHAFT LH AND DRIVESHAFT RH. }		4,200.00	300.00
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHERS, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	300.00

Report Ref No. CS/TP18003826/Kvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			12,400.00	1,165.00
	<b>GRAND TOTAL</b>		<b>129,294.48</b>	<b>13,005.07</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>10,400.00</b>

Report Ref No. CS/TP18003826/Kvbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.