

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
INSIGHT ADJUSTERS AND SURVEYORS PL			Ref : CS/IAS18003876/Gvbn2		
133 CECIL STREET #14-02 KECK SENG TOWER SINGAPORE 069535		Date: 24-04-2018  Code: IAS			
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	FBH 4319P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	IA2018-36971/YCK	Excess (\$)	0.00	
	Assign From	KENNETH YEE	Assign Date	28/02/2018	
2. Vehicle Particulars & Condition					
	Make & Model	BMW R1200GS	c.c	1170	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WB1047006DZY30168	Colour	BLACK	
	Odometer	31639	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	110/80 R19	METZELER	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	150/70 R17	METZELER	4 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/12/2017	Inspection Date	28/02/2018	
	Survey held at	DE XING MOTOR PTE LTD			
		BLK 3006 UBI ROAD 1 #01-356 SINGAPORE 408700			
5a.	Remarks				
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				